**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TB4002-0AG1 | 3RT1016-1AK61 | |
| 3TB4010-0AA8 | 3RT1016-1AK61 | |
| 3TB4010-0AB8 | 3RT1016-1AM21 | |
| 3TB4010-0AC1 | 3RT1016-1AB01 | |
| 3TB4010-0AC8 | 3RT1016-1AP61 | |
| 3TB4010-0AD8 | 3RT1016-1AV61 | |
| 3TB4010-0AE8 | 3RT1016-1AT61 | |
| 3TB4010-0AF8 | 3RT1016-1AB01 | |
| 3TB4010-0AG0 | NO DIRECT REPLACEMENT | |
| 3TB4010-0AG1 | 3RT1016-1AK61 | |
| 3TB4010-0AG8 | 3RT1016-1AU61 | |
| 3TB4010-0AH0 | 3RT1016-1AH01 | |
| 3TB4010-0AJ1 | 3RT1016-1AK61 | |
| 3TB4010-0AK1 | 3RT1016-1AK61 | |
| 3TB4010-0AM0 | 3RT1016-1AP61 | |
| 3TB4010-0AM1 | 3RT1016-1AM21 | |
| 3TB4010-0AN1 | 3RT1016-1AP61 | |
| 3TB4010-0BB4 | 3RT1016-1BB41 | |
| 3TB4010-0BG4 | 3RT1016-1BG41 | |
| 3TB4010-0BV4 | NO DIRECT REPLACEMENT | |
| 3TB4011-0AC1 | 3RT1016-1AB02 | |
| 3TB4011-0AJ1 | 3RT1016-1AK62 | |
| 3TB4011-0AK6 | 3RT1016-1AK62 | |
| 3TB4011-0AM0 | 3RT1016-1AP62 | |
| 3TB4011-0AN1 | 3RT1016-1AP62 | |
| 3TB4011-0BB4 | 3RT1016-1BB42 | |
| 3TB4012-0AA8 | 3RT1016-1AK61 + 3RH1911-1HA01 | |
| 3TB4012-0AB8 | 3RT1016-1AM21 + 3RH1911-1HA01 | |
| 3TB4012-0AC1 | 3RT1016-1AB01 + 3RH1911-1HA01 | |
| 3TB4012-0AC8 | 3RT1016-1AP61 + 3RH1911-1HA01 | |
| 3TB4012-0AD8 | 3RT1016-1AV61 + 3RH1911-1HA01 | |
| 3TB4012-0AE8 | 3RT1016-1AT61 + 3RH1911-1HA01 | |
| 3TB4012-0AF8 | 3RT1016-1AB01 + 3RH1911-1HA01 | |
| 3TB4012-0AG0 | NO DIRECT REPLACEMENT | |
| 3TB4012-0AG1 | 3RT1016-1AK61 + 3RH1911-1HA01 | |
| 3TB4012-0AG8 | 3RT1016-1AU61 + 3RH1911-1HA01 | |
| 3TB4012-0AM0 | 3RT1016-1AP61 + 3RH1911-1HA01 | |
| 3TB4012-0AN1 | 3RT1016-1AP61 + 3RH1911-1HA01 | |
| 3TB4012-0BB4 | 3RT1016-1BB41 + 3RH1911-1HA01 | |
| 3TB4012-0BG4 | 3RT1016-1BG41 + 3RH1911-1HA01 | |
| 3TB4012-0BZ74 | NO DIRECT REPLACEMENT | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TB4017-0AA8 | 3RT1016-1AK61 + 3RH1911-1HA12 | |
| 3TB4017-0AB8 | 3RT1016-1AM21 + 3RH1911-1HA12 | |
| 3TB4017-0AC1 | 3RT1016-1AB01 + 3RH1911-1HA12 | |
| 3TB4017-0AC8 | 3RT1016-1AP61 + 3RH1911-1HA12 | |
| 3TB4017-0AD0 | 3RT1016-1AD01 + 3RH1911-1HA12 | |
| 3TB4017-0AD8 | 3RT1016-1AV61 + 3RH1911-1HA12 | |
| 3TB4017-0AE8 | 3RT1016-1AT61 + 3RH1911-1HA12 | |
| 3TB4017-0AF8 | 3RT1016-1AB01 + 3RH1911-1HA12 | |
| 3TB4017-0AG8 | 3RT1016-1AU61 + 3RH1911-1HA12 | |
| 3TB4017-0AJ1 | 3RT1016-1AK61 + 3RH1911-1HA12 | |
| 3TB4017-0AK1 | 3RT1016-1AK61 + 3RH1911-1HA12 | |
| 3TB4017-0AN1 | 3RT1016-1AP61 + 3RH1911-1HA12 | |
| 3TB4017-0AR1 | 3RT1016-1AV61 + 3RH1911-1HA12 | |
| 3TB4017-0BB4 | 3RT1016-1BB41 + 3RH1911-1HA12 | |
| 3TB4017-0BG4 | 3RT1016-1BG41 + 3RH1911-1HA12 | |
| 3TB4017-4BB4 | 3RT1016-1BB41 + 3RH1911-1HA12 | |
| 3TB4017-4MC1 | 3RT1016-1BB01 + 3RH1911-1HA12 | |
| 3TB4102-0AC0 | NO DIRECT REPLACEMENT | |
| 3TB4102-0AC1 | 3RT1017-1AB01 + 3RH1911-1HA01 | |
| 3TB4110-0AA8 | 3RT1017-1AK61 | |
| 3TB4110-0AB8 | 3RT1017-1AM21 | |
| 3TB4110-0AC1 | 3RT1017-1AB01 | |
| 3TB4110-0AC8 | 3RT1017-1AP61 | |
| 3TB4110-0AD8 | 3RT1017-1AV61 | |
| 3TB4110-0AE8 | 3RT1017-1AT61 | |
| 3TB4110-0AF8 | 3RT1017-1AB01 | |
| 3TB4110-0AG8 | 3RT1017-1AU61 | |
| 3TB4110-0AJ1 | 3RT1017-1AK61 | |
| 3TB4110-0AM0 | 3RT1017-1AP61 | |
| 3TB4110-0AN1 | 3RT1017-1AP61 | |
| 3TB4110-0BB4 | 3RT1017-1BB41 | |
| 3TB4110-0BG4 | 3RT1017-1BG41 | |
| 3TB4111-0AG1 | 3RT1017-1AK62 | |
| 3TB4111-0AJ1 | 3RT1017-1AK62 | |
| 3TB4111-0AN1 | 3RT1017-1AP62 | |
| 3TB4112-0AA8 | 3RT1017-1AK61 + 3RH1911-1HA01 | |
| 3TB4112-0AB8 | 3RT1017-1AM21 + 3RH1911-1HA01 | |
| 3TB4112-0AC1 | 3RT1017-1AB01 + 3RH1911-1HA01 | |
| 3TB4112-0AC8 | 3RT1017-1AP61 + 3RH1911-1HA01 | |
| 3TB4112-0AD8 | 3RT1017-1AV61 + 3RH1911-1HA01 | |
| 3TB4112-0AE8 | 3RT1017-1AT61 + 3RH1911-1HA01 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TB4112-0AF8 | 3RT1017-1AB01 + 3RH1911-1HA01 | |
| 3TB4112-0AG8 | 3RT1017-1AU61 + 3RH1911-1HA01 | |
| 3TB4112-0AJ1 | 3RT1017-1AK61 + 3RH1911-1HA01 | |
| 3TB4112-0AK1 | 3RT1017-1AK61 + 3RH1911-1HA01 | |
| 3TB4112-0AM0 | 3RT1017-1AP61 + 3RH1911-1HA01 | |
| 3TB4112-0AN1 | 3RT1017-1AP61 + 3RH1911-1HA01 | |
| 3TB4112-0BB4 | 3RT1017-1BB41 + 3RH1911-1HA01 | |
| 3TB4112-0BG4 | 3RT1017-1BG41 + 3RH1911-1HA01 | |
| 3TB4117-0AA8 | 3RT1017-1AK61 + 3RH1911-1HA12 | |
| 3TB4117-0AB8 | 3RT1017-1AM21 + 3RH1911-1HA12 | |
| 3TB4117-0AC1 | 3RT1017-1AB01 + 3RH1911-1HA12 | |
| 3TB4117-0AC8 | 3RT1017-1AP61 + 3RH1911-1HA12 | |
| 3TB4117-0AD8 | 3RT1017-1AV61 + 3RH1911-1HA12 | |
| 3TB4117-0AE8 | 3RT1017-1AT61 + 3RH1911-1HA12 | |
| 3TB4117-0AF8 | 3RT1017-1AB01 + 3RH1911-1HA12 | |
| 3TB4117-0AG8 | 3RT1017-1AU61 + 3RH1911-1HA12 | |
| 3TB4117-0AJ1 | 3RT1017-1AK61 + 3RH1911-1HA12 | |
| 3TB4117-0AM0 | 3RT1017-1AP61 + 3RH1911-1HA12 | |
| 3TB4117-0AN1 | 3RT1017-1AP61 + 3RH1911-1HA12 | |
| 3TB4117-0BB4 | 3RT1017-1BB41 + 3RH1911-1HA12 | |
| 3TB4117-0BG4 | 3RT1017-1BG41 + 3RH1911-1HA12 | |
| 3TB4117-0BM4 | 3RT1017-1BP41 + 3RH1911-1HA12 | |
| 3TB4210-0AA8 | 3RT1025-1AK60 + 3RH1921-1CA10 | |
| 3TB4210-0AB8 | 3RT1025-1AM20 + 3RH1921-1CA10 | |
| 3TB4210-0AC1 | 3RT1025-1AC20 + 3RH1921-1CA10 | |
| 3TB4210-0AC8 | 3RT1025-1AP60 + 3RH1921-1CA10 | |
| 3TB4210-0AD8 | 3RT1025-1AV60 + 3RH1921-1CA10 | |
| 3TB4210-0AE8 | 3RT1025-1AT60 + 3RH1921-1CA10 | |
| 3TB4210-0AF0 | 3RT1025-1AK60 + 3RH1921-1CA10 | |
| 3TB4210-0AF8 | 3RT1025-1AC20 + 3RH1921-1CA10 | |
| 3TB4210-0AG8 | 3RT1025-1AU60 + 3RH1921-1CA10 | |
| 3TB4210-0AJ1 | 3RT1025-1AK60 + 3RH1921-1CA10 | |
| 3TB4210-0AM0 | 3RT1025-1AP60 + 3RH1921-1CA10 | |
| 3TB4210-0AN1 | 3RT1025-1AP60 + 3RH1921-1CA10 | |
| 3TB4210-0BB4 | 3RT1025-1BB40 + 3RH1921-1CA10 | |
| 3TB4210-0BG4 | 3RT1025-1BG40 + 3RH1921-1CA10 | |
| 3TB4210-0BV4 | NO DIRECT REPLACEMENT | |
| 3TB4212-0AA8 | 3RT1025-1AK60 + 3RH1921-1EA11 | |
| 3TB4212-0AB8 | 3RT1025-1AM20 + 3RH1921-1EA11 | |
| 3TB4212-0AC1 | 3RT1025-1AC20 + 3RH1921-1EA11 | |
| 3TB4212-0AC8 | 3RT1025-1AP60 + 3RH1921-1EA11 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TB4212-0AD8 | 3RT1025-1AV60 + 3RH1921-1EA11 | |
| 3TB4212-0AE0 | NO DIRECT REPLACEMENT | |
| 3TB4212-0AE8 | 3RT1025-1AT60 + 3RH1921-1EA11 | |
| 3TB4212-0AF8 | 3RT1025-1AC20 + 3RH1921-1EA11 | |
| 3TB4212-0AG8 | 3RT1025-1AU60 + 3RH1921-1EA11 | |
| 3TB4212-0AH0 | 3RT1025-1AH00 + 3RH1921-1EA11 | |
| 3TB4212-0AJ1 | 3RT1025-1AK60 + 3RH1921-1EA11 | |
| 3TB4212-0AM0 | 3RT1025-1AP60 + 3RH1921-1EA11 | |
| 3TB4212-0AN1 | 3RT1025-1AP60 + 3RH1921-1EA11 | |
| 3TB4212-0AP1 | 3RT1025-1AP60 + 3RH1921-1EA11 | |
| 3TB4212-0AQ0 | 3RT1025-1AV00 + 3RH1921-1EA11 | |
| 3TB4212-0AR1 | 3RT1025-1AV60 + 3RH1921-1EA11 | |
| 3TB4212-0AS1 | 3RT1025-1AT60 + 3RH1921-1EA11 | |
| 3TB4212-0BB4 | 3RT1025-1BB40 + 3RH1921-1EA11 | |
| 3TB4212-0BF4 | 3RT1025-1BF40 + 3RH1921-1EA11 | |
| 3TB4212-0BG4 | 3RT1025-1BG40 + 3RH1921-1EA11 | |
| 3TB4212-0BM4 | 3RT1025-1BP40 + 3RH1921-1EA11 | |
| 3TB4212-6BB4 | 3RT1025-1BB40 + 3RH1921-1EA11 | |
| 3TB4213-0AC1 | 3RT1025-1AC20 + 3RH1921-1EA20 | |
| 3TB4213-0AJ1 | 3RT1025-1AK60 + 3RH1921-1EA20 | |
| 3TB4213-0AN1 | 3RT1025-1AP60 + 3RH1921-1EA20 | |
| 3TB4213-0AR0 | 3RT1025-1AV00 + 3RH1921-1EA20 | |
| 3TB4217-0AA8 | 3RT1025-1AK60 + 3RH1921-1FA22 | |
| 3TB4217-0AB0 | 3RT1025-1AC20 + 3RH1921-1FA22 | |
| 3TB4217-0AB8 | 3RT1025-1AM20 + 3RH1921-1FA22 | |
| 3TB4217-0AC1 | 3RT1025-1AC20 + 3RH1921-1FA22 | |
| 3TB4217-0AC8 | 3RT1025-1AP60 + 3RH1921-1FA22 | |
| 3TB4217-0AD8 | 3RT1025-1AV60 + 3RH1921-1FA22 | |
| 3TB4217-0AE8 | 3RT1025-1AT60 + 3RH1921-1FA22 | |
| 3TB4217-0AF0 | 3RT1025-1AK60 + 3RH1921-1FA22 | |
| 3TB4217-0AF8 | 3RT1025-1AC20 + 3RH1921-1FA22 | |
| 3TB4217-0AG0 | NO DIRECT REPLACEMENT | |
| 3TB4217-0AG8 | 3RT1025-1AU60 + 3RH1921-1FA22 | |
| 3TB4217-0AH0 | 3RT1025-1AH00 + 3RH1921-1FA22 | |
| 3TB4217-0AJ1 | 3RT1025-1AK60 + 3RH1921-1FA22 | |
| 3TB4217-0AM0 | 3RT1025-1AP60 + 3RH1921-1FA22 | |
| 3TB4217-0AN1 | 3RT1025-1AP60 + 3RH1921-1FA22 | |
| 3TB4217-0AR1 | 3RT1025-1AV60 + 3RH1921-1FA22 | |
| 3TB4217-0BB4 | 3RT1025-1BB40 + 3RH1921-1FA22 | |
| 3TB4217-0BE4 | 3RT1025-1BE40 + 3RH1921-1FA22 | |
| 3TB4217-0BE8 | 3RT1025-1BT60 + 3RH1921-1FA22 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TB4217-0BG4 | 3RT1025-1BG40 + 3RH1921-1FA22 | |
| 3TB4217-0BM4 | 3RT1025-1BP40 + 3RH1921-1FA22 | |
| 3TB4217-0BP4 | 3RT1025-1BP40 + 3RH1921-1FA22 | |
| 3TB4217-0BV4 | NO DIRECT REPLACEMENT | |
| 3TB4217-0BZ80 | NO DIRECT REPLACEMENT | |
| 3TB4217-4MC1 | 3RT1025-1BC20 + 3RH1921-1FA22 | |
| 3TB4217-6EG1 | NO DIRECT REPLACEMENT | |
| 3TB4217-6EK6 | 3RT1025-1BK60 + 3RH1921-1FA22 | |
| 3TB4217-7EG1 | NO DIRECT REPLACEMENT | |
| 3TB4217-7EK6 | NO DIRECT REPLACEMENT | |
| 3TB4310-0AA8 | 3RT1026-1AK60 + 3RH1921-1CA10 | |
| 3TB4310-0AB8 | 3RT1026-1AM20 + 3RH1921-1CA10 | |
| 3TB4310-0AC1 | 3RT1026-1AC20 + 3RH1921-1CA10 | |
| 3TB4310-0AC8 | 3RT1026-1AP60 + 3RH1921-1CA10 | |
| 3TB4310-0AD8 | 3RT1026-1AV60 + 3RH1921-1CA10 | |
| 3TB4310-0AE8 | 3RT1026-1AT60 + 3RH1921-1CA10 | |
| 3TB4310-0AF8 | 3RT1026-1AC20 + 3RH1921-1CA10 | |
| 3TB4310-0AG8 | 3RT1026-1AU60 + 3RH1921-1CA10 | |
| 3TB4310-0AN1 | 3RT1026-1AP60 + 3RH1921-1CA10 | |
| 3TB4310-0BB4 | 3RT1026-1BB40 + 3RH1921-1CA10 | |
| 3TB4310-0BG4 | 3RT1026-1BG40 + 3RH1921-1CA10 | |
| 3TB4310-8GB4 | 3RT1026-1BB40 + 3RH1921-1CA10 | |
| 3TB4312-0AA8 | 3RT1026-1AK60 + 3RH1921-1EA11 | |
| 3TB4312-0AB8 | 3RT1026-1AM20 + 3RH1921-1EA11 | |
| 3TB4312-0AC8 | 3RT1026-1AP60 + 3RH1921-1EA11 | |
| 3TB4312-0AD8 | 3RT1026-1AV60 + 3RH1921-1EA11 | |
| 3TB4312-0AE8 | 3RT1026-1AT60 + 3RH1921-1EA11 | |
| 3TB4312-0AF8 | 3RT1026-1AC20 + 3RH1921-1EA11 | |
| 3TB4312-0AG8 | 3RT1026-1AU60 + 3RH1921-1EA11 | |
| 3TB4312-0AJ1 | 3RT1026-1AK60 + 3RH1921-1EA11 | |
| 3TB4312-0AN1 | 3RT1026-1AP60 + 3RH1921-1EA11 | |
| 3TB4312-0BB4 | 3RT1026-1BB40 + 3RH1921-1EA11 | |
| 3TB4312-0BG4 | 3RT1026-1BG40 + 3RH1921-1EA11 | |
| 3TB4312-6BB4 | 3RT1026-1BB40 + 3RH1921-1EA11 | |
| 3TB4313-0AJ1 | 3RT1026-1AK60 + 3RH1921-1FA22 | |
| 3TB4317-0AA8 | 3RT1026-1AK60 + 3RH1921-1FA22 | |
| 3TB4317-0AB8 | 3RT1026-1AM20 + 3RH1921-1FA22 | |
| 3TB4317-0AC1 | 3RT1026-1AC20 + 3RH1921-1FA22 | |
| 3TB4317-0AC8 | 3RT1026-1AP60 + 3RH1921-1FA22 | |
| 3TB4317-0AD1 | 3RT1026-1AD20 + 3RH1921-1FA22 | |
| 3TB4317-0AD8 | 3RT1026-1AV60 + 3RH1921-1FA22 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TB4317-0AE8 | 3RT1026-1AT60 + 3RH1921-1FA22 | |
| 3TB4317-0AF0 | 3RT1026-1AK60 + 3RH1921-1FA22 | |
| 3TB4317-0AF8 | 3RT1026-1AC20 + 3RH1921-1FA22 | |
| 3TB4317-0AG8 | 3RT1026-1AU60 + 3RH1921-1FA22 | |
| 3TB4317-0AJ1 | 3RT1026-1AK60 + 3RH1921-1FA22 | |
| 3TB4317-0AK1 | 3RT1026-1AK60 + 3RH1921-1FA22 | |
| 3TB4317-0AM0 | 3RT1026-1AP60 + 3RH1921-1FA22 | |
| 3TB4317-0AN1 | 3RT1026-1AP60 + 3RH1921-1FA22 | |
| 3TB4317-0AV0 | 3RT1026-1AV00 + 3RH1921-1FA22 | |
| 3TB4317-0BB4 | 3RT1026-1BB40 + 3RH1921-1FA22 | |
| 3TB4317-0BD4 | 3RT1026-1BD40 + 3RH1921-1FA22 | |
| 3TB4317-0BG4 | 3RT1026-1BG40 + 3RH1921-1FA22 | |
| 3TB4317-0BZ80 | NO DIRECT REPLACEMENT | |
| 3TB4317-6EH0 | 3RT1026-1BH00 + 3RH1921-1FA22 | |
| 3TB4317-6EK6 | 3RT1026-1BK60 + 3RH1921-1FA22 | |
| 3TB4317-7EH0 | 3RT1026-1BH00 + 3RH1921-1FA22 | |
| 3TB4317-7EK6 | 3RT1026-1BK60 + 3RH1921-1FA22 | |
| 3TB4317-8GB4 | 3RT1026-1BB40 + 3RH1921-1FA22 | |
| 3TB4417-0AA8 | 3RT1034-1AK60 + 3RH1921-1FA22 | |
| 3TB4417-0AB8 | 3RT1034-1AM20 + 3RH1921-1FA22 | |
| 3TB4417-0AC8 | 3RT1034-1AP60 + 3RH1921-1FA22 | |
| 3TB4417-0AD8 | 3RT1034-1AV60 + 3RH1921-1FA22 | |
| 3TB4417-0AE8 | 3RT1034-1AT60 + 3RH1921-1FA22 | |
| 3TB4417-0AF8 | 3RT1034-1AC20 + 3RH1921-1FA22 | |
| 3TB4417-0AG1 | 3RT1034-1AK60 + 3RH1921-1FA22 | |
| 3TB4417-0AG1Z0E | NO DIRECT REPLACEMENT | |
| 3TB4417-0AG8 | 3RT1034-1AU60 + 3RH1921-1FA22 | |
| 3TB4417-0AJ1 | 3RT1034-1AK60 + 3RH1921-1FA22 | |
| 3TB4417-0AK6Z0E | NO DIRECT REPLACEMENT | |
| 3TB4417-0AM0 | 3RT1034-1AP60 + 3RH1921-1FA22 | |
| 3TB4417-0AN1 | 3RT1034-1AP60 + 3RH1921-1FA22 | |
| 3TB4417-0AV0 | 3RT1034-1AV00 + 3RH1921-1FA22 | |
| 3TB4417-0BB4 | 3RT1034-1BB40 + 3RH1921-1FA22 | |
| 3TB4417-0BC4 | NO DIRECT REPLACEMENT | |
| 3TB4417-0BE4 | 3RT1034-1BE40 + 3RH1921-1FA22 | |
| 3TB4417-0BF4 | 3RT1034-1BF40 + 3RH1921-1FA22 | |
| 3TB4417-0BG4 | 3RT1034-1BG40 + 3RH1921-1FA22 | |
| 3TB4417-0BV4 | NO DIRECT REPLACEMENT | |
| 3TB4417-0BW4 | 3RT1034-1BW40 + 3RH1921-1FA22 | |
| 3TB4417-0BZ74 | NO DIRECT REPLACEMENT | |
| 3TB4417-0BZ80 | NO DIRECT REPLACEMENT | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TB4422-0BW4 | 3RT1034-1BW40 + 3RH1921-1FA22 | |
| 3TB4614-0AG1 | NO DIRECT REPLACEMENT | |
| 3TB4617-0AA8 | 3RT1036-1AK60 + 3RH1921-1FA22 | |
| 3TB4617-0AC8 | 3RT1036-1AP60 + 3RH1921-1FA22 | |
| 3TB4617-0AD0 | 3RT1036-1AD00 + 3RH1921-1FA22 | |
| 3TB4617-0AD8 | 3RT1036-1AV60 + 3RH1921-1FA22 | |
| 3TB4617-0AF8 | 3RT1036-1AC20 + 3RH1921-1FA22 | |
| 3TB4617-0BB4 | 3RT1036-1BB40 + 3RH1921-1FA22 | |
| 3TB4617-0BG4 | 3RT1036-1BG40 + 3RH1921-1FA22 | |
| 3TB4617-0BV4 | NO DIRECT REPLACEMENT | |
| 3TB4717-0AA8 | 3RT1044-1AK60 + 3RH1921-1FA22 | |
| 3TB4717-0AC8 | 3RT1044-1AP60 + 3RH1921-1FA22 | |
| 3TB4717-0AD8 | 3RT1044-1AV60 + 3RH1921-1FA22 | |
| 3TB4717-0AF8 | 3RT1044-1AC20 + 3RH1921-1FA22 | |
| 3TB4717-0BB4 | 3RT1044-1BB40 + 3RH1921-1FA22 | |
| 3TB4717-0BC4 | NO DIRECT REPLACEMENT | |
| 3TB4717-0BE4 | 3RT1044-1BE40 + 3RH1921-1FA22 | |
| 3TB4717-0BG4 | 3RT1044-1BG40 + 3RH1921-1FA22 | |
| 3TB4817-0AA8 | 3RT1045-1AK60 + 3RH1921-1FA22 | |
| 3TB4817-0AB8 | 3RT1045-1AM20 + 3RH1921-1FA22 | |
| 3TB4817-0AC8 | 3RT1045-1AP60 + 3RH1921-1FA22 | |
| 3TB4817-0AD8 | 3RT1045-1AV60 + 3RH1921-1FA22 | |
| 3TB4817-0AF8 | 3RT1045-1AC20 + 3RH1921-1FA22 | |
| 3TB4817-0BB4 | 3RT1045-1BB40 + 3RH1921-1FA22 | |
| 3TB4817-0BE4 | 3RT1045-1BE40 + 3RH1921-1FA22 | |
| 3TB4817-0BG4 | 3RT1045-1BG40 + 3RH1921-1FA22 | |
| 3TB4817-0BP4 | 3RT1045-1BP40 + 3RH1921-1FA22 | |
| 3TB4817-0BQ4 | 3RT1045-1BP40 + 3RH1921-1FA22 | |
| 3TB4817-0BV4 | NO DIRECT REPLACEMENT | |
| 3TB4817-0BW4 | 3RT1045-1BW40 + 3RH1921-1FA22 | |
| 3TB4817-0WB4 | 3RT1045-1BB40 + 3RH1921-1FA22 | |
| 3TB5017-0AA8 | SEE 3TF5022-0AK6 | |
| 3TB5017-0BB4 | PRODUCT STILL AVAILABLE | |
| 3TB5017-0BE4 | PRODUCT STILL AVAILABLE | |
| 3TB5017-0BG4 | NO DIRECT REPLACEMENT | |
| 3TB5017-0BW4 | PRODUCT STILL AVAILABLE | |
| 3TB5217-0AA8 | SEE 3TF5222-0AK6 | |
| 3TB5217-0BB4 | PRODUCT STILL AVAILABLE | |
| 3TB5217-0BG4 | PRODUCT STILL AVAILABLE | |
| 3TB5417-0AA8 | SEE 3TF5422-0AK6 | |
| 3TB5417-0BB4 | PRODUCT STILL AVAILABLE | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TB5417-0BC4 | NO DIRECT REPLACEMENT | |
| 3TB5417-0BG4 | PRODUCT STILL AVAILABLE | |
| 3TB5617-0AA8 | SEE 3TF5622-0AK6 | |
| 3TB5617-0BB4 | PRODUCT STILL AVAILABLE | |
| 3TB5617-0BG4 | PRODUCT STILL AVAILABLE | |
| 3TB5617-0LV4 | PRODUCT STILL AVAILABLE | |
| 3TB5697-0AK1 | NO DIRECT REPLACEMENT | |
| 3TB5814-0AF0 | SEE 3TF6844-0CF71 | |
| 3TB5814-0BB4 | NO DIRECT REPLACEMENT | |
| 3TB5814-0BG4 | NO DIRECT REPLACEMENT | |
| 3TB5814-0DB4 | NO DIRECT REPLACEMENT | |
| 3TB5814-0DG4 | NO DIRECT REPLACEMENT | |
| 3TB5814-0DM4 | NO DIRECT REPLACEMENT | |
| 3TB5814-0DW4 | NO DIRECT REPLACEMENT | |
| 3TB5817-0BB4 | NO DIRECT REPLACEMENT | |
| 3TB5817-0BG4 | NO DIRECT REPLACEMENT | |
| 3TB5817-0BM4 | NO DIRECT REPLACEMENT | |
| 3TB5817-0BQ4 | NO DIRECT REPLACEMENT | |
| 3TB5817-0BW4 | NO DIRECT REPLACEMENT | |
| 3TD1011-0BG1 | 3RA1316-8XB30-1AK6 + 3RH1911-1HA01 | |
| 3TD1012-0BG1 | 3RA1316-8XB30-1AK6 + 3RH1911-1LA11 | |
| 3TD1017-0BG1 | 3RA1316-8XB30-1AK6 + 3RH1911-1HA22 | |
| 3TD1017-0CD0 | 3RA1316-8XB30-1AD0 + 3RH1911-1HA22 | |
| 3TD1017-0CF0 | 3RA1316-8XB30-1AK6 + 3RH1911-1HA22 | |
| 3TD1017-0CG1 | 3RA1316-8XB30-1AK6 + 3RH1911-1HA22 | |
| 3TD1017-0CN1 | 3RA1316-8XB30-1AP6 + 3RH1911-1HA22 | |
| 3TD1017-3BG4 | 3RA1316-8XB30-1BG4 + 3RH1911-1HA22 | |
| 3TD1017-3BN4 | NO DIRECT REPLACEMENT | |
| 3TD1017-3BW4 | 3RA1316-8XB30-1BW4 + 3RH1911-1HA22 | |
| 3TD1017-3CB4 | 3RA1316-8XB30-1BB4 + 3RH1911-1HA22 | |
| 3TD1111-0BG1 | 3RA1317-8XB30-1AK6 + 3RH1911-1HA01 | |
| 3TD1112-0BG1 | 3RA1317-8XB30-1AK6 + 3RH1911-1LA11 | |
| 3TD1117-0BG1 | 3RA1317-8XB30-1AK6 + 3RH1911-1HA22 | |
| 3TD1117-0CC1 | 3RA1317-8XB30-1AB0 + 3RH1911-1HA22 | |
| 3TD1117-0CG1 | 3RA1317-8XB30-1AK6 + 3RH1911-1HA22 | |
| 3TD1117-3CB4 | 3RA1317-8XB30-1BB4 + 3RH1911-1HA22 | |
| 3TD2000-0QK6-Z | NO DIRECT REPLACEMENT | |
| 3TD2000-1BA4 | 3RA1316-8XB30-1BA4 | |
| 3TD2000-1BB4 | 3RA1316-8XB30-1BB4 | |
| 3TD2000-1BG4 | 3RA1316-8XB30-1BG4 | |
| 3TD2000-1BW4 | 3RA1316-8XB30-1BW4 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TD2000-1QC2 | 3RA1316-8XB30-1AB0 | |
| 3TD2000-1QK6 | 3RA1316-8XB30-1AK6 | |
| 3TD2000-1QP6 | 3RA1316-8XB30-1AP6 | |
| 3TD2000-1QQ0 | 3RA1316-8XB30-1AV0 | |
| 3TD2000-3QK6-Z | NO DIRECT REPLACEMENT | |
| 3TD2002-2BA4 | 3RA1316-8XB30-1BA4 + (2) 3RH1911-1HA22 | |
| 3TD2002-2BB4 | 3RA1316-8XB30-1BB4 + (2) 3RH1911-1HA22 | |
| 3TD2002-2BG4 | 3RA1316-8XB30-1BG4 + (2) 3RH1911-1HA22 | |
| 3TD2002-2BW4 | 3RA1316-8XB30-1BW4 + (2) 3RH1911-1HA22 | |
| 3TD2002-2QB4 | 3RA1316-8XB30-1AB4 + (2) 3RH1911-1HA22 | |
| 3TD2002-2QC2 | 3RA1316-8XB30-1AB0 + (2) 3RH1911-1HA22 | |
| 3TD2002-2QG2 | 3RA1316-8XB30-1AK6 + (2) 3RH1911-1HA22 | |
| 3TD2002-2QK2 | 3RA1316-8XB30-1AK6 + (2) 3RH1911-1HA22 | |
| 3TD2002-2QK6 | 3RA1316-8XB30-1AK6 + (2) 3RH1911-1HA22 | |
| 3TD2002-2QP6 | 3RA1316-8XB30-1AP6 + (2) 3RH1911-1HA22 | |
| 3TD2002-2QQ0 | 3RA1316-8XB30-1AV0 + (2) 3RH1911-1HA22 | |
| 3TD2003-1BA4 | 3RA1316-8XB30-1BA4 + 3RH1911-1AA10 | |
| 3TD2003-1BB4 | 3RA1316-8XB30-1BB4 + 3RH1911-1AA10 | |
| 3TD2003-1BG4 | 3RA1316-8XB30-1BG4 + 3RH1911-1AA10 | |
| 3TD2003-1BV4 | NO DIRECT REPLACEMENT | |
| 3TD2003-1BW4 | 3RA1316-8XB30-1BW4 + 3RH1911-1AA10 | |
| 3TD2003-1QC2 | 3RA1316-8XB30-1AB0 + 3RH1911-1AA10 | |
| 3TD2003-1QK6 | 3RA1316-8XB30-1AK6 + 3RH1911-1AA10 | |
| 3TD2003-1QP6 | 3RA1316-8XB30-1AP6 + 3RH1911-1AA10 | |
| 3TD2003-1QQ0 | 3RA1316-8XB30-1AV0 + 3RH1911-1AA10 | |
| 3TD2003-6QK6-Z | NO DIRECT REPLACEMENT | |
| 3TD2110-0CZ | NO DIRECT REPLACEMENT | |
| 3TD4000-0AG2 | 3RA1323-8XB30-1AK6 | |
| 3TD4002-0AG2 | 3RA1323-8XB30-1AK6 + (2) 3RH1921-1FA22 | |
| 3TD4002-0BG4 | 3RA1323-8XB30-1BG4 + (2) 3RH1921-1FA22 | |
| 3TD4002-2AC0 | NO DIRECT REPLACEMENT | |
| 3TD4002-2AF0 | 3RA1323-8XB30-1AK6 + (2) 3RH1921-1FA22 | |
| 3TD4002-2AK2 | 3RA1323-8XB30-1AK6 + (2) 3RH1921-1FA22 | |
| 3TD4002-2AK6 | 3RA1323-8XB30-1AK6 + (2) 3RH1921-1FA22 | |
| 3TD4002-2AM0 | 3RA1323-8XB30-1AP6 + (2) 3RH1921-1FA22 | |
| 3TD4002-2AP6 | 3RA1323-8XB30-1AP6 + (2) 3RH1921-1FA22 | |
| 3TD4002-2BB4 | 3RA1323-8XB30-1BB4 + (2) 3RH1921-1FA22 | |
| 3TD4002-2BG4 | 3RA1323-8XB30-1BG4 + (2) 3RH1921-1FA22 | |
| 3TD4002-2BN4 | NO DIRECT REPLACEMENT | |
| 3TD4002-2BW4 | 3RA1323-8XB30-1BW4 + (2) 3RH1921-1FA22 | |
| 3TD4101-0AG2 | 3RA1324-8XB30-1AK6 + 3RH1921-1CA10 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TD4102-0AG2 | 3RA1324-8XB30-1AK6 + (2) 3RH1921-1FA22 | |
| 3TD4102-2AG2 | 3RA1324-8XB30-1AK6 + (2) 3RH1921-1FA22 | |
| 3TD4102-2AK2 | 3RA1324-8XB30-1AK6 + (2) 3RH1921-1FA22 | |
| 3TD4102-2AK6 | 3RA1324-8XB30-1AK6 + (2) 3RH1921-1FA22 | |
| 3TD4102-2BB4 | 3RA1324-8XB30-1BB4 + (2) 3RH1921-1FA22 | |
| 3TD4202-0AG2 | 3RA1325-8XB30-1AK6 + (2) 3RH1921-1FA22 | |
| 3TD4202-2AC2 | 3RA1325-8XB30-1AC2 + (2) 3RH1921-1FA22 | |
| 3TD4202-2AG2 | 3RA1325-8XB30-1AK6 + (2) 3RH1921-1FA22 | |
| 3TD4202-2AK6 | 3RA1325-8XB30-1AK6 + (2) 3RH1921-1FA22 | |
| 3TD4202-2AS0 | 3RA1325-8XB30-1AT6 + (2) 3RH1921-1FA22 | |
| 3TD4202-2BB4 | 3RA1325-8XB30-1BB4 + (2) 3RH1921-1FA22 | |
| 3TD4210-0BG1 | 3RA1325-8XB30-1BK6 + 3RH1921-1CA10 | |
| 3TD4210-0CF0 | 3RA1325-8XB30-1BK6 + 3RH1921-1CA10 | |
| 3TD4210-0CJ1 | 3RA1325-8XB30-1BK6 + 3RH1921-1CA10 | |
| 3TD4210-0CN1 | 3RA1325-8XB30-1BP6 + 3RH1921-1CA10 | |
| 3TD4210-3CB4 | 3RA1325-8XB30-1BB4 + 3RH1921-1CA10 | |
| 3TD4302-2AK6 | 3RA1326-8XB30-1AK6 + (2) 3RH1921-1FA22 | |
| 3TD4302-2BB4 | 3RA1326-8XB30-1BB4 + (2) 3RH1921-1FA22 | |
| 3TD4310-0BG1 | 3RA1326-8XB30-1BK6 + 3RH1921-1CA10 | |
| 3TD4310-0CG1 | 3RA1326-8XB30-1BK6 + 3RH1921-1CA10 | |
| 3TD4310-0CJ1 | 3RA1326-8XB30-1BK6 + 3RH1921-1CA10 | |
| 3TD4310-3CB4 | 3RA1326-8XB30-1BB4 + 3RH1921-1CA10 | |
| 3TD4402-2AK6 | 3RA1334-8XB30-1AK6 + (2) 3RH1921-1FA22 | |
| 3TD4410-0CF0 | 3RA1334-8XB30-1BK6 + 3RH1921-1CA10 | |
| 3TD4410-0CJ1 | 3RA1334-8XB30-1BK6 + 3RH1921-1CA10 | |
| 3TD4502-2AK6 | 3RA1335-8XB30-1AK6 + (2) 3RH1921-1FA22 | |
| 3TD4602-2AK6 | 3RA1336-8XB30-1AK6 + (2) 3RH1921-1FA22 | |
| 3TD4610-0CG1 | 3RA1336-8XB30-1AK6 + (2) 3RH1921-1FA22 | |
| 3TD4702-2AK6 | 3RA1344-8XB30-1AK6 + (2) 3RH1921-1FA22 | |
| 3TD4802-2AJ1 | 3RA1345-8XB30-1AK6 + (2) 3RH1921-1FA22 | |
| 3TD4802-2AK6 | 3RA1345-8XB30-1AK6 + (2) 3RH1921-1FA22 | |
| 3TD5002-2AF0 | PRODUCT STILL AVAILABLE | |
| 3TD5402-2AK6 | PRODUCT STILL AVAILABLE | |
| 3TD5602-2AK6 | PRODUCT STILL AVAILABLE | |
| 3TF2001-0AB0 | 3RT1016-1AB02 | |
| 3TF2001-0AC1 | 3RT1016-1AB02 | |
| 3TF2001-0AC2 | 3RT1016-1AB02 | |
| 3TF2001-0AF0 | 3RT1016-1AK62 | |
| 3TF2001-0AG1 | 3RT1016-1AK62 | |
| 3TF2001-0AG2 | 3RT1016-1AK62 | |
| 3TF2001-0AJ1 | 3RT1016-1AK62 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TF2001-0AJ2 | 3RT1016-1AK62 | |
| 3TF2001-0AK6 | 3RT1016-1AK62 | |
| 3TF2001-0AM1 | 3RT1016-1AM22 | |
| 3TF2001-0AM2 | 3RT1016-1AM22 | |
| 3TF2001-0AP6 | 3RT1016-1AP62 | |
| 3TF2001-0AQ0 | 3RT1016-1AV02 | |
| 3TF2001-0AS0 | 3RT1016-1AT62 | |
| 3TF2001-0AU1 | 3RT1016-1AU62 | |
| 3TF2001-0AV0 | 3RT1016-1AV02 | |
| 3TF2001-0BA4 | 3RT1016-1BA42 | |
| 3TF2001-0BB4 | 3RT1016-1BB42 | |
| 3TF2001-0BC4 | NO DIRECT REPLACEMENT | |
| 3TF2001-0BD4 | 3RT1016-1BD42 | |
| 3TF2001-0BG4 | 3RT1016-1BG42 | |
| 3TF2001-0BN4 | NO DIRECT REPLACEMENT | |
| 3TF2001-0BU4 | NO DIRECT REPLACEMENT | |
| 3TF2001-0BW4 | 3RT1016-1BW42 | |
| 3TF2001-0DB4 | 3RT1016-1HB42 | |
| 3TF2001-0FB4 | 3RT1016-1BB42 | |
| 3TF2001-0JB4 | 3RT1016-1JB42 | |
| 3TF2001-0LB4 | 3RT1016-1KB42 | |
| 3TF2001-0TB4 | 3RT1016-1BB42 | |
| 3TF2001-1AC2 | 3RT1016-1AB02 | |
| 3TF2001-1AK6 | 3RT1016-1AK62 | |
| 3TF2001-1AP6 | 3RT1016-1AP62 | |
| 3TF2001-1AQ0 | 3RT1016-1AV02 | |
| 3TF2001-1BB4 | 3RT1016-1BB42 | |
| 3TF2001-1BG4 | 3RT1016-1BG42 | |
| 3TF2001-1BN4 | NO DIRECT REPLACEMENT | |
| 3TF2001-1BW4 | 3RT1016-1BW42 | |
| 3TF2001-6AC2 | 3RT1016-1AB02 | |
| 3TF2001-6AK6 | 3RT1016-1AK62 | |
| 3TF2001-6AP6 | 3RT1016-1AP62 | |
| 3TF2001-6AQ0 | 3RT1016-1AV02 | |
| 3TF2001-6BB4 | 3RT1016-1BB42 | |
| 3TF2001-6BG4 | 3RT1016-1BG42 | |
| 3TF2001-6BN4 | NO DIRECT REPLACEMENT | |
| 3TF2001-6BW4 | 3RT1016-1BW42 | |
| 3TF2001-7AC2 | 3RT1016-1AB02 | |
| 3TF2001-7AK6 | 3RT1016-1AK62 | |
| 3TF2001-7AP6 | 3RT1016-1AP62 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TF2001-7AQ0 | 3RT1016-1AV02 | |
| 3TF2001-7BB4 | 3RT1016-1BB42 | |
| 3TF2001-7BG4 | 3RT1016-1BG42 | |
| 3TF2001-7BN4 | NO DIRECT REPLACEMENT | |
| 3TF2001-7BW4 | 3RT1016-1BW42 | |
| 3TF2010-0AB0 | 3RT1016-1AB01 | |
| 3TF2010-0AC1 | 3RT1016-1AB01 | |
| 3TF2010-0AC2 | 3RT1016-1AB01 | |
| 3TF2010-0AD0 | 3RT1016-1AD01 | |
| 3TF2010-0AF0 | 3RT1016-1AK61 | |
| 3TF2010-0AF6 | 3RT1016-1AK61 | |
| 3TF2010-0AG0 | 3RT1016-1AD01 | |
| 3TF2010-0AG1 | 3RT1016-1AK61 | |
| 3TF2010-0AG2 | 3RT1016-1AK61 | |
| 3TF2010-0AH0 | 3RT1016-1AH01 | |
| 3TF2010-0AJ1 | 3RT1016-1AK61 | |
| 3TF2010-0AK6 | 3RT1016-1AK61 | |
| 3TF2010-0AL2 | 3RT1016-1AP61 | |
| 3TF2010-0AM1 | 3RT1016-1AM21 | |
| 3TF2010-0AM2 | 3RT1016-1AM21 | |
| 3TF2010-0AN2 | 3RT1016-1AP61 | |
| 3TF2010-0AP0 | 3RT1016-1AP61 | |
| 3TF2010-0AP2 | 3RT1016-1AP61 | |
| 3TF2010-0AP6 | 3RT1016-1AP61 | |
| 3TF2010-0AQ0 | 3RT1016-1AV01 | |
| 3TF2010-0AQ2 | 3RT1016-1AV01 | |
| 3TF2010-0AS0 | 3RT1016-1AT61 | |
| 3TF2010-0AU1 | 3RT1016-1AU61 | |
| 3TF2010-0AV0 | 3RT1016-1AV01 | |
| 3TF2010-0BA4 | 3RT1016-1BA41 | |
| 3TF2010-0BB4 | 3RT1016-1BB41 | |
| 3TF2010-0BF4 | 3RT1016-1BF41 | |
| 3TF2010-0BG4 | 3RT1016-1BG41 | |
| 3TF2010-0BN4 | NO DIRECT REPLACEMENT | |
| 3TF2010-0BQ4 | 3RT1016-1BP41 | |
| 3TF2010-0BV4 | NO DIRECT REPLACEMENT | |
| 3TF2010-0BW4 | 3RT1016-1BW41 | |
| 3TF2010-0DB4 | 3RT1016-1BB41 | |
| 3TF2010-0FB4 | 3RT1016-1BB41 | |
| 3TF2010-0JB4 | 3RT1016-1JB41 | |
| 3TF2010-0LB4 | 3RT1016-1KB41 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TF2010-0LF4 | 3RT1016-2KF41 | |
| 3TF2010-0TB4 | 3RT1016-1BB41 | |
| 3TF2010-1AC2 | 3RT1016-1AB01 | |
| 3TF2010-1AK6 | 3RT1016-1AK61 | |
| 3TF2010-1AM2 | 3RT1016-1AM21 | |
| 3TF2010-1AP0 | 3RT1016-1AP61 | |
| 3TF2010-1AP6 | 3RT1016-1AP61 | |
| 3TF2010-1AQ0 | 3RT1016-1AV01 | |
| 3TF2010-1BB4 | 3RT1016-1BB41 | |
| 3TF2010-1BG4 | 3RT1016-1BG41 | |
| 3TF2010-1BN4 | NO DIRECT REPLACEMENT | |
| 3TF2010-1BW4 | 3RT1016-1BW41 | |
| 3TF2010-6AC2 | 3RT1016-1AB01 | |
| 3TF2010-6AK6 | 3RT1016-1AK61 | |
| 3TF2010-6AP6 | 3RT1016-1AP61 | |
| 3TF2010-6AQ0 | 3RT1016-1AV01 | |
| 3TF2010-6BB4 | 3RT1016-1BB41 | |
| 3TF2010-6BG4 | 3RT1016-1BG41 | |
| 3TF2010-6BN4 | NO DIRECT REPLACEMENT | |
| 3TF2010-6BW4 | 3RT1016-1BW41 | |
| 3TF2010-7AC2 | 3RT1016-1AB01 | |
| 3TF2010-7AK6 | 3RT1016-1AK61 | |
| 3TF2010-7AM2 | 3RT1016-1AM21 | |
| 3TF2010-7AP6 | 3RT1016-1AP61 | |
| 3TF2010-7AQ0 | 3RT1016-1AV01 | |
| 3TF2010-7BA4 | 3RT1016-1BA41 | |
| 3TF2010-7BB4 | 3RT1016-1BB41 | |
| 3TF2010-7BG4 | 3RT1016-1BG41 | |
| 3TF2010-7BN4 | NO DIRECT REPLACEMENT | |
| 3TF2010-7BW4 | 3RT1016-1BW41 | |
| 3TF2080-0AG2 | 3RT1317-1AK60 | |
| 3TF2080-0AP6 | 3RT1317-1AP60 | |
| 3TF2211-0AG1 | 3RT1016-1AK61 + 3RH1911-1HA01 | |
| 3TF2211-0BB4 | 3RT1016-1BB41 + 3RH1911-1HA01 | |
| 3TF2222-0AC1 | 3RT1016-1AB01 + 3RH1911-1HA12 | |
| 3TF2222-0AG2 | 3RT1016-1AK61 + 3RH1911-1HA12 | |
| 3TF2222-0AK6 | 3RT1016-1AK61 + 3RH1911-1HA12 | |
| 3TF2222-0BB4 | 3RT1016-1BB41 + 3RH1911-1HA12 | |
| 3TF2801-0AB0 | 3RT1015-1AB02 | |
| 3TF2801-0AC2 | 3RT1015-1AB02 | |
| 3TF2801-0BB4 | 3RT1015-1BB42 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TF2801-0JB4 | 3RT1015-1JB42 | |
| 3TF2801-0LB4 | 3RT1015-1KB42 | |
| 3TF2810-0BB4 | 3RT1015-1BB41 | |
| 3TF2810-0LB4 | 3RT1015-1KB41 | |
| 3TF2922-0BB4 | 3RT1015-1BB41 | |
| 3TF3000-0AC2 | 3RT1016-1AB01 | |
| 3TF3000-0AC21 | 3RT1016-1AB01 | |
| 3TF3000-0AD0 | 3RT1016-1AD01 | |
| 3TF3000-0AD2 | 3RT1016-1AD31 | |
| 3TF3000-0AD21 | 3RT1016-1AD31 | |
| 3TF3000-0AG2 | 3RT1016-1AK61 | |
| 3TF3000-0AK6 | 3RT1016-1AK61 | |
| 3TF3000-0AK61 | 3RT1016-1AK61 | |
| 3TF3000-0AL1 | 3RT1016-1AP61 | |
| 3TF3000-0AM1 | 3RT1016-1AM21 | |
| 3TF3000-0AM11 | 3RT1016-1AM21 | |
| 3TF3000-0AP0 | 3RT1016-1AP61 | |
| 3TF3000-0AP6 | 3RT1016-1AP61 | |
| 3TF3000-0AP61 | 3RT1016-1AP61 | |
| 3TF3000-0AQ0 | 3RT1016-1AV01 | |
| 3TF3000-0AQ01 | 3RT1016-1AV01 | |
| 3TF3000-0AS0 | 3RT1016-1AT61 | |
| 3TF3000-0AS01 | 3RT1016-1AT61 | |
| 3TF3000-0AS2 | 3RT1016-1AT61 | |
| 3TF3000-0AS21 | 3RT1016-1AT61 | |
| 3TF3000-0AU1 | 3RT1016-1AU61 | |
| 3TF3000-0AU11 | 3RT1016-1AU61 | |
| 3TF3000-0AV0 | 3RT1016-1AV01 | |
| 3TF3000-0AV01 | 3RT1016-1AV01 | |
| 3TF3000-0BA4 | 3RT1016-1BA41 | |
| 3TF3000-0BA41 | 3RT1016-1BA41 | |
| 3TF3000-0BB4 | 3RT1016-1BB41 | |
| 3TF3000-0BB41 | 3RT1016-1BB41 | |
| 3TF3000-0BD4 | 3RT1016-1BD41 | |
| 3TF3000-0BD41 | 3RT1016-1BD41 | |
| 3TF3000-0BE4 | 3RT1016-1BE41 | |
| 3TF3000-0BE41 | 3RT1016-1BE41 | |
| 3TF3000-0BF4 | 3RT1016-1BF41 | |
| 3TF3000-0BF41 | 3RT1016-1BF41 | |
| 3TF3000-0BG4 | 3RT1016-1BG41 | |
| 3TF3000-0BG41 | 3RT1016-1BG41 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TF3000-0BM4 | 3RT1016-1BM41 | |
| 3TF3000-0BM41 | 3RT1016-1BM41 | |
| 3TF3000-0BN4 | NO DIRECT REPLACEMENT | |
| 3TF3000-0BN41 | NO DIRECT REPLACEMENT | |
| 3TF3000-0BQ4 | 3RT1016-1BP41 | |
| 3TF3000-0BW4 | 3RT1016-1BW41 | |
| 3TF3000-0BW41 | 3RT1016-1BW41 | |
| 3TF3000-1AL1 | 3RT1016-1AP61 | |
| 3TF3001-0AC2 | 3RT1016-1AB02 | |
| 3TF3001-0AG2 | 3RT1016-1AK62 | |
| 3TF3001-0AK1 | 3RT1016-1AK62 | |
| 3TF3001-0AK6 | 3RT1016-1AK62 | |
| 3TF3001-0AM1 | 3RT1016-1AM22 | |
| 3TF3001-0AN2 | 3RT1016-1AP62 | |
| 3TF3001-0AP6 | 3RT1016-1AP62 | |
| 3TF3001-0BB4 | 3RT1016-1BB42 | |
| 3TF3001-0BF4 | 3RT1016-1BF42 | |
| 3TF3001-0BG4 | 3RT1016-1BG42 | |
| 3TF3001-0BV4 | NO DIRECT REPLACEMENT | |
| 3TF3010-0AC2 | 3RT1016-1AB01 | |
| 3TF3010-0AC21 | 3RT1016-1AB01 | |
| 3TF3010-0AD2 | 3RT1016-1AD31 | |
| 3TF3010-0AD21 | 3RT1016-1AD31 | |
| 3TF3010-0AF0 | 3RT1016-1AK61 | |
| 3TF3010-0AG2 | 3RT1016-1AK61 | |
| 3TF3010-0AK6 | 3RT1016-1AK61 | |
| 3TF3010-0AK61 | 3RT1016-1AK61 | |
| 3TF3010-0AL0 | 3RT1016-1AP61 | |
| 3TF3010-0AM0 | 3RT1016-1AM21 | |
| 3TF3010-0AM1 | 3RT1016-1AM21 | |
| 3TF3010-0AM11 | 3RT1016-1AM21 | |
| 3TF3010-0AP0 | 3RT1016-1AP61 | |
| 3TF3010-0AP6 | 3RT1016-1AP61 | |
| 3TF3010-0AP61 | 3RT1016-1AP61 | |
| 3TF3010-0AQ0 | 3RT1016-1AV01 | |
| 3TF3010-0AQ01 | 3RT1016-1AV01 | |
| 3TF3010-0AS0 | 3RT1016-1AT61 | |
| 3TF3010-0AS01 | 3RT1016-1AT61 | |
| 3TF3010-0AS2 | 3RT1016-1AT61 | |
| 3TF3010-0AS21 | 3RT1016-1AT61 | |
| 3TF3010-0AU1 | 3RT1016-1AU61 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TF3010-0AU11 | 3RT1016-1AU61 | |
| 3TF3010-0AV0 | 3RT1016-1AV01 | |
| 3TF3010-0AV01 | 3RT1016-1AV01 | |
| 3TF3010-0BA4 | 3RT1016-1BA41 | |
| 3TF3010-0BA41 | 3RT1016-1BA41 | |
| 3TF3010-0BB4 | 3RT1016-1BB41 | |
| 3TF3010-0BB41 | 3RT1016-1BB41 | |
| 3TF3010-0BD4 | 3RT1016-1BD41 | |
| 3TF3010-0BD41 | 3RT1016-1BD41 | |
| 3TF3010-0BE4 | 3RT1016-1BE41 | |
| 3TF3010-0BE41 | 3RT1016-1BE41 | |
| 3TF3010-0BF4 | 3RT1016-1BF41 | |
| 3TF3010-0BF41 | 3RT1016-1BF41 | |
| 3TF3010-0BG4 | 3RT1016-1BG41 | |
| 3TF3010-0BG41 | 3RT1016-1BG41 | |
| 3TF3010-0BM4 | 3RT1016-1BM41 | |
| 3TF3010-0BM41 | 3RT1016-1BM41 | |
| 3TF3010-0BN4 | NO DIRECT REPLACEMENT | |
| 3TF3010-0BN41 | NO DIRECT REPLACEMENT | |
| 3TF3010-0BV4 | NO DIRECT REPLACEMENT | |
| 3TF3010-0BW4 | 3RT1016-1BW41 | |
| 3TF3010-0BW41 | 3RT1016-1BW41 | |
| 3TF3022-0BW4 | NOT A VALID NUMBER | |
| 3TF3100-0AC2 | 3RT1017-1AB01 | |
| 3TF3100-0AD2 | 3RT1017-1AD31 | |
| 3TF3100-0AF0 | 3RT1017-1AK61 | |
| 3TF3100-0AJ2 | 3RT1017-1AK61 | |
| 3TF3100-0AK6 | 3RT1017-1AK61 | |
| 3TF3100-0AM1 | 3RT1017-1AM21 | |
| 3TF3100-0AM2 | 3RT1017-1AM21 | |
| 3TF3100-0AP0 | 3RT1017-1AP61 | |
| 3TF3100-0AP6 | 3RT1017-1AP61 | |
| 3TF3100-0AQ0 | 3RT1017-1AV01 | |
| 3TF3100-0AS0 | 3RT1017-1AT61 | |
| 3TF3100-0AS2 | 3RT1017-1AT61 | |
| 3TF3100-0AU1 | 3RT1017-1AU61 | |
| 3TF3100-0AV0 | 3RT1017-1AV01 | |
| 3TF3100-0BB4 | 3RT1017-1BB41 | |
| 3TF3100-0BD4 | 3RT1017-1BD41 | |
| 3TF3100-0BE4 | 3RT1017-1BE41 | |
| 3TF3100-0BF4 | 3RT1017-1BF41 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TF3100-0BG4 | 3RT1017-1BG41 | |
| 3TF3100-0BM4 | 3RT1017-1BM41 | |
| 3TF3100-0BN4 | NO DIRECT REPLACEMENT | |
| 3TF3100-0BW4 | 3RT1017-1BW41 | |
| 3TF3101-0AC2 | 3RT1017-1AB02 | |
| 3TF3101-0AG2 | 3RT1017-1AK62 | |
| 3TF3101-0AK6 | 3RT1017-1AK62 | |
| 3TF3101-0AM1 | 3RT1017-1AM22 | |
| 3TF3101-0AN2 | 3RT1017-1AP62 | |
| 3TF3101-0BB4 | 3RT1017-1BB42 | |
| 3TF3110-0AC2 | 3RT1017-1AB01 | |
| 3TF3110-0AD2 | 3RT1017-1AD31 | |
| 3TF3110-0AG2 | 3RT1017-1AK61 | |
| 3TF3110-0AK6 | 3RT1017-1AK61 | |
| 3TF3110-0AM1 | 3RT1017-1AM21 | |
| 3TF3110-0AP0 | 3RT1017-1AP61 | |
| 3TF3110-0AP6 | 3RT1017-1AP61 | |
| 3TF3110-0AQ0 | 3RT1017-1AV01 | |
| 3TF3110-0AS0 | 3RT1017-1AT61 | |
| 3TF3110-0AS2 | 3RT1017-1AT61 | |
| 3TF3110-0AU1 | 3RT1017-1AU61 | |
| 3TF3110-0AV0 | 3RT1017-1AV01 | |
| 3TF3110-0BA4 | 3RT1017-1BA41 | |
| 3TF3110-0BB4 | 3RT1017-1BB41 | |
| 3TF3110-0BD4 | 3RT1017-1BD41 | |
| 3TF3110-0BE4 | 3RT1017-1BE41 | |
| 3TF3110-0BF4 | 3RT1017-1BF41 | |
| 3TF3110-0BG4 | 3RT1017-1BG41 | |
| 3TF3110-0BM4 | 3RT1017-1BM41 | |
| 3TF3110-0BN4 | NO DIRECT REPLACEMENT | |
| 3TF3110-0BQ4 | 3RT1017-1BP41 | |
| 3TF3110-0BW4 | 3RT1017-1BW41 | |
| 3TF3200-0AC2 | 3RT1025-1AC20 | |
| 3TF3200-0AC21 | 3RT1025-1AC20 | |
| 3TF3200-0AD2 | 3RT1025-1AD30 | |
| 3TF3200-0AD21 | 3RT1025-1AD30 | |
| 3TF3200-0AE0 | NO DIRECT REPLACEMENT | |
| 3TF3200-0AG2 | 3RT1025-1AK60 | |
| 3TF3200-0AJ1 | 3RT1025-1AK60 | |
| 3TF3200-0AJ2 | 3RT1025-1AK60 | |
| 3TF3200-0AK6 | 3RT1025-1AK60 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TF3200-0AK61 | 3RT1025-1AK60 | |
| 3TF3200-0AM0 | 3RT1025-1AM20 | |
| 3TF3200-0AM1 | 3RT1025-1AM20 | |
| 3TF3200-0AM11 | 3RT1025-1AM20 | |
| 3TF3200-0AM2 | 3RT1025-1AM20 | |
| 3TF3200-0AP0 | 3RT1025-1AP60 | |
| 3TF3200-0AP6 | 3RT1025-1AP60 | |
| 3TF3200-0AP61 | 3RT1025-1AP60 | |
| 3TF3200-0AQ0 | 3RT1025-1AV00 | |
| 3TF3200-0AQ01 | 3RT1025-1AV00 | |
| 3TF3200-0AS0 | 3RT1025-1AT60 | |
| 3TF3200-0AS01 | 3RT1025-1AT60 | |
| 3TF3200-0AS2 | 3RT1025-1AT60 | |
| 3TF3200-0AS21 | 3RT1025-1AT60 | |
| 3TF3200-0AU1 | 3RT1025-1AU60 | |
| 3TF3200-0AU11 | 3RT1025-1AU60 | |
| 3TF3200-0AV0 | 3RT1025-1AV00 | |
| 3TF3200-0AV01 | 3RT1025-1AV00 | |
| 3TF3200-0BA4 | 3RT1025-1BA40 | |
| 3TF3200-0BA41 | 3RT1025-1BA40 | |
| 3TF3200-0BB4 | 3RT1025-1BB40 | |
| 3TF3200-0BB41 | 3RT1025-1BB40 | |
| 3TF3200-0BD4 | 3RT1025-1BD40 | |
| 3TF3200-0BD41 | 3RT1025-1BD40 | |
| 3TF3200-0BE4 | 3RT1025-1BE40 | |
| 3TF3200-0BE41 | 3RT1025-1BE40 | |
| 3TF3200-0BF4 | 3RT1025-1BF40 | |
| 3TF3200-0BF41 | 3RT1025-1BF40 | |
| 3TF3200-0BG4 | 3RT1025-1BG40 | |
| 3TF3200-0BG41 | 3RT1025-1BG40 | |
| 3TF3200-0BM4 | 3RT1025-1BM40 | |
| 3TF3200-0BM41 | 3RT1025-1BM40 | |
| 3TF3200-0BN4 | NO DIRECT REPLACEMENT | |
| 3TF3200-0BN41 | NO DIRECT REPLACEMENT | |
| 3TF3200-0BQ4 | 3RT1025-1BP40 | |
| 3TF3200-0BW4 | 3RT1025-1BW40 | |
| 3TF3200-0BW41 | 3RT1025-1BW40 | |
| 3TF3211-0AC2 | 3RT1025-1AC20 + 3RH1921-1EA11 | |
| 3TF3211-0AK6 | 3RT1025-1AK60 + 3RH1921-1EA11 | |
| 3TF3211-0AL2 | 3RT1025-1AP60 + 3RH1921-1EA11 | |
| 3TF3211-0AM1 | 3RT1025-1AM20 + 3RH1921-1EA11 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TF3211-0AM2 | 3RT1025-1AM20 + 3RH1921-1EA11 | |
| 3TF3211-0AN1 | 3RT1025-1AP60 + 3RH1921-1EA11 | |
| 3TF3211-0AP6 | 3RT1025-1AP60 + 3RH1921-1EA11 | |
| 3TF3211-0AQ0 | 3RT1025-1AV00 + 3RH1921-1EA11 | |
| 3TF3211-0AS0 | 3RT1025-1AT60 + 3RH1921-1EA11 | |
| 3TF3211-0AU1 | 3RT1025-1AU60 + 3RH1921-1EA11 | |
| 3TF3211-0AV0 | 3RT1025-1AV00 + 3RH1921-1EA11 | |
| 3TF3211-0BA4 | 3RT1025-1BA40 + 3RH1921-1EA11 | |
| 3TF3211-0BB4 | 3RT1025-1BB40 + 3RH1921-1EA11 | |
| 3TF3211-0BG4 | 3RT1025-1BG40 + 3RH1921-1EA11 | |
| 3TF3211-0BQ4 | 3RT1025-1BP40 + 3RH1921-1EA11 | |
| 3TF3211-0BW4 | 3RT1025-1BW40 + 3RH1921-1EA11 | |
| 3TF3300-0AC2 | 3RT1026-1AC20 | |
| 3TF3300-0AD2 | 3RT1026-1AD20 | |
| 3TF3300-0AG0 | 3RT1026-1AD20 | |
| 3TF3300-0AG2 | 3RT1026-1AK60 | |
| 3TF3300-0AJ2 | 3RT1026-1AK60 | |
| 3TF3300-0AK6 | 3RT1026-1AK60 | |
| 3TF3300-0AL0 | 3RT1026-1AP60 | |
| 3TF3300-0AL2 | 3RT1026-1AP60 | |
| 3TF3300-0AL6 | NO DIRECT REPLACEMENT | |
| 3TF3300-0AM0 | 3RT1026-1AM20 | |
| 3TF3300-0AM1 | 3RT1026-1AM20 | |
| 3TF3300-0AM2 | 3RT1026-1AM20 | |
| 3TF3300-0AN2 | 3RT1026-1AP60 | |
| 3TF3300-0AP0 | 3RT1026-1AP60 | |
| 3TF3300-0AP6 | 3RT1026-1AP60 | |
| 3TF3300-0AQ0 | 3RT1026-1AV00 | |
| 3TF3300-0AS0 | 3RT1026-1AT60 | |
| 3TF3300-0AS2 | 3RT1026-1AT60 | |
| 3TF3300-0AU1 | 3RT1026-1AU60 | |
| 3TF3300-0AV0 | 3RT1026-1AV00 | |
| 3TF3300-0BA4 | 3RT1026-1BA40 | |
| 3TF3300-0BB4 | 3RT1026-1BB40 | |
| 3TF3300-0BD4 | 3RT1026-1BD40 | |
| 3TF3300-0BE4 | 3RT1026-1BE40 | |
| 3TF3300-0BF4 | 3RT1026-1BF40 | |
| 3TF3300-0BG4 | 3RT1026-1BG40 | |
| 3TF3300-0BM4 | 3RT1026-1BM40 | |
| 3TF3300-0BN4 | NO DIRECT REPLACEMENT | |
| 3TF3300-0BQ4 | 3RT1026-1BP40 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TF3300-0BW4 | 3RT1026-1BW40 | |
| 3TF3311-0AC2 | 3RT1026-1AC20 + 3RH1921-1EA11 | |
| 3TF3311-0AK6 | 3RT1026-1AK60 + 3RH1921-1EA11 | |
| 3TF3311-0AM1 | 3RT1026-1AM20 + 3RH1921-1EA11 | |
| 3TF3311-0AM2 | 3RT1026-1AM20 + 3RH1921-1EA11 | |
| 3TF3311-0AP6 | 3RT1026-1AP60 + 3RH1921-1EA11 | |
| 3TF3311-0AQ0 | 3RT1026-1AV00 + 3RH1921-1EA11 | |
| 3TF3311-0AS0 | 3RT1026-1AT60 + 3RH1921-1EA11 | |
| 3TF3311-0AU1 | 3RT1026-1AU60 + 3RH1921-1EA11 | |
| 3TF3311-0AV0 | 3RT1026-1AV00 + 3RH1921-1EA11 | |
| 3TF3311-0BA4 | 3RT1026-1BA40 + 3RH1921-1EA11 | |
| 3TF3311-0BB4 | 3RT1026-1BB40 + 3RH1921-1EA11 | |
| 3TF3311-0BG4 | 3RT1026-1BG40 + 3RH1921-1EA11 | |
| 3TF3311-0BQ4 | 3RT1026-1BP40 + 3RH1921-1EA11 | |
| 3TF3311-0BW4 | 3RT1026-1BW40 + 3RH1921-1EA11 | |
| 3TF3400-0AC2 | 3RT1034-1AC20 | |
| 3TF3400-0AC21 | 3RT1034-1AC20 | |
| 3TF3400-0AD2 | 3RT1034-1AD20 | |
| 3TF3400-0AD21 | 3RT1034-1AD20 | |
| 3TF3400-0AK6 | 3RT1034-1AK60 | |
| 3TF3400-0AK61 | 3RT1034-1AK60 | |
| 3TF3400-0AL2 | 3RT1034-1AP60 | |
| 3TF3400-0AM0 | 3RT1034-1AM20 | |
| 3TF3400-0AM1 | 3RT1034-1AM20 | |
| 3TF3400-0AM11 | 3RT1034-1AM20 | |
| 3TF3400-0AM2 | 3RT1034-1AM20 | |
| 3TF3400-0AN2 | 3RT1034-1AP60 | |
| 3TF3400-0AP0 | 3RT1034-1AP60 | |
| 3TF3400-0AP6 | 3RT1034-1AP60 | |
| 3TF3400-0AP61 | 3RT1034-1AP60 | |
| 3TF3400-0AQ0 | 3RT1034-1AV00 | |
| 3TF3400-0AQ01 | 3RT1034-1AV00 | |
| 3TF3400-0AS0 | 3RT1034-1AT60 | |
| 3TF3400-0AS01 | 3RT1034-1AT60 | |
| 3TF3400-0AS2 | 3RT1034-1AT60 | |
| 3TF3400-0AS21 | 3RT1034-1AT60 | |
| 3TF3400-0AU1 | 3RT1034-1AU60 | |
| 3TF3400-0AU11 | 3RT1034-1AU60 | |
| 3TF3400-0AV0 | 3RT1034-1AV00 | |
| 3TF3400-0AV01 | 3RT1034-1AV00 | |
| 3TF3400-0BA4 | 3RT1034-1BA40 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TF3400-0BB4 | 3RT1034-1BB40 | |
| 3TF3400-0BB41 | 3RT1034-1BB40 | |
| 3TF3400-0BD4 | 3RT1034-1BD40 | |
| 3TF3400-0BD41 | 3RT1034-1BD40 | |
| 3TF3400-0BE4 | 3RT1034-1BE40 | |
| 3TF3400-0BE41 | 3RT1034-1BE40 | |
| 3TF3400-0BF4 | 3RT1034-1BF40 | |
| 3TF3400-0BF41 | 3RT1034-1BF40 | |
| 3TF3400-0BG4 | 3RT1034-1BG40 | |
| 3TF3400-0BG41 | 3RT1034-1BG40 | |
| 3TF3400-0BM4 | 3RT1034-1BM40 | |
| 3TF3400-0BM41 | 3RT1034-1BM40 | |
| 3TF3400-0BN4 | NO DIRECT REPLACEMENT | |
| 3TF3400-0BN41 | NO DIRECT REPLACEMENT | |
| 3TF3400-0BW4 | 3RT1034-1BW40 | |
| 3TF3400-0BW41 | 3RT1034-1BW40 | |
| 3TF3411-0AC2 | 3RT1034-1AC20 + 3RH1921-1EA11 | |
| 3TF3411-0AK6 | 3RT1034-1AK60 + 3RH1921-1EA11 | |
| 3TF3411-0AM1 | 3RT1034-1AM20 + 3RH1921-1EA11 | |
| 3TF3411-0AM2 | 3RT1034-1AM20 + 3RH1921-1EA11 | |
| 3TF3411-0AN2 | 3RT1034-1AP60 + 3RH1921-1EA11 | |
| 3TF3411-0AP6 | 3RT1034-1AP60 + 3RH1921-1EA11 | |
| 3TF3411-0AQ0 | 3RT1034-1AV00 + 3RH1921-1EA11 | |
| 3TF3411-0AS0 | 3RT1034-1AT60 + 3RH1921-1EA11 | |
| 3TF3411-0AU1 | 3RT1034-1AU60 + 3RH1921-1EA11 | |
| 3TF3411-0AV0 | 3RT1034-1AV00 + 3RH1921-1EA11 | |
| 3TF3411-0BA4 | 3RT1034-1BA40 + 3RH1921-1EA11 | |
| 3TF3411-0BB4 | 3RT1034-1BB40 + 3RH1921-1EA11 | |
| 3TF3411-0BG4 | 3RT1034-1BG40 + 3RH1921-1EA11 | |
| 3TF3411-0BQ4 | 3RT1034-1BP40 + 3RH1921-1EA11 | |
| 3TF3411-0BW4 | 3RT1034-1BW40 + 3RH1921-1EA11 | |
| 3TF3470-0AC2 | 3RT1034-1AC20 + 3RH1921-1HA22 | |
| 3TF3470-0AC21 | 3RT1034-1AC20 + 3RH1921-1HA22 | |
| 3TF3470-0AK6 | 3RT1034-1AK60 + 3RH1921-1HA22 | |
| 3TF3470-0AK61 | 3RT1034-1AK60 + 3RH1921-1HA22 | |
| 3TF3470-0AM1 | 3RT1034-1AM20 + 3RH1921-1HA22 | |
| 3TF3470-0AM11 | 3RT1034-1AM20 + 3RH1921-1HA22 | |
| 3TF3470-0AP6 | 3RT1034-1AP60 + 3RH1921-1HA22 | |
| 3TF3470-0AP61 | 3RT1034-1AP60 + 3RH1921-1HA22 | |
| 3TF3470-0AQ0 | 3RT1034-1AV00 + 3RH1921-1HA22 | |
| 3TF3470-0AQ01 | 3RT1034-1AV00 + 3RH1921-1HA22 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TF3470-0AS0 | 3RT1034-1AT60 + 3RH1921-1HA22 | |
| 3TF3470-0AS01 | 3RT1034-1AT60 + 3RH1921-1HA22 | |
| 3TF3470-0AS2 | 3RT1034-1AT60 + 3RH1921-1HA22 | |
| 3TF3470-0AS21 | 3RT1034-1AT60 + 3RH1921-1HA22 | |
| 3TF3470-0AU1 | 3RT1034-1AU60 + 3RH1921-1HA22 | |
| 3TF3470-0AU11 | 3RT1034-1AU60 + 3RH1921-1HA22 | |
| 3TF3470-0AV0 | 3RT1034-1AV00 + 3RH1921-1HA22 | |
| 3TF3470-0AV01 | 3RT1034-1AV00 + 3RH1921-1HA22 | |
| 3TF3470-0BB4 | 3RT1034-1BB40 + 3RH1921-1HA22 | |
| 3TF3470-0BB41 | 3RT1034-1BB40 + 3RH1921-1HA22 | |
| 3TF3470-0BE4 | 3RT1034-1BE40 + 3RH1921-1HA22 | |
| 3TF3470-0BE41 | 3RT1034-1BE40 + 3RH1921-1HA22 | |
| 3TF3470-0BF4 | 3RT1034-1BF40 + 3RH1921-1HA22 | |
| 3TF3470-0BG4 | 3RT1034-1BG40 + 3RH1921-1HA22 | |
| 3TF3470-0BG41 | 3RT1034-1BG40 + 3RH1921-1HA22 | |
| 3TF3470-0BW4 | 3RT1034-1BW40 + 3RH1921-1HA22 | |
| 3TF3470-0BW41 | 3RT1034-1BW40 + 3RH1921-1HA22 | |
| 3TF3470-4KB4 | 3RT1034-1BB40 + 3RH1921-1HA22 | |
| 3TF3500-0AC2 | 3RT1035-1AC20 | |
| 3TF3500-0AD2 | 3RT1035-1AD20 | |
| 3TF3500-0AK6 | 3RT1035-1AK60 | |
| 3TF3500-0AL2 | 3RT1035-1AP60 | |
| 3TF3500-0AM1 | 3RT1035-1AM20 | |
| 3TF3500-0AM2 | 3RT1035-1AM20 | |
| 3TF3500-0AP6 | 3RT1035-1AP60 | |
| 3TF3500-0AQ0 | 3RT1035-1AV00 | |
| 3TF3500-0AS0 | 3RT1035-1AT60 | |
| 3TF3500-0AS2 | 3RT1035-1AT60 | |
| 3TF3500-0AU1 | 3RT1035-1AU60 | |
| 3TF3500-0AV0 | 3RT1035-1AV00 | |
| 3TF3500-0BB4 | 3RT1035-1BB40 | |
| 3TF3500-0BE4 | 3RT1035-1BE40 | |
| 3TF3500-0BF4 | 3RT1035-1BF40 | |
| 3TF3500-0BG4 | 3RT1035-1BG40 | |
| 3TF3500-0BV4 | NO DIRECT REPLACEMENT | |
| 3TF3500-0BW4 | 3RT1035-1BW40 | |
| 3TF3511-0AC2 | 3RT1035-1AC20 + 3RH1921-1EA11 | |
| 3TF3511-0AK6 | 3RT1035-1AK60 + 3RH1921-1EA11 | |
| 3TF3511-0AM1 | 3RT1035-1AM20 + 3RH1921-1EA11 | |
| 3TF3511-0AM2 | 3RT1035-1AM20 + 3RH1921-1EA11 | |
| 3TF3511-0AP6 | 3RT1035-1AP60 + 3RH1921-1EA11 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TF3511-0AQ0 | 3RT1035-1AV00 + 3RH1921-1EA11 | |
| 3TF3511-0AS0 | 3RT1035-1AT60 + 3RH1921-1EA11 | |
| 3TF3511-0AU1 | 3RT1035-1AU60 + 3RH1921-1EA11 | |
| 3TF3511-0AV0 | 3RT1035-1AV00 + 3RH1921-1EA11 | |
| 3TF3511-0BA4 | 3RT1035-1BA40 + 3RH1921-1EA11 | |
| 3TF3511-0BB4 | 3RT1035-1BB40 + 3RH1921-1EA11 | |
| 3TF3511-0BG4 | 3RT1035-1BG40 + 3RH1921-1EA11 | |
| 3TF3511-0BQ4 | 3RT1035-1BP40 + 3RH1921-1EA11 | |
| 3TF3511-0BW4 | 3RT1035-1BW40 + 3RH1921-1EA11 | |
| 3TF3570-0AC2 | 3RT1035-1AC20 + 3RH1921-1HA22 | |
| 3TF3570-0AK6 | 3RT1035-1AK60 + 3RH1921-1HA22 | |
| 3TF3570-0AM1 | 3RT1035-1AM20 + 3RH1921-1HA22 | |
| 3TF3570-0AP6 | 3RT1035-1AP60 + 3RH1921-1HA22 | |
| 3TF3570-0AQ0 | 3RT1035-1AV00 + 3RH1921-1HA22 | |
| 3TF3570-0AS0 | 3RT1035-1AT60 + 3RH1921-1HA22 | |
| 3TF3570-0AS2 | 3RT1035-1AT60 + 3RH1921-1HA22 | |
| 3TF3570-0AU1 | 3RT1035-1AU60 + 3RH1921-1HA22 | |
| 3TF3570-0AV0 | 3RT1035-1AV00 + 3RH1921-1HA22 | |
| 3TF3570-0BB4 | 3RT1035-1BB40 + 3RH1921-1HA22 | |
| 3TF3570-0BE4 | 3RT1035-1BE40 + 3RH1921-1HA22 | |
| 3TF3570-0BF4 | 3RT1035-1BF40 + 3RH1921-1HA22 | |
| 3TF3570-0BG4 | 3RT1035-1BG40 + 3RH1921-1HA22 | |
| 3TF3570-0BW4 | 3RT1035-1BW40 + 3RH1921-1HA22 | |
| 3TF4001-0AC2 | 3RT1016-1AB02 | |
| 3TF4001-0AF0 | 3RT1016-1AK62 | |
| 3TF4001-0AK6 | 3RT1016-1AK62 | |
| 3TF4001-0AM1 | 3RT1016-1AM22 | |
| 3TF4001-0AM2 | 3RT1016-1AM22 | |
| 3TF4001-0AN2 | 3RT1016-1AP62 | |
| 3TF4001-0AP6 | 3RT1016-1AP62 | |
| 3TF4001-0AQ0 | 3RT1016-1AV02 | |
| 3TF4001-0AS0 | 3RT1016-1AT62 | |
| 3TF4001-0AU1 | 3RT1016-1AU62 | |
| 3TF4001-0AV0 | 3RT1016-1AV02 | |
| 3TF4001-0BB4 | 3RT1016-1BB42 | |
| 3TF4010-0AC2 | 3RT1016-1AB01 | |
| 3TF4010-0AC21 | 3RT1016-1AB01 | |
| 3TF4010-0AD0 | 3RT1016-1AD01 | |
| 3TF4010-0AG2 | 3RT1016-1AK61 | |
| 3TF4010-0AG6 | 3RT1016-1AG61 | |
| 3TF4010-0AJ2 | 3RT1016-1AK61 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TF4010-0AK6 | 3RT1016-1AK61 | |
| 3TF4010-0AK61 | 3RT1016-1AK61 | |
| 3TF4010-0AL2 | 3RT1016-1AP61 | |
| 3TF4010-0AM1 | 3RT1016-1AM21 | |
| 3TF4010-0AM11 | 3RT1016-1AM21 | |
| 3TF4010-0AM2 | 3RT1016-1AM21 | |
| 3TF4010-0AM21 | 3RT1016-1AM21 | |
| 3TF4010-0AN1 | 3RT1016-1AP61 | |
| 3TF4010-0AN2 | 3RT1016-1AP61 | |
| 3TF4010-0AP6 | 3RT1016-1AP61 | |
| 3TF4010-0AP61 | 3RT1016-1AP61 | |
| 3TF4010-0AQ0 | 3RT1016-1AV01 | |
| 3TF4010-0AQ01 | 3RT1016-1AV01 | |
| 3TF4010-0AS0 | 3RT1016-1AT61 | |
| 3TF4010-0AS01 | 3RT1016-1AT61 | |
| 3TF4010-0AS2 | 3RT1016-1AT61 | |
| 3TF4010-0AS21 | 3RT1016-1AT61 | |
| 3TF4010-0AU1 | 3RT1016-1AU61 | |
| 3TF4010-0AU11 | 3RT1016-1AU61 | |
| 3TF4010-0AV0 | 3RT1016-1AV01 | |
| 3TF4010-0AV01 | 3RT1016-1AV01 | |
| 3TF4010-0BA4 | 3RT1016-1BA41 | |
| 3TF4010-0BA41 | 3RT1016-1BA41 | |
| 3TF4010-0BB4 | 3RT1016-1BB41 | |
| 3TF4010-0BB41 | 3RT1016-1BB41 | |
| 3TF4010-0BG4 | 3RT1016-1BG41 | |
| 3TF4010-0BG41 | 3RT1016-1BG41 | |
| 3TF4010-0BQ4 | 3RT1016-1BP41 | |
| 3TF4010-0BQ41 | 3RT1016-1BP41 | |
| 3TF4010-0BW4 | 3RT1016-1BW41 | |
| 3TF4010-0BW41 | 3RT1016-1BW41 | |
| 3TF4010-0LV4 | NO DIRECT REPLACEMENT | |
| 3TF4011-0AC1 | 3RT1016-1AB01 + 3RH1911-1HA01 | |
| 3TF4011-0AC2 | 3RT1016-1AB01 + 3RH1911-1HA01 | |
| 3TF4011-0AC21 | 3RT1016-1AB01 + 3RH1911-1HA01 | |
| 3TF4011-0AD0 | 3RT1016-1AD01 + 3RH1911-1HA01 | |
| 3TF4011-0AG1 | 3RT1016-1AK61 + 3RH1911-1HA01 | |
| 3TF4011-0AG2 | 3RT1016-1AK61 + 3RH1911-1HA01 | |
| 3TF4011-0AG21 | 3RT1016-1AK61 + 3RH1911-1HA01 | |
| 3TF4011-0AH0 | 3RT1016-1AH01 + 3RH1911-1HA01 | |
| 3TF4011-0AK6 | 3RT1016-1AK61 + 3RH1911-1HA01 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TF4011-0AK61 | 3RT1016-1AK61 + 3RH1911-1HA01 | |
| 3TF4011-0AM1 | 3RT1016-1AM21 + 3RH1911-1HA01 | |
| 3TF4011-0AM11 | 3RT1016-1AM21 + 3RH1911-1HA01 | |
| 3TF4011-0AM2 | 3RT1016-1AM21 + 3RH1911-1HA01 | |
| 3TF4011-0AM21 | 3RT1016-1AM21 + 3RH1911-1HA01 | |
| 3TF4011-0AN2 | 3RT1016-1AP61 + 3RH1911-1HA01 | |
| 3TF4011-0AP0 | 3RT1016-1AP61 + 3RH1911-1HA01 | |
| 3TF4011-0AP6 | 3RT1016-1AP61 + 3RH1911-1HA01 | |
| 3TF4011-0AP61 | 3RT1016-1AP61 + 3RH1911-1HA01 | |
| 3TF4011-0AQ0 | 3RT1016-1AV01 + 3RH1911-1HA01 | |
| 3TF4011-0AQ01 | 3RT1016-1AV01 + 3RH1911-1HA01 | |
| 3TF4011-0AS0 | 3RT1016-1AT61 + 3RH1911-1HA01 | |
| 3TF4011-0AS01 | 3RT1016-1AT61 + 3RH1911-1HA01 | |
| 3TF4011-0AU1 | 3RT1016-1AU61 + 3RH1911-1HA01 | |
| 3TF4011-0AU11 | 3RT1016-1AU61 + 3RH1911-1HA01 | |
| 3TF4011-0AV0 | 3RT1016-1AV01 + 3RH1911-1HA01 | |
| 3TF4011-0AV01 | 3RT1016-1AV01 + 3RH1911-1HA01 | |
| 3TF4011-0BA4 | 3RT1016-1BA41 + 3RH1911-1HA01 | |
| 3TF4011-0BA41 | 3RT1016-1BA41 + 3RH1911-1HA01 | |
| 3TF4011-0BB4 | 3RT1016-1BB41 + 3RH1911-1HA01 | |
| 3TF4011-0BB41 | 3RT1016-1BB41 + 3RH1911-1HA01 | |
| 3TF4011-0BG4 | 3RT1016-1BG41 + 3RH1911-1HA01 | |
| 3TF4011-0BG41 | 3RT1016-1BG41 + 3RH1911-1HA01 | |
| 3TF4011-0BQ4 | 3RT1016-1BP41 + 3RH1911-1HA01 | |
| 3TF4011-0BQ41 | 3RT1016-1BP41 + 3RH1911-1HA01 | |
| 3TF4011-0BW4 | 3RT1016-1BW41 + 3RH1911-1HA01 | |
| 3TF4011-0BW41 | 3RT1016-1BW41 + 3RH1911-1HA01 | |
| 3TF4022-0AC2 | 3RT1016-1AB01 + 3RH1911-1HA12 | |
| 3TF4022-0AC21 | 3RT1016-1AB01 + 3RH1911-1HA12 | |
| 3TF4022-0AD0 | 3RT1016-1AD01 + 3RH1911-1HA12 | |
| 3TF4022-0AD2 | 3RT1016-1AD21 + 3RH1911-1HA12 | |
| 3TF4022-0AE0 | NO DIRECT REPLACEMENT | |
| 3TF4022-0AF0 | 3RT1016-1AK61 + 3RH1911-1HA12 | |
| 3TF4022-0AG0 | 3RT1016-1AD01 + 3RH1911-1HA12 | |
| 3TF4022-0AG1 | 3RT1016-1AK61 + 3RH1911-1HA12 | |
| 3TF4022-0AG2 | 3RT1016-1AK61 + 3RH1911-1HA12 | |
| 3TF4022-0AJ1 | 3RT1016-1AK61 + 3RH1911-1HA12 | |
| 3TF4022-0AK2 | 3RT1016-1AK61 + 3RH1911-1HA12 | |
| 3TF4022-0AK6 | 3RT1016-1AK61 + 3RH1911-1HA12 | |
| 3TF4022-0AK61 | 3RT1016-1AK61 + 3RH1911-1HA12 | |
| 3TF4022-0AL0 | 3RT1016-1AP61 + 3RH1911-1HA12 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TF4022-0AL2 | 3RT1016-1AP61 + 3RH1911-1HA12 | |
| 3TF4022-0AM1 | 3RT1016-1AM21 + 3RH1911-1HA12 | |
| 3TF4022-0AM11 | 3RT1016-1AM21 + 3RH1911-1HA12 | |
| 3TF4022-0AM2 | 3RT1016-1AM21 + 3RH1911-1HA12 | |
| 3TF4022-0AM21 | 3RT1016-1AM21 + 3RH1911-1HA12 | |
| 3TF4022-0AN2 | 3RT1016-1AP61 + 3RH1911-1HA12 | |
| 3TF4022-0AP0 | 3RT1016-1AP61 + 3RH1911-1HA12 | |
| 3TF4022-0AP6 | 3RT1016-1AP61 + 3RH1911-1HA12 | |
| 3TF4022-0AP61 | 3RT1016-1AP61 + 3RH1911-1HA12 | |
| 3TF4022-0AQ0 | 3RT1016-1AV01 + 3RH1911-1HA12 | |
| 3TF4022-0AQ01 | 3RT1016-1AV01 + 3RH1911-1HA12 | |
| 3TF4022-0AR6 | 3RT1016-1AR61 + 3RH1911-1HA12 | |
| 3TF4022-0AS0 | 3RT1016-1AT61 + 3RH1911-1HA12 | |
| 3TF4022-0AS01 | 3RT1016-1AT61 + 3RH1911-1HA12 | |
| 3TF4022-0AS2 | 3RT1016-1AT61 + 3RH1911-1HA12 | |
| 3TF4022-0AS21 | 3RT1016-1AT61 + 3RH1911-1HA12 | |
| 3TF4022-0AU1 | 3RT1016-1AU61 + 3RH1911-1HA12 | |
| 3TF4022-0AU11 | 3RT1016-1AU61 + 3RH1911-1HA12 | |
| 3TF4022-0AV0 | 3RT1016-1AV01 + 3RH1911-1HA12 | |
| 3TF4022-0AV01 | 3RT1016-1AV01 + 3RH1911-1HA12 | |
| 3TF4022-0BA4 | 3RT1016-1BA41 + 3RH1911-1HA12 | |
| 3TF4022-0BA41 | 3RT1016-1BA41 + 3RH1911-1HA12 | |
| 3TF4022-0BB4 | 3RT1016-1BB41 + 3RH1911-1HA12 | |
| 3TF4022-0BB41 | 3RT1016-1BB41 + 3RH1911-1HA12 | |
| 3TF4022-0BG4 | 3RT1016-1BG41 + 3RH1911-1HA12 | |
| 3TF4022-0BG41 | 3RT1016-1BG41 + 3RH1911-1HA12 | |
| 3TF4022-0BQ4 | 3RT1016-1BP41 + 3RH1911-1HA12 | |
| 3TF4022-0BQ41 | 3RT1016-1BP41 + 3RH1911-1HA12 | |
| 3TF4022-0BV4 | NO DIRECT REPLACEMENT | |
| 3TF4022-0BW4 | 3RT1016-1BW41 + 3RH1911-1HA12 | |
| 3TF4022-0BW41 | 3RT1016-1BW41 + 3RH1911-1HA12 | |
| 3TF4022-0LB4 | 3RT1016-1BB41 + 3RH1911-1HA12 | |
| 3TF4022-0LV4 | NO DIRECT REPLACEMENT | |
| 3TF4022-3KB41 | 3RT1016-1BB41 + 3RH1911-1HA12 | |
| 3TF4022-4KB4 | 3RT1016-1BB41 + 3RH1911-1HA12 | |
| 3TF4022-4MC1 | 3RT1016-1BB01 + 3RH1911-1HA12 | |
| 3TF4022-4MC2 | 3RT1016-1BB01 + 3RH1911-1HA12 | |
| 3TF4022-5MB4 | 3RT1016-1BB41 + 3RH1911-1HA12 | |
| 3TF4101-0AC2 | 3RT1017-1AB02 | |
| 3TF4101-0AK6 | 3RT1017-1AK62 | |
| 3TF4101-0AM1 | 3RT1017-1AM22 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TF4101-0AM2 | 3RT1017-1AM22 | |
| 3TF4101-0AN2 | 3RT1017-1AP62 | |
| 3TF4101-0AP6 | 3RT1017-1AP62 | |
| 3TF4101-0AQ0 | 3RT1017-1AV02 | |
| 3TF4101-0AS0 | 3RT1017-1AT62 | |
| 3TF4101-0AU1 | 3RT1017-1AU62 | |
| 3TF4101-0AV0 | 3RT1017-1AV02 | |
| 3TF4110-0AC2 | 3RT1017-1AB01 | |
| 3TF4110-0AG2 | 3RT1017-1AK61 | |
| 3TF4110-0AG6 | 3RT1017-1AG61 | |
| 3TF4110-0AJ2 | 3RT1017-1AK61 | |
| 3TF4110-0AK6 | 3RT1017-1AK61 | |
| 3TF4110-0AK61 | 3RT1017-1AK61 | |
| 3TF4110-0AM1 | 3RT1017-1AM21 | |
| 3TF4110-0AM2 | 3RT1017-1AM21 | |
| 3TF4110-0AN1 | 3RT1017-1AP61 | |
| 3TF4110-0AN2 | 3RT1017-1AP61 | |
| 3TF4110-0AP6 | 3RT1017-1AP61 | |
| 3TF4110-0AQ0 | 3RT1017-1AV01 | |
| 3TF4110-0AS0 | 3RT1017-1AT61 | |
| 3TF4110-0AS2 | 3RT1017-1AT61 | |
| 3TF4110-0AU1 | 3RT1017-1AU61 | |
| 3TF4110-0AV0 | 3RT1017-1AV01 | |
| 3TF4110-0BA4 | 3RT1017-1BA41 | |
| 3TF4110-0BB4 | 3RT1017-1BB41 | |
| 3TF4110-0BG4 | 3RT1017-1BG41 | |
| 3TF4110-0BQ4 | 3RT1017-1BP41 | |
| 3TF4110-0BW4 | 3RT1017-1BW41 | |
| 3TF4110-0LV4 | NO DIRECT REPLACEMENT | |
| 3TF4111-0AC2 | 3RT1017-1AB01 + 3RH1911-1HA01 | |
| 3TF4111-0AG2 | 3RT1017-1AK61 + 3RH1911-1HA01 | |
| 3TF4111-0AK6 | 3RT1017-1AK61 + 3RH1911-1HA01 | |
| 3TF4111-0AM1 | 3RT1017-1AM21 + 3RH1911-1HA01 | |
| 3TF4111-0AM2 | 3RT1017-1AM21 + 3RH1911-1HA01 | |
| 3TF4111-0AN2 | 3RT1017-1AP61 + 3RH1911-1HA01 | |
| 3TF4111-0AP6 | 3RT1017-1AP61 + 3RH1911-1HA01 | |
| 3TF4111-0AQ0 | 3RT1017-1AV01 + 3RH1911-1HA01 | |
| 3TF4111-0AS0 | 3RT1017-1AT61 + 3RH1911-1HA01 | |
| 3TF4111-0AS2 | 3RT1017-1AT61 + 3RH1911-1HA01 | |
| 3TF4111-0AU1 | 3RT1017-1AU61 + 3RH1911-1HA01 | |
| 3TF4111-0AV0 | 3RT1017-1AV01 + 3RH1911-1HA01 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TF4111-0BA4 | 3RT1017-1BA41 + 3RH1911-1HA01 | |
| 3TF4111-0BB4 | 3RT1017-1BB41 + 3RH1911-1HA01 | |
| 3TF4111-0BG4 | 3RT1017-1BG41 + 3RH1911-1HA01 | |
| 3TF4111-0BQ4 | 3RT1017-1BP41 + 3RH1911-1HA01 | |
| 3TF4111-0BW4 | 3RT1017-1BW41 + 3RH1911-1HA01 | |
| 3TF4122-0AC2 | 3RT1017-1AB01 + 3RH1911-1HA12 | |
| 3TF4122-0AD0 | 3RT1017-1AD01 + 3RH1911-1HA12 | |
| 3TF4122-0AD2 | 3RT1017-1AD21 + 3RH1911-1HA12 | |
| 3TF4122-0AG0 | 3RT1017-1AD01 + 3RH1911-1HA12 | |
| 3TF4122-0AG2 | 3RT1017-1AK61 + 3RH1911-1HA12 | |
| 3TF4122-0AH0 | 3RT1017-1AH01 + 3RH1911-1HA12 | |
| 3TF4122-0AJ2 | 3RT1017-1AK61 + 3RH1911-1HA12 | |
| 3TF4122-0AK6 | 3RT1017-1AK61 + 3RH1911-1HA12 | |
| 3TF4122-0AL2 | 3RT1017-1AP61 + 3RH1911-1HA12 | |
| 3TF4122-0AM1 | 3RT1017-1AM21 + 3RH1911-1HA12 | |
| 3TF4122-0AM2 | 3RT1017-1AM21 + 3RH1911-1HA12 | |
| 3TF4122-0AN1 | 3RT1017-1AP61 + 3RH1911-1HA12 | |
| 3TF4122-0AN2 | 3RT1017-1AP61 + 3RH1911-1HA12 | |
| 3TF4122-0AP6 | 3RT1017-1AP61 + 3RH1911-1HA12 | |
| 3TF4122-0AQ0 | 3RT1017-1AV01 + 3RH1911-1HA12 | |
| 3TF4122-0AS0 | 3RT1017-1AT61 + 3RH1911-1HA12 | |
| 3TF4122-0AS2 | 3RT1017-1AT61 + 3RH1911-1HA12 | |
| 3TF4122-0AU1 | 3RT1017-1AU61 + 3RH1911-1HA12 | |
| 3TF4122-0AV0 | 3RT1017-1AV01 + 3RH1911-1HA12 | |
| 3TF4122-0BA4 | 3RT1017-1BA41 + 3RH1911-1HA12 | |
| 3TF4122-0BB4 | 3RT1017-1BB41 + 3RH1911-1HA12 | |
| 3TF4122-0BC4 | NO DIRECT REPLACEMENT | |
| 3TF4122-0BD4 | 3RT1017-1BD41 + 3RH1911-1HA12 | |
| 3TF4122-0BG4 | 3RT1017-1BG41 + 3RH1911-1HA12 | |
| 3TF4122-0BQ4 | 3RT1017-1BP41 + 3RH1911-1HA12 | |
| 3TF4122-0BW4 | 3RT1017-1BW41 + 3RH1911-1HA12 | |
| 3TF4122-0LV4 | NO DIRECT REPLACEMENT | |
| 3TF4122-4BB4 | 3RT1017-1BB41 + 3RH1911-1HA12 | |
| 3TF4122-6EK6 | 3RT1017-1BK61 + 3RH1911-1HA12 | |
| 3TF4122-6EM1 | 3RT1017-1BM21 + 3RH1911-1HA12 | |
| 3TF4122-7EK6 | 3RT1017-1BK61 + 3RH1911-1HA12 | |
| 3TF4122-7EM1 | 3RT1017-1BM21 + 3RH1911-1HA12 | |
| 3TF4180-0AC2 | 3RT1017-1AC21 + 3RH1911-1FA31 | |
| 3TF4180-0AK6 | 3RT1017-1AK61 + 3RH1911-1FA31 | |
| 3TF4180-0AM1 | 3RT1017-1AM21 + 3RH1911-1FA31 | |
| 3TF4180-0AM2 | 3RT1017-1AM21 + 3RH1911-1FA31 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TF4180-0AP6 | 3RT1017-1AP61 + 3RH1911-1FA31 | |
| 3TF4180-0AQ0 | 3RT1017-1AV01 + 3RH1911-1FA31 | |
| 3TF4180-0AS0 | 3RT1017-1AT61 + 3RH1911-1FA31 | |
| 3TF4180-0AS2 | 3RT1017-1AT61 + 3RH1911-1FA31 | |
| 3TF4180-0AU1 | 3RT1017-1AU61 + 3RH1911-1FA31 | |
| 3TF4180-0AV0 | 3RT1017-1AV01 + 3RH1911-1FA31 | |
| 3TF4180-0BB4 | 3RT1017-1BB41 + 3RH1911-1FA31 | |
| 3TF4182-0AC2 | 3RT1017-1AC21 + 3RH1911-1HA12 | |
| 3TF4182-0AJ1 | 3RT1017-1AK61 + 3RH1911-1HA12 | |
| 3TF4182-0AK6 | 3RT1017-1AK61 + 3RH1911-1HA12 | |
| 3TF4182-0AM1 | 3RT1017-1AM21 + 3RH1911-1HA12 | |
| 3TF4182-0AM2 | 3RT1017-1AM21 + 3RH1911-1HA12 | |
| 3TF4182-0AP6 | 3RT1017-1AP61 + 3RH1911-1HA12 | |
| 3TF4182-0AQ0 | 3RT1017-1AV01 + 3RH1911-1HA12 | |
| 3TF4182-0AS0 | 3RT1017-1AT61 + 3RH1911-1HA12 | |
| 3TF4182-0AU1 | 3RT1017-1AU61 + 3RH1911-1HA12 | |
| 3TF4182-0AV0 | 3RT1017-1AV01 + 3RH1911-1HA12 | |
| 3TF4184-0AK6 | 3RT1017-1AK61 + 3RH1911-1HA12 | |
| 3TF4201-0AC2 | 3RT1025-1AC20 + 3RH1921-1CA01 | |
| 3TF4201-0AK6 | 3RT1025-1AK60 + 3RH1921-1CA01 | |
| 3TF4201-0AM1 | 3RT1025-1AM20 + 3RH1921-1CA01 | |
| 3TF4201-0AM2 | 3RT1025-1AM20 + 3RH1921-1CA01 | |
| 3TF4201-0AP6 | 3RT1025-1AP60 + 3RH1921-1CA01 | |
| 3TF4201-0AQ0 | 3RT1025-1AV00 + 3RH1921-1CA01 | |
| 3TF4201-0AS0 | 3RT1025-1AT60 + 3RH1921-1CA01 | |
| 3TF4201-0AU1 | 3RT1025-1AU60 + 3RH1921-1CA01 | |
| 3TF4201-0AV0 | 3RT1025-1AV00 + 3RH1921-1CA01 | |
| 3TF4210-0AC2 | 3RT1025-1AC20 + 3RH1921-1CA10 | |
| 3TF4210-0AC21 | 3RT1025-1AC20 + 3RH1921-1CA10 | |
| 3TF4210-0AH0 | 3RT1025-1AH00 + 3RH1921-1CA10 | |
| 3TF4210-0AK6 | 3RT1025-1AK60 + 3RH1921-1CA10 | |
| 3TF4210-0AK61 | 3RT1025-1AK60 + 3RH1921-1CA10 | |
| 3TF4210-0AM1 | 3RT1025-1AM20 + 3RH1921-1CA10 | |
| 3TF4210-0AM11 | 3RT1025-1AM20 + 3RH1921-1CA10 | |
| 3TF4210-0AM2 | 3RT1025-1AM20 + 3RH1921-1CA10 | |
| 3TF4210-0AM21 | 3RT1025-1AM20 + 3RH1921-1CA10 | |
| 3TF4210-0AN1 | 3RT1025-1AP60 + 3RH1921-1CA10 | |
| 3TF4210-0AP6 | 3RT1025-1AP60 + 3RH1921-1CA10 | |
| 3TF4210-0AP61 | 3RT1025-1AP60 + 3RH1921-1CA10 | |
| 3TF4210-0AQ0 | 3RT1025-1AV00 + 3RH1921-1CA10 | |
| 3TF4210-0AQ01 | 3RT1025-1AV00 + 3RH1921-1CA10 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TF4210-0AS0 | 3RT1025-1AT60 + 3RH1921-1CA10 | |
| 3TF4210-0AS01 | 3RT1025-1AT60 + 3RH1921-1CA10 | |
| 3TF4210-0AU1 | 3RT1025-1AU60 + 3RH1921-1CA10 | |
| 3TF4210-0AU11 | 3RT1025-1AU60 + 3RH1921-1CA10 | |
| 3TF4210-0AV0 | 3RT1025-1AV00 + 3RH1921-1CA10 | |
| 3TF4210-0AV01 | 3RT1025-1AV00 + 3RH1921-1CA10 | |
| 3TF4210-0BA4 | 3RT1025-1BA40 + 3RH1921-1CA10 | |
| 3TF4210-0BA41 | 3RT1025-1BA40 + 3RH1921-1CA10 | |
| 3TF4210-0BB4 | 3RT1025-1BB40 + 3RH1921-1CA10 | |
| 3TF4210-0BB41 | 3RT1025-1BB40 + 3RH1921-1CA10 | |
| 3TF4210-0BE4 | 3RT1025-1BE40 + 3RH1921-1CA10 | |
| 3TF4210-0BF4 | 3RT1025-1BF40 + 3RH1921-1CA10 | |
| 3TF4210-0BG4 | 3RT1025-1BG40 + 3RH1921-1CA10 | |
| 3TF4210-0BG41 | 3RT1025-1BG40 + 3RH1921-1CA10 | |
| 3TF4210-0BK4 | NO DIRECT REPLACEMENT | |
| 3TF4210-0BQ4 | 3RT1025-1BP40 + 3RH1921-1CA10 | |
| 3TF4210-0BQ41 | 3RT1025-1BP40 + 3RH1921-1CA10 | |
| 3TF4210-0BW4 | 3RT1025-1BW40 + 3RH1921-1CA10 | |
| 3TF4210-0BW41 | 3RT1025-1BW40 + 3RH1921-1CA10 | |
| 3TF4211-0AC2 | 3RT1025-1AC20 + 3RH1921-1EA11 | |
| 3TF4211-0AC21 | 3RT1025-1AC20 + 3RH1921-1EA11 | |
| 3TF4211-0AD0 | 3RT1025-1AD20 + 3RH1921-1EA11 | |
| 3TF4211-0AG2 | 3RT1025-1AK60 + 3RH1921-1EA11 | |
| 3TF4211-0AG21 | 3RT1025-1AK60 + 3RH1921-1EA11 | |
| 3TF4211-0AH0 | 3RT1025-1AH00 + 3RH1921-1EA11 | |
| 3TF4211-0AK6 | 3RT1025-1AK60 + 3RH1921-1EA11 | |
| 3TF4211-0AK61 | 3RT1025-1AK60 + 3RH1921-1EA11 | |
| 3TF4211-0AM1 | 3RT1025-1AM20 + 3RH1921-1EA11 | |
| 3TF4211-0AM11 | 3RT1025-1AM20 + 3RH1921-1EA11 | |
| 3TF4211-0AM2 | 3RT1025-1AM20 + 3RH1921-1EA11 | |
| 3TF4211-0AM21 | 3RT1025-1AM20 + 3RH1921-1EA11 | |
| 3TF4211-0AN2 | 3RT1025-1AP60 + 3RH1921-1EA11 | |
| 3TF4211-0AP0 | 3RT1025-1AP60 + 3RH1921-1EA11 | |
| 3TF4211-0AP6 | 3RT1025-1AP60 + 3RH1921-1EA11 | |
| 3TF4211-0AP61 | 3RT1025-1AP60 + 3RH1921-1EA11 | |
| 3TF4211-0AQ0 | 3RT1025-1AV00 + 3RH1921-1EA11 | |
| 3TF4211-0AQ01 | 3RT1025-1AV00 + 3RH1921-1EA11 | |
| 3TF4211-0AS0 | 3RT1025-1AT60 + 3RH1921-1EA11 | |
| 3TF4211-0AS01 | 3RT1025-1AT60 + 3RH1921-1EA11 | |
| 3TF4211-0AU1 | 3RT1025-1AU60 + 3RH1921-1EA11 | |
| 3TF4211-0AU11 | 3RT1025-1AU60 + 3RH1921-1EA11 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TF4211-0AV0 | 3RT1025-1AV00 + 3RH1921-1EA11 | |
| 3TF4211-0AV01 | 3RT1025-1AV00 + 3RH1921-1EA11 | |
| 3TF4211-0BA4 | 3RT1025-1BA40 + 3RH1921-1EA11 | |
| 3TF4211-0BA41 | 3RT1025-1BA40 + 3RH1921-1EA11 | |
| 3TF4211-0BB4 | 3RT1025-1BB40 + 3RH1921-1EA11 | |
| 3TF4211-0BB41 | 3RT1025-1BB40 + 3RH1921-1EA11 | |
| 3TF4211-0BG4 | 3RT1025-1BG40 + 3RH1921-1EA11 | |
| 3TF4211-0BG41 | 3RT1025-1BG40 + 3RH1921-1EA11 | |
| 3TF4211-0BQ4 | 3RT1025-1BP40 + 3RH1921-1EA11 | |
| 3TF4211-0BQ41 | 3RT1025-1BP40 + 3RH1921-1EA11 | |
| 3TF4211-0BW4 | 3RT1025-1BW40 + 3RH1921-1EA11 | |
| 3TF4211-0BW41 | 3RT1025-1BW40 + 3RH1921-1EA11 | |
| 3TF4220-0AK2 | 3RT1025- 1AK60 + 3RH1921-1EA20 | |
| 3TF4222-0AC2 | 3RT1025-1AC20 + 3RH1921-1FA22 | |
| 3TF4222-0AC21 | 3RT1025-1AC20 + 3RH1921-1FA22 | |
| 3TF4222-0AD0 | 3RT1025-1AD20 + 3RH1921-1FA22 | |
| 3TF4222-0AD2 | 3RT1025-1AD20 + 3RH1921-1FA22 | |
| 3TF4222-0AF0 | 3RT1025-1AK60 + 3RH1921-1FA22 | |
| 3TF4222-0AG0 | 3RT1025-1AG20 + 3RH1921-1FA22 | |
| 3TF4222-0AG1 | 3RT1025-1AK60 + 3RH1921-1FA22 | |
| 3TF4222-0AG2 | 3RT1025-1AK60 + 3RH1921-1FA22 | |
| 3TF4222-0AH0 | 3RT1025-1AH00 + 3RH1921-1FA22 | |
| 3TF4222-0AJ1 | 3RT1025-1AK60 + 3RH1921-1FA22 | |
| 3TF4222-0AJ2 | 3RT1025-1AK60 + 3RH1921-1FA22 | |
| 3TF4222-0AK1 | 3RT1025-1AK60 + 3RH1921-1FA22 | |
| 3TF4222-0AK2 | 3RT1025-1AK60 + 3RH1921-1FA22 | |
| 3TF4222-0AK6 | 3RT1025-1AK60 + 3RH1921-1FA22 | |
| 3TF4222-0AK61 | 3RT1025-1AK60 + 3RH1921-1FA22 | |
| 3TF4222-0AL2 | 3RT1025-1AP60 + 3RH1921-1FA22 | |
| 3TF4222-0AM0 | 3RT1025-1AM20 + 3RH1921-1FA22 | |
| 3TF4222-0AM1 | 3RT1025-1AM20 + 3RH1921-1FA22 | |
| 3TF4222-0AM11 | 3RT1025-1AM20 + 3RH1921-1FA22 | |
| 3TF4222-0AM2 | 3RT1025-1AM20 + 3RH1921-1FA22 | |
| 3TF4222-0AM21 | 3RT1025-1AM20 + 3RH1921-1FA22 | |
| 3TF4222-0AN2 | 3RT1025-1AP60 + 3RH1921-1FA22 | |
| 3TF4222-0AP0 | 3RT1025-1AP60 + 3RH1921-1FA22 | |
| 3TF4222-0AP6 | 3RT1025-1AP60 + 3RH1921-1FA22 | |
| 3TF4222-0AP61 | 3RT1025-1AP60 + 3RH1921-1FA22 | |
| 3TF4222-0AQ0 | 3RT1025-1AV00 + 3RH1921-1FA22 | |
| 3TF4222-0AQ01 | 3RT1025-1AV00 + 3RH1921-1FA22 | |
| 3TF4222-0AR1 | 3RT1025-1AR60 + 3RH1921-1FA22 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TF4222-0AS0 | 3RT1025-1AT60 + 3RH1921-1FA22 | |
| 3TF4222-0AS01 | 3RT1025-1AT60 + 3RH1921-1FA22 | |
| 3TF4222-0AS1 | 3RT1025-1AT60 + 3RH1921-1FA22 | |
| 3TF4222-0AS2 | 3RT1025-1AT60 + 3RH1921-1FA22 | |
| 3TF4222-0AS21 | 3RT1025-1AT60 + 3RH1921-1FA22 | |
| 3TF4222-0AU1 | 3RT1025-1AU60 + 3RH1921-1FA22 | |
| 3TF4222-0AU11 | 3RT1025-1AU60 + 3RH1921-1FA22 | |
| 3TF4222-0AV0 | 3RT1025-1AV00 + 3RH1921-1FA22 | |
| 3TF4222-0AV01 | 3RT1025-1AV00 + 3RH1921-1FA22 | |
| 3TF4222-0BA4 | 3RT1025-1BA40 + 3RH1921-1FA22 | |
| 3TF4222-0BA41 | 3RT1025-1BA40 + 3RH1921-1FA22 | |
| 3TF4222-0BB4 | 3RT1025-1BB40 + 3RH1921-1FA22 | |
| 3TF4222-0BB41 | 3RT1025-1BB40 + 3RH1921-1FA22 | |
| 3TF4222-0BD4 | 3RT1025-1BD40 + 3RH1921-1FA22 | |
| 3TF4222-0BE8 | NO DIRECT REPLACEMENT | |
| 3TF4222-0BF4 | 3RT1025-1BF40 + 3RH1921-1FA22 | |
| 3TF4222-0BG4 | 3RT1025-1BG40 + 3RH1921-1FA22 | |
| 3TF4222-0BG41 | 3RT1025-1BG40 + 3RH1921-1FA22 | |
| 3TF4222-0BQ4 | 3RT1025-1BP40 + 3RH1921-1FA22 | |
| 3TF4222-0BQ41 | 3RT1025-1BP40 + 3RH1921-1FA22 | |
| 3TF4222-0BV4 | NO DIRECT REPLACEMENT | |
| 3TF4222-0BW4 | 3RT1025-1BW40 + 3RH1921-1FA22 | |
| 3TF4222-0BW41 | 3RT1025-1BW40 + 3RH1921-1FA22 | |
| 3TF4222-0Q011 | NO DIRECT REPLACEMENT | |
| 3TF4222-4KB4 | 3RT1025-1BB40 + 3RH1921-1FA22 + SURGE | |
| 3TF4222-4MC2 | 3RT1025-1BC20 + 3RH1921-1FA22 | |
| 3TF4222-6EK6 | NO DIRECT REPLACEMENT | |
| 3TF4222-6EK61 | NO DIRECT REPLACEMENT | |
| 3TF4222-6EP6 | NO DIRECT REPLACEMENT | |
| 3TF4222-6FB4 | NO DIRECT REPLACEMENT | |
| 3TF4222-7EK6 | NO DIRECT REPLACEMENT | |
| 3TF4222-7EK61 | NO DIRECT REPLACEMENT | |
| 3TF4222-7FB4 | NO DIRECT REPLACEMENT | |
| 3TF4301-0AC2 | 3RT1026-1AC20 + 3RH1921-1CA01 | |
| 3TF4301-0AK6 | 3RT1026-1AK60 + 3RH1921-1CA01 | |
| 3TF4301-0AM1 | 3RT1026-1AM20 + 3RH1921-1CA01 | |
| 3TF4301-0AM2 | 3RT1026-1AM20 + 3RH1921-1CA01 | |
| 3TF4301-0AP6 | 3RT1026-1AP60 + 3RH1921-1CA01 | |
| 3TF4301-0AQ0 | 3RT1026-1AV00 + 3RH1921-1CA01 | |
| 3TF4301-0AS0 | 3RT1026-1AT60 + 3RH1921-1CA01 | |
| 3TF4301-0AU1 | 3RT1026-1AU60 + 3RH1921-1CA01 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TF4301-0AV0 | 3RT1026-1AV00 + 3RH1921-1CA01 | |
| 3TF4310-0AC2 | 3RT1026-1AC20 + 3RH1921-1CA10 | |
| 3TF4310-0AK6 | 3RT1026-1AK60 + 3RH1921-1CA10 | |
| 3TF4310-0AM1 | 3RT1026-1AM20 + 3RH1921-1CA10 | |
| 3TF4310-0AM2 | 3RT1026-1AM20 + 3RH1921-1CA10 | |
| 3TF4310-0AN1 | 3RT1026-1AP60 + 3RH1921-1CA10 | |
| 3TF4310-0AP6 | 3RT1026-1AP60 + 3RH1921-1CA10 | |
| 3TF4310-0AQ0 | 3RT1026-1AV00 + 3RH1921-1CA10 | |
| 3TF4310-0AS0 | 3RT1026-1AT60 + 3RH1921-1CA10 | |
| 3TF4310-0AU1 | 3RT1026-1AU60 + 3RH1921-1CA10 | |
| 3TF4310-0AV0 | 3RT1026-1AV00 + 3RH1921-1CA10 | |
| 3TF4310-0BB4 | 3RT1026-1BB40 + 3RH1921-1CA10 | |
| 3TF4310-0BW4 | 3RT1026-1BW40 + 3RH1921-1CA10 | |
| 3TF4311-0AC2 | 3RT1026-1AC20 + 3RH1921-1EA11 | |
| 3TF4311-0AG2 | 3RT1026-1AK60 + 3RH1921-1EA11 | |
| 3TF4311-0AK6 | 3RT1026-1AK60 + 3RH1921-1EA11 | |
| 3TF4311-0AM1 | 3RT1026-1AM20 + 3RH1921-1EA11 | |
| 3TF4311-0AM2 | 3RT1026-1AM20 + 3RH1921-1EA11 | |
| 3TF4311-0AN2 | 3RT1026-1AP60 + 3RH1921-1EA11 | |
| 3TF4311-0AP6 | 3RT1026-1AP60 + 3RH1921-1EA11 | |
| 3TF4311-0AQ0 | 3RT1026-1AV00 + 3RH1921-1EA11 | |
| 3TF4311-0AS0 | 3RT1026-1AT60 + 3RH1921-1EA11 | |
| 3TF4311-0AU1 | 3RT1026-1AU60 + 3RH1921-1EA11 | |
| 3TF4311-0AV0 | 3RT1026-1AV00 + 3RH1921-1EA11 | |
| 3TF4311-0BA4 | 3RT1026-1BA40 + 3RH1921-1EA11 | |
| 3TF4311-0BB4 | 3RT1026-1BB40 + 3RH1921-1EA11 | |
| 3TF4311-0BG4 | 3RT1026-1BG40 + 3RH1921-1EA11 | |
| 3TF4311-0BQ4 | 3RT1026-1BP40 + 3RH1921-1EA11 | |
| 3TF4311-0BW4 | 3RT1026-1BW40 + 3RH1921-1EA11 | |
| 3TF4322-0AC2 | 3RT1026-1AC20 + 3RH1921-1FA22 | |
| 3TF4322-0AD2 | 3RT1026-1AD20 + 3RH1921-1FA22 | |
| 3TF4322-0AG2 | 3RT1026-1AK60 + 3RH1921-1FA22 | |
| 3TF4322-0AJ2 | 3RT1026-1AK60 + 3RH1921-1FA22 | |
| 3TF4322-0AK6 | 3RT1026-1AK60 + 3RH1921-1FA22 | |
| 3TF4322-0AL2 | 3RT1026-1AP60 + 3RH1921-1FA22 | |
| 3TF4322-0AM0 | 3RT1026-1AM20 + 3RH1921-1FA22 | |
| 3TF4322-0AM1 | 3RT1026-1AM20 + 3RH1921-1FA22 | |
| 3TF4322-0AM2 | 3RT1026-1AM20 + 3RH1921-1FA22 | |
| 3TF4322-0AN2 | 3RT1026-1AP60 + 3RH1921-1FA22 | |
| 3TF4322-0AP0 | 3RT1026-1AP60 + 3RH1921-1FA22 | |
| 3TF4322-0AP6 | 3RT1026-1AP60 + 3RH1921-1FA22 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TF4322-0AQ0 | 3RT1026-1AV00 + 3RH1921-1FA22 | |
| 3TF4322-0AS0 | 3RT1026-1AT60 + 3RH1921-1FA22 | |
| 3TF4322-0AS2 | 3RT1026-1AT60 + 3RH1921-1FA22 | |
| 3TF4322-0AU1 | 3RT1026-1AU60 + 3RH1921-1FA22 | |
| 3TF4322-0AV0 | 3RT1026-1AV00 + 3RH1921-1FA22 | |
| 3TF4322-0BA4 | 3RT1026-1BA40 + 3RH1921-1FA22 | |
| 3TF4322-0BB4 | 3RT1026-1BB40 + 3RH1921-1FA22 | |
| 3TF4322-0BC4 | NO DIRECT REPLACEMENT | |
| 3TF4322-0BG4 | 3RT1026-1BG40 + 3RH1921-1FA22 | |
| 3TF4322-0BQ4 | 3RT1026-1BP40 + 3RH1921-1FA22 | |
| 3TF4322-0BW4 | 3RT1026-1BW40 + 3RH1921-1FA22 | |
| 3TF4322-6EK6 | NO DIRECT REPLACEMENT | |
| 3TF4322-6EP6 | NO DIRECT REPLACEMENT | |
| 3TF4322-7EC1 | NO DIRECT REPLACEMENT | |
| 3TF4322-7EK6 | NO DIRECT REPLACEMENT | |
| 3TF4322-7EP6 | NO DIRECT REPLACEMENT | |
| 3TF4411-0AC2 | 3RT1034-1AC20 + 3RH1921-1EA11 | |
| 3TF4411-0AC21 | 3RT1034-1AC20 + 3RH1921-1EA11 | |
| 3TF4411-0AD0 | 3RT1034-1AD20 + 3RH1921-1EA11 | |
| 3TF4411-0AG21 | 3RT1034-1AK60 + 3RH1921-1EA11 | |
| 3TF4411-0AK6 | 3RT1034-1AK60 + 3RH1921-1EA11 | |
| 3TF4411-0AK61 | 3RT1034-1AK60 + 3RH1921-1EA11 | |
| 3TF4411-0AM1 | 3RT1034-1AM20 + 3RH1921-1EA11 | |
| 3TF4411-0AM11 | 3RT1034-1AM20 + 3RH1921-1EA11 | |
| 3TF4411-0AM2 | 3RT1034-1AM20 + 3RH1921-1EA11 | |
| 3TF4411-0AM21 | 3RT1034-1AM20 + 3RH1921-1EA11 | |
| 3TF4411-0AN2 | 3RT1034-1AP60 + 3RH1921-1EA11 | |
| 3TF4411-0AP6 | 3RT1034-1AP60 + 3RH1921-1EA11 | |
| 3TF4411-0AP61 | 3RT1034-1AP60 + 3RH1921-1EA11 | |
| 3TF4411-0AQ0 | 3RT1034-1AV00 + 3RH1921-1EA11 | |
| 3TF4411-0AQ01 | 3RT1034-1AV00 + 3RH1921-1EA11 | |
| 3TF4411-0AS0 | 3RT1034-1AT60 + 3RH1921-1EA11 | |
| 3TF4411-0AS01 | 3RT1034-1AT60 + 3RH1921-1EA11 | |
| 3TF4411-0AU1 | 3RT1034-1AU60 + 3RH1921-1EA11 | |
| 3TF4411-0AU11 | 3RT1034-1AU60 + 3RH1921-1EA11 | |
| 3TF4411-0AV0 | 3RT1034-1AV00 + 3RH1921-1EA11 | |
| 3TF4411-0AV01 | 3RT1034-1AV00 + 3RH1921-1EA11 | |
| 3TF4411-0BA4 | 3RT1034-1BA40 + 3RH1921-1EA11 | |
| 3TF4411-0BA41 | 3RT1034-1BA40 + 3RH1921-1EA11 | |
| 3TF4411-0BB4 | 3RT1034-1BB40 + 3RH1921-1EA11 | |
| 3TF4411-0BB41 | 3RT1034-1BB40 + 3RH1921-1EA11 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TF4411-0BG4 | 3RT1034-1BG40 + 3RH1921-1EA11 | |
| 3TF4411-0BG41 | 3RT1034-1BG40 + 3RH1921-1EA11 | |
| 3TF4411-0BQ4 | 3RT1034-1BP40 + 3RH1921-1EA11 | |
| 3TF4411-0BQ41 | 3RT1034-1BP40 + 3RH1921-1EA11 | |
| 3TF4411-0BW4 | 3RT1034-1BW40 + 3RH1921-1EA11 | |
| 3TF4411-0BW41 | 3RT1034-1BW40 + 3RH1921-1EA11 | |
| 3TF4411-0LB4 | NO DIRECT REPLACEMENT | |
| 3TF4422-0AC2 | 3RT1034-1AC20 + 3RH1921-1FA22 | |
| 3TF4422-0AC21 | 3RT1034-1AC20 + 3RH1921-1FA22 | |
| 3TF4422-0AD2 | 3RT1034-1AD20 + 3RH1921-1FA22 | |
| 3TF4422-0AE0 | NO DIRECT REPLACEMENT | |
| 3TF4422-0AF0 | 3RT1034-1AK60 + 3RH1921-1FA22 | |
| 3TF4422-0AG0 | 3RT1034-1AG20 + 3RH1921-1FA22 | |
| 3TF4422-0AG1 | 3RT1034-1AK60 + 3RH1921-1FA22 | |
| 3TF4422-0AG2 | 3RT1034-1AK60 + 3RH1921-1FA22 | |
| 3TF4422-0AH0 | 3RT1034-1AH00 + 3RH1921-1FA22 | |
| 3TF4422-0AJ1 | 3RT1034-1AK60 + 3RH1921-1FA22 | |
| 3TF4422-0AK2 | 3RT1034-1AK60 + 3RH1921-1FA22 | |
| 3TF4422-0AK21 | 3RT1034-1AK60 + 3RH1921-1FA22 | |
| 3TF4422-0AK6 | 3RT1034-1AK60 + 3RH1921-1FA22 | |
| 3TF4422-0AK61 | 3RT1034-1AK60 + 3RH1921-1FA22 | |
| 3TF4422-0AK6ZB01 | 3RT1034-1AK60 + 3RH1921-1FA22 | |
| 3TF4422-0AL2 | 3RT1034-1AP60 + 3RH1921-1FA22 | |
| 3TF4422-0AM0 | 3RT1034-1AM20 + 3RH1921-1FA22 | |
| 3TF4422-0AM1 | 3RT1034-1AM20 + 3RH1921-1FA22 | |
| 3TF4422-0AM11 | 3RT1034-1AM20 + 3RH1921-1FA22 | |
| 3TF4422-0AM2 | 3RT1034-1AM20 + 3RH1921-1FA22 | |
| 3TF4422-0AM21 | 3RT1034-1AM20 + 3RH1921-1FA22 | |
| 3TF4422-0AN1 | 3RT1034-1AP60 + 3RH1921-1FA22 | |
| 3TF4422-0AN2 | 3RT1034-1AP60 + 3RH1921-1FA22 | |
| 3TF4422-0AP0 | 3RT1034-1AP60 + 3RH1921-1FA22 | |
| 3TF4422-0AP6 | 3RT1034-1AP60 + 3RH1921-1FA22 | |
| 3TF4422-0AP61 | 3RT1034-1AP60 + 3RH1921-1FA22 | |
| 3TF4422-0AQ0 | 3RT1034-1AV00 + 3RH1921-1FA22 | |
| 3TF4422-0AQ01 | 3RT1034-1AV00 + 3RH1921-1FA22 | |
| 3TF4422-0AR0 | 3RT1034-1AV60 + 3RH1921-1FA22 | |
| 3TF4422-0AR1 | 3RT1034-1AR60 + 3RH1921-1FA22 | |
| 3TF4422-0AS0 | 3RT1034-1AT60 + 3RH1921-1FA22 | |
| 3TF4422-0AS01 | 3RT1034-1AT60 + 3RH1921-1FA22 | |
| 3TF4422-0AS2 | 3RT1034-1AT60 + 3RH1921-1FA22 | |
| 3TF4422-0AS21 | 3RT1034-1AT60 + 3RH1921-1FA22 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TF4422-0AU1 | 3RT1034-1AU60 + 3RH1921-1FA22 | |
| 3TF4422-0AU11 | 3RT1034-1AU60 + 3RH1921-1FA22 | |
| 3TF4422-0AV0 | 3RT1034-1AV00 + 3RH1921-1FA22 | |
| 3TF4422-0AV01 | 3RT1034-1AV00 + 3RH1921-1FA22 | |
| 3TF4422-0BA4 | 3RT1034-1BA40 + 3RH1921-1FA22 | |
| 3TF4422-0BA41 | 3RT1034-1BA40 + 3RH1921-1FA22 | |
| 3TF4422-0BB4 | 3RT1034-1BB40 + 3RH1921-1FA22 | |
| 3TF4422-0BB41 | 3RT1034-1BB40 + 3RH1921-1FA22 | |
| 3TF4422-0BD4 | 3RT1034-1BD40 + 3RH1921-1FA22 | |
| 3TF4422-0BE4 | 3RT1034-1BE40 + 3RH1921-1FA22 | |
| 3TF4422-0BE8 | NO DIRECT REPLACEMENT | |
| 3TF4422-0BG4 | 3RT1034-1BG40 + 3RH1921-1FA22 | |
| 3TF4422-0BG41 | 3RT1034-1BG40 + 3RH1921-1FA22 | |
| 3TF4422-0BQ4 | 3RT1034-1BP40 + 3RH1921-1FA22 | |
| 3TF4422-0BQ41 | 3RT1034-1BP40 + 3RH1921-1FA22 | |
| 3TF4422-0BW4 | 3RT1034-1BW40 + 3RH1921-1FA22 | |
| 3TF4422-0BW41 | 3RT1034-1BW40 + 3RH1921-1FA22 | |
| 3TF4422-4MB0 | NO DIRECT REPLACEMENT | |
| 3TF4422-5KB41 | NO DIRECT REPLACEMENT | |
| 3TF4511-0AC2 | 3RT1035-1AC20 + 3RH1921-1EA11 | |
| 3TF4511-0AD2 | 3RT1035-1AD20 + 3RH1921-1EA11 | |
| 3TF4511-0AK6 | 3RT1035-1AK60 + 3RH1921-1EA11 | |
| 3TF4511-0AM1 | 3RT1035-1AM20 + 3RH1921-1EA11 | |
| 3TF4511-0AM2 | 3RT1035-1AM20 + 3RH1921-1EA11 | |
| 3TF4511-0AP6 | 3RT1035-1AP60 + 3RH1921-1EA11 | |
| 3TF4511-0AQ0 | 3RT1035-1AV00 + 3RH1921-1EA11 | |
| 3TF4511-0AS0 | 3RT1035-1AT60 + 3RH1921-1EA11 | |
| 3TF4511-0AU1 | 3RT1035-1AU60 + 3RH1921-1EA11 | |
| 3TF4511-0AV0 | 3RT1035-1AV00 + 3RH1921-1EA11 | |
| 3TF4511-0BA4 | 3RT1035-1BA40 + 3RH1921-1EA11 | |
| 3TF4511-0BB4 | 3RT1035-1BB40 + 3RH1921-1EA11 | |
| 3TF4511-0BG4 | 3RT1035-1BG40 + 3RH1921-1EA11 | |
| 3TF4511-0BQ4 | 3RT1035-1BP40 + 3RH1921-1EA11 | |
| 3TF4511-0BW4 | 3RT1035-1BW40 + 3RH1921-1EA11 | |
| 3TF4522-0AC2 | 3RT1035-1AC20 + 3RH1921-1FA22 | |
| 3TF4522-0AE0 | NO DIRECT REPLACEMENT | |
| 3TF4522-0AG2 | 3RT1035-1AK60 + 3RH1921-1FA22 | |
| 3TF4522-0AK6 | 3RT1035-1AK60 + 3RH1921-1FA22 | |
| 3TF4522-0AL2 | 3RT1035-1AP60 + 3RH1921-1FA22 | |
| 3TF4522-0AM0 | 3RT1035-1AM20 + 3RH1921-1FA22 | |
| 3TF4522-0AM1 | 3RT1035-1AM20 + 3RH1921-1FA22 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TF4522-0AM2 | 3RT1035-1AM20 + 3RH1921-1FA22 | |
| 3TF4522-0AP6 | 3RT1035-1AP60 + 3RH1921-1FA22 | |
| 3TF4522-0AQ0 | 3RT1035-1AV00 + 3RH1921-1FA22 | |
| 3TF4522-0AR2 | 3RT1035-1AR60 + 3RH1921-1FA22 | |
| 3TF4522-0AS0 | 3RT1035-1AT60 + 3RH1921-1FA22 | |
| 3TF4522-0AS2 | 3RT1035-1AT60 + 3RH1921-1FA22 | |
| 3TF4522-0AU1 | 3RT1035-1AU60 + 3RH1921-1FA22 | |
| 3TF4522-0AV0 | 3RT1035-1AV00 + 3RH1921-1FA22 | |
| 3TF4522-0BA4 | 3RT1035-1BA40 + 3RH1921-1FA22 | |
| 3TF4522-0BB4 | 3RT1035-1BB40 + 3RH1921-1FA22 | |
| 3TF4522-0BG4 | 3RT1035-1BG40 + 3RH1921-1FA22 | |
| 3TF4522-0BQ4 | 3RT1035-1BP40 + 3RH1921-1FA22 | |
| 3TF4522-0BW4 | 3RT1035-1BW40 + 3RH1921-1FA22 | |
| 3TF4611-0AC1 | 3RT1036-1AC20 + 3RH1921-1EA11 | |
| 3TF4611-0AC2 | 3RT1036-1AC20 + 3RH1921-1EA11 | |
| 3TF4611-0AC21 | 3RT1036-1AC20 + 3RH1921-1EA11 | |
| 3TF4611-0AG21 | 3RT1036-1AK60 + 3RH1921-1EA11 | |
| 3TF4611-0AK6 | 3RT1036-1AK60 + 3RH1921-1EA11 | |
| 3TF4611-0AK61 | 3RT1036-1AK60 + 3RH1921-1EA11 | |
| 3TF4611-0AM1 | 3RT1036-1AM20 + 3RH1921-1EA11 | |
| 3TF4611-0AM11 | 3RT1036-1AM20 + 3RH1921-1EA11 | |
| 3TF4611-0AM2 | 3RT1036-1AM20 + 3RH1921-1EA11 | |
| 3TF4611-0AM21 | 3RT1036-1AM20 + 3RH1921-1EA11 | |
| 3TF4611-0AP0 | 3RT1036-1AP60 + 3RH1921-1EA11 | |
| 3TF4611-0AP6 | 3RT1036-1AP60 + 3RH1921-1EA11 | |
| 3TF4611-0AP61 | 3RT1036-1AP60 + 3RH1921-1EA11 | |
| 3TF4611-0AQ0 | 3RT1036-1AV00 + 3RH1921-1EA11 | |
| 3TF4611-0AQ01 | 3RT1036-1AV00 + 3RH1921-1EA11 | |
| 3TF4611-0AS0 | 3RT1036-1AT60 + 3RH1921-1EA11 | |
| 3TF4611-0AS01 | 3RT1036-1AT60 + 3RH1921-1EA11 | |
| 3TF4611-0AU1 | 3RT1036-1AU60 + 3RH1921-1EA11 | |
| 3TF4611-0AU11 | 3RT1036-1AU60 + 3RH1921-1EA11 | |
| 3TF4611-0AV0 | 3RT1036-1AV00 + 3RH1921-1EA11 | |
| 3TF4611-0AV01 | 3RT1036-1AV00 + 3RH1921-1EA11 | |
| 3TF4622-0AC01 | 3RT1036-1AD20 + 3RH1921-1FA22 | |
| 3TF4622-0AC1 | 3RT1036-1AC20 + 3RH1921-1FA22 | |
| 3TF4622-0AC11 | 3RT1036-1AC20 + 3RH1921-1FA22 | |
| 3TF4622-0AC2 | 3RT1036-1AC20 + 3RH1921-1FA22 | |
| 3TF4622-0AC21 | 3RT1036-1AC20 + 3RH1921-1FA22 | |
| 3TF4622-0AD0 | 3RT1036-1AD20 + 3RH1921-1FA22 | |
| 3TF4622-0AD2 | 3RT1036-1AD20 + 3RH1921-1FA22 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TF4622-0AF0 | 3RT1036-1AK60 + 3RH1921-1FA22 | |
| 3TF4622-0AG0 | 3RT1036-1AG20 + 3RH1921-1FA22 | |
| 3TF4622-0AG1 | 3RT1036-1AK60 + 3RH1921-1FA22 | |
| 3TF4622-0AG2 | 3RT1036-1AK60 + 3RH1921-1FA22 | |
| 3TF4622-0AH0 | 3RT1036-1AH00 + 3RH1921-1FA22 | |
| 3TF4622-0AJ1 | 3RT1036-1AK60 + 3RH1921-1FA22 | |
| 3TF4622-0AJ11 | 3RT1036-1AK60 + 3RH1921-1FA22 | |
| 3TF4622-0AJ2 | 3RT1036-1AK60 + 3RH1921-1FA22 | |
| 3TF4622-0AK1 | 3RT1036-1AK60 + 3RH1921-1FA22 | |
| 3TF4622-0AK2 | 3RT1036-1AK60 + 3RH1921-1FA22 | |
| 3TF4622-0AK21 | 3RT1036-1AK60 + 3RH1921-1FA22 | |
| 3TF4622-0AK6 | 3RT1036-1AK60 + 3RH1921-1FA22 | |
| 3TF4622-0AK61 | 3RT1036-1AK60 + 3RH1921-1FA22 | |
| 3TF4622-0AK6Z/Z | 3RT1036-1AK60 + 3RH1921-1FA22 | |
| 3TF4622-0AK6Z0E | 3RT1036-1AK60 + 3RH1921-1FA22 | |
| 3TF4622-0AK6-ZB01 | 3RT1036-1AK60 + 3RH1921-1FA22 | |
| 3TF4622-0AL2 | 3RT1036-1AP60 + 3RH1921-1FA22 | |
| 3TF4622-0AM0 | 3RT1036-1AM20 + 3RH1921-1FA22 | |
| 3TF4622-0AM1 | 3RT1036-1AM20 + 3RH1921-1FA22 | |
| 3TF4622-0AM11 | 3RT1036-1AM20 + 3RH1921-1FA22 | |
| 3TF4622-0AM2 | 3RT1036-1AM20 + 3RH1921-1FA22 | |
| 3TF4622-0AM21 | 3RT1036-1AM20 + 3RH1921-1FA22 | |
| 3TF4622-0AN1 | 3RT1036-1AP60 + 3RH1921-1FA22 | |
| 3TF4622-0AN2 | 3RT1036-1AP60 + 3RH1921-1FA22 | |
| 3TF4622-0AP0 | 3RT1036-1AP60 + 3RH1921-1FA22 | |
| 3TF4622-0AP6 | 3RT1036-1AP60 + 3RH1921-1FA22 | |
| 3TF4622-0AP61 | 3RT1036-1AP60 + 3RH1921-1FA22 | |
| 3TF4622-0AQ0 | 3RT1036-1AV00 + 3RH1921-1FA22 | |
| 3TF4622-0AQ01 | 3RT1036-1AV00 + 3RH1921-1FA22 | |
| 3TF4622-0AR1 | 3RT1036-1AR60 + 3RH1921-1FA22 | |
| 3TF4622-0AS0 | 3RT1036-1AT60 + 3RH1921-1FA22 | |
| 3TF4622-0AS01 | 3RT1036-1AT60 + 3RH1921-1FA22 | |
| 3TF4622-0AS2 | 3RT1036-1AT60 + 3RH1921-1FA22 | |
| 3TF4622-0AS21 | 3RT1036-1AT60 + 3RH1921-1FA22 | |
| 3TF4622-0AU1 | 3RT1036-1AU60 + 3RH1921-1FA22 | |
| 3TF4622-0AU11 | 3RT1036-1AU60 + 3RH1921-1FA22 | |
| 3TF4622-0AV0 | 3RT1036-1AV00 + 3RH1921-1FA22 | |
| 3TF4622-0AV01 | 3RT1036-1AV00 + 3RH1921-1FA22 | |
| 3TF4622-0BA4 | 3RT1036-1BA40 + 3RH1921-1FA22 | |
| 3TF4622-0BA41 | 3RT1036-1BA40 + 3RH1921-1FA22 | |
| 3TF4622-0BB4 | 3RT1036-1BB40 + 3RH1921-1FA22 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TF4622-0BB41 | 3RT1036-1BB40 + 3RH1921-1FA22 | |
| 3TF4622-0BG4 | 3RT1036-1BG40 + 3RH1921-1FA22 | |
| 3TF4622-0BG41 | 3RT1036-1BG40 + 3RH1921-1FA22 | |
| 3TF4622-0BN4 | NO DIRECT REPLACEMENT | |
| 3TF4622-0BQ4 | 3RT1036-1BP40 + 3RH1921-1FA22 | |
| 3TF4622-0BQ41 | 3RT1036-1BP40 + 3RH1921-1FA22 | |
| 3TF4622-0BV4 | NO DIRECT REPLACEMENT | |
| 3TF4622-0BW4 | 3RT1036-1BW40 + 3RH1921-1FA22 | |
| 3TF4622-0BW41 | 3RT1036-1BW40 + 3RH1921-1FA22 | |
| 3TF4622-0DA4 | NO DIRECT REPLACEMENT | |
| 3TF4622-0DB4 | NO DIRECT REPLACEMENT | |
| 3TF4622-0DB41 | NO DIRECT REPLACEMENT | |
| 3TF4622-0DG4 | NO DIRECT REPLACEMENT | |
| 3TF4622-0DG41 | NO DIRECT REPLACEMENT | |
| 3TF4622-0DQ4 | NO DIRECT REPLACEMENT | |
| 3TF4622-0DQ41 | NO DIRECT REPLACEMENT | |
| 3TF4622-0DV4 | NO DIRECT REPLACEMENT | |
| 3TF4622-0DW4 | NO DIRECT REPLACEMENT | |
| 3TF4622-0DW41 | NO DIRECT REPLACEMENT | |
| 3TF4622-0LV4 | NO DIRECT REPLACEMENT | |
| 3TF4622-4MJ2 | NO DIRECT REPLACEMENT | |
| 3TF4644-0AC2 | 3RT1036-1AC24 | |
| 3TF4644-0AJ1 | NO DIRECT REPLACEMENT | |
| 3TF4644-0AM1 | NO DIRECT REPLACEMENT | |
| 3TF4644-0AR1 | NO DIRECT REPLACEMENT | |
| 3TF4644-1AK6 | NO DIRECT REPLACEMENT | |
| 3TF4711-0AC2 | 3RT1044-1AC20 + 3RH1921-1EA11 | |
| 3TF4711-0AK6 | 3RT1044-1AK60 + 3RH1921-1EA11 | |
| 3TF4711-0AM1 | 3RT1044-1AM20 + 3RH1921-1EA11 | |
| 3TF4711-0AM2 | 3RT1044-1AM20 + 3RH1921-1EA11 | |
| 3TF4711-0AN1 | 3RT1044-1AP60 + 3RH1921-1EA11 | |
| 3TF4711-0AP6 | 3RT1044-1AP60 + 3RH1921-1EA11 | |
| 3TF4711-0AQ0 | 3RT1044-1AV00 + 3RH1921-1EA11 | |
| 3TF4711-0AS0 | 3RT1044-1AT60 + 3RH1921-1EA11 | |
| 3TF4711-0AU1 | 3RT1044-1AU60 + 3RH1921-1EA11 | |
| 3TF4711-0AV0 | 3RT1044-1AV00 + 3RH1921-1EA11 | |
| 3TF4722-0AC1 | 3RT1044-1AC20 + 3RH1921-1FA22 | |
| 3TF4722-0AC2 | 3RT1044-1AC20 + 3RH1921-1FA22 | |
| 3TF4722-0AG1 | 3RT1044-1AK60 + 3RH1921-1FA22 | |
| 3TF4722-0AG2 | 3RT1044-1AK60 + 3RH1921-1FA22 | |
| 3TF4722-0AG6 | 3RT1044-1AG60 + 3RH1921-1FA22 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TF4722-0AK6 | 3RT1044-1AK60 + 3RH1921-1FA22 | |
| 3TF4722-0AK6Z/Z | 3RT1044-1AK60 + 3RH1921-1FA22 | |
| 3TF4722-0AL2 | 3RT1044-1AP60 + 3RH1921-1FA22 | |
| 3TF4722-0AM0 | 3RT1044-1AM20 + 3RH1921-1FA22 | |
| 3TF4722-0AM1 | 3RT1044-1AM20 + 3RH1921-1FA22 | |
| 3TF4722-0AM2 | 3RT1044-1AM20 + 3RH1921-1FA22 | |
| 3TF4722-0AN2 | 3RT1044-1AP60 + 3RH1921-1FA22 | |
| 3TF4722-0AP0 | 3RT1044-1AP60 + 3RH1921-1FA22 | |
| 3TF4722-0AP6 | 3RT1044-1AP60 + 3RH1921-1FA22 | |
| 3TF4722-0AQ0 | 3RT1044-1AV00 + 3RH1921-1FA22 | |
| 3TF4722-0AR6 | 3RT1044-1AR60 + 3RH1921-1FA22 | |
| 3TF4722-0AS0 | 3RT1044-1AT60 + 3RH1921-1FA22 | |
| 3TF4722-0AS2 | 3RT1044-1AT60 + 3RH1921-1FA22 | |
| 3TF4722-0AU1 | 3RT1044-1AU60 + 3RH1921-1FA22 | |
| 3TF4722-0AV0 | 3RT1044-1AV00 + 3RH1921-1FA22 | |
| 3TF4722-0BA4 | 3RT1044-1BA40 + 3RH1921-1FA22 | |
| 3TF4722-0BB4 | 3RT1044-1BB40 + 3RH1921-1FA22 | |
| 3TF4722-0BG4 | 3RT1044-1BG40 + 3RH1921-1FA22 | |
| 3TF4722-0BQ4 | 3RT1044-1BP40 + 3RH1921-1FA22 | |
| 3TF4722-0BW4 | 3RT1044-1BW40 + 3RH1921-1FA22 | |
| 3TF4722-0DB4 | NO DIRECT REPLACEMENT | |
| 3TF4722-0DF4 | NO DIRECT REPLACEMENT | |
| 3TF4722-0DG4 | NO DIRECT REPLACEMENT | |
| 3TF4722-0DQ4 | NO DIRECT REPLACEMENT | |
| 3TF4722-0DW4 | NO DIRECT REPLACEMENT | |
| 3TF4722-5MB4 | NO DIRECT REPLACEMENT | |
| 3TF4811-0AC1 | 3RT1045-1AC20 + 3RH1921-1EA11 | |
| 3TF4811-0AC2 | 3RT1045-1AC20 + 3RH1921-1EA11 | |
| 3TF4811-0AC21 | 3RT1045-1AC20 + 3RH1921-1EA11 | |
| 3TF4811-0AD2 | 3RT1045-1AD20 + 3RH1921-1EA11 | |
| 3TF4811-0AG21 | 3RT1045-1AK60 + 3RH1921-1EA11 | |
| 3TF4811-0AK6 | 3RT1045-1AK60 + 3RH1921-1EA11 | |
| 3TF4811-0AK61 | 3RT1045-1AK60 + 3RH1921-1EA11 | |
| 3TF4811-0AM1 | 3RT1045-1AM20 + 3RH1921-1EA11 | |
| 3TF4811-0AM11 | 3RT1045-1AM20 + 3RH1921-1EA11 | |
| 3TF4811-0AM2 | 3RT1045-1AM20 + 3RH1921-1EA11 | |
| 3TF4811-0AM21 | 3RT1045-1AM20 + 3RH1921-1EA11 | |
| 3TF4811-0AP6 | 3RT1045-1AP60 + 3RH1921-1EA11 | |
| 3TF4811-0AP61 | 3RT1045-1AP60 + 3RH1921-1EA11 | |
| 3TF4811-0AQ0 | 3RT1045-1AV00 + 3RH1921-1EA11 | |
| 3TF4811-0AQ01 | 3RT1045-1AV00 + 3RH1921-1EA11 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TF4811-0AS0 | 3RT1045-1AT60 + 3RH1921-1EA11 | |
| 3TF4811-0AS01 | 3RT1045-1AT60 + 3RH1921-1EA11 | |
| 3TF4811-0AU1 | 3RT1045-1AU60 + 3RH1921-1EA11 | |
| 3TF4811-0AU11 | 3RT1045-1AU60 + 3RH1921-1EA11 | |
| 3TF4811-0AV0 | 3RT1045-1AV00 + 3RH1921-1EA11 | |
| 3TF4811-0AV01 | 3RT1045-1AV00 + 3RH1921-1EA11 | |
| 3TF4822-0AC01 | 3RT1045-1AD20 + 3RH1921-1FA22 | |
| 3TF4822-0AC1 | 3RT1045-1AC20 + 3RH1921-1FA22 | |
| 3TF4822-0AC11 | 3RT1045-1AC20 + 3RH1921-1FA22 | |
| 3TF4822-0AC2 | 3RT1045-1AC20 + 3RH1921-1FA22 | |
| 3TF4822-0AC21 | 3RT1045-1AC20 + 3RH1921-1FA22 | |
| 3TF4822-0AG1 | 3RT1045-1AK60 + 3RH1921-1FA22 | |
| 3TF4822-0AG11 | 3RT1045-1AK60 + 3RH1921-1FA22 | |
| 3TF4822-0AG2 | 3RT1045-1AK60 + 3RH1921-1FA22 | |
| 3TF4822-0AJ1 | 3RT1045-1AK60 + 3RH1921-1FA22 | |
| 3TF4822-0AJ2 | 3RT1045-1AK60 + 3RH1921-1FA22 | |
| 3TF4822-0AK2 | 3RT1045-1AK60 + 3RH1921-1FA22 | |
| 3TF4822-0AK21 | 3RT1045-1AK60 + 3RH1921-1FA22 | |
| 3TF4822-0AK6 | 3RT1045-1AK60 + 3RH1921-1FA22 | |
| 3TF4822-0AK61 | 3RT1045-1AK60 + 3RH1921-1FA22 | |
| 3TF4822-0AK6Z/Z | 3RT1045-1AK60 + 3RH1921-1FA22 | |
| 3TF4822-0AK6Z0E | 3RT1045-1AK60 + 3RH1921-1FA22 | |
| 3TF4822-0AK6-ZB01 | 3RT1045-1AK60 + 3RH1921-1FA22 | |
| 3TF4822-0AL2 | 3RT1045-1AP60 + 3RH1921-1FA22 | |
| 3TF4822-0AM0 | 3RT1045-1AM20 + 3RH1921-1FA22 | |
| 3TF4822-0AM1 | 3RT1045-1AM20 + 3RH1921-1FA22 | |
| 3TF4822-0AM11 | 3RT1045-1AM20 + 3RH1921-1FA22 | |
| 3TF4822-0AM2 | 3RT1045-1AM20 + 3RH1921-1FA22 | |
| 3TF4822-0AM21 | 3RT1045-1AM20 + 3RH1921-1FA22 | |
| 3TF4822-0AN1 | 3RT1045-1AP60 + 3RH1921-1FA22 | |
| 3TF4822-0AP0 | 3RT1045-1AP60 + 3RH1921-1FA22 | |
| 3TF4822-0AP6 | 3RT1045-1AP60 + 3RH1921-1FA22 | |
| 3TF4822-0AP61 | 3RT1045-1AP60 + 3RH1921-1FA22 | |
| 3TF4822-0AP6Z0E | 3RT1045-1AP60 + 3RH1921-1FA22 | |
| 3TF4822-0AQ0 | 3RT1045-1AV00 + 3RH1921-1FA22 | |
| 3TF4822-0AQ01 | 3RT1045-1AV00 + 3RH1921-1FA22 | |
| 3TF4822-0AR01 | 3RT1045-1AV60 + 3RH1921-1FA22 | |
| 3TF4822-0AR1 | 3RT1045-1AR60 + 3RH1921-1FA22 | |
| 3TF4822-0AS0 | 3RT1045-1AT60 + 3RH1921-1FA22 | |
| 3TF4822-0AS01 | 3RT1045-1AT60 + 3RH1921-1FA22 | |
| 3TF4822-0AS2 | 3RT1045-1AT60 + 3RH1921-1FA22 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TF4822-0AS21 | 3RT1045-1AT60 + 3RH1921-1FA22 | |
| 3TF4822-0AU1 | 3RT1045-1AU60 + 3RH1921-1FA22 | |
| 3TF4822-0AU11 | 3RT1045-1AU60 + 3RH1921-1FA22 | |
| 3TF4822-0AV0 | 3RT1045-1AV00 + 3RH1921-1FA22 | |
| 3TF4822-0AV01 | 3RT1045-1AV00 + 3RH1921-1FA22 | |
| 3TF4822-0AW2 | 3RT1045-1AV60 + 3RH1921-1FA22 | |
| 3TF4822-0DB4 | NO DIRECT REPLACEMENT | |
| 3TF4822-0DB41 | NO DIRECT REPLACEMENT | |
| 3TF4822-0DG4 | NO DIRECT REPLACEMENT | |
| 3TF4822-0DG41 | NO DIRECT REPLACEMENT | |
| 3TF4822-0DN4 | NO DIRECT REPLACEMENT | |
| 3TF4822-0DQ4 | NO DIRECT REPLACEMENT | |
| 3TF4822-0DQ41 | NO DIRECT REPLACEMENT | |
| 3TF4822-0DW4 | NO DIRECT REPLACEMENT | |
| 3TF4822-0DW41 | NO DIRECT REPLACEMENT | |
| 3TF4822-4MJ2 | NO DIRECT REPLACEMENT | |
| 3TF4844-0AJ1 | 3RT1045-1AK60 + 4NO & 4NC AUX | |
| 3TF4844-0AK6 | 3RT1045-1AK60 + 4NO & 4NC AUX | |
| 3TF4844-0AP6 | 3RT1045-1AP60 + 4NO & 4NC AUX | |
| 3TF4844-0AR1 | 3RT1045-1AR60 + 4NO & 4NC AUX | |
| 3TF4844-0AU1 | 3RT1045-1AU60 + 4NO & 4NC AUX | |
| 3TF4844-0AV0 | 3RT1045-1AV00 + 4NO & 4NC AUX | |
| 3TF4911-0AC1 | 3RT1046-1AC20 + 3RH1921-1EA11 | |
| 3TF4911-0AC2 | 3RT1046-1AC20 + 3RH1921-1EA11 | |
| 3TF4911-0AK6 | 3RT1046-1AK60 + 3RH1921-1EA11 | |
| 3TF4911-0AK61 | 3RT1046-1AK60 + 3RH1921-1EA11 | |
| 3TF4911-0AM1 | 3RT1046-1AM20 + 3RH1921-1EA11 | |
| 3TF4911-0AM2 | 3RT1046-1AM20 + 3RH1921-1EA11 | |
| 3TF4911-0AP6 | 3RT1046-1AP60 + 3RH1921-1EA11 | |
| 3TF4911-0AQ0 | 3RT1046-1AV00 + 3RH1921-1EA11 | |
| 3TF4911-0AS0 | 3RT1046-1AT60 + 3RH1921-1EA11 | |
| 3TF4911-0AU1 | 3RT1046-1AU60 + 3RH1921-1EA11 | |
| 3TF4911-0AV0 | 3RT1046-1AV00 + 3RH1921-1EA11 | |
| 3TF4922-0AC1 | 3RT1046-1AC20 + 3RH1921-1FA22 | |
| 3TF4922-0AC2 | 3RT1046-1AC20 + 3RH1921-1FA22 | |
| 3TF4922-0AK6 | 3RT1046-1AK60 + 3RH1921-1FA22 | |
| 3TF4922-0AM1 | 3RT1046-1AM20 + 3RH1921-1FA22 | |
| 3TF4922-0AM2 | 3RT1046-1AM20 + 3RH1921-1FA22 | |
| 3TF4922-0AN2 | 3RT1046-1AP60 + 3RH1921-1FA22 | |
| 3TF4922-0AP6 | 3RT1046-1AP60 + 3RH1921-1FA22 | |
| 3TF4922-0AQ0 | 3RT1046-1AV00 + 3RH1921-1FA22 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TF4922-0AS0 | 3RT1046-1AT60 + 3RH1921-1FA22 | |
| 3TF4922-0AS2 | 3RT1046-1AT60 + 3RH1921-1FA22 | |
| 3TF4922-0AU1 | 3RT1046-1AU60 + 3RH1921-1FA22 | |
| 3TF4922-0AV0 | 3RT1046-1AV00 + 3RH1921-1FA22 | |
| 3TF4922-0DB4 | NO DIRECT REPLACEMENT | |
| 3TF5011-0AC1 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1054-6AB36 |
| 3TF5011-0AC2 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1054-6AB36 |
| 3TF5011-0AK6 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1054-6AF36 |
| 3TF5011-0AM1 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1054-6AM36 |
| 3TF5011-0AM2 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1054-6AM36 |
| 3TF5011-0AP6 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1054-6AP36 |
| 3TF5011-0AQ0 | SEE 3TF5011-0AV0 UNTIL SEPTEMBER 2001 | AFTER SEPTEMBER 2001, ORDER 3RT1054-6AV36 |
| 3TF5011-0AS0 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1054-6AS36 |
| 3TF5011-0AU1 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1054-6AU36 |
| 3TF5011-0AV0 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1054-6AV36 |
| 3TF5022-0AC1 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1054-6AB36 |
| 3TF5022-0AC2 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1054-6AB36 |
| 3TF5022-0AG0 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | NO DIRECT REPLACEMENT |
| 3TF5022-0AG2 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1054-6AF36 |
| 3TF5022-0AJ1 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1054-6AF36 |
| 3TF5022-0AK6 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1054-6AF36 |
| 3TF50220AK6ZB01 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | NO DIRECT REPLACEMENT |
| 3TF5022-0AK6-ZB01 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1054-6AF36 |
| 3TF5022-0AM0 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1054-6AP36 |
| 3TF5022-0AM1 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1054-6AM36 |
| 3TF5022-0AN1 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1054-6AP36 |
| 3TF5022-0AP0 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1054-6AU36 |
| 3TF5022-0AP6 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1054-6AP36 |
| 3TF5022-0AQ0 | SEE 3TF5022-0AV0 UNTIL SEPTEMBER 2001 | AFTER SEPTEMBER 2001, ORDER 3RT1054-6AV36 |
| 3TF5022-0AR0 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1054-6AR36 |
| 3TF5022-0AR1 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1054-6AR36 |
| 3TF5022-0AS0 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1054-6AS36 |
| 3TF5022-0AS2 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1054-6AT36 |
| 3TF5022-0AU1 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1054-6AU36 |
| 3TF5022-0AV0 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1054-6AV36 |
| 3TF5022-0DB4 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1054-6AB36 |
| 3TF5022-0DG4 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1054-6AF36 |
| 3TF5022-0DW4 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1054-6AD36 |
| 3TF5022-4MG1 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1054-6AF36 |
| 3TF5044-0AC2 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1054-6AB36 + 3RH1921-1FA22 |
| 3TF5044-0AK6 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1054-6AF36 + 3RH1921-1FA22 |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TF5044-0AM0 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1054-6AP36 + 3RH1921-1FA22 |
| 3TF5044-0AP6 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1054-6AP36 + 3RH1921-1FA22 |
| 3TF5044-0AR1 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1054-6AR36 + 3RH1921-1FA22 |
| 3TF5044-0AV0 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1054-6AV36 + 3RH1921-1FA22 |
| 3TF50-BAG3 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | NO DIRECT REPLACEMENT |
| 3TF5111-0AC2 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1055-6AB36 |
| 3TF5111-0AK6 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1055-6AF36 |
| 3TF5111-0AK6L | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1055-6AF36 |
| 3TF5111-0AM1 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1055-6AM36 |
| 3TF5111-0AM2 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1055-6AM36 |
| 3TF5111-0AP6 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1055-6AP36 |
| 3TF5111-0AQ0 | SEE 3TF5111-0AV0 UNTIL SEPTEMBER 2001 | AFTER SEPTEMBER 2001, ORDER 3RT1055-6AV36 |
| 3TF5111-0AS0 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1055-6AS36 |
| 3TF5111-0AU1 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1055-6AU36 |
| 3TF5111-0AV0 | SEE 3TF5211-0AV0 UNTIL SEPTEMBER 2001 | AFTER SEPTEMBER 2001, ORDER 3RT1055-6AV36 |
| 3TF5122-0AC1 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1055-6AB36 |
| 3TF5122-0AG2 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1055-6AF36 |
| 3TF5122-0AK6 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1055-6AF36 |
| 3TF5122-0AK6L | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1055-6AF36 |
| 3TF51220AK6ZB01 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | NO DIRECT REPLACEMENT |
| 3TF5122-0AM1 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1055-6AM36 |
| 3TF5122-0AP0 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1055-6AU36 |
| 3TF5122-0AP6 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1055-6AP36 |
| 3TF5122-0AQ0 | SEE 3TF5122-0AV0 UNTIL SEPTEMBER 2001 | AFTER SEPTEMBER 2001, ORDER 3RT1055-6AV36 |
| 3TF5122-0AS0 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1055-6AS36 |
| 3TF5122-0AS2 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1055-6AT36 |
| 3TF5122-0AU1 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1055-6AU36 |
| 3TF5122-0AV0 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1055-6AV36 |
| 3TF5122-0DB4 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1055-6AB36 |
| 3TF5211-0AC1 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AB36 | |
| 3TF5211-0AC2 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AB36 |
| 3TF5211-0AC21 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AB36 | |
| 3TF5211-0AG21 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AF36 |
| 3TF5211-0AK6 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AF36 |
| 3TF5211-0AK61 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AF36 |
| 3TF5211-0AK6L | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AF36 |
| 3TF5211-0AM1 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AM36 |
| 3TF5211-0AM11 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AM36 |
| 3TF5211-0AM2 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AM36 |
| 3TF5211-0AM21 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AM36 |
| 3TF5211-0AM6 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AP36 |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TF5211-0AP6 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AP36 |
| 3TF5211-0AP61 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AP36 |
| 3TF5211-0AQ0 | SEE 3TF5211-0AV0 UNTIL SEPTEMBER 2001 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AV36 |
| 3TF5211-0AQ01 | SEE 3TF5211-0AV01 UNTIL SEPTEMBER 2001 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AV36 |
| 3TF5211-0AS0 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AS36 |
| 3TF5211-0AS01 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AS36 |
| 3TF5211-0AU1 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AU36 |
| 3TF5211-0AU11 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AU36 |
| 3TF5211-0AV0 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AV36 |
| 3TF5211-0AV01 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AV36 |
| 3TF5222-0AC1 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AB36 |
| 3TF5222-0AC11 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AB36 | |
| 3TF5222-0AG1 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AF36 |
| 3TF5222-0AG11 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AF36 |
| 3TF5222-0AG2 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AF36 |
| 3TF5222-0AG21 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AF36 |
| 3TF5222-0AJ1 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AF36 |
| 3TF5222-0AK1 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AF36 |
| 3TF5222-0AK2 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AF36 |
| 3TF5222-0AK21 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AF36 |
| 3TF5222-0AK6 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AF36 |
| 3TF5222-0AK61 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AF36 |
| 3TF5222-0AK6L | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AF36 |
| 3TF5222-0AM0 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AP36 |
| 3TF5222-0AM1 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AM36 |
| 3TF5222-0AM11 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AM36 |
| 3TF5222-0AM2 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AM36 |
| 3TF5222-0AN1 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AP36 |
| 3TF5222-0AP0 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AU36 |
| 3TF5222-0AP6 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AP36 |
| 3TF5222-0AP61 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AP36 |
| 3TF5222-0AQ0 | SEE 3TF5222-0AV0 UNTIL SEPTEMBER 2001 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AV36 |
| 3TF5222-0AQ01 | SEE 3TF5222-0AV01 UNTIL SEPTEMBER 2001 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AV36 |
| 3TF5222-0AR1 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AR36 |
| 3TF5222-0AS0 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AS36 |
| 3TF5222-0AS01 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AS36 |
| 3TF5222-0AS2 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AT36 |
| 3TF5222-0AS21 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AT36 |
| 3TF5222-0AU1 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AU36 |
| 3TF5222-0AU11 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AU36 |
| 3TF5222-0AV0 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AV36 |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TF5222-0AV01 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AV36 |
| 3TF5222-0DB4 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AB36 |
| 3TF5222-1DB4 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AB36 |
| 3TF5222-1DB41 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AB36 |
| 3TF5222-1DG4 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AF36 |
| 3TF5222-1DG41 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AF36 |
| 3TF5222-1DW4 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AD36 |
| 3TF5222-1DW41 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AD36 |
| 3TF5244-0AJ1 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AF36 + 3RH1921-1FA22 |
| 3TF5244-0AP6 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AP36 + 3RH1921-1FA22 |
| 3TF5244-0AR1 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AR36 + 3RH1921-1FA22 |
| 3TF5311-0AC2 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AB36 |
| 3TF5311-0AK6 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AF36 |
| 3TF5311-0AK6L | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AF36 |
| 3TF5311-0AM1 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AM36 |
| 3TF5311-0AM2 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AM36 |
| 3TF5311-0AP6 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AP36 |
| 3TF5311-0AQ0 | SEE 3TF5311-0AV0 UNTIL SEPTEMBER 2001 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AV36 |
| 3TF5311-0AS0 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AS36 |
| 3TF5311-0AU1 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AU36 |
| 3TF5311-0AV0 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AV36 |
| 3TF5322-0AC2 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AB36 | |
| 3TF5322-0AG2 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AF36 |
| 3TF5322-0AK6 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AF36 |
| 3TF5322-0AK6L | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AF36 |
| 3TF5322-0AM0 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AP36 |
| 3TF5322-0AM1 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AM36 |
| 3TF5322-0AM2 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AM36 |
| 3TF5322-0AP6 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AP36 |
| 3TF5322-0AQ0 | SEE 3TF5322-0AV0 UNTIL SEPTEMBER 2001 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AV36 |
| 3TF5322-0AS0 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AS36 |
| 3TF5322-0AS2 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AT36 |
| 3TF5322-0AU1 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AU36 |
| 3TF5322-0AV0 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AV36 |
| 3TF5322-1DB4 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1056-6AB36 |
| 3TF5411-0AC2 | AFTER SEPTEMBER 2001, ORDER 3RT1065-6AB36 | |
| 3TF5411-0AK6 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1065-6AF36 |
| 3TF5411-0AK6L | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1065-6AF36 |
| 3TF5411-0AM1 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1065-6AM36 |
| 3TF5411-0AM2 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1065-6AM36 |
| 3TF5411-0AP6 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1065-6AP36 |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TF5411-0AQ0 | SEE 3TF5411-0AV0 UNTIL SEPTEMBER 2001 | AFTER SEPTEMBER 2001, ORDER 3RT1065-6AV36 |
| 3TF5411-0AS0 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1065-6AS36 |
| 3TF5411-0AU1 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1065-6AU36 |
| 3TF5411-0AV0 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1065-6AV36 |
| 3TF5422-0AC2 | AFTER SEPTEMBER 2001, ORDER 3RT1065-6AB36 | |
| 3TF5422-0AF0 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | NO DIRECT REPLACEMENT |
| 3TF5422-0AG1 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1065-6AF36 |
| 3TF5422-0AG2 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1065-6AF36 |
| 3TF5422-0AJ1 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1065-6AF36 |
| 3TF5422-0AK6 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1065-6AF36 |
| 3TF5422-0AK6L | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1065-6AF36 |
| 3TF5422-0AM0 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1065-6AP36 |
| 3TF5422-0AM1 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1065-6AM36 |
| 3TF5422-0AM2 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1065-6AM36 |
| 3TF5422-0AN2 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1065-6APE6 |
| 3TF5422-0AP0 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1065-6AU36 |
| 3TF5422-0AP6 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1065-6AP36 |
| 3TF5422-0AQ0 | SEE 3TF5422-0AV0 UNTIL SEPTEMBER 2001 | AFTER SEPTEMBER 2001, ORDER 3RT1065-6AV36 |
| 3TF5422-0AR0 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1065-6AR36 |
| 3TF5422-0AS0 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1065-6AS36 |
| 3TF5422-0AS2 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1065-6AT36 |
| 3TF5422-0AU1 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1065-6AU36 |
| 3TF5422-0AV0 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1065-6AV36 |
| 3TF5422-0DB4 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1065-6AB36 |
| 3TF5422-0DG4 | SEE 3TF5422-1DG4 UNTIL SEPTEMBER 2001 | AFTER SEPTEMBER 2001, ORDER 3RT1065-6AF36 |
| 3TF5422-0DZ9 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | NO DIRECT REPLACEMENT |
| 3TF5422-1DB4 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1065-6AB36 |
| 3TF5422-1DG4 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1065-6AF36 |
| 3TF5422-1DW4 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1065-6AD36 |
| 3TF5444-0AJ1 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1065-6AF36 + 3RH1921-1FA22 |
| 3TF5444-0AK6 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1065-6AF36 + 3RH1921-1FA22 |
| 3TF5444-0AR1 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1065-6AR36 + 3RH1921-1FA22 |
| 3TF5444-0AV0 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1065-6AV36 + 3RH1921-1FA22 |
| 3TF5511-0AC2 | AFTER SEPTEMBER 2001, ORDER 3RT1066-6AB36 | |
| 3TF5511-0AK6 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1066-6AF36 |
| 3TF5511-0AK6L | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1066-6AF36 |
| 3TF5511-0AM1 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1066-6AM36 |
| 3TF5511-0AM2 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1066-6AM36 |
| 3TF5511-0AP6 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1066-6AP36 |
| 3TF5511-0AQ0 | SEE 3TF5511-0AV0 UNTIL SEPTEMBER 2001 | AFTER SEPTEMBER 2001, ORDER 3RT1066-6AV36 |
| 3TF5511-0AS0 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1066-6AS36 |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TF5511-0AU1 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1066-6AU36 |
| 3TF5511-0AV0 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1066-6AV36 |
| 3TF5522-0AC2 | AFTER SEPTEMBER 2001, ORDER 3RT1066-6AB36 | |
| 3TF5522-0AG1 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1066-6AF36 |
| 3TF5522-0AG2 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1066-6AF36 |
| 3TF5522-0AK6 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1066-6AF36 |
| 3TF5522-0AK6L | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1066-6AF36 |
| 3TF5522-0AM1 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1066-6AM36 |
| 3TF5522-0AM2 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1066-6AM36 |
| 3TF5522-0AP0 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1066-6AU36 |
| 3TF5522-0AP6 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1066-6AP36 |
| 3TF5522-0AQ0 | SEE 3TF5522-0AV0 UNTIL SEPTEMBER 2001 | AFTER SEPTEMBER 2001, ORDER 3RT1066-6AV36 |
| 3TF5522-0AS0 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1066-6AS36 |
| 3TF5522-0AS2 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1066-6AT36 |
| 3TF5522-0AU1 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1066-6AU36 |
| 3TF5522-0AV0 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1066-6AV36 |
| 3TF5544-0AK6 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1066-6AF36 + 3RH1921-1FA22 |
| 3TF5622-0AC2 | AFTER SEPTEMBER 2001, ORDER 3RT1075-6AB36 | |
| 3TF5622-0AC21 | AFTER SEPTEMBER 2001, ORDER 3RT1075-6AB36 | |
| 3TF5622-0AF0 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | NO DIRECT REPLACEMENT |
| 3TF5622-0AG11 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1075-6AF36 |
| 3TF5622-0AG2 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1075-6AF36 |
| 3TF5622-0AG21 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1075-6AF36 |
| 3TF5622-0AJ1 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1075-6AF36 |
| 3TF5622-0AK2 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1075-6AF36 |
| 3TF5622-0AK6 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1075-6AF36 |
| 3TF5622-0AK61 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1075-6AF36 |
| 3TF5622-0AK6L | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1075-6AF36 |
| 3TF5622-0AM1 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1075-6AM36 |
| 3TF5622-0AM11 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1075-6AM36 |
| 3TF5622-0AM2 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1075-6AM36 |
| 3TF5622-0AM21 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1075-6AM36 |
| 3TF5622-0AP0 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1075-6AU36 |
| 3TF5622-0AP6 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1075-6AP36 |
| 3TF5622-0AP61 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1075-6AP36 |
| 3TF5622-0AP61L | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1075-6AP36 |
| 3TF5622-0AQ0 | SEE 3TF5622-0AV0 UNTIL SEPTEMBER 2001 | AFTER SEPTEMBER 2001, ORDER 3RT1075-6AV36 |
| 3TF5622-0AQ01 | SEE 3TF5622-0AV01 UNTIL SEPTEMBER 2001 | AFTER SEPTEMBER 2001, ORDER 3RT1075-6AV36 |
| 3TF5622-0AR0 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1075-6AR36 |
| 3TF5622-0AR01 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1075-6AR36 |
| 3TF5622-0AR1 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1075-6AR36 |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TF5622-0AS0 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1075-6AS36 |
| 3TF5622-0AS01 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1075-6AS36 |
| 3TF5622-0AS2 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1075-6AT36 |
| 3TF5622-0AS21 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1075-6AT36 |
| 3TF5622-0AU1 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1075-6AU36 |
| 3TF5622-0AU11 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1075-6AU36 |
| 3TF5622-0AV0 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1075-6AV36 |
| 3TF5622-0AV01 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1075-6AV36 |
| 3TF5622-1DB4 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1075-6AB36 |
| 3TF5622-1DB41 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1075-6AB36 |
| 3TF5622-1DF4 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1075-6AF36 |
| 3TF5622-1DG4 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1075-6AF36 |
| 3TF5622-1DG41 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1075-6AF36 |
| 3TF5622-1DW4 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1075-6AD36 |
| 3TF5622-1DW41 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1075-6AD36 |
| 3TF5644-0AJ1 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1075-6AF36 + 3RH1921-1FA22 |
| 3TF5644-0AR1 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1075-6AR36 + 3RH1921-1FA22 |
| 3TF5644-0AV0 | SEE 3TF5622-0AV0 UNTIL SEPTEMBER 2001 | AFTER SEPTEMBER 2001, ORDER 3RT1075-6AV36 + 3RH1921-1FA22 |
| 3TF5722-0AC2 | AFTER SEPTEMBER 2001, ORDER 3RT1076-6AB36 | |
| 3TF5722-0AK6 | SEE 3TF5722-0CF7 UNTIL SEPTEMBER 2001 | AFTER SEPTEMBER 2001, ORDER 3RT1076-6AF36 |
| 3TF5722-0AM1 | SEE 3TF5722-0CM7 UNTIL SEPTEMBER 2001 | AFTER SEPTEMBER 2001, ORDER 3RT1076-6AM36 |
| 3TF5722-0AM2 | SEE 3TF5722-0CM7 UNTIL SEPTEMBER 2001 | AFTER SEPTEMBER 2001, ORDER 3RT1076-6AM36 |
| 3TF5722-0AP6 | SEE 3TF5722-0CM7 UNTIL SEPTEMBER 2001 | AFTER SEPTEMBER 2001, ORDER 3RT1076-6AP36 |
| 3TF5722-0AQ0 | SEE 3TF5722-0CQ7 UNTIL SEPTEMBER 2001 | AFTER SEPTEMBER 2001, ORDER 3RT1076-6AV36 |
| 3TF5722-0AS0 | SEE 3TF5722-0CS7 UNTIL SEPTEMBER 2001 | AFTER SEPTEMBER 2001, ORDER 3RT1076-6AS36 |
| 3TF5722-0AS2 | SEE 3TF5722-0CS7 UNTIL SEPTEMBER 2001 | AFTER SEPTEMBER 2001, ORDER 3RT1076-6AT36 |
| 3TF5722-0AU1 | AFTER SEPTEMBER 2001, ORDER 3RT1076-6AU36 | |
| 3TF5722-0CF7 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1076-6AF36 |
| 3TF5722-0CF7L | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1076-6AF36 |
| 3TF5722-0CM7 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1076-6AP36 |
| 3TF5722-0CQ7 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1076-6AV36 |
| 3TF5722-0CS7 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1076-6AT36 |
| 3TF5744-0AR1 | SEE 3TF5744-0CQ7 UNTIL SEPTEMBER 2001 | AFTER SEPTEMBER 2001, ORDER 3RT1076-6AR36 + 3RH1921-1FA22 |
| 3TF5744-0CQ7 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RT1076-6AV36 + 3RH1921-1FA22 |
| 3TF6833-1DG4 | NO DIRECT REPLACEMENT | |
| 3TF6844-0CF7 | PRODUCT STILL AVAILABLE | |
| 3TF6844-0CF71 | PRODUCT STILL AVAILABLE | |
| 3TF6844-0CM7 | PRODUCT STILL AVAILABLE | |
| 3TF6844-0CM71 | PRODUCT STILL AVAILABLE | |
| 3TF6844-0CQ7 | PRODUCT STILL AVAILABLE | |
| 3TF6844-0CQ71 | PRODUCT STILL AVAILABLE | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TF6844-0CS7 | NO DIRECT REPLACEMENT | |
| 3TF6844-0CS71 | NO DIRECT REPLACEMENT | |
| 3TF6933-1DB4 | PRODUCT STILL AVAILABLE | |
| 3TF6933-1DF4 | PRODUCT STILL AVAILABLE | |
| 3TF6933-8DB4 | PRODUCT STILL AVAILABLE | |
| 3TF6944-0CF7 | PRODUCT STILL AVAILABLE | |
| 3TF6944-0CM7 | PRODUCT STILL AVAILABLE | |
| 3TF6944-0CQ7 | PRODUCT STILL AVAILABLE | |
| 3TF6944-0CS7 | PRODUCT STILL AVAILABLE | |
| 3TF8131-0AC1 | NO DIRECT REPLACEMENT | |
| 3TF8131-0AK1 | PRODUCT STILL AVAILABLE | |
| 3TF8131-0AK6 | SEE 3TF8131-0AK1 | |
| 3TF8131-0AP1 | PRODUCT STILL AVAILABLE | |
| 3TF8133-0AC1 | PRODUCT STILL AVAILABLE | |
| 3TF8133-0AG0 | PRODUCT STILL AVAILABLE | |
| 3TF8133-0AK1 | PRODUCT STILL AVAILABLE | |
| 3TF8133-0AK6 | SEE 3TF8131-0AK1 | |
| 3TF8232-0AC1 | PRODUCT STILL AVAILABLE | |
| 3TF8232-0AJ1 | PRODUCT STILL AVAILABLE | |
| 3TF8232-0AK6 | PRODUCT STILL AVAILABLE | |
| 3TF8232-0AM0 | PRODUCT STILL AVAILABLE | |
| 3TF8232-0AM2 | PRODUCT STILL AVAILABLE | |
| 3TF8232-0AP0 | PRODUCT STILL AVAILABLE | |
| 3TF8232-0AP6 | PRODUCT STILL AVAILABLE | |
| 3TF8332-0AC1 | NO DIRECT REPLACEMENT | |
| 3TF8332-0AG2 | PRODUCT STILL AVAILABLE | |
| 3TF8332-0AK6 | PRODUCT STILL AVAILABLE | |
| 3TF8332-0AP6 | PRODUCT STILL AVAILABLE | |
| 3TF8631-0AC1 | PRODUCT STILL AVAILABLE | |
| 3TF8631-0AJ1 | PRODUCT STILL AVAILABLE | |
| 3TF8631-0AK1 | PRODUCT STILL AVAILABLE | |
| 3TF8631-0AK6 | PRODUCT STILL AVAILABLE | |
| 3TF8631-0AN1 | PRODUCT STILL AVAILABLE | |
| 3TF8631-0AP1 | PRODUCT STILL AVAILABLE | |
| 3TF8633-0AC1 | NO DIRECT REPLACEMENT | |
| 3TF8633-0AJ1 | PRODUCT STILL AVAILABLE | |
| 3TF8633-0AK1 | PRODUCT STILL AVAILABLE | |
| 3TF8633-0AK6 | PRODUCT STILL AVAILABLE | |
| 3TF8633-0AN1 | PRODUCT STILL AVAILABLE | |
| 3TF8633-0AN2 | SEE 3TF8633-0AN1 | |
| 3TF8633-0AP1 | PRODUCT STILL AVAILABLE | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TF8683-0AK1 | PRODUCT STILL AVAILABLE | |
| 3TH2022-0AC1 | 3RH1122-1AB00 | |
| 3TH2022-0AC2 | 3RH1122-1AB00 | |
| 3TH2022-0AD0 | 3RH1122-1AD00 | |
| 3TH2022-0AF0 | 3RH1122-1AK60 | |
| 3TH2022-0AG1 | 3RH1122-1AK60 | |
| 3TH2022-0AG2 | 3RH1122-1AK60 | |
| 3TH2022-0AJ1 | 3RH1122-1AK60 | |
| 3TH2022-0AJ2 | 3RH1122-1AK60 | |
| 3TH2022-0AK1 | 3RH1122-1AK60 | |
| 3TH2022-0AK6 | 3RH1122-1AK60 | |
| 3TH2022-0AK6-Z | NO DIRECT REPLACEMENT | |
| 3TH2022-0AM0 | 3RH1122-1AM20 | |
| 3TH2022-0AM2 | 3RH1122-1AM20 | |
| 3TH2022-0AN1 | 3RH1122-1AP60 | |
| 3TH2022-0AP0 | 3RH1122-1AP60 | |
| 3TH2022-0AP6 | 3RH1122-1AP60 | |
| 3TH2022-0AQ0 | 3RH1122-1AV00 | |
| 3TH2022-0AS0 | 3RH1122-1AT60 | |
| 3TH2022-0AU1 | 3RH1122-1AU60 | |
| 3TH2022-0AV0 | 3RH1122-1AV00 | |
| 3TH2022-0BA4 | 3RH1122-1BA40 | |
| 3TH2022-0BB4 | 3RH1122-1BB40 | |
| 3TH2022-0BB4-Z | NO DIRECT REPLACEMENT | |
| 3TH2022-0BC4 | 3RH1122-1BC40 | |
| 3TH2022-0BE4 | 3RH1122-1BE40 | |
| 3TH2022-0BE8 | NO DIRECT REPLACEMENT | |
| 3TH2022-0BF4 | 3RH1122-1BF40 | |
| 3TH2022-0BG4 | 3RH1122-1BG40 | |
| 3TH2022-0BM4 | 3RH1122-1BM40 | |
| 3TH2022-0BN4 | NO DIRECT REPLACEMENT | |
| 3TH2022-0BQ4 | 3RH1122-1BP40 | |
| 3TH2022-0BW4 | 3RH1122-1BW40 | |
| 3TH2022-0DB4 | 3RH1122-1BB40 + SURGE | |
| 3TH2022-0FB4 | 3RH1122-1BB40 + SURGE | |
| 3TH2022-0JB4 | 3RH1122-1BB40 + SURGE | |
| 3TH2022-0LB4 | 3RH1122-1BB40 + SURGE | |
| 3TH2022-0TB4 | 3RH1122-1JB40 | |
| 3TH2022-1AC2 | 3RH1122-1AB00 | |
| 3TH2022-1AD2 | 3RH1122-1AD00 | |
| 3TH2022-1AG1 | 3RH1122-1AK60 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TH2022-1AJ2 | 3RH1122-1AK60 | |
| 3TH2022-1AK6 | 3RH1122-1AK60 | |
| 3TH2022-1AM2 | 3RH1122-1AM20 | |
| 3TH2022-1AP6 | 3RH1122-1AP60 | |
| 3TH2022-1AQ0 | 3RH1122-1AV00 | |
| 3TH2022-1AS0 | 3RH1122-1AT60 | |
| 3TH2022-1BA4 | 3RH1122-1BA40 | |
| 3TH2022-1BB4 | 3RH1122-1BB40 | |
| 3TH2022-1BG4 | 3RH1122-1BG40 | |
| 3TH2022-1BQ4 | 3RH1122-1BP40 | |
| 3TH2022-1BW4 | 3RH1122-1BW40 | |
| 3TH2022-3AC2 | 3RH1122-1AB00 | |
| 3TH2022-3AJ2 | 3RH1122-1AK60 | |
| 3TH2022-3AK6 | 3RH1122-1AK60 | |
| 3TH2022-3AM2 | 3RH1122-1AM20 | |
| 3TH2022-3AP6 | 3RH1122-1AP60 | |
| 3TH2022-3AQ0 | 3RH1122-1AV00 | |
| 3TH2022-3AS0 | 3RH1122-1AT60 | |
| 3TH2022-3BA4 | 3RH1122-1BA40 | |
| 3TH2022-3BB4 | 3RH1122-1BB40 | |
| 3TH2022-3BG4 | 3RH1122-1BG40 | |
| 3TH2022-3BQ4 | NO DIRECT REPLACEMENT | |
| 3TH2022-3BW4 | 3RH1122-1BW40 | |
| 3TH2022-6AJ2 | 3RH1122-1AK60 | |
| 3TH2022-6AJ2-Z | NO DIRECT REPLACEMENT | |
| 3TH2022-6JB4 | 3RH1122-1BB40 + SURGE | |
| 3TH2022-7AC2 | 3RH1122-1AB00 | |
| 3TH2022-7AG1 | 3RH1122-1AK60 | |
| 3TH2022-7AJ2 | 3RH1122-1AK60 | |
| 3TH2022-7AM0 | 3RH1122-1AM20 | |
| 3TH2022-7AP0 | 3RH1122-1AP60 | |
| 3TH2022-7BB4 | 3RH1122-1BB40 | |
| 3TH2022-7BG4 | 3RH1122-1BG40 | |
| 3TH2022-7BN4 | NO DIRECT REPLACEMENT | |
| 3TH2022-7BW4 | 3RH1122-1BW40 | |
| 3TH2022-7JB4 | 3RH1122-1BB40 + SURGE | |
| 3TH2031-0AB0 | 3RH1131-1AB00 | |
| 3TH2031-0AC1 | 3RH1131-1AB00 | |
| 3TH2031-0AC2 | 3RH1131-1AB00 | |
| 3TH2031-0AD0 | 3RH1131-1AD00 | |
| 3TH2031-0AD2 | 3RH1131-1AD00 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TH2031-0AF0 | 3RH1131-1AK60 | |
| 3TH2031-0AG1 | 3RH1131-1AK60 | |
| 3TH2031-0AG2 | 3RH1131-1AK60 | |
| 3TH2031-0AJ1 | 3RH1131-1AK60 | |
| 3TH2031-0AJ2 | 3RH1131-1AK60 | |
| 3TH2031-0AK6 | 3RH1131-1AK60 | |
| 3TH2031-0AK6-Z | NO DIRECT REPLACEMENT | |
| 3TH2031-0AM0 | 3RH1131-1AM20 | |
| 3TH2031-0AM2 | 3RH1131-1AM20 | |
| 3TH2031-0AN1 | 3RH1131-1AP60 | |
| 3TH2031-0AN2 | 3RH1131-1AP60 | |
| 3TH2031-0AP0 | 3RH1131-1AP60 | |
| 3TH2031-0AP6 | 3RH1131-1AP60 | |
| 3TH2031-0AQ0 | 3RH1131-1AV00 | |
| 3TH2031-0AS0 | 3RH1131-1AT60 | |
| 3TH2031-0AU1 | 3RH1131-1AU60 | |
| 3TH2031-0AV0 | 3RH1131-1AV00 | |
| 3TH2031-0BA4 | 3RH1131-1BA40 | |
| 3TH2031-0BB4 | 3RH1131-1BB40 | |
| 3TH2031-0BB4-Z | NO DIRECT REPLACEMENT | |
| 3TH2031-0BC4 | 3RH1131-1BC40 | |
| 3TH2031-0BE4 | 3RH1131-1BE40 | |
| 3TH2031-0BE8 | NO DIRECT REPLACEMENT | |
| 3TH2031-0BF4 | 3RH1131-1BF40 | |
| 3TH2031-0BG4 | 3RH1131-1BG40 | |
| 3TH2031-0BM4 | 3RH1131-1BM40 | |
| 3TH2031-0BN4 | NO DIRECT REPLACEMENT | |
| 3TH2031-0BQ4 | 3RH1131-1BP40 | |
| 3TH2031-0BW4 | 3RH1131-1BW40 | |
| 3TH2031-0DB4 | 3RH1131-1BB40 + SURGE | |
| 3TH2031-0FB4 | 3RH1131-1BB40 + SURGE | |
| 3TH2031-0HX4 | 3RH1131-1BB40 + SURGE | |
| 3TH2031-0JB4 | 3RH1131-1BB40 + SURGE | |
| 3TH2031-0LB4 | 3RH1131-1BB40 + SURGE | |
| 3TH2031-0MB4 | 3RH1131-1KB40 | |
| 3TH2031-1AC2 | 3RH1131-1AB00 | |
| 3TH2031-1AG1 | 3RH1131-1AK60 | |
| 3TH2031-1AJ2 | 3RH1131-1AK60 | |
| 3TH2031-1AK6 | 3RH1131-1AK60 | |
| 3TH2031-1AM2 | 3RH1131-1AM20 | |
| 3TH2031-1AN2 | 3RH1131-1AP60 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TH2031-1AP6 | 3RH1131-1AP60 | |
| 3TH2031-1AQ0 | 3RH1131-1AV00 | |
| 3TH2031-1AS0 | 3RH1131-1AT60 | |
| 3TH2031-1BA4 | 3RH1131-1BA40 | |
| 3TH2031-1BB4 | 3RH1131-1BB40 | |
| 3TH2031-1BG4 | 3RH1131-1BG40 | |
| 3TH2031-1BQ4 | 3RH1131-1BP40 | |
| 3TH2031-1BW4 | 3RH1131-1BW40 | |
| 3TH2031-3AC2 | 3RH1131-1AB00 | |
| 3TH2031-3AJ2 | 3RH1131-1AK60 | |
| 3TH2031-3AK6 | 3RH1131-1AK60 | |
| 3TH2031-3AM2 | 3RH1131-1AM20 | |
| 3TH2031-3AP6 | 3RH1131-1AP60 | |
| 3TH2031-3AQ0 | 3RH1131-1AV00 | |
| 3TH2031-3AS0 | 3RH1131-1AT60 | |
| 3TH2031-3BA4 | 3RH1131-1BA40 | |
| 3TH2031-3BB4 | 3RH1131-1BB40 | |
| 3TH2031-3BG4 | 3RH1131-1BG40 | |
| 3TH2031-3BQ4 | 3RH1131-1BP40 | |
| 3TH2031-3BW4 | 3RH1131-1BW40 | |
| 3TH2031-6AC2 | 3RH1131-1AB00 | |
| 3TH2031-6AJ2 | 3RH1131-1AK60 | |
| 3TH2031-6BF4 | 3RH1131-1BF40 | |
| 3TH2031-6JB4 | 3RH1131-1BB40 + SURGE | |
| 3TH2031-7AF0 | 3RH1131-1AK60 | |
| 3TH2031-7AF0-Z | NO DIRECT REPLACEMENT | |
| 3TH2031-7AG1 | 3RH1131-1AK60 | |
| 3TH2031-7AG1-Z | NO DIRECT REPLACEMENT | |
| 3TH2031-7AJ2 | 3RH1131-1AK60 | |
| 3TH2031-7BB4 | 3RH1131-1BB40 | |
| 3TH2031-7BD4 | 3RH1131-1BD40 | |
| 3TH2031-7BF4 | 3RH1131-1BF40 | |
| 3TH2031-7DB4 | 3RH1131-1BB40 + SURGE | |
| 3TH2040-0AC1 | 3RH1140-1AB00 | |
| 3TH2040-0AC2 | 3RH1140-1AB00 | |
| 3TH2040-0AD2 | 3RH1140-1AD00 | |
| 3TH2040-0AF0 | 3RH1140-1AK60 | |
| 3TH2040-0AG1 | 3RH1140-1AK60 | |
| 3TH2040-0AG2 | 3RH1140-1AK60 | |
| 3TH2040-0AJ2 | 3RH1140-1AK60 | |
| 3TH2040-0AK6 | 3RH1140-1AK60 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TH2040-0AK6-Z | 3RH1140-1AK60 | |
| 3TH2040-0AM0 | 3RH1140-1AM20 | |
| 3TH2040-0AM1 | 3RH1140-1AM20 | |
| 3TH2040-0AM2 | 3RH1140-1AM20 | |
| 3TH2040-0AN1 | 3RH1140-1AP60 | |
| 3TH2040-0AP0 | 3RH1140-1AP60 | |
| 3TH2040-0AP6 | 3RH1140-1AP60 | |
| 3TH2040-0AQ0 | 3RH1140-1AV00 | |
| 3TH2040-0AS0 | 3RH1140-1AT60 | |
| 3TH2040-0AU1 | 3RH1140-1AU60 | |
| 3TH2040-0AV0 | 3RH1140-1AV00 | |
| 3TH2040-0BA4 | 3RH1140-1BA40 | |
| 3TH2040-0BB0 | 3RH1140-1BB00 | |
| 3TH2040-0BB4 | 3RH1140-1BB40 | |
| 3TH2040-0BB4-Z | NO DIRECT REPLACEMENT | |
| 3TH2040-0BE8 | NO DIRECT REPLACEMENT | |
| 3TH2040-0BG4 | 3RH1140-1BG40 | |
| 3TH2040-0BG4-Z | NO DIRECT REPLACEMENT | |
| 3TH2040-0BN4 | NO DIRECT REPLACEMENT | |
| 3TH2040-0BQ4 | 3RH1140-1BP40 | |
| 3TH2040-0BV4 | NO DIRECT REPLACEMENT | |
| 3TH2040-0BV4-Z | NO DIRECT REPLACEMENT | |
| 3TH2040-0BW4 | 3RH1140-1BW40 | |
| 3TH2040-0DB4 | 3RH1140-1BB40 + SURGE | |
| 3TH2040-0FB4 | 3RH1140-1BB40 + SURGE | |
| 3TH2040-0JB4 | 3RH1140-1BB40 + SURGE | |
| 3TH2040-0LB4 | 3RH1140-1BB40 + SURGE | |
| 3TH2040-0MB4 | 3RH1140-1KB40 | |
| 3TH2040-0TB4 | 3RH1140-1JB40 | |
| 3TH2040-1AC2 | 3RH1140-1AB00 | |
| 3TH2040-1AG1 | 3RH1140-1AK60 | |
| 3TH2040-1AJ2 | 3RH1140-1AK60 | |
| 3TH2040-1AK6 | 3RH1140-1AK60 | |
| 3TH2040-1AM2 | 3RH1140-1AM20 | |
| 3TH2040-1AP6 | 3RH1140-1AP60 | |
| 3TH2040-1AQ0 | 3RH1140-1AV00 | |
| 3TH2040-1AS0 | 3RH1140-1AT60 | |
| 3TH2040-1BA4 | 3RH1140-1BA40 | |
| 3TH2040-1BB4 | 3RH1140-1BB40 | |
| 3TH2040-1BG4 | 3RH1140-1BG40 | |
| 3TH2040-1BQ4 | 3RH1140-1BP40 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TH2040-1BW4 | 3RH1140-1BW40 | |
| 3TH2040-3AC2 | 3RH1140-1AB00 | |
| 3TH2040-3AJ2 | 3RH1140-1AK60 | |
| 3TH2040-3AK6 | 3RH1140-1AK60 | |
| 3TH2040-3AM2 | 3RH1140-1AM20 | |
| 3TH2040-3AP6 | 3RH1140-1AP60 | |
| 3TH2040-3AQ0 | 3RH1140-1AV00 | |
| 3TH2040-3AS0 | 3RH1140-1AT60 | |
| 3TH2040-3BA4 | 3RH1140-1BA40 | |
| 3TH2040-3BB4 | 3RH1140-1BB40 | |
| 3TH2040-3BG4 | 3RH1140-1BG40 | |
| 3TH2040-3BQ4 | 3RH1140-1BP40 | |
| 3TH2040-3BW4 | 3RH1140-1BW40 | |
| 3TH2040-6AJ2 | 3RH1140-1AK60 | |
| 3TH2040-7BF4 | 3RH1140-1BF40 | |
| 3TH2144-0AB0 | 3RH1122-1AB00 + 3RH1911-1FA22 | |
| 3TH2144-0AC2 | 3RH1122-1AB00 + 3RH1911-1FA22 | |
| 3TH2144-0AJ2 | 3RH1122-1AK60 + 3RH1911-1FA22 | |
| 3TH2144-0AK6 | 3RH1122-1AK60 + 3RH1911-1FA22 | |
| 3TH2144-0AM2 | 3RH1122-1AM20 + 3RH1911-1FA22 | |
| 3TH2144-0AP6 | 3RH1122-1AP60 + 3RH1911-1FA22 | |
| 3TH2144-0AQ0 | 3RH1122-1AV00 + 3RH1911-1FA22 | |
| 3TH2144-0AS0 | 3RH1122-1AT60 + 3RH1911-1FA22 | |
| 3TH2144-0AU1 | 3RH1122-1AU60 + 3RH1911-1FA22 | |
| 3TH2144-0AV0 | 3RH1122-1AV00 + 3RH1911-1FA22 | |
| 3TH2144-0BA4 | 3RH1122-1BA40 + 3RH1911-1FA22 | |
| 3TH2144-0BB4 | 3RH1122-1BB40 + 3RH1911-1FA22 | |
| 3TH2144-0BG4 | 3RH1122-1BG40 + 3RH1911-1FA22 | |
| 3TH2144-0BQ4 | 3RH1122-1BP40 + 3RH1911-1FA22 | |
| 3TH2144-0BW4 | 3RH1122-1BW40 + 3RH1911-1FA22 | |
| 3TH2153-0AC2 | 3RH1131-1AB00 + 3RH1911-1FA22 | |
| 3TH2153-0AJ2 | 3RH1131-1AK60 + 3RH1911-1FA22 | |
| 3TH2153-0AK6 | 3RH1131-1AK60 + 3RH1911-1FA22 | |
| 3TH2153-0AM2 | 3RH1131-1AM20 + 3RH1911-1FA22 | |
| 3TH2153-0AP6 | 3RH1131-1AP60 + 3RH1911-1FA22 | |
| 3TH2153-0AQ0 | 3RH1131-1AV00 + 3RH1911-1FA22 | |
| 3TH2153-0AS0 | 3RH1131-1AT60 + 3RH1911-1FA22 | |
| 3TH2153-0AU1 | 3RH1131-1AU60 + 3RH1911-1FA22 | |
| 3TH2153-0BA4 | 3RH1131-1BA40 + 3RH1911-1FA22 | |
| 3TH2153-0BB4 | 3RH1131-1BB40 + 3RH1911-1FA22 | |
| 3TH2153-0BG4 | 3RH1131-1BG40 + 3RH1911-1FA22 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TH2153-0BQ4 | 3RH1131-1BP40 + 3RH1911-1FA22 | |
| 3TH2153-0BW4 | 3RH1131-1BW40 + 3RH1911-1FA22 | |
| 3TH2162-0AC2 | 3RH1140-1AB00 + 3RH1911-1FA22 | |
| 3TH2162-0AD0 | 3RH1140-1AD00 + 3RH1911-1FA22 | |
| 3TH2162-0AJ2 | 3RH1140-1AK60 + 3RH1911-1FA22 | |
| 3TH2162-0AK6 | 3RH1140-1AK60 + 3RH1911-1FA22 | |
| 3TH2162-0AM2 | 3RH1140-1AM20 + 3RH1911-1FA22 | |
| 3TH2162-0AP6 | 3RH1140-1AP60 + 3RH1911-1FA22 | |
| 3TH2162-0AQ0 | 3RH1140-1AV00 + 3RH1911-1FA22 | |
| 3TH2162-0AS0 | 3RH1140-1AT60 + 3RH1911-1FA22 | |
| 3TH2162-0AU1 | 3RH1140-1AU60 + 3RH1911-1FA22 | |
| 3TH2162-0BA4 | 3RH1140-1BA40 + 3RH1911-1FA22 | |
| 3TH2162-0BB4 | 3RH1140-1BB40 + 3RH1911-1FA22 | |
| 3TH2162-0BG4 | 3RH1140-1BG40 + 3RH1911-1FA22 | |
| 3TH2162-0BQ4 | 3RH1140-1BP40 + 3RH1911-1FA22 | |
| 3TH2162-0BW4 | 3RH1140-1BW40 + 3RH1911-1FA22 | |
| 3TH2171-0AC2 | 3RH1140-1AB00 + 3RH1911-1FA31 | |
| 3TH2171-0AJ2 | 3RH1140-1AK60 + 3RH1911-1FA31 | |
| 3TH2171-0AK6 | 3RH1140-1AK60 + 3RH1911-1FA31 | |
| 3TH2171-0AM2 | 3RH1140-1AM20 + 3RH1911-1FA31 | |
| 3TH2171-0AP6 | 3RH1140-1AP60 + 3RH1911-1FA31 | |
| 3TH2171-0AQ0 | 3RH1140-1AV00 + 3RH1911-1FA31 | |
| 3TH2171-0AS0 | 3RH1140-1AT60 + 3RH1911-1FA31 | |
| 3TH2171-0AU1 | 3RH1140-1AU60 + 3RH1911-1FA31 | |
| 3TH2171-0BA4 | 3RH1140-1BA40 + 3RH1911-1FA31 | |
| 3TH2171-0BB4 | 3RH1140-1BB40 + 3RH1911-1FA31 | |
| 3TH2171-0BG4 | 3RH1140-1BG40 + 3RH1911-1FA31 | |
| 3TH2171-0BQ4 | 3RH1140-1BP40 + 3RH1911-1FA31 | |
| 3TH2171-0BW4 | 3RH1140-1BW40 + 3RH1911-1FA31 | |
| 3TH2180-0AC2 | 3RH1140-1AB00 + 3RH1911-1FA40 | |
| 3TH2180-0AJ2 | 3RH1140-1AK60 + 3RH1911-1FA40 | |
| 3TH2180-0AK6 | 3RH1140-1AK60 + 3RH1911-1FA40 | |
| 3TH2180-0AM2 | 3RH1140-1AM20 + 3RH1911-1FA40 | |
| 3TH2180-0AP6 | 3RH1140-1AP60 + 3RH1911-1FA40 | |
| 3TH2180-0AQ0 | 3RH1140-1AV00 + 3RH1911-1FA40 | |
| 3TH2180-0AS0 | 3RH1140-1AT60 + 3RH1911-1FA40 | |
| 3TH2180-0AU1 | 3RH1140-1AU60 + 3RH1911-1FA40 | |
| 3TH2180-0BA4 | 3RH1140-1BA40 + 3RH1911-1FA40 | |
| 3TH2180-0BB4 | 3RH1140-1BB40 + 3RH1911-1FA40 | |
| 3TH2180-0BG4 | 3RH1140-1BG40 + 3RH1911-1FA40 | |
| 3TH2180-0BQ4 | 3RH1140-1BP40 + 3RH1911-1FA40 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TH2180-0BW4 | 3RH1140-1BW40 + 3RH1911-1FA40 | |
| 3TH2244-0AC2 | 3RH1122-1AB00 + 3RH1911-1FA22 | |
| 3TH2244-0AG2 | 3RH1122-1AK60 + 3RH1911-1FA22 | |
| 3TH2244-0AJ2 | 3RH1122-1AK60 + 3RH1911-1FA22 | |
| 3TH2244-0AK6 | 3RH1122-1AK60 + 3RH1911-1FA22 | |
| 3TH2244-0AM2 | 3RH1122-1AM20 + 3RH1911-1FA22 | |
| 3TH2244-0AN2 | 3RH1122-1AP60 + 3RH1911-1FA22 | |
| 3TH2244-0AP0 | 3RH1122-1AP60 + 3RH1911-1FA22 | |
| 3TH2244-0AP6 | 3RH1122-1AP60 + 3RH1911-1FA22 | |
| 3TH22440AQ0 | NO DIRECT REPLACEMENT | |
| 3TH2244-0AQ0 | 3RH1122-1AV00 + 3RH1911-1FA22 | |
| 3TH2244-0AS0 | 3RH1122-1AT60 + 3RH1911-1FA22 | |
| 3TH2244-0AU1 | 3RH1122-1AU60 + 3RH1911-1FA22 | |
| 3TH2244-0AV0 | 3RH1122-1AV00 + 3RH1911-1FA22 | |
| 3TH2244-0BA4 | 3RH1122-1BA40 + 3RH1911-1FA22 | |
| 3TH2244-0BB4 | 3RH1122-1BB40 + 3RH1911-1FA22 | |
| 3TH2244-0BG4 | 3RH1122-1BG40 + 3RH1911-1FA22 | |
| 3TH2244-0BQ4 | 3RH1122-1BP40 + 3RH1911-1FA22 | |
| 3TH2244-0BW4 | 3RH1122-1BW40 + 3RH1911-1FA22 | |
| 3TH2253-0AC2 | 3RH1131-1AB00 + 3RH1911-1FA22 | |
| 3TH2253-0AG1 | 3RH1131-1AK60 + 3RH1911-1FA22 | |
| 3TH2253-0AJ2 | 3RH1131-1AK60 + 3RH1911-1FA22 | |
| 3TH2253-0AK6 | 3RH1131-1AK60 + 3RH1911-1FA22 | |
| 3TH2253-0AM2 | 3RH1131-1AM20 + 3RH1911-1FA22 | |
| 3TH2253-0AP6 | 3RH1131-1AP60 + 3RH1911-1FA22 | |
| 3TH2253-0AQ0 | 3RH1131-1AV00 + 3RH1911-1FA22 | |
| 3TH2253-0AS0 | 3RH1131-1AT60 + 3RH1911-1FA22 | |
| 3TH2253-0AU1 | 3RH1131-1AU60 + 3RH1911-1FA22 | |
| 3TH2253-0BA4 | 3RH1131-1BA40 + 3RH1911-1FA22 | |
| 3TH2253-0BB4 | 3RH1131-1BB40 + 3RH1911-1FA22 | |
| 3TH2253-0BC4 | 3RH1131-1BC40 + 3RH1911-1FA22 | |
| 3TH2253-0BG4 | 3RH1131-1BG40 + 3RH1911-1FA22 | |
| 3TH2253-0BQ4 | 3RH1131-1BP40 + 3RH1911-1FA22 | |
| 3TH2253-0BW4 | 3RH1131-1BW40 + 3RH1911-1FA22 | |
| 3TH2262-0AC2 | 3RH1140-1AB00 + 3RH1911-1FA22 | |
| 3TH2262-0AD2 | 3RH1140-1AD00 + 3RH1911-1FA22 | |
| 3TH2262-0AG2 | 3RH1140-1AK60 + 3RH1911-1FA22 | |
| 3TH2262-0AJ2 | 3RH1140-1AK60 + 3RH1911-1FA22 | |
| 3TH2262-0AK6 | 3RH1140-1AK60 + 3RH1911-1FA22 | |
| 3TH2262-0AM2 | 3RH1140-1AM20 + 3RH1911-1FA22 | |
| 3TH2262-0AN2 | 3RH1140-1AP60 + 3RH1911-1FA22 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TH2262-0AP6 | 3RH1140-1AP60 + 3RH1911-1FA22 | |
| 3TH2262-0AQ0 | 3RH1140-1AV00 + 3RH1911-1FA22 | |
| 3TH2262-0AS0 | 3RH1140-1AT60 + 3RH1911-1FA22 | |
| 3TH2262-0AU1 | 3RH1140-1AU60 + 3RH1911-1FA22 | |
| 3TH2262-0BA4 | 3RH1140-1BA40 + 3RH1911-1FA22 | |
| 3TH2262-0BB4 | 3RH1140-1BB40 + 3RH1911-1FA22 | |
| 3TH2262-0BG4 | 3RH1140-1BG40 + 3RH1911-1FA22 | |
| 3TH2262-0BQ4 | 3RH1140-1BP40 + 3RH1911-1FA22 | |
| 3TH2262-0BW4 | 3RH1140-1BW40 + 3RH1911-1FA22 | |
| 3TH2271-0AC2 | 3RH1140-1AB00 + 3RH1911-1FA31 | |
| 3TH2271-0AJ2 | 3RH1140-1AK60 + 3RH1911-1FA31 | |
| 3TH2271-0AK6 | 3RH1140-1AK60 + 3RH1911-1FA31 | |
| 3TH2271-0AM2 | 3RH1140-1AM20 + 3RH1911-1FA31 | |
| 3TH2271-0AP6 | 3RH1140-1AP60 + 3RH1911-1FA31 | |
| 3TH2271-0AQ0 | 3RH1140-1AV00 + 3RH1911-1FA31 | |
| 3TH2271-0AS0 | 3RH1140-1AT60 + 3RH1911-1FA31 | |
| 3TH2271-0AU1 | 3RH1140-1AU60 + 3RH1911-1FA31 | |
| 3TH2271-0BA4 | 3RH1140-1BA40 + 3RH1911-1FA31 | |
| 3TH2271-0BB4 | 3RH1140-1BB40 + 3RH1911-1FA31 | |
| 3TH2271-0BG4 | 3RH1140-1BG40 + 3RH1911-1FA31 | |
| 3TH2271-0BQ4 | 3RH1140-1BP40 + 3RH1911-1FA31 | |
| 3TH2271-0BW4 | 3RH1140-1BW40 + 3RH1911-1FA31 | |
| 3TH2280-0AC2 | 3RH1140-1AB00 + 3RH1911-1FA40 | |
| 3TH2280-0AJ2 | 3RH1140-1AK60 + 3RH1911-1FA40 | |
| 3TH2280-0AK6 | 3RH1140-1AK60 + 3RH1911-1FA40 | |
| 3TH2280-0AM2 | 3RH1140-1AM20 + 3RH1911-1FA40 | |
| 3TH2280-0AP6 | 3RH1140-1AP60 + 3RH1911-1FA40 | |
| 3TH2280-0AQ0 | 3RH1140-1AV00 + 3RH1911-1FA40 | |
| 3TH2280-0AS0 | 3RH1140-1AT60 + 3RH1911-1FA40 | |
| 3TH2280-0AU1 | 3RH1140-1AU60 + 3RH1911-1FA40 | |
| 3TH2280-0BA4 | 3RH1140-1BA40 + 3RH1911-1FA40 | |
| 3TH2280-0BB4 | 3RH1140-1BB40 + 3RH1911-1FA40 | |
| 3TH2280-0BG4 | 3RH1140-1BG40 + 3RH1911-1FA40 | |
| 3TH2280-0BQ4 | 3RH1140-1BP40 + 3RH1911-1FA40 | |
| 3TH2280-0BW4 | 3RH1140-1BW40 + 3RH1911-1FA40 | |
| 3TH2722-0AC2 | 3RH1422-1AB00 | |
| 3TH2722-0AJ2 | 3RH1422-1AK60 | |
| 3TH2722-0AK6 | 3RH1422-1AK60 | |
| 3TH2722-0AM2 | 3RH1422-1AM20 | |
| 3TH2722-0AP2 | 3RH1422-1AP60 | |
| 3TH2722-0AP6 | 3RH1422-1AP60 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TH2722-0AQ0 | 3RH1422-1AV00 | |
| 3TH2722-0AS0 | 3RH1422-1AT60 | |
| 3TH2722-0AU1 | 3RH1422-1AU60 | |
| 3TH2722-0BA4 | 3RH1422-1BA40 | |
| 3TH2722-0BB4 | 3RH1422-1BB40 | |
| 3TH2722-0BG4 | 3RH1422-1BG40 | |
| 3TH2722-0BQ4 | 3RH1422-1BP40 | |
| 3TH2722-0BW4 | 3RH1422-1BW40 | |
| 3TH2731-0AC2 | 3RH1431-1AB00 | |
| 3TH2731-0AJ2 | 3RH1431-1AK60 | |
| 3TH2731-0AK6 | 3RH1431-1AK60 | |
| 3TH2731-0AM2 | 3RH1431-1AM20 | |
| 3TH2731-0AP6 | 3RH1431-1AP60 | |
| 3TH2731-0AQ0 | 3RH1431-1AV00 | |
| 3TH2731-0AS0 | 3RH1431-1AT60 | |
| 3TH2731-0AU1 | 3RH1431-1AU60 | |
| 3TH2731-0BA4 | 3RH1431-1BA40 | |
| 3TH2731-0BB4 | 3RH1431-1BB40 | |
| 3TH2731-0BG4 | 3RH1431-1BG40 | |
| 3TH2731-0BQ4 | 3RH1431-1BP40 | |
| 3TH2731-0BW4 | 3RH1431-1BW40 | |
| 3TH2740-0AC2 | 3RH1440-1AB00 | |
| 3TH2740-0AJ2 | 3RH1440-1AK60 | |
| 3TH2740-0AK6 | 3RH1440-1AK60 | |
| 3TH2740-0AM2 | 3RH1440-1AM20 | |
| 3TH2740-0AP6 | 3RH1440-1AP60 | |
| 3TH2740-0AQ0 | 3RH1440-1AV00 | |
| 3TH2740-0AS0 | 3RH1440-1AT60 | |
| 3TH2740-0AU1 | 3RH1440-1AU60 | |
| 3TH2740-0BA4 | 3RH1440-1BA40 | |
| 3TH2740-0BB4 | 3RH1440-1BB40 | |
| 3TH2740-0BG4 | 3RH1440-1BG40 | |
| 3TH2740-0BQ4 | 3RH1440-1BP40 | |
| 3TH2740-0BW4 | 3RH1440-1BW40 | |
| 3TH3022-0AC1 | 3RH1122-1AB00 | |
| 3TH3022-0AC2 | 3RH1122-1AB00 | |
| 3TH3022-0AJ2 | 3RH1122-1AK60 | |
| 3TH3022-0AK6 | 3RH1122-1AK60 | |
| 3TH3022-0AM1 | 3RH1122-1AM20 | |
| 3TH3022-0AM2 | 3RH1122-1AM20 | |
| 3TH3022-0AP0 | 3RH1122-1AP60 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TH3022-0AP6 | 3RH1122-1AP60 | |
| 3TH3022-0AQ0 | 3RH1122-1AV00 | |
| 3TH3022-0AS0 | 3RH1122-1AT60 | |
| 3TH3022-0AU1 | 3RH1122-1AU60 | |
| 3TH3022-0AV0 | 3RH1122-1AV00 | |
| 3TH3022-0BA4 | 3RH1122-1BA40 | |
| 3TH3022-0BB4 | 3RH1122-1BB40 | |
| 3TH3022-0BG4 | 3RH1122-1BG40 | |
| 3TH3022-0BQ4 | 3RH1122-1BP40 | |
| 3TH3022-0BW4 | 3RH1122-1BW40 | |
| 3TH3031-0AC1 | 3RH1131-1AB00 | |
| 3TH3031-0AC2 | 3RH1131-1AB00 | |
| 3TH3031-0AD2 | 3RH1131-1AD00 | |
| 3TH3031-0AG2 | 3RH1131-1AK60 | |
| 3TH3031-0AJ2 | 3RH1131-1AK60 | |
| 3TH3031-0AK6 | 3RH1131-1AK60 | |
| 3TH3031-0AM1 | 3RH1131-1AM20 | |
| 3TH3031-0AM2 | 3RH1131-1AM20 | |
| 3TH3031-0AP0 | 3RH1131-1AP60 | |
| 3TH3031-0AP6 | 3RH1131-1AP60 | |
| 3TH3031-0AQ0 | 3RH1131-1AV00 | |
| 3TH3031-0AS0 | 3RH1131-1AT60 | |
| 3TH3031-0AU1 | 3RH1131-1AU60 | |
| 3TH3031-0AV0 | 3RH1131-1AV00 | |
| 3TH3031-0BA4 | 3RH1131-1BA40 | |
| 3TH3031-0BB4 | 3RH1131-1BB40 | |
| 3TH3031-0BG4 | 3RH1131-1BG40 | |
| 3TH3031-0BQ4 | 3RH1131-1BP40 | |
| 3TH3031-0BW4 | 3RH1131-1BW40 | |
| 3TH3040-0AC1 | 3RH1140-1AB00 | |
| 3TH3040-0AC2 | 3RH1140-1AB00 | |
| 3TH3040-0AD0 | 3RH1140-1AD00 | |
| 3TH3040-0AG2 | 3RH1140-1AK60 | |
| 3TH3040-0AJ2 | 3RH1140-1AK60 | |
| 3TH3040-0AK6 | 3RH1140-1AK60 | |
| 3TH3040-0AM1 | 3RH1140-1AM20 | |
| 3TH3040-0AM2 | 3RH1140-1AM20 | |
| 3TH3040-0AP0 | 3RH1140-1AP60 | |
| 3TH3040-0AP6 | 3RH1140-1AP60 | |
| 3TH3040-0AQ0 | 3RH1140-1AV00 | |
| 3TH3040-0AS0 | 3RH1140-1AT60 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TH3040-0AU1 | 3RH1140-1AU60 | |
| 3TH3040-0AV0 | 3RH1140-1AV00 | |
| 3TH3040-0BA4 | 3RH1140-1BA40 | |
| 3TH3040-0BB4 | 3RH1140-1BB40 | |
| 3TH3040-0BG4 | 3RH1140-1BG40 | |
| 3TH3040-0BQ4 | 3RH1140-1BP40 | |
| 3TH3040-0BW4 | 3RH1140-1BW40 | |
| 3TH4004-0AC2 | 3RH1122-1AB00 + 3RH1911-1FA22 | |
| 3TH4004-0AG1 | 3RH1122-1AK60 + 3RH1911-1FA22 | |
| 3TH4004-0AJ2 | 3RH1122-1AK60 + 3RH1911-1FA22 | |
| 3TH4004-0AK6 | 3RH1122-1AK60 + 3RH1911-1FA22 | |
| 3TH4004-0AM2 | 3RH1122-1AM20 + 3RH1911-1FA22 | |
| 3TH4004-0AP6 | 3RH1122-1AP60 + 3RH1911-1FA22 | |
| 3TH4004-0AQ0 | 3RH1122-1AV00 + 3RH1911-1FA22 | |
| 3TH4004-0AS0 | 3RH1122-1AT60 + 3RH1911-1FA22 | |
| 3TH4004-0AU1 | 3RH1122-1AU60 + 3RH1911-1FA22 | |
| 3TH4004-0AV0 | 3RH1122-1AV00 + 3RH1911-1FA22 | |
| 3TH4004-0BA4 | 3RH1122-1BA40 + 3RH1911-1FA22 | |
| 3TH4004-0BB4 | 3RH1122-1BB40 + 3RH1911-1FA22 | |
| 3TH4004-0BG4 | 3RH1122-1BG40 + 3RH1911-1FA22 | |
| 3TH4004-0BQ4 | 3RH1122-1BP40 + 3RH1911-1FA22 | |
| 3TH4004-0BW4 | 3RH1122-1BW40 + 3RH1911-1FA22 | |
| 3TH4013-0AC1 | 3RH1122-1AB00 + 3RH1911-1FA22 | |
| 3TH4013-0AC2 | 3RH1122-1AB00 + 3RH1911-1FA22 | |
| 3TH4013-0AJ2 | 3RH1122-1AK60 + 3RH1911-1FA22 | |
| 3TH4013-0AK6 | 3RH1122-1AK60 + 3RH1911-1FA22 | |
| 3TH4013-0AM1 | 3RH1122-1AM20 + 3RH1911-1FA22 | |
| 3TH4013-0AM2 | 3RH1122-1AM20 + 3RH1911-1FA22 | |
| 3TH4013-0AP6 | 3RH1122-1AP60 + 3RH1911-1FA22 | |
| 3TH4013-0AQ0 | 3RH1122-1AV00 + 3RH1911-1FA22 | |
| 3TH4013-0AS0 | 3RH1122-1AT60 + 3RH1911-1FA22 | |
| 3TH4013-0AU1 | 3RH1122-1AU60 + 3RH1911-1FA22 | |
| 3TH4013-0AV0 | 3RH1122-1AV00 + 3RH1911-1FA22 | |
| 3TH4013-0BA4 | 3RH1122-1BA40 + 3RH1911-1FA22 | |
| 3TH4013-0BB4 | 3RH1122-1BB40 + 3RH1911-1FA22 | |
| 3TH4013-0BG4 | 3RH1122-1BG40 + 3RH1911-1FA22 | |
| 3TH4013-0BQ4 | 3RH1122-1BP40 + 3RH1911-1FA22 | |
| 3TH4013-0BW4 | 3RH1122-1BW40 + 3RH1911-1FA22 | |
| 3TH4022-0AC0 | 3RH1122-1AD00 | |
| 3TH4022-0AC1 | 3RH1122-1AB00 | |
| 3TH4022-0AC2 | 3RH1122-1AB00 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TH4022-0AD0 | 3RH1122-1AD00 | |
| 3TH4022-0AF0 | 3RH1122-1AK60 | |
| 3TH4022-0AG0 | 3RH1122-1AG00 | |
| 3TH4022-0AG1 | 3RH1122-1AK60 | |
| 3TH4022-0AG2 | 3RH1122-1AK60 | |
| 3TH4022-0AG6 | 3RH1122-1AG60 | |
| 3TH4022-0AHO | 3RH1122-1AH00 | |
| 3TH4022-0AJ2 | 3RH1122-1AK60 | |
| 3TH4022-0AK6 | 3RH1122-1AK60 | |
| 3TH4022-0AL0 | 3RH1122-1AP60 | |
| 3TH4022-0AM1 | 3RH1122-1AM20 | |
| 3TH4022-0AM2 | 3RH1122-1AM20 | |
| 3TH4022-0AN1 | 3RH1122-1AP60 | |
| 3TH4022-0AN2 | 3RH1122-1AP60 | |
| 3TH4022-0AP0 | 3RH1122-1AP60 | |
| 3TH4022-0AP6 | 3RH1122-1AP60 | |
| 3TH4022-0AQ0 | 3RH1122-1AV00 | |
| 3TH4022-0AR1 | 3RH1122-1AR60 | |
| 3TH4022-0AS0 | 3RH1122-1AT60 | |
| 3TH4022-0AU1 | 3RH1122-1AU60 | |
| 3TH4022-0AV0 | 3RH1122-1AV00 | |
| 3TH4022-0BA4 | 3RH1122-1BA40 | |
| 3TH4022-0BB4 | 3RH1122-1BB40 | |
| 3TH4022-0BE8 | NO DIRECT REPLACEMENT | |
| 3TH4022-0BF4 | 3RH1122-1BF40 | |
| 3TH4022-0BG4 | 3RH1122-1BG40 | |
| 3TH4022-0BM4 | 3RH1122-1BM40 | |
| 3TH4022-0BQ4 | 3RH1122-1BP40 | |
| 3TH4022-0BW4 | 3RH1122-1BW40 | |
| 3TH4022-0BZ80 | NO DIRECT REPLACEMENT | |
| 3TH4022-0LB4 | 3RH1122-1BB40 + SURGE | |
| 3TH4022-3BB4 | 3RH1122-1BB40 | |
| 3TH4022-4BB4 | 3RH1122-1BB40 | |
| 3TH4022-4MC1 | 3RH1122-1AB00 | |
| 3TH4022-4MC2 | 3RH1122-1AB00 | |
| 3TH4022-4ML2 | 3RH1122-1ABP6 | |
| 3TH4022-6CC8 | NO DIRECT REPLACEMENT | |
| 3TH4031-0AC2 | 3RH1131-1AB00 | |
| 3TH4031-0AF0 | 3RH1131-1AK60 | |
| 3TH4031-0AG0 | 3RH1131-1AG00 | |
| 3TH4031-0AG1 | 3RH1131-1AK60 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TH4031-0AG2 | 3RH1131-1AK60 | |
| 3TH4031-0AH0 | 3RH1131-1AH00 | |
| 3TH4031-0AJ2 | 3RH1131-1AK60 | |
| 3TH4031-0AK6 | 3RH1131-1AK60 | |
| 3TH4031-0AL2 | 3RH1131-1AP60 | |
| 3TH4031-0AM2 | 3RH1131-1AM20 | |
| 3TH4031-0AN1 | 3RH1131-1AP60 | |
| 3TH4031-0AN2 | 3RH1131-1AP60 | |
| 3TH4031-0AP6 | 3RH1131-1AP60 | |
| 3TH4031-0AQ0 | 3RH1131-1AV00 | |
| 3TH4031-0AS0 | 3RH1131-1AT60 | |
| 3TH4031-0AU1 | 3RH1131-1AU60 | |
| 3TH4031-0AV0 | 3RH1131-1AV00 | |
| 3TH4031-0BA4 | 3RH1131-1BA40 | |
| 3TH4031-0BB4 | 3RH1131-1BB40 | |
| 3TH4031-0BE8 | NO DIRECT REPLACEMENT | |
| 3TH4031-0BG4 | 3RH1131-1BG40 | |
| 3TH4031-0BP4 | 3RH1131-1BP40 | |
| 3TH4031-0BQ4 | 3RH1131-1BP40 | |
| 3TH4031-0BW4 | 3RH1131-1BW40 | |
| 3TH4031-0LC8 | NO DIRECT REPLACEMENT | |
| 3TH4031-6CC8 | NO DIRECT REPLACEMENT | |
| 3TH4040-0AC2 | 3RH1140-1AB00 | |
| 3TH4040-0AD0 | 3RH1140-1AD00 | |
| 3TH4040-0AD2 | 3RH1140-1AD00 | |
| 3TH4040-0AG0 | 3RH1140-1AG00 | |
| 3TH4040-0AG6 | 3RH1140-1AG60 | |
| 3TH4040-0AJ2 | 3RH1140-1AK60 | |
| 3TH4040-0AK6 | 3RH1140-1AK60 | |
| 3TH4040-0AL0 | 3RH1140-1AP60 | |
| 3TH4040-0AM2 | 3RH1140-1AM20 | |
| 3TH4040-0AN1 | 3RH1140-1AP60 | |
| 3TH4040-0AP6 | 3RH1140-1AP60 | |
| 3TH4040-0AQ0 | 3RH1140-1AV00 | |
| 3TH4040-0AS0 | 3RH1140-1AT60 | |
| 3TH4040-0AU1 | 3RH1140-1AU60 | |
| 3TH4040-0AV0 | 3RH1140-1AV00 | |
| 3TH4040-0BA4 | 3RH1140-1BA40 | |
| 3TH4040-0BB4 | 3RH1140-1BB40 | |
| 3TH4040-0BE4 | 3RH1140-1BE40 | |
| 3TH4040-0BE8 | NO DIRECT REPLACEMENT | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TH4040-0BF4 | 3RH1140-1BF40 | |
| 3TH4040-0BG4 | 3RH1140-1BG40 | |
| 3TH4040-0BQ4 | 3RH1140-1BP40 | |
| 3TH4040-0BW4 | 3RH1140-1BW40 | |
| 3TH4092-0AC2 | 3RH1122-1AB00 | |
| 3TH4092-0AJ2 | 3RH1122-1AK60 | |
| 3TH4092-0AK6 | 3RH1122-1AK60 | |
| 3TH4092-0AM2 | 3RH1122-1AM20 | |
| 3TH4092-0AP2 | 3RH1122-1AP60 | |
| 3TH4092-0AP6 | 3RH1122-1AP60 | |
| 3TH4092-0AQ0 | 3RH1122-1AV00 | |
| 3TH4092-0AS0 | 3RH1122-1AT60 | |
| 3TH4092-0AU1 | 3RH1122-1AU60 | |
| 3TH4092-0AV0 | 3RH1122-1AV00 | |
| 3TH4092-0BA4 | 3RH1122-1BA40 | |
| 3TH4092-0BB4 | 3RH1122-1BB40 | |
| 3TH4092-0BG4 | 3RH1122-1BG40 | |
| 3TH4092-0BQ4 | 3RH1122-1BP40 | |
| 3TH4092-0BW4 | 3RH1122-1BW40 | |
| 3TH4095-0AC1 | 3RH1131-1AB00 | |
| 3TH4095-0AC2 | 3RH1131-1AB00 | |
| 3TH4095-0AD2 | 3RH1131-1AD00 | |
| 3TH4095-0AJ2 | 3RH1131-1AK60 | |
| 3TH4095-0AK6 | 3RH1131-1AK60 | |
| 3TH4095-0AM2 | 3RH1131-1AM20 | |
| 3TH4095-0AP6 | 3RH1131-1AP60 | |
| 3TH4095-0AQ0 | 3RH1131-1AV00 | |
| 3TH4095-0AS0 | 3RH1131-1AT60 | |
| 3TH4095-0AU1 | 3RH1131-1AU60 | |
| 3TH4095-0AV0 | 3RH1131-1AV00 | |
| 3TH4095-0BA4 | 3RH1131-1BA40 | |
| 3TH4095-0BB4 | 3RH1131-1BB40 | |
| 3TH4095-0BG4 | 3RH1131-1BG40 | |
| 3TH4095-0BQ4 | 3RH1131-1BP40 | |
| 3TH4095-0BW4 | 3RH1131-1BW40 | |
| 3TH4096-0AC2 | 3RH1122-1AB00 | |
| 3TH4096-0AG2 | 3RH1122-1AK60 | |
| 3TH4096-0AJ2 | 3RH1122-1AK60 | |
| 3TH4096-0AK6 | 3RH1122-1AK60 | |
| 3TH4096-0AM2 | 3RH1122-1AM20 | |
| 3TH4096-0AP6 | 3RH1122-1AP60 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TH4096-0AQ0 | 3RH1122-1AV00 | |
| 3TH4096-0AS0 | 3RH1122-1AT60 | |
| 3TH4096-0AU1 | 3RH1122-1AU60 | |
| 3TH4096-0AV0 | 3RH1122-1AV00 | |
| 3TH4096-0BA4 | 3RH1122-1BA40 | |
| 3TH4096-0BB4 | 3RH1122-1BB40 | |
| 3TH4096-0BG4 | 3RH1122-1BG40 | |
| 3TH4096-0BQ4 | 3RH1122-1BP40 | |
| 3TH4096-0BW4 | 3RH1122-1BW40 | |
| 3TH4243-2EG1 | 3RH1122-1AK60 + 3RH1911-1FA22 | |
| 3TH4243-2EK1 | 3RH1122-1AK60 + 3RH1911-1FA22 | |
| 3TH4244-0AC1 | 3RH1122-1AB00 + 3RH1911-1FA22 | |
| 3TH4244-0AC2 | 3RH1122-1AB00 + 3RH1911-1FA22 | |
| 3TH4244-0AD2 | 3RH1122-1AD00 + 3RH1911-1FA22 | |
| 3TH4244-0AE0 | NO DIRECT REPLACEMENT | |
| 3TH4244-0AG2 | 3RH1122-1AK60 + 3RH1911-1FA22 | |
| 3TH4244-0AH0 | 3RH1122-1AH00 + 3RH1911-1FA22 | |
| 3TH4244-0AJ1 | 3RH1122-1AK60 + 3RH1911-1FA22 | |
| 3TH4244-0AJ2 | 3RH1122-1AK60 + 3RH1911-1FA22 | |
| 3TH4244-0AK6 | 3RH1122-1AK60 + 3RH1911-1FA22 | |
| 3TH4244-0AL0 | 3RH1122-1AP60 + 3RH1911-1FA22 | |
| 3TH4244-0AL2 | 3RH1122-1AP60 + 3RH1911-1FA22 | |
| 3TH4244-0AM0 | 3RH1122-1AM20 + 3RH1911-1FA22 | |
| 3TH4244-0AM2 | 3RH1122-1AM20 + 3RH1911-1FA22 | |
| 3TH4244-0AN1 | 3RH1122-1AP60 + 3RH1911-1FA22 | |
| 3TH4244-0AN2 | 3RH1122-1AP60 + 3RH1911-1FA22 | |
| 3TH4244-0AP0 | 3RH1122-1AP60 + 3RH1911-1FA22 | |
| 3TH4244-0AP6 | 3RH1122-1AP60 + 3RH1911-1FA22 | |
| 3TH4244-0AQ0 | 3RH1122-1AV00 + 3RH1911-1FA22 | |
| 3TH4244-0AS0 | 3RH1122-1AT60 + 3RH1911-1FA22 | |
| 3TH4244-0AU1 | 3RH1122-1AU60 + 3RH1911-1FA22 | |
| 3TH4244-0AV0 | 3RH1122-1AV00 + 3RH1911-1FA22 | |
| 3TH4244-0BA4 | 3RH1122-1BA40 + 3RH1911-1FA22 | |
| 3TH4244-0BB4 | 3RH1122-1BB40 + 3RH1911-1FA22 | |
| 3TH4244-0BE4 | 3RH1122-1BE40 + 3RH1911-1FA22 | |
| 3TH4244-0BF4 | 3RH1122-1BF40 + 3RH1911-1FA22 | |
| 3TH4244-0BG4 | 3RH1122-1BG40 + 3RH1911-1FA22 | |
| 3TH4244-0BM4 | 3RH1122-1BM40 + 3RH1911-1FA22 | |
| 3TH4244-0BN4 | NO DIRECT REPLACEMENT | |
| 3TH4244-0BQ4 | 3RH1122-1BP40 + 3RH1911-1FA22 | |
| 3TH4244-0BW4 | 3RH1122-1BW40 + 3RH1911-1FA22 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TH4244-0LB4 | 3RH1122-1BB40 + SURGE | |
| 3TH4244-0LC8 | NO DIRECT REPLACEMENT | |
| 3TH4244-3BB4 | 3RH1122-1BB40 + 3RH1911-1FA22 | |
| 3TH4244-3BF4 | 3RH1122-1BF40 + 3RH1911-1FA22 | |
| 3TH4244-4MC1 | 3RH1122-1AB00 + 3RH1911-1FA22 | |
| 3TH4244-4MG2 | 3RH1122-1AK60 + 3RH1911-1FA22 | |
| 3TH4244-5KZ9 | NO DIRECT REPLACEMENT | |
| 3TH4244-6BB4 | 3RH1122-1BB40 + 3RH1911-1FA22 | |
| 3TH4244-6CC8 | NO DIRECT REPLACEMENT | |
| 3TH4250-0LC8 | NO DIRECT REPLACEMENT | |
| 3TH4253-0AC2 | 3RH1131-1AB00 + 3RH1911-1FA22 | |
| 3TH4253-0AD0 | 3RH1131-1AD00 + 3RH1911-1FA22 | |
| 3TH4253-0AF0 | 3RH1131-1AK60 + 3RH1911-1FA22 | |
| 3TH4253-0AG2 | 3RH1131-1AK60 + 3RH1911-1FA22 | |
| 3TH4253-0AJ1 | 3RH1131-1AK60 + 3RH1911-1FA22 | |
| 3TH4253-0AJ2 | 3RH1131-1AK60 + 3RH1911-1FA22 | |
| 3TH4253-0AK6 | 3RH1131-1AK60 + 3RH1911-1FA22 | |
| 3TH4253-0AM2 | 3RH1131-1AM20 + 3RH1911-1FA22 | |
| 3TH4253-0AN2 | 3RH1131-1AP60 + 3RH1911-1FA22 | |
| 3TH4253-0AP6 | 3RH1131-1AP60 + 3RH1911-1FA22 | |
| 3TH4253-0AQ0 | 3RH1131-1AV00 + 3RH1911-1FA22 | |
| 3TH4253-0AS0 | 3RH1131-1AT60 + 3RH1911-1FA22 | |
| 3TH4253-0AU1 | 3RH1131-1AU60 + 3RH1911-1FA22 | |
| 3TH4253-0AV0 | 3RH1131-1AV00 + 3RH1911-1FA22 | |
| 3TH4253-0BA4 | 3RH1131-1BA40 + 3RH1911-1FA22 | |
| 3TH4253-0BB4 | 3RH1131-1BB40 + 3RH1911-1FA22 | |
| 3TH4253-0BG4 | 3RH1131-1BG40 + 3RH1911-1FA22 | |
| 3TH4253-0BQ4 | 3RH1131-1BP40 + 3RH1911-1FA22 | |
| 3TH4253-0BW4 | 3RH1131-1BW40 + 3RH1911-1FA22 | |
| 3TH4253-0BZ9-Z | NO DIRECT REPLACEMENT | |
| 3TH4253-0LB4 | 3RH1131-1BW40 + 3RH1911-1FA22 | |
| 3TH4253-0LC8 | NO DIRECT REPLACEMENT | |
| 3TH4253-4MG1 | 3RH1131-1AK60 + 3RH1911-1FA22 | |
| 3TH4253-5KZ9 | NO DIRECT REPLACEMENT | |
| 3TH4262-0AB0 | 3RH1140-1AB00 + 3RH1911-1FA22 | |
| 3TH4262-0AC2 | 3RH1140-1AB00 + 3RH1911-1FA22 | |
| 3TH4262-0AD0 | 3RH1140-1AD00 + 3RH1911-1FA22 | |
| 3TH4262-0AD2 | 3RH1140-1AD00 + 3RH1911-1FA22 | |
| 3TH4262-0AF0 | 3RH1140-1AK60 + 3RH1911-1FA22 | |
| 3TH4262-0AG1 | 3RH1140-1AK60 + 3RH1911-1FA22 | |
| 3TH4262-0AG2 | 3RH1140-1AK60 + 3RH1911-1FA22 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TH4262-0AJ1 | 3RH1140-1AK60 + 3RH1911-1FA22 | |
| 3TH4262-0AJ2 | 3RH1140-1AK60 + 3RH1911-1FA22 | |
| 3TH4262-0AK6 | 3RH1140-1AK60 + 3RH1911-1FA22 | |
| 3TH4262-0AL0 | 3RH1140-1AP60 + 3RH1911-1FA22 | |
| 3TH4262-0AL2 | 3RH1140-1AP60 + 3RH1911-1FA22 | |
| 3TH4262-0AM2 | 3RH1140-1AM20 + 3RH1911-1FA22 | |
| 3TH4262-0AN1 | 3RH1140-1AP60 + 3RH1911-1FA22 | |
| 3TH4262-0AN2 | 3RH1140-1AP60 + 3RH1911-1FA22 | |
| 3TH4262-0AP0 | 3RH1140-1AP60 + 3RH1911-1FA22 | |
| 3TH4262-0AP6 | 3RH1140-1AP60 + 3RH1911-1FA22 | |
| 3TH4262-0AQ0 | 3RH1140-1AV00 + 3RH1911-1FA22 | |
| 3TH4262-0AQ1 | 3RH1140-1AV00 + 3RH1911-1FA22 | |
| 3TH4262-0AS0 | 3RH1140-1AT60 + 3RH1911-1FA22 | |
| 3TH4262-0AU1 | 3RH1140-1AU60 + 3RH1911-1FA22 | |
| 3TH4262-0AV0 | 3RH1140-1AV00 + 3RH1911-1FA22 | |
| 3TH4262-0BA4 | 3RH1140-1BA40 + 3RH1911-1FA22 | |
| 3TH4262-0BB4 | 3RH1140-1BB40 + 3RH1911-1FA22 | |
| 3TH4262-0BE8 | NO DIRECT REPLACEMENT | |
| 3TH4262-0BG4 | 3RH1140-1BG40 + 3RH1911-1FA22 | |
| 3TH4262-0BQ4 | 3RH1140-1BP40 + 3RH1911-1FA22 | |
| 3TH4262-0BW4 | 3RH1140-1BW40 + 3RH1911-1FA22 | |
| 3TH4262-0LB4 | 3RH1140-1BB40 + SURGE | |
| 3TH4262-0LC8 | NO DIRECT REPLACEMENT | |
| 3TH4262-4BB4 | 3RH1140-1BB40 + 3RH1911-1FA22 | |
| 3TH4262-4KB4 | 3RH1140-1BB40 + 3RH1911-1FA22 | |
| 3TH4262-4MG0 | 3RH1140-1AG00 + 3RH1911-1FA22 | |
| 3TH4262-5KZ9 | NO DIRECT REPLACEMENT | |
| 3TH4262-6CC8 | NO DIRECT REPLACEMENT | |
| 3TH4271-0AC2 | 3RH1140-1AB00 + 3RH1911-1FA31 | |
| 3TH4271-0AJ2 | 3RH1140-1AK60 + 3RH1911-1FA31 | |
| 3TH4271-0AK6 | 3RH1140-1AK60 + 3RH1911-1FA31 | |
| 3TH4271-0AM2 | 3RH1140-1AM20 + 3RH1911-1FA31 | |
| 3TH4271-0AP6 | 3RH1140-1AP60 + 3RH1911-1FA31 | |
| 3TH4271-0AQ0 | 3RH1140-1AV00 + 3RH1911-1FA31 | |
| 3TH4271-0AS0 | 3RH1140-1AT60 + 3RH1911-1FA31 | |
| 3TH4271-0AU1 | 3RH1140-1AU60 + 3RH1911-1FA31 | |
| 3TH4271-0AV0 | 3RH1140-1AV00 + 3RH1911-1FA31 | |
| 3TH4271-0BA4 | 3RH1140-1BA40 + 3RH1911-1FA31 | |
| 3TH4271-0BB4 | 3RH1140-1BB40 + 3RH1911-1FA31 | |
| 3TH4271-0BG4 | 3RH1140-1BG40 + 3RH1911-1FA31 | |
| 3TH4271-0BQ4 | 3RH1140-1BP40 + 3RH1911-1FA31 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TH4271-0BW4 | 3RH1140-1BW40 + 3RH1911-1FA31 | |
| 3TH4271-0LB4 | 3RH1140-1BB40 + 3RH1911-1FA31 | |
| 3TH4271-0LC8 | NO DIRECT REPLACEMENT | |
| 3TH4271-5KB4 | 3RH1140-1BB40 + 3RH1911-1FA31 | |
| 3TH4271-5KZ9 | NO DIRECT REPLACEMENT | |
| 3TH4280-0AC2 | 3RH1140-1AB00 + 3RH1911-1FA40 | |
| 3TH4280-0AJ1 | 3RH1140-1AK60 + 3RH1911-1FA40 | |
| 3TH4280-0AJ2 | 3RH1140-1AK60 + 3RH1911-1FA40 | |
| 3TH4280-0AK6 | 3RH1140-1AK60 + 3RH1911-1FA40 | |
| 3TH4280-0AM0 | 3RH1140-1AM20 + 3RH1911-1FA40 | |
| 3TH4280-0AM2 | 3RH1140-1AM20 + 3RH1911-1FA40 | |
| 3TH4280-0AN1 | 3RH1140-1AP60 + 3RH1911-1FA40 | |
| 3TH4280-0AN2 | 3RH1140-1AP60 + 3RH1911-1FA40 | |
| 3TH4280-0AP6 | 3RH1140-1AP60 + 3RH1911-1FA40 | |
| 3TH4280-0AQ0 | 3RH1140-1AV00 + 3RH1911-1FA40 | |
| 3TH4280-0AS0 | 3RH1140-1AT60 + 3RH1911-1FA40 | |
| 3TH4280-0AU1 | 3RH1140-1AU60 + 3RH1911-1FA40 | |
| 3TH4280-0AV0 | 3RH1140-1AV00 + 3RH1911-1FA40 | |
| 3TH4280-0BA4 | 3RH1140-1BA40 + 3RH1911-1FA40 | |
| 3TH4280-0BB4 | 3RH1140-1BB40 + 3RH1911-1FA40 | |
| 3TH4280-0BG4 | 3RH1140-1BG40 + 3RH1911-1FA40 | |
| 3TH4280-0BQ4 | 3RH1140-1BP40 + 3RH1911-1FA40 | |
| 3TH4280-0BW4 | 3RH1140-1BW40 + 3RH1911-1FA40 | |
| 3TH4280-0LC8 | NO DIRECT REPLACEMENT | |
| 3TH4280-5MB4 | 3RH1140-1BB40 + 3RH1911-1FA40 | |
| 3TH4293-0AC2 | 3RH1140-1AB00 + 3RH1911-1FA40 | |
| 3TH4293-0AJ2 | 3RH1140-1AK60 + 3RH1911-1FA40 | |
| 3TH4293-0AK6 | 3RH1140-1AK60 + 3RH1911-1FA40 | |
| 3TH4293-0AM2 | 3RH1140-1AM20 + 3RH1911-1FA40 | |
| 3TH4293-0AP6 | 3RH1140-1AP60 + 3RH1911-1FA40 | |
| 3TH4293-0AQ0 | 3RH1140-1AV00 + 3RH1911-1FA40 | |
| 3TH4293-0AS0 | 3RH1140-1AT60 + 3RH1911-1FA40 | |
| 3TH4293-0AU1 | 3RH1140-1AU60 + 3RH1911-1FA40 | |
| 3TH4293-0AV0 | 3RH1140-1AV00 + 3RH1911-1FA40 | |
| 3TH4293-0BA4 | 3RH1140-1BA40 + 3RH1911-1FA40 | |
| 3TH4293-0BB4 | 3RH1140-1BB40 + 3RH1911-1FA40 | |
| 3TH4293-0BG4 | 3RH1140-1BG40 + 3RH1911-1FA40 | |
| 3TH4293-0BQ4 | 3RH1140-1BP40 + 3RH1911-1FA40 | |
| 3TH4293-0BW4 | 3RH1140-1BW40 + 3RH1911-1FA40 | |
| 3TH4310-0AC2 | NO DIRECT REPLACEMENT | |
| 3TH4310-0AG1 | NO DIRECT REPLACEMENT | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TH4310-0AJ2 | NO DIRECT REPLACEMENT | |
| 3TH4310-0AK6 | NO DIRECT REPLACEMENT | |
| 3TH4310-0AM2 | NO DIRECT REPLACEMENT | |
| 3TH4310-0AP6 | NO DIRECT REPLACEMENT | |
| 3TH4310-0AQ0 | NO DIRECT REPLACEMENT | |
| 3TH4310-0AS0 | NO DIRECT REPLACEMENT | |
| 3TH4310-0AU1 | NO DIRECT REPLACEMENT | |
| 3TH4310-0AV0 | NO DIRECT REPLACEMENT | |
| 3TH4310-0BA4 | NO DIRECT REPLACEMENT | |
| 3TH4310-0BB4 | NO DIRECT REPLACEMENT | |
| 3TH4310-0BG4 | NO DIRECT REPLACEMENT | |
| 3TH4310-0BQ4 | NO DIRECT REPLACEMENT | |
| 3TH4310-0BW4 | NO DIRECT REPLACEMENT | |
| 3TH4310-0LB4 | NO DIRECT REPLACEMENT | |
| 3TH4310-5KB4 | NO DIRECT REPLACEMENT | |
| 3TH4346-0AC1 | NO DIRECT REPLACEMENT | |
| 3TH4346-0AF0 | NO DIRECT REPLACEMENT | |
| 3TH4346-0AG2 | NO DIRECT REPLACEMENT | |
| 3TH4346-0AK6 | NO DIRECT REPLACEMENT | |
| 3TH4346-0AP0 | NO DIRECT REPLACEMENT | |
| 3TH4346-0BB4 | NO DIRECT REPLACEMENT | |
| 3TH4355-0AB0 | NO DIRECT REPLACEMENT | |
| 3TH4355-0AC2 | NO DIRECT REPLACEMENT | |
| 3TH4355-0AD0 | NO DIRECT REPLACEMENT | |
| 3TH4355-0AE0 | NO DIRECT REPLACEMENT | |
| 3TH4355-0AG0 | NO DIRECT REPLACEMENT | |
| 3TH4355-0AJ1 | NO DIRECT REPLACEMENT | |
| 3TH4355-0AJ2 | NO DIRECT REPLACEMENT | |
| 3TH4355-0AK6 | NO DIRECT REPLACEMENT | |
| 3TH4355-0AM2 | NO DIRECT REPLACEMENT | |
| 3TH4355-0AN1 | NO DIRECT REPLACEMENT | |
| 3TH4355-0AN2 | NO DIRECT REPLACEMENT | |
| 3TH4355-0AP6 | NO DIRECT REPLACEMENT | |
| 3TH4355-0AQ0 | NO DIRECT REPLACEMENT | |
| 3TH4355-0AS0 | NO DIRECT REPLACEMENT | |
| 3TH4355-0AU1 | NO DIRECT REPLACEMENT | |
| 3TH4355-0AV0 | NO DIRECT REPLACEMENT | |
| 3TH4355-0BA4 | NO DIRECT REPLACEMENT | |
| 3TH4355-0BB4 | NO DIRECT REPLACEMENT | |
| 3TH4355-0BF4 | NO DIRECT REPLACEMENT | |
| 3TH4355-0BG4 | NO DIRECT REPLACEMENT | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TH4355-0BQ4 | NO DIRECT REPLACEMENT | |
| 3TH4355-0BW4 | NO DIRECT REPLACEMENT | |
| 3TH4355-0LB4 | NO DIRECT REPLACEMENT | |
| 3TH4355-0LC8 | NO DIRECT REPLACEMENT | |
| 3TH4355-3BB4 | NO DIRECT REPLACEMENT | |
| 3TH4355-4MK6 | NO DIRECT REPLACEMENT | |
| 3TH4355-5KZ9 | NO DIRECT REPLACEMENT | |
| 3TH4364-0AC2 | NO DIRECT REPLACEMENT | |
| 3TH4364-0AG2 | NO DIRECT REPLACEMENT | |
| 3TH4364-0AJ2 | NO DIRECT REPLACEMENT | |
| 3TH4364-0AK6 | NO DIRECT REPLACEMENT | |
| 3TH4364-0AM0 | NO DIRECT REPLACEMENT | |
| 3TH4364-0AM2 | NO DIRECT REPLACEMENT | |
| 3TH4364-0AP6 | NO DIRECT REPLACEMENT | |
| 3TH4364-0AQ0 | NO DIRECT REPLACEMENT | |
| 3TH4364-0AS0 | NO DIRECT REPLACEMENT | |
| 3TH4364-0AU1 | NO DIRECT REPLACEMENT | |
| 3TH4364-0AV0 | NO DIRECT REPLACEMENT | |
| 3TH4364-0BA4 | NO DIRECT REPLACEMENT | |
| 3TH4364-0BB4 | NO DIRECT REPLACEMENT | |
| 3TH4364-0BG4 | NO DIRECT REPLACEMENT | |
| 3TH4364-0BQ4 | NO DIRECT REPLACEMENT | |
| 3TH4364-0BW4 | NO DIRECT REPLACEMENT | |
| 3TH4364-0LC8 | NO DIRECT REPLACEMENT | |
| 3TH4364-5MB4 | NO DIRECT REPLACEMENT | |
| 3TH4373-0AC2 | NO DIRECT REPLACEMENT | |
| 3TH4373-0AJ2 | NO DIRECT REPLACEMENT | |
| 3TH4373-0AK6 | NO DIRECT REPLACEMENT | |
| 3TH4373-0AM0 | NO DIRECT REPLACEMENT | |
| 3TH4373-0AM2 | NO DIRECT REPLACEMENT | |
| 3TH4373-0AN2 | NO DIRECT REPLACEMENT | |
| 3TH4373-0AP6 | NO DIRECT REPLACEMENT | |
| 3TH4373-0AQ0 | NO DIRECT REPLACEMENT | |
| 3TH4373-0AS0 | NO DIRECT REPLACEMENT | |
| 3TH4373-0AU1 | NO DIRECT REPLACEMENT | |
| 3TH4373-0AV0 | NO DIRECT REPLACEMENT | |
| 3TH4373-0BA4 | NO DIRECT REPLACEMENT | |
| 3TH4373-0BB4 | NO DIRECT REPLACEMENT | |
| 3TH4373-0BG4 | NO DIRECT REPLACEMENT | |
| 3TH4373-0BQ4 | NO DIRECT REPLACEMENT | |
| 3TH4373-0BW4 | NO DIRECT REPLACEMENT | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TH4373-0LB4 | NO DIRECT REPLACEMENT | |
| 3TH4373-0LC8 | NO DIRECT REPLACEMENT | |
| 3TH4373-5KB4 | NO DIRECT REPLACEMENT | |
| 3TH4382-0AC2 | NO DIRECT REPLACEMENT | |
| 3TH4382-0AG2 | NO DIRECT REPLACEMENT | |
| 3TH4382-0AJ2 | NO DIRECT REPLACEMENT | |
| 3TH4382-0AK6 | NO DIRECT REPLACEMENT | |
| 3TH4382-0AM2 | NO DIRECT REPLACEMENT | |
| 3TH4382-0AP6 | NO DIRECT REPLACEMENT | |
| 3TH4382-0AQ0 | NO DIRECT REPLACEMENT | |
| 3TH4382-0AS0 | NO DIRECT REPLACEMENT | |
| 3TH4382-0AU1 | NO DIRECT REPLACEMENT | |
| 3TH4382-0AV0 | NO DIRECT REPLACEMENT | |
| 3TH4382-0BA4 | NO DIRECT REPLACEMENT | |
| 3TH4382-0BB4 | NO DIRECT REPLACEMENT | |
| 3TH4382-0BG4 | NO DIRECT REPLACEMENT | |
| 3TH4382-0BQ4 | NO DIRECT REPLACEMENT | |
| 3TH4382-0BW4 | NO DIRECT REPLACEMENT | |
| 3TH4382-0LB4 | NO DIRECT REPLACEMENT | |
| 3TH4382-0LC8 | NO DIRECT REPLACEMENT | |
| 3TH4391-0AC1 | NO DIRECT REPLACEMENT | |
| 3TH4391-0AC2 | NO DIRECT REPLACEMENT | |
| 3TH4391-0AJ2 | NO DIRECT REPLACEMENT | |
| 3TH4391-0AK6 | NO DIRECT REPLACEMENT | |
| 3TH4391-0AM2 | NO DIRECT REPLACEMENT | |
| 3TH4391-0AP6 | NO DIRECT REPLACEMENT | |
| 3TH4391-0AQ0 | NO DIRECT REPLACEMENT | |
| 3TH4391-0AS0 | NO DIRECT REPLACEMENT | |
| 3TH4391-0AU1 | NO DIRECT REPLACEMENT | |
| 3TH4391-0AV0 | NO DIRECT REPLACEMENT | |
| 3TH4391-0BA4 | NO DIRECT REPLACEMENT | |
| 3TH4391-0BB4 | NO DIRECT REPLACEMENT | |
| 3TH4391-0BG4 | NO DIRECT REPLACEMENT | |
| 3TH4391-0BQ4 | NO DIRECT REPLACEMENT | |
| 3TH4391-0BW4 | NO DIRECT REPLACEMENT | |
| 3TH4391-0LB4 | NO DIRECT REPLACEMENT | |
| 3TH4391-0LC8 | NO DIRECT REPLACEMENT | |
| 3TH4391-5KB4 | NO DIRECT REPLACEMENT | |
| 3TH4391-5KZ9 | NO DIRECT REPLACEMENT | |
| 3TH4394-0AC2 | NO DIRECT REPLACEMENT | |
| 3TH4394-0AD0 | NO DIRECT REPLACEMENT | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TH4394-0AD2 | NO DIRECT REPLACEMENT | |
| 3TH4394-0AF0 | NO DIRECT REPLACEMENT | |
| 3TH4394-0AJ1 | NO DIRECT REPLACEMENT | |
| 3TH4394-0AJ2 | NO DIRECT REPLACEMENT | |
| 3TH4394-0AK6 | NO DIRECT REPLACEMENT | |
| 3TH4394-0AM2 | NO DIRECT REPLACEMENT | |
| 3TH4394-0AP6 | NO DIRECT REPLACEMENT | |
| 3TH4394-0AQ0 | NO DIRECT REPLACEMENT | |
| 3TH4394-0AS0 | NO DIRECT REPLACEMENT | |
| 3TH4394-0AU1 | NO DIRECT REPLACEMENT | |
| 3TH4394-0AV0 | NO DIRECT REPLACEMENT | |
| 3TH4394-0BA4 | NO DIRECT REPLACEMENT | |
| 3TH4394-0BB4 | NO DIRECT REPLACEMENT | |
| 3TH4394-0BG4 | NO DIRECT REPLACEMENT | |
| 3TH4394-0BQ4 | NO DIRECT REPLACEMENT | |
| 3TH4394-0BW4 | NO DIRECT REPLACEMENT | |
| 3TH4394-0LC8 | NO DIRECT REPLACEMENT | |
| 3TH4454-0AB4 | NO DIRECT REPLACEMENT | |
| 3TH4454-0AC2 | NO DIRECT REPLACEMENT | |
| 3TH4454-0AG2 | NO DIRECT REPLACEMENT | |
| 3TH4454-0AJ2 | NO DIRECT REPLACEMENT | |
| 3TH4454-0AK2 | NO DIRECT REPLACEMENT | |
| 3TH4454-0AK6 | NO DIRECT REPLACEMENT | |
| 3TH4454-0AM2 | NO DIRECT REPLACEMENT | |
| 3TH4454-0AN2 | NO DIRECT REPLACEMENT | |
| 3TH4454-0AP2 | NO DIRECT REPLACEMENT | |
| 3TH4454-0AP6 | NO DIRECT REPLACEMENT | |
| 3TH4454-0AQ0 | NO DIRECT REPLACEMENT | |
| 3TH4454-0AS0 | NO DIRECT REPLACEMENT | |
| 3TH4454-0AV0 | NO DIRECT REPLACEMENT | |
| 3TH4454-0AW4 | NO DIRECT REPLACEMENT | |
| 3TH4454-0BA4 | NO DIRECT REPLACEMENT | |
| 3TH4454-0BB4 | NO DIRECT REPLACEMENT | |
| 3TH4454-0BG4 | NO DIRECT REPLACEMENT | |
| 3TH4454-0BQ4 | NO DIRECT REPLACEMENT | |
| 3TH4454-0BW4 | NO DIRECT REPLACEMENT | |
| 3TH4454-1EC2 | NO DIRECT REPLACEMENT | |
| 3TH4454-1EJ2 | NO DIRECT REPLACEMENT | |
| 3TH4454-1EK2 | NO DIRECT REPLACEMENT | |
| 3TH4454-1EK6 | NO DIRECT REPLACEMENT | |
| 3TH4454-1EM2 | NO DIRECT REPLACEMENT | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TH4454-1EP6 | NO DIRECT REPLACEMENT | |
| 3TH4454-1EQ0 | NO DIRECT REPLACEMENT | |
| 3TH4454-1ES0 | NO DIRECT REPLACEMENT | |
| 3TH4454-1FA4 | NO DIRECT REPLACEMENT | |
| 3TH4454-1FB4 | NO DIRECT REPLACEMENT | |
| 3TH4454-1FF4 | NO DIRECT REPLACEMENT | |
| 3TH4454-1FG4 | NO DIRECT REPLACEMENT | |
| 3TH4454-1FK4 | NO DIRECT REPLACEMENT | |
| 3TH4454-1FQ4 | NO DIRECT REPLACEMENT | |
| 3TH4454-1FW4 | NO DIRECT REPLACEMENT | |
| 3TH4454-8EC2 | NO DIRECT REPLACEMENT | |
| 3TH4454-8EJ2 | NO DIRECT REPLACEMENT | |
| 3TH4454-8EK6 | NO DIRECT REPLACEMENT | |
| 3TH4454-8EM2 | NO DIRECT REPLACEMENT | |
| 3TH4454-8EP6 | NO DIRECT REPLACEMENT | |
| 3TH4454-8EQ0 | NO DIRECT REPLACEMENT | |
| 3TH4454-8ES0 | NO DIRECT REPLACEMENT | |
| 3TH4844-0AV0 | NO DIRECT REPLACEMENT | |
| 3TH8004-0AB0 | 3RH1122-1AB00 + 3RH1911-1FA22 | |
| 3TH8004-0AC0 | 3RH1122-1AD00 + 3RH1911-1FA22 | |
| 3TH8004-0AC1 | 3RH1122-1AB00 + 3RH1911-1FA22 | |
| 3TH8004-0AC2 | 3RH1122-1AB00 + 3RH1911-1FA22 | |
| 3TH8004-0AD0 | 3RH1122-1AD00 + 3RH1911-1FA22 | |
| 3TH8004-0AD1 | 3RH1122-1AD00 + 3RH1911-1FA22 | |
| 3TH8004-0AE0 | NO DIRECT REPLACEMENT | |
| 3TH8004-0AF0 | 3RH1122-1AK60 + 3RH1911-1FA22 | |
| 3TH8004-0AG0 | 3RH1122-1AG00 + 3RH1911-1FA22 | |
| 3TH8004-0AG1 | 3RH1122-1AK60 + 3RH1911-1FA22 | |
| 3TH8004-0AH0 | 3RH1122-1AH00 + 3RH1911-1FA22 | |
| 3TH8004-0AJ1 | 3RH1122-1AK60 + 3RH1911-1FA22 | |
| 3TH8004-0AJ2 | 3RH1122-1AK60 + 3RH1911-1FA22 | |
| 3TH8004-0AK1 | 3RH1122-1AK60 + 3RH1911-1FA22 | |
| 3TH8004-0AK6 | 3RH1122-1AK60 + 3RH1911-1FA22 | |
| 3TH8004-0AL0 | 3RH1122-1AP60 + 3RH1911-1FA22 | |
| 3TH8004-0AL1 | 3RH1122-1AP60 + 3RH1911-1FA22 | |
| 3TH8004-0AM0 | 3RH1122-1AM20 + 3RH1911-1FA22 | |
| 3TH8004-0AM1 | 3RH1122-1AM20 + 3RH1911-1FA22 | |
| 3TH8004-0AM2 | 3RH1122-1AM20 + 3RH1911-1FA22 | |
| 3TH8004-0AN1 | 3RH1122-1AP60 + 3RH1911-1FA22 | |
| 3TH8004-0AP0 | 3RH1122-1AP60 + 3RH1911-1FA22 | |
| 3TH8004-0AP1 | 3RH1122-1AP60 + 3RH1911-1FA22 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TH8004-0AP6 | 3RH1122-1AP60 + 3RH1911-1FA22 | |
| 3TH8004-0AQ0 | 3RH1122-1AV00 + 3RH1911-1FA22 | |
| 3TH8004-0AR0 | 3RH1122-1AV60 + 3RH1911-1FA22 | |
| 3TH8004-0AR1 | 3RH1122-1AR60 + 3RH1911-1FA22 | |
| 3TH8004-0AS0 | 3RH1122-1AT60 + 3RH1911-1FA22 | |
| 3TH8004-0AS1 | 3RH1122-1AT60 + 3RH1911-1FA22 | |
| 3TH8004-0AU0 | 3RH1122-1AU60 + 3RH1911-1FA22 | |
| 3TH8004-0AV0 | 3RH1122-1AV00 + 3RH1911-1FA22 | |
| 3TH8004-0BA4 | 3RH1122-1BA40 + 3RH1911-1FA22 | |
| 3TH8004-0BB4 | 3RH1122-1BB40 + 3RH1911-1FA22 | |
| 3TH8004-0BC4 | 3RH1122-1BC40 + 3RH1911-1FA22 | |
| 3TH8004-0BD4 | 3RH1122-1BD40 + 3RH1911-1FA22 | |
| 3TH8004-0BE4 | 3RH1122-1BE40 + 3RH1911-1FA22 | |
| 3TH8004-0BF4 | 3RH1122-1BF40 + 3RH1911-1FA22 | |
| 3TH8004-0BG4 | 3RH1122-1BG40 + 3RH1911-1FA22 | |
| 3TH8004-0BK4 | NO DIRECT REPLACEMENT | |
| 3TH8004-0BM4 | 3RH1122-1BM40 + 3RH1911-1FA22 | |
| 3TH8004-0BN4 | NO DIRECT REPLACEMENT | |
| 3TH8004-0BP4 | 3RH1122-1BP40 + 3RH1911-1FA22 | |
| 3TH8004-0BQ4 | 3RH1122-1BP40 + 3RH1911-1FA22 | |
| 3TH8004-0BU4 | NO DIRECT REPLACEMENT | |
| 3TH8004-0BV4 | NO DIRECT REPLACEMENT | |
| 3TH8004-0BW4 | 3RH1122-1BW40 + 3RH1911-1FA22 | |
| 3TH8013-0AB0 | 3RH1122-1AB00 + 3RH1911-1FA22 | |
| 3TH8013-0AC0 | 3RH1122-1AD00 + 3RH1911-1FA22 | |
| 3TH8013-0AC1 | 3RH1122-1AB00 + 3RH1911-1FA22 | |
| 3TH8013-0AC2 | 3RH1122-1AB00 + 3RH1911-1FA22 | |
| 3TH8013-0AD0 | 3RH1122-1AD00 + 3RH1911-1FA22 | |
| 3TH8013-0AD1 | 3RH1122-1AD00 + 3RH1911-1FA22 | |
| 3TH8013-0AE0 | NO DIRECT REPLACEMENT | |
| 3TH8013-0AF0 | 3RH1122-1AK60 + 3RH1911-1FA22 | |
| 3TH8013-0AG0 | 3RH1122-1AG00 + 3RH1911-1FA22 | |
| 3TH8013-0AG1 | 3RH1122-1AK60 + 3RH1911-1FA22 | |
| 3TH8013-0AH0 | 3RH1122-1AH00 + 3RH1911-1FA22 | |
| 3TH8013-0AJ1 | 3RH1122-1AK60 + 3RH1911-1FA22 | |
| 3TH8013-0AJ2 | 3RH1122-1AK60 + 3RH1911-1FA22 | |
| 3TH8013-0AK1 | 3RH1122-1AK60 + 3RH1911-1FA22 | |
| 3TH8013-0AK6 | 3RH1122-1AK60 + 3RH1911-1FA22 | |
| 3TH8013-0AL0 | 3RH1122-1AP60 + 3RH1911-1FA22 | |
| 3TH8013-0AL1 | 3RH1122-1AP60 + 3RH1911-1FA22 | |
| 3TH8013-0AM0 | 3RH1122-1AM20 + 3RH1911-1FA22 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TH8013-0AM1 | 3RH1122-1AM20 + 3RH1911-1FA22 | |
| 3TH8013-0AM2 | 3RH1122-1AM20 + 3RH1911-1FA22 | |
| 3TH8013-0AN1 | 3RH1122-1AP60 + 3RH1911-1FA22 | |
| 3TH8013-0AP0 | 3RH1122-1AP60 + 3RH1911-1FA22 | |
| 3TH8013-0AP1 | 3RH1122-1AP60 + 3RH1911-1FA22 | |
| 3TH8013-0AP6 | 3RH1122-1AP60 + 3RH1911-1FA22 | |
| 3TH8013-0AQ0 | 3RH1122-1AV00 + 3RH1911-1FA22 | |
| 3TH8013-0AR0 | 3RH1122-1AV60 + 3RH1911-1FA22 | |
| 3TH8013-0AR1 | 3RH1122-1AR60 + 3RH1911-1FA22 | |
| 3TH8013-0AS0 | 3RH1122-1AT60 + 3RH1911-1FA22 | |
| 3TH8013-0AS1 | 3RH1122-1AT60 + 3RH1911-1FA22 | |
| 3TH8013-0AU0 | 3RH1122-1AU60 + 3RH1911-1FA22 | |
| 3TH8013-0AV0 | 3RH1122-1AV00 + 3RH1911-1FA22 | |
| 3TH8013-0BA4 | 3RH1122-1BA40 + 3RH1911-1FA22 | |
| 3TH8013-0BB4 | 3RH1122-1BB40 + 3RH1911-1FA22 | |
| 3TH8013-0BC4 | 3RH1122-1BC40 + 3RH1911-1FA22 | |
| 3TH8013-0BD4 | 3RH1122-1BD40 + 3RH1911-1FA22 | |
| 3TH8013-0BE4 | 3RH1122-1BE40 + 3RH1911-1FA22 | |
| 3TH8013-0BF4 | 3RH1122-1BF40 + 3RH1911-1FA22 | |
| 3TH8013-0BG4 | 3RH1122-1BG40 + 3RH1911-1FA22 | |
| 3TH8013-0BK4 | NO DIRECT REPLACEMENT | |
| 3TH8013-0BM4 | 3RH1122-1BM40 + 3RH1911-1FA22 | |
| 3TH8013-0BN4 | NO DIRECT REPLACEMENT | |
| 3TH8013-0BP4 | 3RH1122-1BP40 + 3RH1911-1FA22 | |
| 3TH8013-0BQ4 | 3RH1122-1BP40 + 3RH1911-1FA22 | |
| 3TH8013-0BU4 | NO DIRECT REPLACEMENT | |
| 3TH8013-0BV4 | NO DIRECT REPLACEMENT | |
| 3TH8013-0BW4 | 3RH1122-1BW40 + 3RH1911-1FA22 | |
| 3TH8017-0AM0 | 3RH1122-1AM20 | |
| 3TH8022-0AB0 | 3RH1122-1AB00 | |
| 3TH8022-0AC0 | 3RH1122-1AD00 | |
| 3TH8022-0AC1 | 3RH1122-1AB00 | |
| 3TH8022-0AC2 | 3RH1122-1AB00 | |
| 3TH8022-0AD0 | 3RH1122-1AD00 | |
| 3TH8022-0AD1 | 3RH1122-1AD00 | |
| 3TH8022-0AE0 | NO DIRECT REPLACEMENT | |
| 3TH8022-0AF0 | 3RH1122-1AK60 | |
| 3TH8022-0AG0 | 3RH1122-1AG00 | |
| 3TH8022-0AG1 | 3RH1122-1AK60 | |
| 3TH8022-0AH0 | 3RH1122-1AH00 | |
| 3TH8022-0AJ1 | 3RH1122-1AK60 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TH8022-0AJ2 | 3RH1122-1AK60 | |
| 3TH8022-0AK1 | 3RH1122-1AK60 | |
| 3TH8022-0AK6 | 3RH1122-1AK60 | |
| 3TH8022-0AL0 | 3RH1122-1AP60 | |
| 3TH8022-0AL1 | 3RH1122-1AP60 | |
| 3TH8022-0AM0 | 3RH1122-1AM20 | |
| 3TH8022-0AM1 | 3RH1122-1AM20 | |
| 3TH8022-0AM2 | 3RH1122-1AM20 | |
| 3TH8022-0AN1 | 3RH1122-1AP60 | |
| 3TH8022-0AP0 | 3RH1122-1AP60 | |
| 3TH8022-0AP1 | 3RH1122-1AP60 | |
| 3TH8022-0AP6 | 3RH1122-1AP60 | |
| 3TH8022-0AQ0 | 3RH1122-1AV00 | |
| 3TH8022-0AR0 | 3RH1122-1AV60 | |
| 3TH8022-0AR1 | 3RH1122-1AR60 | |
| 3TH8022-0AS0 | 3RH1122-1AT60 | |
| 3TH8022-0AS1 | 3RH1122-1AT60 | |
| 3TH8022-0AU0 | 3RH1122-1AU60 | |
| 3TH8022-0AV0 | 3RH1122-1AV00 | |
| 3TH8022-0BA4 | 3RH1122-1BA40 | |
| 3TH8022-0BB4 | 3RH1122-1BB40 | |
| 3TH8022-0BC4 | 3RH1122-1BC40 | |
| 3TH8022-0BD4 | 3RH1122-1BD40 | |
| 3TH8022-0BE4 | 3RH1122-1BE40 | |
| 3TH8022-0BF4 | 3RH1122-1BF40 | |
| 3TH8022-0BG4 | 3RH1122-1BG40 | |
| 3TH8022-0BK4 | NO DIRECT REPLACEMENT | |
| 3TH8022-0BM4 | 3RH1122-1BM40 | |
| 3TH8022-0BN4 | NO DIRECT REPLACEMENT | |
| 3TH8022-0BP4 | 3RH1122-1BP40 | |
| 3TH8022-0BQ4 | 3RH1122-1BP40 | |
| 3TH8022-0BU4 | NO DIRECT REPLACEMENT | |
| 3TH8022-0BV4 | NO DIRECT REPLACEMENT | |
| 3TH8022-0BW4 | 3RH1122-1BW40 | |
| 3TH8022-0BZ80 | NO DIRECT REPLACEMENT | |
| 3TH8022-0EG1 | 3RH1122-1AK60 | |
| 3TH8022-0EN1 | 3RH1122-1AP60 | |
| 3TH8022-3BB4 | 3RH1122-1BB40 | |
| 3TH8022-4BB4 | 3RH1122-1BB40 | |
| 3TH8022-6CC8 | NO DIRECT REPLACEMENT | |
| 3TH8031-0AB0 | 3RH1131-1AB00 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TH8031-0AC0 | 3RH1131-1AD00 | |
| 3TH8031-0AC1 | 3RH1131-1AB00 | |
| 3TH8031-0AC2 | 3RH1131-1AB00 | |
| 3TH8031-0AD0 | 3RH1131-1AD00 | |
| 3TH8031-0AD1 | 3RH1131-1AD00 | |
| 3TH8031-0AE0 | NO DIRECT REPLACEMENT | |
| 3TH8031-0AF0 | 3RH1131-1AK60 | |
| 3TH8031-0AG0 | 3RH1131-1AG00 | |
| 3TH8031-0AG1 | 3RH1131-1AK60 | |
| 3TH8031-0AG2 | 3RH1131-1AK60 | |
| 3TH8031-0AH0 | 3RH1131-1AH00 | |
| 3TH8031-0AJ1 | 3RH1131-1AK60 | |
| 3TH8031-0AJ2 | 3RH1131-1AK60 | |
| 3TH8031-0AK1 | 3RH1131-1AK60 | |
| 3TH8031-0AK6 | 3RH1131-1AK60 | |
| 3TH8031-0AL0 | 3RH1131-1AP60 | |
| 3TH8031-0AL1 | 3RH1131-1AP60 | |
| 3TH8031-0AM0 | 3RH1131-1AM20 | |
| 3TH8031-0AM1 | 3RH1131-1AM20 | |
| 3TH8031-0AM2 | 3RH1131-1AM20 | |
| 3TH8031-0AN1 | 3RH1131-1AP60 | |
| 3TH8031-0AP0 | 3RH1131-1AP60 | |
| 3TH8031-0AP1 | 3RH1131-1AP60 | |
| 3TH8031-0AP6 | 3RH1131-1AP60 | |
| 3TH8031-0AQ0 | 3RH1131-1AV00 | |
| 3TH8031-0AR0 | 3RH1131-1AV60 | |
| 3TH8031-0AR1 | 3RH1131-1AR60 | |
| 3TH8031-0AS0 | 3RH1131-1AT60 | |
| 3TH8031-0AS1 | 3RH1131-1AT60 | |
| 3TH8031-0AU0 | 3RH1131-1AU60 | |
| 3TH8031-0AV0 | 3RH1131-1AV00 | |
| 3TH8031-0BA4 | 3RH1131-1BA40 | |
| 3TH8031-0BB4 | 3RH1131-1BB40 | |
| 3TH8031-0BC4 | 3RH1131-1BC40 | |
| 3TH8031-0BD4 | 3RH1131-1BD40 | |
| 3TH8031-0BE4 | 3RH1131-1BE40 | |
| 3TH8031-0BF4 | 3RH1131-1BF40 | |
| 3TH8031-0BG4 | 3RH1131-1BG40 | |
| 3TH8031-0BK4 | NO DIRECT REPLACEMENT | |
| 3TH8031-0BM4 | 3RH1131-1BM40 | |
| 3TH8031-0BN4 | NO DIRECT REPLACEMENT | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TH8031-0BP4 | 3RH1131-1BP40 | |
| 3TH8031-0BQ4 | 3RH1131-1BP40 | |
| 3TH8031-0BU4 | NO DIRECT REPLACEMENT | |
| 3TH8031-0BV4 | NO DIRECT REPLACEMENT | |
| 3TH8031-0BW4 | 3RH1131-1BW40 | |
| 3TH8031-0EN1 | 3RH1131-1AP60 | |
| 3TH8031-6CC8 | NO DIRECT REPLACEMENT | |
| 3TH8040-0AB0 | 3RH1140-1AB00 | |
| 3TH8040-0AC0 | 3RH1140-1AD00 | |
| 3TH8040-0AC1 | 3RH1140-1AB00 | |
| 3TH8040-0AC2 | 3RH1140-1AB00 | |
| 3TH8040-0AD0 | 3RH1140-1AD00 | |
| 3TH8040-0AD1 | 3RH1140-1AD00 | |
| 3TH8040-0AE0 | NO DIRECT REPLACEMENT | |
| 3TH8040-0AF0 | 3RH1140-1AK60 | |
| 3TH8040-0AG0 | 3RH1140-1AG00 | |
| 3TH8040-0AG1 | 3RH1140-1AK60 | |
| 3TH8040-0AH0 | 3RH1140-1AH00 | |
| 3TH8040-0AJ1 | 3RH1140-1AK60 | |
| 3TH8040-0AJ2 | 3RH1140-1AK60 | |
| 3TH8040-0AK1 | 3RH1140-1AK60 | |
| 3TH8040-0AK6 | 3RH1140-1AK60 | |
| 3TH8040-0AL0 | 3RH1140-1AP60 | |
| 3TH8040-0AL1 | 3RH1140-1AP60 | |
| 3TH8040-0AM0 | 3RH1140-1AM20 | |
| 3TH8040-0AM1 | 3RH1140-1AM20 | |
| 3TH8040-0AM2 | 3RH1140-1AM20 | |
| 3TH8040-0AN1 | 3RH1140-1AP60 | |
| 3TH8040-0AP0 | 3RH1140-1AP60 | |
| 3TH8040-0AP1 | 3RH1140-1AP60 | |
| 3TH8040-0AP6 | 3RH1140-1AP60 | |
| 3TH8040-0AQ0 | 3RH1140-1AV00 | |
| 3TH8040-0AR0 | 3RH1140-1AV60 | |
| 3TH8040-0AR1 | 3RH1140-1AR60 | |
| 3TH8040-0AS0 | 3RH1140-1AT60 | |
| 3TH8040-0AS1 | 3RH1140-1AT60 | |
| 3TH8040-0AU0 | 3RH1140-1AU60 | |
| 3TH8040-0AV0 | 3RH1140-1AV00 | |
| 3TH8040-0BA4 | 3RH1140-1BA40 | |
| 3TH8040-0BB4 | 3RH1140-1BB40 | |
| 3TH8040-0BC4 | 3RH1140-1BC40 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TH8040-0BD4 | 3RH1140-1BD40 | |
| 3TH8040-0BE4 | 3RH1140-1BE40 | |
| 3TH8040-0BF4 | 3RH1140-1BF40 | |
| 3TH8040-0BG4 | 3RH1140-1BG40 | |
| 3TH8040-0BK4 | NO DIRECT REPLACEMENT | |
| 3TH8040-0BM4 | 3RH1140-1BM40 | |
| 3TH8040-0BN4 | NO DIRECT REPLACEMENT | |
| 3TH8040-0BP4 | 3RH1140-1BP40 | |
| 3TH8040-0BQ4 | 3RH1140-1BP40 | |
| 3TH8040-0BU4 | NO DIRECT REPLACEMENT | |
| 3TH8040-0BV4 | NO DIRECT REPLACEMENT | |
| 3TH8040-0BW4 | 3RH1140-1BW40 | |
| 3TH8040-0BZ74 | NO DIRECT REPLACEMENT | |
| 3TH8040-0BZ80 | NO DIRECT REPLACEMENT | |
| 3TH8040-0EN1 | 3RH1140-1AP60 | |
| 3TH8092-0AB0 | 3RH1122-1AB00 | |
| 3TH8092-0AC0 | 3RH1122-1AD00 | |
| 3TH8092-0AC1 | 3RH1122-1AB00 | |
| 3TH8092-0AC2 | 3RH1122-1AB00 | |
| 3TH8092-0AD0 | 3RH1122-1AD00 | |
| 3TH8092-0AD1 | 3RH1122-1AD00 | |
| 3TH8092-0AE0 | NO DIRECT REPLACEMENT | |
| 3TH8092-0AF0 | 3RH1122-1AK60 | |
| 3TH8092-0AG0 | 3RH1122-1AG00 | |
| 3TH8092-0AG1 | 3RH1122-1AK60 | |
| 3TH8092-0AH0 | 3RH1122-1AH00 | |
| 3TH8092-0AJ1 | 3RH1122-1AK60 | |
| 3TH8092-0AJ2 | 3RH1122-1AK60 | |
| 3TH8092-0AK1 | 3RH1122-1AK60 | |
| 3TH8092-0AK6 | 3RH1122-1AK60 | |
| 3TH8092-0AL0 | 3RH1122-1AP60 | |
| 3TH8092-0AL1 | 3RH1122-1AP60 | |
| 3TH8092-0AM0 | 3RH1122-1AM20 | |
| 3TH8092-0AM1 | 3RH1122-1AM20 | |
| 3TH8092-0AM2 | 3RH1122-1AM20 | |
| 3TH8092-0AN1 | 3RH1122-1AP60 | |
| 3TH8092-0AP0 | 3RH1122-1AP60 | |
| 3TH8092-0AP1 | 3RH1122-1AP60 | |
| 3TH8092-0AP6 | 3RH1122-1AP60 | |
| 3TH8092-0AQ0 | 3RH1122-1AV00 | |
| 3TH8092-0AR0 | 3RH1122-1AV60 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TH8092-0AR1 | 3RH1122-1AR60 | |
| 3TH8092-0AS0 | 3RH1122-1AT60 | |
| 3TH8092-0AS1 | 3RH1122-1AT60 | |
| 3TH8092-0AU0 | 3RH1122-1AU60 | |
| 3TH8092-0AV0 | 3RH1122-1AV00 | |
| 3TH8092-0BA4 | 3RH1122-1BA40 | |
| 3TH8092-0BB4 | 3RH1122-1BB40 | |
| 3TH8092-0BC4 | 3RH1122-1BC40 | |
| 3TH8092-0BD4 | 3RH1122-1BD40 | |
| 3TH8092-0BE4 | 3RH1122-1BE40 | |
| 3TH8092-0BF4 | 3RH1122-1BF40 | |
| 3TH8092-0BG4 | 3RH1122-1BG40 | |
| 3TH8092-0BK4 | NO DIRECT REPLACEMENT | |
| 3TH8092-0BM4 | 3RH1122-1BM40 | |
| 3TH8092-0BN4 | NO DIRECT REPLACEMENT | |
| 3TH8092-0BP4 | 3RH1122-1BP40 | |
| 3TH8092-0BQ4 | 3RH1122-1BP40 | |
| 3TH8092-0BU4 | NO DIRECT REPLACEMENT | |
| 3TH8092-0BV4 | NO DIRECT REPLACEMENT | |
| 3TH8092-0BW4 | 3RH1122-1BW40 | |
| 3TH8095-0AB0 | 3RH1131-1AB00 | |
| 3TH8095-0AC0 | 3RH1131-1AD00 | |
| 3TH8095-0AC1 | 3RH1131-1AB00 | |
| 3TH8095-0AC2 | 3RH1131-1AB00 | |
| 3TH8095-0AD0 | 3RH1131-1AD00 | |
| 3TH8095-0AD1 | 3RH1131-1AD00 | |
| 3TH8095-0AE0 | NO DIRECT REPLACEMENT | |
| 3TH8095-0AF0 | 3RH1131-1AK60 | |
| 3TH8095-0AG0 | 3RH1131-1AG00 | |
| 3TH8095-0AG1 | 3RH1131-1AK60 | |
| 3TH8095-0AH0 | 3RH1131-1AH00 | |
| 3TH8095-0AJ1 | 3RH1131-1AK60 | |
| 3TH8095-0AJ2 | 3RH1131-1AK60 | |
| 3TH8095-0AK1 | 3RH1131-1AK60 | |
| 3TH8095-0AK6 | 3RH1131-1AK60 | |
| 3TH8095-0AL0 | 3RH1131-1AP60 | |
| 3TH8095-0AL1 | 3RH1131-1AP60 | |
| 3TH8095-0AM0 | 3RH1131-1AM20 | |
| 3TH8095-0AM1 | 3RH1131-1AM20 | |
| 3TH8095-0AM2 | 3RH1131-1AM20 | |
| 3TH8095-0AN1 | 3RH1131-1AP60 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TH8095-0AP0 | 3RH1131-1AP60 | |
| 3TH8095-0AP1 | 3RH1131-1AP60 | |
| 3TH8095-0AP6 | 3RH1131-1AP60 | |
| 3TH8095-0AQ0 | 3RH1131-1AV00 | |
| 3TH8095-0AR0 | 3RH1131-1AV60 | |
| 3TH8095-0AR1 | 3RH1131-1AR60 | |
| 3TH8095-0AS0 | 3RH1131-1AT60 | |
| 3TH8095-0AS1 | 3RH1131-1AT60 | |
| 3TH8095-0AU0 | 3RH1131-1AU60 | |
| 3TH8095-0AV0 | 3RH1131-1AV00 | |
| 3TH8095-0BA4 | 3RH1131-1BA40 | |
| 3TH8095-0BB4 | 3RH1131-1BB40 | |
| 3TH8095-0BC4 | 3RH1131-1BC40 | |
| 3TH8095-0BD4 | 3RH1131-1BD40 | |
| 3TH8095-0BE4 | 3RH1131-1BE40 | |
| 3TH8095-0BF4 | 3RH1131-1BF40 | |
| 3TH8095-0BG4 | 3RH1131-1BG40 | |
| 3TH8095-0BK4 | NO DIRECT REPLACEMENT | |
| 3TH8095-0BM4 | 3RH1131-1BM40 | |
| 3TH8095-0BN4 | NO DIRECT REPLACEMENT | |
| 3TH8095-0BP4 | 3RH1131-1BP40 | |
| 3TH8095-0BQ4 | 3RH1131-1BP40 | |
| 3TH8095-0BU4 | NO DIRECT REPLACEMENT | |
| 3TH8095-0BV4 | NO DIRECT REPLACEMENT | |
| 3TH8095-0BW4 | 3RH1131-1BW40 | |
| 3TH8096-0AB0 | 3RH1122-1AB00 | |
| 3TH8096-0AC0 | 3RH1122-1AD00 | |
| 3TH8096-0AC1 | 3RH1122-1AB00 | |
| 3TH8096-0AC2 | 3RH1122-1AB00 | |
| 3TH8096-0AD0 | 3RH1122-1AD00 | |
| 3TH8096-0AD1 | 3RH1122-1AD00 | |
| 3TH8096-0AE0 | NO DIRECT REPLACEMENT | |
| 3TH8096-0AF0 | 3RH1122-1AK60 | |
| 3TH8096-0AG0 | 3RH1122-1AG00 | |
| 3TH8096-0AG1 | 3RH1122-1AK60 | |
| 3TH8096-0AH0 | 3RH1122-1AH00 | |
| 3TH8096-0AJ1 | 3RH1122-1AK60 | |
| 3TH8096-0AJ2 | 3RH1122-1AK60 | |
| 3TH8096-0AK1 | 3RH1122-1AK60 | |
| 3TH8096-0AK6 | 3RH1122-1AK60 | |
| 3TH8096-0AL0 | 3RH1122-1AP60 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TH8096-0AL1 | 3RH1122-1AP60 | |
| 3TH8096-0AM0 | 3RH1122-1AM20 | |
| 3TH8096-0AM1 | 3RH1122-1AM20 | |
| 3TH8096-0AM2 | 3RH1122-1AM20 | |
| 3TH8096-0AN1 | 3RH1122-1AP60 | |
| 3TH8096-0AP0 | 3RH1122-1AP60 | |
| 3TH8096-0AP1 | 3RH1122-1AP60 | |
| 3TH8096-0AP6 | 3RH1122-1AP60 | |
| 3TH8096-0AQ0 | 3RH1122-1AV00 | |
| 3TH8096-0AR0 | 3RH1122-1AV60 | |
| 3TH8096-0AR1 | 3RH1122-1AR60 | |
| 3TH8096-0AS0 | 3RH1122-1AT60 | |
| 3TH8096-0AS1 | 3RH1122-1AT60 | |
| 3TH8096-0AU0 | 3RH1122-1AU60 | |
| 3TH8096-0AV0 | 3RH1122-1AV00 | |
| 3TH8096-0BA4 | 3RH1122-1BA40 | |
| 3TH8096-0BB4 | 3RH1122-1BB40 | |
| 3TH8096-0BC4 | 3RH1122-1BC40 | |
| 3TH8096-0BD4 | 3RH1122-1BD40 | |
| 3TH8096-0BE4 | 3RH1122-1BE40 | |
| 3TH8096-0BF4 | 3RH1122-1BF40 | |
| 3TH8096-0BG4 | 3RH1122-1BG40 | |
| 3TH8096-0BK4 | NO DIRECT REPLACEMENT | |
| 3TH8096-0BM4 | 3RH1122-1BM40 | |
| 3TH8096-0BN4 | NO DIRECT REPLACEMENT | |
| 3TH8096-0BP4 | 3RH1122-1BP40 | |
| 3TH8096-0BQ4 | 3RH1122-1BP40 | |
| 3TH8096-0BU4 | NO DIRECT REPLACEMENT | |
| 3TH8096-0BV4 | NO DIRECT REPLACEMENT | |
| 3TH8096-0BW4 | 3RH1122-1BW40 | |
| 3TH8226-0AG1 | 3RH1140-1AK60 + 3RH1911-1FA31 | |
| 3TH8226-0AJ1 | 3RH1140-1AK60 + 3RH1911-1FA31 | |
| 3TH8227-0AG1 | 3RH1131-1AK60 + 3RH1911-1FA22 | |
| 3TH8227-0AM0 | 3RH1131-1AM20 + 3RH1911-1FA22 | |
| 3TH8243-2EK1 | 3RH1140-1AK60 + 3RH1911-1FA31 | |
| 3TH8244-0AB0 | 3RH1122-1AB00 + 3RH1911-1FA22 | |
| 3TH8244-0AC0 | 3RH1122-1AD00 + 3RH1911-1FA22 | |
| 3TH8244-0AC1 | 3RH1122-1AB00 + 3RH1911-1FA22 | |
| 3TH8244-0AC2 | 3RH1122-1AB00 + 3RH1911-1FA22 | |
| 3TH8244-0AD0 | 3RH1122-1AD00 + 3RH1911-1FA22 | |
| 3TH8244-0AD1 | 3RH1122-1AD00 + 3RH1911-1FA22 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TH8244-0AE0 | NO DIRECT REPLACEMENT | |
| 3TH8244-0AF0 | 3RH1122-1AK60 + 3RH1911-1FA22 | |
| 3TH8244-0AG0 | 3RH1122-1AG00 + 3RH1911-1FA22 | |
| 3TH8244-0AG1 | 3RH1122-1AK60 + 3RH1911-1FA22 | |
| 3TH8244-0AH0 | 3RH1122-1AH00 + 3RH1911-1FA22 | |
| 3TH8244-0AJ1 | 3RH1122-1AK60 + 3RH1911-1FA22 | |
| 3TH8244-0AJ2 | 3RH1122-1AK60 + 3RH1911-1FA22 | |
| 3TH8244-0AK1 | 3RH1122-1AK60 + 3RH1911-1FA22 | |
| 3TH8244-0AK6 | 3RH1122-1AK60 + 3RH1911-1FA22 | |
| 3TH8244-0AL0 | 3RH1122-1AP60 + 3RH1911-1FA22 | |
| 3TH8244-0AL1 | 3RH1122-1AP60 + 3RH1911-1FA22 | |
| 3TH8244-0AM0 | 3RH1122-1AM20 + 3RH1911-1FA22 | |
| 3TH8244-0AM1 | 3RH1122-1AM20 + 3RH1911-1FA22 | |
| 3TH8244-0AM2 | 3RH1122-1AM20 + 3RH1911-1FA22 | |
| 3TH8244-0AN1 | 3RH1122-1AP60 + 3RH1911-1FA22 | |
| 3TH8244-0AP0 | 3RH1122-1AP60 + 3RH1911-1FA22 | |
| 3TH8244-0AP1 | 3RH1122-1AP60 + 3RH1911-1FA22 | |
| 3TH8244-0AP6 | 3RH1122-1AP60 + 3RH1911-1FA22 | |
| 3TH8244-0AQ0 | 3RH1122-1AV00 + 3RH1911-1FA22 | |
| 3TH8244-0AR0 | 3RH1122-1AV60 + 3RH1911-1FA22 | |
| 3TH8244-0AR1 | 3RH1122-1AR60 + 3RH1911-1FA22 | |
| 3TH8244-0AS0 | 3RH1122-1AT60 + 3RH1911-1FA22 | |
| 3TH8244-0AS1 | 3RH1122-1AT60 + 3RH1911-1FA22 | |
| 3TH8244-0AU0 | 3RH1122-1AU60 + 3RH1911-1FA22 | |
| 3TH8244-0AV0 | 3RH1122-1AV00 + 3RH1911-1FA22 | |
| 3TH8244-0BA4 | 3RH1122-1BA40 + 3RH1911-1FA22 | |
| 3TH8244-0BB4 | 3RH1122-1BB40 + 3RH1911-1FA22 | |
| 3TH8244-0BC4 | 3RH1122-1BC40 + 3RH1911-1FA22 | |
| 3TH8244-0BD4 | 3RH1122-1BD40 + 3RH1911-1FA22 | |
| 3TH8244-0BE4 | 3RH1122-1BE40 + 3RH1911-1FA22 | |
| 3TH8244-0BF4 | 3RH1122-1BF40 + 3RH1911-1FA22 | |
| 3TH8244-0BG4 | 3RH1122-1BG40 + 3RH1911-1FA22 | |
| 3TH8244-0BK4 | NO DIRECT REPLACEMENT | |
| 3TH8244-0BM4 | 3RH1122-1BM40 + 3RH1911-1FA22 | |
| 3TH8244-0BN4 | NO DIRECT REPLACEMENT | |
| 3TH8244-0BP4 | 3RH1122-1BP40 + 3RH1911-1FA22 | |
| 3TH8244-0BQ4 | 3RH1122-1BP40 + 3RH1911-1FA22 | |
| 3TH8244-0BU4 | NO DIRECT REPLACEMENT | |
| 3TH8244-0BV4 | NO DIRECT REPLACEMENT | |
| 3TH8244-0BW4 | 3RH1122-1BW40 + 3RH1911-1FA22 | |
| 3TH8244-0EG1 | 3RH1122-1AK60 + 3RH1911-1FA22 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TH8244-0EN1 | 3RH1122-1AP60 + 3RH1911-1FA22 | |
| 3TH8244-0FP4 | 3RH1122-1BP40 + SURGE | |
| 3TH8244-6CC8 | NO DIRECT REPLACEMENT | |
| 3TH8252-2EK1 | 3RH1140-1AK60 + 3RH1911-1FA22 | |
| 3TH8253-0AB0 | 3RH1131-1AB00 + 3RH1911-1FA22 | |
| 3TH8253-0AC0 | 3RH1131-1AD00 + 3RH1911-1FA22 | |
| 3TH8253-0AC1 | 3RH1131-1AB00 + 3RH1911-1FA22 | |
| 3TH8253-0AC2 | 3RH1131-1AB00 + 3RH1911-1FA22 | |
| 3TH8253-0AD0 | 3RH1131-1AD00 + 3RH1911-1FA22 | |
| 3TH8253-0AD1 | 3RH1131-1AD00 + 3RH1911-1FA22 | |
| 3TH8253-0AE0 | NO DIRECT REPLACEMENT | |
| 3TH8253-0AF0 | 3RH1131-1AK60 + 3RH1911-1FA22 | |
| 3TH8253-0AG0 | 3RH1131-1AG00 + 3RH1911-1FA22 | |
| 3TH8253-0AG1 | 3RH1131-1AK60 + 3RH1911-1FA22 | |
| 3TH8253-0AH0 | 3RH1131-1AH00 + 3RH1911-1FA22 | |
| 3TH8253-0AJ1 | 3RH1131-1AK60 + 3RH1911-1FA22 | |
| 3TH8253-0AJ2 | 3RH1131-1AK60 + 3RH1911-1FA22 | |
| 3TH8253-0AK1 | 3RH1131-1AK60 + 3RH1911-1FA22 | |
| 3TH8253-0AK6 | 3RH1131-1AK60 + 3RH1911-1FA22 | |
| 3TH8253-0AL0 | 3RH1131-1AP60 + 3RH1911-1FA22 | |
| 3TH8253-0AL1 | 3RH1131-1AP60 + 3RH1911-1FA22 | |
| 3TH8253-0AM0 | 3RH1131-1AM20 + 3RH1911-1FA22 | |
| 3TH8253-0AM1 | 3RH1131-1AM20 + 3RH1911-1FA22 | |
| 3TH8253-0AM2 | 3RH1131-1AM20 + 3RH1911-1FA22 | |
| 3TH8253-0AN1 | 3RH1131-1AP60 + 3RH1911-1FA22 | |
| 3TH8253-0AP0 | 3RH1131-1AP60 + 3RH1911-1FA22 | |
| 3TH8253-0AP1 | 3RH1131-1AP60 + 3RH1911-1FA22 | |
| 3TH8253-0AP6 | 3RH1131-1AP60 + 3RH1911-1FA22 | |
| 3TH8253-0AQ0 | 3RH1131-1AV00 + 3RH1911-1FA22 | |
| 3TH8253-0AR0 | 3RH1131-1AV60 + 3RH1911-1FA22 | |
| 3TH8253-0AR1 | 3RH1131-1AR60 + 3RH1911-1FA22 | |
| 3TH8253-0AS0 | 3RH1131-1AT60 + 3RH1911-1FA22 | |
| 3TH8253-0AS1 | 3RH1131-1AT60 + 3RH1911-1FA22 | |
| 3TH8253-0AU0 | 3RH1131-1AU60 + 3RH1911-1FA22 | |
| 3TH8253-0AV0 | 3RH1131-1AV00 + 3RH1911-1FA22 | |
| 3TH8253-0BA4 | 3RH1131-1BA40 + 3RH1911-1FA22 | |
| 3TH8253-0BB4 | 3RH1131-1BB40 + 3RH1911-1FA22 | |
| 3TH8253-0BC4 | 3RH1131-1BC40 + 3RH1911-1FA22 | |
| 3TH8253-0BD4 | 3RH1131-1BD40 + 3RH1911-1FA22 | |
| 3TH8253-0BE4 | 3RH1131-1BE40 + 3RH1911-1FA22 | |
| 3TH8253-0BF4 | 3RH1131-1BF40 + 3RH1911-1FA22 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TH8253-0BG4 | 3RH1131-1BG40 + 3RH1911-1FA22 | |
| 3TH8253-0BK4 | NO DIRECT REPLACEMENT | |
| 3TH8253-0BM4 | 3RH1131-1BM40 + 3RH1911-1FA22 | |
| 3TH8253-0BN4 | NO DIRECT REPLACEMENT | |
| 3TH8253-0BP4 | 3RH1131-1BP40 + 3RH1911-1FA22 | |
| 3TH8253-0BQ4 | 3RH1131-1BP40 + 3RH1911-1FA22 | |
| 3TH8253-0BU4 | NO DIRECT REPLACEMENT | |
| 3TH8253-0BV4 | NO DIRECT REPLACEMENT | |
| 3TH8253-0BW4 | 3RH1131-1BW40 + 3RH1911-1FA22 | |
| 3TH8262-0AB0 | 3RH1140-1AB00 + 3RH1911-1FA22 | |
| 3TH8262-0AC0 | 3RH1140-1AD00 + 3RH1911-1FA22 | |
| 3TH8262-0AC1 | 3RH1140-1AB00 + 3RH1911-1FA22 | |
| 3TH8262-0AC2 | 3RH1140-1AB00 + 3RH1911-1FA22 | |
| 3TH8262-0AD0 | 3RH1140-1AD00 + 3RH1911-1FA22 | |
| 3TH8262-0AD1 | 3RH1140-1AD00 + 3RH1911-1FA22 | |
| 3TH8262-0AE0 | NO DIRECT REPLACEMENT | |
| 3TH8262-0AF0 | 3RH1140-1AK60 + 3RH1911-1FA22 | |
| 3TH8262-0AG0 | 3RH1140-1AG00 + 3RH1911-1FA22 | |
| 3TH8262-0AG1 | 3RH1140-1AK60 + 3RH1911-1FA22 | |
| 3TH8262-0AH0 | 3RH1140-1AH00 + 3RH1911-1FA22 | |
| 3TH8262-0AJ1 | 3RH1140-1AK60 + 3RH1911-1FA22 | |
| 3TH8262-0AJ2 | 3RH1140-1AK60 + 3RH1911-1FA22 | |
| 3TH8262-0AK1 | 3RH1140-1AK60 + 3RH1911-1FA22 | |
| 3TH8262-0AK6 | 3RH1140-1AK60 + 3RH1911-1FA22 | |
| 3TH8262-0AL0 | 3RH1140-1AP60 + 3RH1911-1FA22 | |
| 3TH8262-0AL1 | 3RH1140-1AP60 + 3RH1911-1FA22 | |
| 3TH8262-0AM0 | 3RH1140-1AM20 + 3RH1911-1FA22 | |
| 3TH8262-0AM1 | 3RH1140-1AM20 + 3RH1911-1FA22 | |
| 3TH8262-0AM2 | 3RH1140-1AM20 + 3RH1911-1FA22 | |
| 3TH8262-0AN1 | 3RH1140-1AP60 + 3RH1911-1FA22 | |
| 3TH8262-0AP0 | 3RH1140-1AP60 + 3RH1911-1FA22 | |
| 3TH8262-0AP1 | 3RH1140-1AP60 + 3RH1911-1FA22 | |
| 3TH8262-0AP6 | 3RH1140-1AP60 + 3RH1911-1FA22 | |
| 3TH8262-0AQ0 | 3RH1140-1AV00 + 3RH1911-1FA22 | |
| 3TH8262-0AR0 | 3RH1140-1AV60 + 3RH1911-1FA22 | |
| 3TH8262-0AR1 | 3RH1140-1AR60 + 3RH1911-1FA22 | |
| 3TH8262-0AS0 | 3RH1140-1AT60 + 3RH1911-1FA22 | |
| 3TH8262-0AS1 | 3RH1140-1AT60 + 3RH1911-1FA22 | |
| 3TH8262-0AU0 | 3RH1140-1AU60 + 3RH1911-1FA22 | |
| 3TH8262-0AV0 | 3RH1140-1AV00 + 3RH1911-1FA22 | |
| 3TH8262-0BA4 | 3RH1140-1BA40 + 3RH1911-1FA22 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TH8262-0BB4 | 3RH1140-1BB40 + 3RH1911-1FA22 | |
| 3TH8262-0BC4 | 3RH1140-1BC40 + 3RH1911-1FA22 | |
| 3TH8262-0BD4 | 3RH1140-1BD40 + 3RH1911-1FA22 | |
| 3TH8262-0BE4 | 3RH1140-1BE40 + 3RH1911-1FA22 | |
| 3TH8262-0BF4 | 3RH1140-1BF40 + 3RH1911-1FA22 | |
| 3TH8262-0BG4 | 3RH1140-1BG40 + 3RH1911-1FA22 | |
| 3TH8262-0BK4 | NO DIRECT REPLACEMENT | |
| 3TH8262-0BM4 | 3RH1140-1BM40 + 3RH1911-1FA22 | |
| 3TH8262-0BN4 | NO DIRECT REPLACEMENT | |
| 3TH8262-0BP4 | 3RH1140-1BP40 + 3RH1911-1FA22 | |
| 3TH8262-0BQ4 | 3RH1140-1BP40 + 3RH1911-1FA22 | |
| 3TH8262-0BU4 | NO DIRECT REPLACEMENT | |
| 3TH8262-0BV4 | NO DIRECT REPLACEMENT | |
| 3TH8262-0BW4 | 3RH1140-1BW40 + 3RH1911-1FA22 | |
| 3TH8262-0BZ80 | NO DIRECT REPLACEMENT | |
| 3TH8262-0BZ9 | NO DIRECT REPLACEMENT | |
| 3TH8262-6CC8 | NO DIRECT REPLACEMENT | |
| 3TH8271-0AB0 | 3RH1140-1AB00 + 3RH1911-1FA31 | |
| 3TH8271-0AC0 | 3RH1140-1AD00 + 3RH1911-1FA31 | |
| 3TH8271-0AC1 | 3RH1140-1AB00 + 3RH1911-1FA31 | |
| 3TH8271-0AC2 | 3RH1140-1AB00 + 3RH1911-1FA31 | |
| 3TH8271-0AD0 | 3RH1140-1AD00 + 3RH1911-1FA31 | |
| 3TH8271-0AD1 | 3RH1140-1AD00 + 3RH1911-1FA31 | |
| 3TH8271-0AE0 | NO DIRECT REPLACEMENT | |
| 3TH8271-0AF0 | 3RH1140-1AK60 + 3RH1911-1FA31 | |
| 3TH8271-0AG0 | 3RH1140-1AG00 + 3RH1911-1FA31 | |
| 3TH8271-0AG1 | 3RH1140-1AK60 + 3RH1911-1FA31 | |
| 3TH8271-0AH0 | 3RH1140-1AH00 + 3RH1911-1FA31 | |
| 3TH8271-0AJ1 | 3RH1140-1AK60 + 3RH1911-1FA31 | |
| 3TH8271-0AJ2 | 3RH1140-1AK60 + 3RH1911-1FA31 | |
| 3TH8271-0AK1 | 3RH1140-1AK60 + 3RH1911-1FA31 | |
| 3TH8271-0AK6 | 3RH1140-1AK60 + 3RH1911-1FA31 | |
| 3TH8271-0AL0 | 3RH1140-1AP60 + 3RH1911-1FA31 | |
| 3TH8271-0AL1 | 3RH1140-1AP60 + 3RH1911-1FA31 | |
| 3TH8271-0AM0 | 3RH1140-1AM20 + 3RH1911-1FA31 | |
| 3TH8271-0AM1 | 3RH1140-1AM20 + 3RH1911-1FA31 | |
| 3TH8271-0AM2 | 3RH1140-1AM20 + 3RH1911-1FA31 | |
| 3TH8271-0AN1 | 3RH1140-1AP60 + 3RH1911-1FA31 | |
| 3TH8271-0AP0 | 3RH1140-1AP60 + 3RH1911-1FA31 | |
| 3TH8271-0AP1 | 3RH1140-1AP60 + 3RH1911-1FA31 | |
| 3TH8271-0AP6 | 3RH1140-1AP60 + 3RH1911-1FA31 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TH8271-0AQ0 | 3RH1140-1AV00 + 3RH1911-1FA31 | |
| 3TH8271-0AR0 | 3RH1140-1AV60 + 3RH1911-1FA31 | |
| 3TH8271-0AR1 | 3RH1140-1AR60 + 3RH1911-1FA31 | |
| 3TH8271-0AS0 | 3RH1140-1AT60 + 3RH1911-1FA31 | |
| 3TH8271-0AS1 | 3RH1140-1AT60 + 3RH1911-1FA31 | |
| 3TH8271-0AU0 | 3RH1140-1AU60 + 3RH1911-1FA31 | |
| 3TH8271-0AV0 | 3RH1140-1AV00 + 3RH1911-1FA31 | |
| 3TH8271-0BA4 | 3RH1140-1BA40 + 3RH1911-1FA31 | |
| 3TH8271-0BB4 | 3RH1140-1BB40 + 3RH1911-1FA31 | |
| 3TH8271-0BC4 | 3RH1140-1BC40 + 3RH1911-1FA31 | |
| 3TH8271-0BD4 | 3RH1140-1BD40 + 3RH1911-1FA31 | |
| 3TH8271-0BE4 | 3RH1140-1BE40 + 3RH1911-1FA31 | |
| 3TH8271-0BF4 | 3RH1140-1BF40 + 3RH1911-1FA31 | |
| 3TH8271-0BG4 | 3RH1140-1BG40 + 3RH1911-1FA31 | |
| 3TH8271-0BK4 | NO DIRECT REPLACEMENT | |
| 3TH8271-0BM4 | 3RH1140-1BM40 + 3RH1911-1FA31 | |
| 3TH8271-0BN4 | NO DIRECT REPLACEMENT | |
| 3TH8271-0BP4 | 3RH1140-1BP40 + 3RH1911-1FA31 | |
| 3TH8271-0BQ4 | 3RH1140-1BP40 + 3RH1911-1FA31 | |
| 3TH8271-0BU4 | NO DIRECT REPLACEMENT | |
| 3TH8271-0BV4 | NO DIRECT REPLACEMENT | |
| 3TH8271-0BW4 | 3RH1140-1BW40 + 3RH1911-1FA31 | |
| 3TH8271-0FB4 | 3RH1140-1BB40 + SURGE | |
| 3TH8271-3FB4 | 3RH1140-1BB40 + SURGE | |
| 3TH8280-0AB0 | 3RH1140-1AB00 + 3RH1911-1FA40 | |
| 3TH8280-0AC0 | 3RH1140-1AD00 + 3RH1911-1FA40 | |
| 3TH8280-0AC1 | 3RH1140-1AB00 + 3RH1911-1FA40 | |
| 3TH8280-0AC2 | 3RH1140-1AB00 + 3RH1911-1FA40 | |
| 3TH8280-0AD0 | 3RH1140-1AD00 + 3RH1911-1FA40 | |
| 3TH8280-0AD1 | 3RH1140-1AD00 + 3RH1911-1FA40 | |
| 3TH8280-0AE0 | NO DIRECT REPLACEMENT | |
| 3TH8280-0AF0 | 3RH1140-1AK60 + 3RH1911-1FA40 | |
| 3TH8280-0AG0 | 3RH1140-1AG00 + 3RH1911-1FA40 | |
| 3TH8280-0AG1 | 3RH1140-1AK60 + 3RH1911-1FA40 | |
| 3TH8280-0AH0 | 3RH1140-1AH00 + 3RH1911-1FA40 | |
| 3TH8280-0AJ1 | 3RH1140-1AK60 + 3RH1911-1FA40 | |
| 3TH8280-0AJ2 | 3RH1140-1AK60 + 3RH1911-1FA40 | |
| 3TH8280-0AK1 | 3RH1140-1AK60 + 3RH1911-1FA40 | |
| 3TH8280-0AK6 | 3RH1140-1AK60 + 3RH1911-1FA40 | |
| 3TH8280-0AL0 | 3RH1140-1AP60 + 3RH1911-1FA40 | |
| 3TH8280-0AL1 | 3RH1140-1AP60 + 3RH1911-1FA40 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TH8280-0AM0 | 3RH1140-1AM20 + 3RH1911-1FA40 | |
| 3TH8280-0AM1 | 3RH1140-1AM20 + 3RH1911-1FA40 | |
| 3TH8280-0AM2 | 3RH1140-1AM20 + 3RH1911-1FA40 | |
| 3TH8280-0AN1 | 3RH1140-1AP60 + 3RH1911-1FA40 | |
| 3TH8280-0AP0 | 3RH1140-1AP60 + 3RH1911-1FA40 | |
| 3TH8280-0AP1 | 3RH1140-1AP60 + 3RH1911-1FA40 | |
| 3TH8280-0AP6 | 3RH1140-1AP60 + 3RH1911-1FA40 | |
| 3TH8280-0AQ0 | 3RH1140-1AV00 + 3RH1911-1FA40 | |
| 3TH8280-0AR0 | 3RH1140-1AV60 + 3RH1911-1FA40 | |
| 3TH8280-0AR1 | 3RH1140-1AR60 + 3RH1911-1FA40 | |
| 3TH8280-0AS0 | 3RH1140-1AT60 + 3RH1911-1FA40 | |
| 3TH8280-0AS1 | 3RH1140-1AT60 + 3RH1911-1FA40 | |
| 3TH8280-0AU0 | 3RH1140-1AU60 + 3RH1911-1FA40 | |
| 3TH8280-0AV0 | 3RH1140-1AV00 + 3RH1911-1FA40 | |
| 3TH8280-0BA4 | 3RH1140-1BA40 + 3RH1911-1FA40 | |
| 3TH8280-0BB4 | 3RH1140-1BB40 + 3RH1911-1FA40 | |
| 3TH8280-0BC4 | 3RH1140-1BC40 + 3RH1911-1FA40 | |
| 3TH8280-0BD4 | 3RH1140-1BD40 + 3RH1911-1FA40 | |
| 3TH8280-0BE4 | 3RH1140-1BE40 + 3RH1911-1FA40 | |
| 3TH8280-0BF4 | 3RH1140-1BF40 + 3RH1911-1FA40 | |
| 3TH8280-0BG4 | 3RH1140-1BG40 + 3RH1911-1FA40 | |
| 3TH8280-0BK4 | NO DIRECT REPLACEMENT | |
| 3TH8280-0BM4 | 3RH1140-1BM40 + 3RH1911-1FA40 | |
| 3TH8280-0BN4 | NO DIRECT REPLACEMENT | |
| 3TH8280-0BP4 | 3RH1140-1BP40 + 3RH1911-1FA40 | |
| 3TH8280-0BQ4 | 3RH1140-1BP40 + 3RH1911-1FA40 | |
| 3TH8280-0BU4 | NO DIRECT REPLACEMENT | |
| 3TH8280-0BV4 | NO DIRECT REPLACEMENT | |
| 3TH8280-0BW4 | 3RH1140-1BW40 + 3RH1911-1FA40 | |
| 3TH8280-0EJ1 | 3RH1140-1AK60 + 3RH1911-1FA40 | |
| 3TH8280-0EN1 | 3RH1140-1AP60 + 3RH1911-1FA40 | |
| 3TH8280-3FG4 | 3RH1140-1BG40 + SURGE | |
| 3TH8293-0AB0 | 3RH1122-1AB00 + 3RH1911-1FA22 | |
| 3TH8293-0AC0 | 3RH1122-1AD00 + 3RH1911-1FA22 | |
| 3TH8293-0AC1 | 3RH1122-1AB00 + 3RH1911-1FA22 | |
| 3TH8293-0AC2 | 3RH1122-1AB00 + 3RH1911-1FA22 | |
| 3TH8293-0AD0 | 3RH1122-1AD00 + 3RH1911-1FA22 | |
| 3TH8293-0AD1 | 3RH1122-1AD00 + 3RH1911-1FA22 | |
| 3TH8293-0AE0 | NO DIRECT REPLACEMENT | |
| 3TH8293-0AF0 | 3RH1122-1AK60 + 3RH1911-1FA22 | |
| 3TH8293-0AG0 | 3RH1122-1AG00 + 3RH1911-1FA22 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TH8293-0AG1 | 3RH1122-1AK60 + 3RH1911-1FA22 | |
| 3TH8293-0AH0 | 3RH1122-1AH00 + 3RH1911-1FA22 | |
| 3TH8293-0AJ1 | 3RH1122-1AK60 + 3RH1911-1FA22 | |
| 3TH8293-0AJ2 | 3RH1122-1AK60 + 3RH1911-1FA22 | |
| 3TH8293-0AK1 | 3RH1122-1AK60 + 3RH1911-1FA22 | |
| 3TH8293-0AK6 | 3RH1122-1AK60 + 3RH1911-1FA22 | |
| 3TH8293-0AL0 | 3RH1122-1AP60 + 3RH1911-1FA22 | |
| 3TH8293-0AL1 | 3RH1122-1AP60 + 3RH1911-1FA22 | |
| 3TH8293-0AM0 | 3RH1122-1AM20 + 3RH1911-1FA22 | |
| 3TH8293-0AM1 | 3RH1122-1AM20 + 3RH1911-1FA22 | |
| 3TH8293-0AM2 | 3RH1122-1AM20 + 3RH1911-1FA22 | |
| 3TH8293-0AN1 | 3RH1122-1AP60 + 3RH1911-1FA22 | |
| 3TH8293-0AP0 | 3RH1122-1AP60 + 3RH1911-1FA22 | |
| 3TH8293-0AP1 | 3RH1122-1AP60 + 3RH1911-1FA22 | |
| 3TH8293-0AP6 | 3RH1122-1AP60 + 3RH1911-1FA22 | |
| 3TH8293-0AQ0 | 3RH1122-1AV00 + 3RH1911-1FA22 | |
| 3TH8293-0AR0 | 3RH1122-1AV60 + 3RH1911-1FA22 | |
| 3TH8293-0AR1 | 3RH1122-1AR60 + 3RH1911-1FA22 | |
| 3TH8293-0AS0 | 3RH1122-1AT60 + 3RH1911-1FA22 | |
| 3TH8293-0AS1 | 3RH1122-1AT60 + 3RH1911-1FA22 | |
| 3TH8293-0AU0 | 3RH1122-1AU60 + 3RH1911-1FA22 | |
| 3TH8293-0AV0 | 3RH1122-1AV00 + 3RH1911-1FA22 | |
| 3TH8293-0BA4 | 3RH1122-1BA40 + 3RH1911-1FA22 | |
| 3TH8293-0BB4 | 3RH1122-1BB40 + 3RH1911-1FA22 | |
| 3TH8293-0BC4 | 3RH1122-1BC40 + 3RH1911-1FA22 | |
| 3TH8293-0BD4 | 3RH1122-1BD40 + 3RH1911-1FA22 | |
| 3TH8293-0BE4 | 3RH1122-1BE40 + 3RH1911-1FA22 | |
| 3TH8293-0BF4 | 3RH1122-1BF40 + 3RH1911-1FA22 | |
| 3TH8293-0BG4 | 3RH1122-1BG40 + 3RH1911-1FA22 | |
| 3TH8293-0BK4 | NO DIRECT REPLACEMENT | |
| 3TH8293-0BM4 | 3RH1122-1BM40 + 3RH1911-1FA22 | |
| 3TH8293-0BN4 | NO DIRECT REPLACEMENT | |
| 3TH8293-0BP4 | 3RH1122-1BP40 + 3RH1911-1FA22 | |
| 3TH8293-0BQ4 | 3RH1122-1BP40 + 3RH1911-1FA22 | |
| 3TH8293-0BU4 | NO DIRECT REPLACEMENT | |
| 3TH8293-0BV4 | NO DIRECT REPLACEMENT | |
| 3TH8293-0BW4 | 3RH1122-1BW40 + 3RH1911-1FA22 | |
| 3TH8293-0EG1 | 3RH1122-1AK60 + 3RH1911-1FA22 | |
| 3TH8297-0AG1 | 3RH1122-1AK60 + 3RH1911-1FA22 | |
| 3TH8310-0AB0 | NO DIRECT REPLACEMENT | |
| 3TH8310-0AC0 | NO DIRECT REPLACEMENT | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TH8310-0AC1 | NO DIRECT REPLACEMENT | |
| 3TH8310-0AC2 | NO DIRECT REPLACEMENT | |
| 3TH8310-0AD0 | NO DIRECT REPLACEMENT | |
| 3TH8310-0AD1 | NO DIRECT REPLACEMENT | |
| 3TH8310-0AE0 | NO DIRECT REPLACEMENT | |
| 3TH8310-0AF0 | NO DIRECT REPLACEMENT | |
| 3TH8310-0AG0 | NO DIRECT REPLACEMENT | |
| 3TH8310-0AG1 | NO DIRECT REPLACEMENT | |
| 3TH8310-0AH0 | NO DIRECT REPLACEMENT | |
| 3TH8310-0AJ1 | NO DIRECT REPLACEMENT | |
| 3TH8310-0AJ2 | NO DIRECT REPLACEMENT | |
| 3TH8310-0AK1 | NO DIRECT REPLACEMENT | |
| 3TH8310-0AK6 | NO DIRECT REPLACEMENT | |
| 3TH8310-0AL0 | NO DIRECT REPLACEMENT | |
| 3TH8310-0AL1 | NO DIRECT REPLACEMENT | |
| 3TH8310-0AM0 | NO DIRECT REPLACEMENT | |
| 3TH8310-0AM1 | NO DIRECT REPLACEMENT | |
| 3TH8310-0AM2 | NO DIRECT REPLACEMENT | |
| 3TH8310-0AN1 | NO DIRECT REPLACEMENT | |
| 3TH8310-0AP0 | NO DIRECT REPLACEMENT | |
| 3TH8310-0AP1 | NO DIRECT REPLACEMENT | |
| 3TH8310-0AP6 | NO DIRECT REPLACEMENT | |
| 3TH8310-0AQ0 | NO DIRECT REPLACEMENT | |
| 3TH8310-0AR0 | NO DIRECT REPLACEMENT | |
| 3TH8310-0AR1 | NO DIRECT REPLACEMENT | |
| 3TH8310-0AS0 | NO DIRECT REPLACEMENT | |
| 3TH8310-0AS1 | NO DIRECT REPLACEMENT | |
| 3TH8310-0AU0 | NO DIRECT REPLACEMENT | |
| 3TH8310-0AV0 | NO DIRECT REPLACEMENT | |
| 3TH8310-0BA4 | NO DIRECT REPLACEMENT | |
| 3TH8310-0BB4 | NO DIRECT REPLACEMENT | |
| 3TH8310-0BC4 | NO DIRECT REPLACEMENT | |
| 3TH8310-0BD4 | NO DIRECT REPLACEMENT | |
| 3TH8310-0BE4 | NO DIRECT REPLACEMENT | |
| 3TH8310-0BF4 | NO DIRECT REPLACEMENT | |
| 3TH8310-0BG4 | NO DIRECT REPLACEMENT | |
| 3TH8310-0BK4 | NO DIRECT REPLACEMENT | |
| 3TH8310-0BM4 | NO DIRECT REPLACEMENT | |
| 3TH8310-0BN4 | NO DIRECT REPLACEMENT | |
| 3TH8310-0BP4 | NO DIRECT REPLACEMENT | |
| 3TH8310-0BQ4 | NO DIRECT REPLACEMENT | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TH8310-0BU4 | NO DIRECT REPLACEMENT | |
| 3TH8310-0BV4 | NO DIRECT REPLACEMENT | |
| 3TH8310-0BW4 | NO DIRECT REPLACEMENT | |
| 3TH8328-0AM0 | NO DIRECT REPLACEMENT | |
| 3TH8346-0AC1 | NO DIRECT REPLACEMENT | |
| 3TH8346-0AD0 | NO DIRECT REPLACEMENT | |
| 3TH8346-0AG1 | NO DIRECT REPLACEMENT | |
| 3TH8346-0AM0 | NO DIRECT REPLACEMENT | |
| 3TH8346-0AN1 | NO DIRECT REPLACEMENT | |
| 3TH8346-0BB4 | NO DIRECT REPLACEMENT | |
| 3TH8354-1EC1 | NO DIRECT REPLACEMENT | |
| 3TH8354-1EC2 | NO DIRECT REPLACEMENT | |
| 3TH8354-1EG1 | NO DIRECT REPLACEMENT | |
| 3TH8354-1EJ1 | NO DIRECT REPLACEMENT | |
| 3TH8354-1EJ2 | NO DIRECT REPLACEMENT | |
| 3TH8354-1EK1 | NO DIRECT REPLACEMENT | |
| 3TH8354-1EK6 | NO DIRECT REPLACEMENT | |
| 3TH8354-1EM2 | NO DIRECT REPLACEMENT | |
| 3TH8354-1EN1 | NO DIRECT REPLACEMENT | |
| 3TH8354-1EP1 | NO DIRECT REPLACEMENT | |
| 3TH8354-1EP6 | NO DIRECT REPLACEMENT | |
| 3TH8354-1EQ0 | NO DIRECT REPLACEMENT | |
| 3TH8354-1ES0 | NO DIRECT REPLACEMENT | |
| 3TH8354-1FA4 | NO DIRECT REPLACEMENT | |
| 3TH8354-1FB4 | NO DIRECT REPLACEMENT | |
| 3TH8354-1FF4 | NO DIRECT REPLACEMENT | |
| 3TH8354-1FG4 | NO DIRECT REPLACEMENT | |
| 3TH8354-1FK4 | NO DIRECT REPLACEMENT | |
| 3TH8354-1FQ4 | NO DIRECT REPLACEMENT | |
| 3TH8354-1FW4 | NO DIRECT REPLACEMENT | |
| 3TH8354-8EC2 | NO DIRECT REPLACEMENT | |
| 3TH8354-8EJ2 | NO DIRECT REPLACEMENT | |
| 3TH8354-8EK6 | NO DIRECT REPLACEMENT | |
| 3TH8354-8EM2 | NO DIRECT REPLACEMENT | |
| 3TH8354-8EP6 | NO DIRECT REPLACEMENT | |
| 3TH8354-8EQ0 | NO DIRECT REPLACEMENT | |
| 3TH8354-8ES0 | NO DIRECT REPLACEMENT | |
| 3TH8355-0AB0 | NO DIRECT REPLACEMENT | |
| 3TH8355-0AC0 | NO DIRECT REPLACEMENT | |
| 3TH8355-0AC1 | NO DIRECT REPLACEMENT | |
| 3TH8355-0AC2 | NO DIRECT REPLACEMENT | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TH8355-0AD0 | NO DIRECT REPLACEMENT | |
| 3TH8355-0AD1 | NO DIRECT REPLACEMENT | |
| 3TH8355-0AE0 | NO DIRECT REPLACEMENT | |
| 3TH8355-0AF0 | NO DIRECT REPLACEMENT | |
| 3TH8355-0AG0 | NO DIRECT REPLACEMENT | |
| 3TH8355-0AG1 | NO DIRECT REPLACEMENT | |
| 3TH8355-0AH0 | NO DIRECT REPLACEMENT | |
| 3TH8355-0AJ1 | NO DIRECT REPLACEMENT | |
| 3TH8355-0AJ2 | NO DIRECT REPLACEMENT | |
| 3TH8355-0AK1 | NO DIRECT REPLACEMENT | |
| 3TH8355-0AK6 | NO DIRECT REPLACEMENT | |
| 3TH8355-0AL0 | NO DIRECT REPLACEMENT | |
| 3TH8355-0AL1 | NO DIRECT REPLACEMENT | |
| 3TH8355-0AM0 | NO DIRECT REPLACEMENT | |
| 3TH8355-0AM1 | NO DIRECT REPLACEMENT | |
| 3TH8355-0AM2 | NO DIRECT REPLACEMENT | |
| 3TH8355-0AN1 | NO DIRECT REPLACEMENT | |
| 3TH8355-0AP0 | NO DIRECT REPLACEMENT | |
| 3TH8355-0AP1 | NO DIRECT REPLACEMENT | |
| 3TH8355-0AP6 | NO DIRECT REPLACEMENT | |
| 3TH8355-0AQ0 | NO DIRECT REPLACEMENT | |
| 3TH8355-0AR0 | NO DIRECT REPLACEMENT | |
| 3TH8355-0AR1 | NO DIRECT REPLACEMENT | |
| 3TH8355-0AS0 | NO DIRECT REPLACEMENT | |
| 3TH8355-0AS1 | NO DIRECT REPLACEMENT | |
| 3TH8355-0AU0 | NO DIRECT REPLACEMENT | |
| 3TH8355-0AV0 | NO DIRECT REPLACEMENT | |
| 3TH8355-0BA4 | NO DIRECT REPLACEMENT | |
| 3TH8355-0BB4 | NO DIRECT REPLACEMENT | |
| 3TH8355-0BC4 | NO DIRECT REPLACEMENT | |
| 3TH8355-0BD4 | NO DIRECT REPLACEMENT | |
| 3TH8355-0BE4 | NO DIRECT REPLACEMENT | |
| 3TH8355-0BF4 | NO DIRECT REPLACEMENT | |
| 3TH8355-0BG4 | NO DIRECT REPLACEMENT | |
| 3TH8355-0BK4 | NO DIRECT REPLACEMENT | |
| 3TH8355-0BM4 | NO DIRECT REPLACEMENT | |
| 3TH8355-0BN4 | NO DIRECT REPLACEMENT | |
| 3TH8355-0BP4 | NO DIRECT REPLACEMENT | |
| 3TH8355-0BQ4 | NO DIRECT REPLACEMENT | |
| 3TH8355-0BU4 | NO DIRECT REPLACEMENT | |
| 3TH8355-0BV4 | NO DIRECT REPLACEMENT | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TH8355-0BW4 | NO DIRECT REPLACEMENT | |
| 3TH8364-0AB0 | NO DIRECT REPLACEMENT | |
| 3TH8364-0AC0 | NO DIRECT REPLACEMENT | |
| 3TH8364-0AC1 | NO DIRECT REPLACEMENT | |
| 3TH8364-0AC2 | NO DIRECT REPLACEMENT | |
| 3TH8364-0AD0 | NO DIRECT REPLACEMENT | |
| 3TH8364-0AD1 | NO DIRECT REPLACEMENT | |
| 3TH8364-0AE0 | NO DIRECT REPLACEMENT | |
| 3TH8364-0AF0 | NO DIRECT REPLACEMENT | |
| 3TH8364-0AG0 | NO DIRECT REPLACEMENT | |
| 3TH8364-0AG1 | NO DIRECT REPLACEMENT | |
| 3TH8364-0AH0 | NO DIRECT REPLACEMENT | |
| 3TH8364-0AJ1 | NO DIRECT REPLACEMENT | |
| 3TH8364-0AJ2 | NO DIRECT REPLACEMENT | |
| 3TH8364-0AK1 | NO DIRECT REPLACEMENT | |
| 3TH8364-0AK6 | NO DIRECT REPLACEMENT | |
| 3TH8364-0AL0 | NO DIRECT REPLACEMENT | |
| 3TH8364-0AL1 | NO DIRECT REPLACEMENT | |
| 3TH8364-0AM0 | NO DIRECT REPLACEMENT | |
| 3TH8364-0AM1 | NO DIRECT REPLACEMENT | |
| 3TH8364-0AM2 | NO DIRECT REPLACEMENT | |
| 3TH8364-0AN1 | NO DIRECT REPLACEMENT | |
| 3TH8364-0AP0 | NO DIRECT REPLACEMENT | |
| 3TH8364-0AP1 | NO DIRECT REPLACEMENT | |
| 3TH8364-0AP6 | NO DIRECT REPLACEMENT | |
| 3TH8364-0AQ0 | NO DIRECT REPLACEMENT | |
| 3TH8364-0AR0 | NO DIRECT REPLACEMENT | |
| 3TH8364-0AR1 | NO DIRECT REPLACEMENT | |
| 3TH8364-0AS0 | NO DIRECT REPLACEMENT | |
| 3TH8364-0AS1 | NO DIRECT REPLACEMENT | |
| 3TH8364-0AU0 | NO DIRECT REPLACEMENT | |
| 3TH8364-0AV0 | NO DIRECT REPLACEMENT | |
| 3TH8364-0BA4 | NO DIRECT REPLACEMENT | |
| 3TH8364-0BB4 | NO DIRECT REPLACEMENT | |
| 3TH8364-0BC4 | NO DIRECT REPLACEMENT | |
| 3TH8364-0BD4 | NO DIRECT REPLACEMENT | |
| 3TH8364-0BE4 | NO DIRECT REPLACEMENT | |
| 3TH8364-0BF4 | NO DIRECT REPLACEMENT | |
| 3TH8364-0BG4 | NO DIRECT REPLACEMENT | |
| 3TH8364-0BK4 | NO DIRECT REPLACEMENT | |
| 3TH8364-0BM4 | NO DIRECT REPLACEMENT | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TH8364-0BN4 | NO DIRECT REPLACEMENT | |
| 3TH8364-0BP4 | NO DIRECT REPLACEMENT | |
| 3TH8364-0BQ4 | NO DIRECT REPLACEMENT | |
| 3TH8364-0BU4 | NO DIRECT REPLACEMENT | |
| 3TH8364-0BV4 | NO DIRECT REPLACEMENT | |
| 3TH8364-0BW4 | NO DIRECT REPLACEMENT | |
| 3TH8373-0AB0 | NO DIRECT REPLACEMENT | |
| 3TH8373-0AC0 | NO DIRECT REPLACEMENT | |
| 3TH8373-0AC1 | NO DIRECT REPLACEMENT | |
| 3TH8373-0AC2 | NO DIRECT REPLACEMENT | |
| 3TH8373-0AD0 | NO DIRECT REPLACEMENT | |
| 3TH8373-0AD1 | NO DIRECT REPLACEMENT | |
| 3TH8373-0AE0 | NO DIRECT REPLACEMENT | |
| 3TH8373-0AF0 | NO DIRECT REPLACEMENT | |
| 3TH8373-0AG0 | NO DIRECT REPLACEMENT | |
| 3TH8373-0AG1 | NO DIRECT REPLACEMENT | |
| 3TH8373-0AH0 | NO DIRECT REPLACEMENT | |
| 3TH8373-0AJ1 | NO DIRECT REPLACEMENT | |
| 3TH8373-0AJ2 | NO DIRECT REPLACEMENT | |
| 3TH8373-0AK1 | NO DIRECT REPLACEMENT | |
| 3TH8373-0AK6 | NO DIRECT REPLACEMENT | |
| 3TH8373-0AL0 | NO DIRECT REPLACEMENT | |
| 3TH8373-0AL1 | NO DIRECT REPLACEMENT | |
| 3TH8373-0AM0 | NO DIRECT REPLACEMENT | |
| 3TH8373-0AM1 | NO DIRECT REPLACEMENT | |
| 3TH8373-0AM2 | NO DIRECT REPLACEMENT | |
| 3TH8373-0AN1 | NO DIRECT REPLACEMENT | |
| 3TH8373-0AP0 | NO DIRECT REPLACEMENT | |
| 3TH8373-0AP1 | NO DIRECT REPLACEMENT | |
| 3TH8373-0AP6 | NO DIRECT REPLACEMENT | |
| 3TH8373-0AQ0 | NO DIRECT REPLACEMENT | |
| 3TH8373-0AR0 | NO DIRECT REPLACEMENT | |
| 3TH8373-0AR1 | NO DIRECT REPLACEMENT | |
| 3TH8373-0AS0 | NO DIRECT REPLACEMENT | |
| 3TH8373-0AS1 | NO DIRECT REPLACEMENT | |
| 3TH8373-0AU0 | NO DIRECT REPLACEMENT | |
| 3TH8373-0AV0 | NO DIRECT REPLACEMENT | |
| 3TH8373-0BA4 | NO DIRECT REPLACEMENT | |
| 3TH8373-0BB4 | NO DIRECT REPLACEMENT | |
| 3TH8373-0BC4 | NO DIRECT REPLACEMENT | |
| 3TH8373-0BD4 | NO DIRECT REPLACEMENT | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TH8373-0BE4 | NO DIRECT REPLACEMENT | |
| 3TH8373-0BF4 | NO DIRECT REPLACEMENT | |
| 3TH8373-0BG4 | NO DIRECT REPLACEMENT | |
| 3TH8373-0BK4 | NO DIRECT REPLACEMENT | |
| 3TH8373-0BM4 | NO DIRECT REPLACEMENT | |
| 3TH8373-0BN4 | NO DIRECT REPLACEMENT | |
| 3TH8373-0BP4 | NO DIRECT REPLACEMENT | |
| 3TH8373-0BQ4 | NO DIRECT REPLACEMENT | |
| 3TH8373-0BU4 | NO DIRECT REPLACEMENT | |
| 3TH8373-0BV4 | NO DIRECT REPLACEMENT | |
| 3TH8373-0BW4 | NO DIRECT REPLACEMENT | |
| 3TH8382-0AB0 | NO DIRECT REPLACEMENT | |
| 3TH8382-0AC0 | NO DIRECT REPLACEMENT | |
| 3TH8382-0AC1 | NO DIRECT REPLACEMENT | |
| 3TH8382-0AC2 | NO DIRECT REPLACEMENT | |
| 3TH8382-0AD0 | NO DIRECT REPLACEMENT | |
| 3TH8382-0AD1 | NO DIRECT REPLACEMENT | |
| 3TH8382-0AE0 | NO DIRECT REPLACEMENT | |
| 3TH8382-0AF0 | NO DIRECT REPLACEMENT | |
| 3TH8382-0AG0 | NO DIRECT REPLACEMENT | |
| 3TH8382-0AG1 | NO DIRECT REPLACEMENT | |
| 3TH8382-0AH0 | NO DIRECT REPLACEMENT | |
| 3TH8382-0AJ1 | NO DIRECT REPLACEMENT | |
| 3TH8382-0AJ2 | NO DIRECT REPLACEMENT | |
| 3TH8382-0AK1 | NO DIRECT REPLACEMENT | |
| 3TH8382-0AK6 | NO DIRECT REPLACEMENT | |
| 3TH8382-0AL0 | NO DIRECT REPLACEMENT | |
| 3TH8382-0AL1 | NO DIRECT REPLACEMENT | |
| 3TH8382-0AM0 | NO DIRECT REPLACEMENT | |
| 3TH8382-0AM1 | NO DIRECT REPLACEMENT | |
| 3TH8382-0AM2 | NO DIRECT REPLACEMENT | |
| 3TH8382-0AN1 | NO DIRECT REPLACEMENT | |
| 3TH8382-0AP0 | NO DIRECT REPLACEMENT | |
| 3TH8382-0AP1 | NO DIRECT REPLACEMENT | |
| 3TH8382-0AP6 | NO DIRECT REPLACEMENT | |
| 3TH8382-0AQ0 | NO DIRECT REPLACEMENT | |
| 3TH8382-0AR0 | NO DIRECT REPLACEMENT | |
| 3TH8382-0AR1 | NO DIRECT REPLACEMENT | |
| 3TH8382-0AS0 | NO DIRECT REPLACEMENT | |
| 3TH8382-0AS1 | NO DIRECT REPLACEMENT | |
| 3TH8382-0AU0 | NO DIRECT REPLACEMENT | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TH8382-0AV0 | NO DIRECT REPLACEMENT | |
| 3TH8382-0BA4 | NO DIRECT REPLACEMENT | |
| 3TH8382-0BB4 | NO DIRECT REPLACEMENT | |
| 3TH8382-0BC4 | NO DIRECT REPLACEMENT | |
| 3TH8382-0BD4 | NO DIRECT REPLACEMENT | |
| 3TH8382-0BE4 | NO DIRECT REPLACEMENT | |
| 3TH8382-0BF4 | NO DIRECT REPLACEMENT | |
| 3TH8382-0BG4 | NO DIRECT REPLACEMENT | |
| 3TH8382-0BK4 | NO DIRECT REPLACEMENT | |
| 3TH8382-0BM4 | NO DIRECT REPLACEMENT | |
| 3TH8382-0BN4 | NO DIRECT REPLACEMENT | |
| 3TH8382-0BP4 | NO DIRECT REPLACEMENT | |
| 3TH8382-0BQ4 | NO DIRECT REPLACEMENT | |
| 3TH8382-0BU4 | NO DIRECT REPLACEMENT | |
| 3TH8382-0BV4 | NO DIRECT REPLACEMENT | |
| 3TH8382-0BW4 | NO DIRECT REPLACEMENT | |
| 3TH8382-0EK1 | NO DIRECT REPLACEMENT | |
| 3TH8391-0AB0 | NO DIRECT REPLACEMENT | |
| 3TH8391-0AC0 | NO DIRECT REPLACEMENT | |
| 3TH8391-0AC1 | NO DIRECT REPLACEMENT | |
| 3TH8391-0AC2 | NO DIRECT REPLACEMENT | |
| 3TH8391-0AD0 | NO DIRECT REPLACEMENT | |
| 3TH8391-0AD1 | NO DIRECT REPLACEMENT | |
| 3TH8391-0AE0 | NO DIRECT REPLACEMENT | |
| 3TH8391-0AF0 | NO DIRECT REPLACEMENT | |
| 3TH8391-0AG0 | NO DIRECT REPLACEMENT | |
| 3TH8391-0AG1 | NO DIRECT REPLACEMENT | |
| 3TH8391-0AH0 | NO DIRECT REPLACEMENT | |
| 3TH8391-0AJ1 | NO DIRECT REPLACEMENT | |
| 3TH8391-0AJ2 | NO DIRECT REPLACEMENT | |
| 3TH8391-0AK1 | NO DIRECT REPLACEMENT | |
| 3TH8391-0AK6 | NO DIRECT REPLACEMENT | |
| 3TH8391-0AL0 | NO DIRECT REPLACEMENT | |
| 3TH8391-0AL1 | NO DIRECT REPLACEMENT | |
| 3TH8391-0AM0 | NO DIRECT REPLACEMENT | |
| 3TH8391-0AM1 | NO DIRECT REPLACEMENT | |
| 3TH8391-0AM2 | NO DIRECT REPLACEMENT | |
| 3TH8391-0AN1 | NO DIRECT REPLACEMENT | |
| 3TH8391-0AP0 | NO DIRECT REPLACEMENT | |
| 3TH8391-0AP1 | NO DIRECT REPLACEMENT | |
| 3TH8391-0AP6 | NO DIRECT REPLACEMENT | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TH8391-0AQ0 | NO DIRECT REPLACEMENT | |
| 3TH8391-0AR0 | NO DIRECT REPLACEMENT | |
| 3TH8391-0AR1 | NO DIRECT REPLACEMENT | |
| 3TH8391-0AS0 | NO DIRECT REPLACEMENT | |
| 3TH8391-0AS1 | NO DIRECT REPLACEMENT | |
| 3TH8391-0AU0 | NO DIRECT REPLACEMENT | |
| 3TH8391-0AV0 | NO DIRECT REPLACEMENT | |
| 3TH8391-0BA4 | NO DIRECT REPLACEMENT | |
| 3TH8391-0BB4 | NO DIRECT REPLACEMENT | |
| 3TH8391-0BC4 | NO DIRECT REPLACEMENT | |
| 3TH8391-0BD4 | NO DIRECT REPLACEMENT | |
| 3TH8391-0BE4 | NO DIRECT REPLACEMENT | |
| 3TH8391-0BF4 | NO DIRECT REPLACEMENT | |
| 3TH8391-0BG4 | NO DIRECT REPLACEMENT | |
| 3TH8391-0BK4 | NO DIRECT REPLACEMENT | |
| 3TH8391-0BM4 | NO DIRECT REPLACEMENT | |
| 3TH8391-0BN4 | NO DIRECT REPLACEMENT | |
| 3TH8391-0BP4 | NO DIRECT REPLACEMENT | |
| 3TH8391-0BQ4 | NO DIRECT REPLACEMENT | |
| 3TH8391-0BU4 | NO DIRECT REPLACEMENT | |
| 3TH8391-0BV4 | NO DIRECT REPLACEMENT | |
| 3TH8391-0BW4 | NO DIRECT REPLACEMENT | |
| 3TH8394-0AB0 | NO DIRECT REPLACEMENT | |
| 3TH8394-0AC0 | NO DIRECT REPLACEMENT | |
| 3TH8394-0AC1 | NO DIRECT REPLACEMENT | |
| 3TH8394-0AC2 | NO DIRECT REPLACEMENT | |
| 3TH8394-0AD0 | NO DIRECT REPLACEMENT | |
| 3TH8394-0AD1 | NO DIRECT REPLACEMENT | |
| 3TH8394-0AE0 | NO DIRECT REPLACEMENT | |
| 3TH8394-0AF0 | NO DIRECT REPLACEMENT | |
| 3TH8394-0AG0 | NO DIRECT REPLACEMENT | |
| 3TH8394-0AG1 | NO DIRECT REPLACEMENT | |
| 3TH8394-0AH0 | NO DIRECT REPLACEMENT | |
| 3TH8394-0AJ1 | NO DIRECT REPLACEMENT | |
| 3TH8394-0AJ2 | NO DIRECT REPLACEMENT | |
| 3TH8394-0AK1 | NO DIRECT REPLACEMENT | |
| 3TH8394-0AK6 | NO DIRECT REPLACEMENT | |
| 3TH8394-0AL0 | NO DIRECT REPLACEMENT | |
| 3TH8394-0AL1 | NO DIRECT REPLACEMENT | |
| 3TH8394-0AM0 | NO DIRECT REPLACEMENT | |
| 3TH8394-0AM1 | NO DIRECT REPLACEMENT | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TH8394-0AM2 | NO DIRECT REPLACEMENT | |
| 3TH8394-0AN1 | NO DIRECT REPLACEMENT | |
| 3TH8394-0AP0 | NO DIRECT REPLACEMENT | |
| 3TH8394-0AP1 | NO DIRECT REPLACEMENT | |
| 3TH8394-0AP6 | NO DIRECT REPLACEMENT | |
| 3TH8394-0AQ0 | NO DIRECT REPLACEMENT | |
| 3TH8394-0AR0 | NO DIRECT REPLACEMENT | |
| 3TH8394-0AR1 | NO DIRECT REPLACEMENT | |
| 3TH8394-0AS0 | NO DIRECT REPLACEMENT | |
| 3TH8394-0AS1 | NO DIRECT REPLACEMENT | |
| 3TH8394-0AU0 | NO DIRECT REPLACEMENT | |
| 3TH8394-0AV0 | NO DIRECT REPLACEMENT | |
| 3TH8394-0BA4 | NO DIRECT REPLACEMENT | |
| 3TH8394-0BB4 | NO DIRECT REPLACEMENT | |
| 3TH8394-0BC4 | NO DIRECT REPLACEMENT | |
| 3TH8394-0BD4 | NO DIRECT REPLACEMENT | |
| 3TH8394-0BE4 | NO DIRECT REPLACEMENT | |
| 3TH8394-0BF4 | NO DIRECT REPLACEMENT | |
| 3TH8394-0BG4 | NO DIRECT REPLACEMENT | |
| 3TH8394-0BK4 | NO DIRECT REPLACEMENT | |
| 3TH8394-0BM4 | NO DIRECT REPLACEMENT | |
| 3TH8394-0BN4 | NO DIRECT REPLACEMENT | |
| 3TH8394-0BP4 | NO DIRECT REPLACEMENT | |
| 3TH8394-0BQ4 | NO DIRECT REPLACEMENT | |
| 3TH8394-0BU4 | NO DIRECT REPLACEMENT | |
| 3TH8394-0BV4 | NO DIRECT REPLACEMENT | |
| 3TH8394-0BW4 | NO DIRECT REPLACEMENT | |
| 3TH8505-0AB0 | NO DIRECT REPLACEMENT | |
| 3TH8505-0AC0 | NO DIRECT REPLACEMENT | |
| 3TH8505-0AC1 | NO DIRECT REPLACEMENT | |
| 3TH8505-0AD0 | NO DIRECT REPLACEMENT | |
| 3TH8505-0AD1 | NO DIRECT REPLACEMENT | |
| 3TH8505-0AE0 | NO DIRECT REPLACEMENT | |
| 3TH8505-0AF0 | NO DIRECT REPLACEMENT | |
| 3TH8505-0AG0 | NO DIRECT REPLACEMENT | |
| 3TH8505-0AG1 | NO DIRECT REPLACEMENT | |
| 3TH8505-0AH0 | NO DIRECT REPLACEMENT | |
| 3TH8505-0AJ1 | NO DIRECT REPLACEMENT | |
| 3TH8505-0AK1 | NO DIRECT REPLACEMENT | |
| 3TH8505-0AK6 | NO DIRECT REPLACEMENT | |
| 3TH8505-0AL0 | NO DIRECT REPLACEMENT | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TH8505-0AL1 | NO DIRECT REPLACEMENT | |
| 3TH8505-0AM0 | NO DIRECT REPLACEMENT | |
| 3TH8505-0AM1 | NO DIRECT REPLACEMENT | |
| 3TH8505-0AN1 | NO DIRECT REPLACEMENT | |
| 3TH8505-0AP0 | NO DIRECT REPLACEMENT | |
| 3TH8505-0AP1 | NO DIRECT REPLACEMENT | |
| 3TH8505-0AP6 | NO DIRECT REPLACEMENT | |
| 3TH8505-0AQ0 | NO DIRECT REPLACEMENT | |
| 3TH8505-0AR0 | NO DIRECT REPLACEMENT | |
| 3TH8505-0AR1 | NO DIRECT REPLACEMENT | |
| 3TH8505-0AS0 | NO DIRECT REPLACEMENT | |
| 3TH8505-0AS1 | NO DIRECT REPLACEMENT | |
| 3TH8505-0AU0 | NO DIRECT REPLACEMENT | |
| 3TH8505-0AV0 | NO DIRECT REPLACEMENT | |
| 3TX0461-1A | 3RA1943-2A | |
| 3TX0481-1A | 3RA1943-2A | |
| 3TX0501-1A | PRODUCT STILL AVAILABLE | |
| 3TX0521-1A | PRODUCT STILL AVAILABLE | |
| 3TX0541-1A | PRODUCT STILL AVAILABLE | |
| 3TX0561-1A | PRODUCT STILL AVAILABLE | |
| 3TX1623-0C | NO DIRECT REPLACEMENT | |
| 3TX2746-2F | SEE SIRIUS 3RT ACCESSORIES | |
| 3TX4001-2A | 3RH1911-1HA01 | |
| 3TX4001-4A | 3RH1911-1FB11 | |
| 3TX4010-2A | 3RH1911-1AA10 | |
| 3TX4010-3A | 3RH1911-1AA10 | |
| 3TX4010-4A | 3RH1911-1FB11 | |
| 3TX4011-8A | 3RH1911-1LA11 | |
| 3TX4090-0C | 3RH1924-1GP11 | |
| 3TX4090-0D | 3RH1924-1GP11 | |
| 3TX4090-0GF3 | NO DIRECT REPLACEMENT | |
| 3TX4091-1A | 3RA1924-2B | |
| 3TX4091-1H | NO DIRECT REPLACEMENT | |
| 3TX4092-0A | SEE SIRIUS 3RT1916-2C** OR 3RT1926-2C** | |
| 3TX4092-1A | SEE SIRIUS 3RT1916-2C** OR 3RT1926-2C** | |
| 3TX4092-5A | SEE SIRIUS 3RT1916-2D** OR 3RT1926-2D** | |
| 3TX4092-6A | SEE SIRIUS 3RT1916-2D** OR 3RT1926-2D** | |
| 3TX4180-0A | SEE SIRIUS 3RT1916-2C** OR 3RT1926-2C** | |
| 3TX4180-1D | NO DIRECT REPLACEMENT | |
| 3TX4180-2A | NO DIRECT REPLACEMENT | |
| 3TX4180-2B | NO DIRECT REPLACEMENT | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TX4180-2C | NO DIRECT REPLACEMENT | |
| 3TX4180-2D | NO DIRECT REPLACEMENT | |
| 3TX4180-2E | NO DIRECT REPLACEMENT | |
| 3TX4180-2F | NO DIRECT REPLACEMENT | |
| 3TX4180-3C | 3RH1924-1GP11 | |
| 3TX4180-3D | 3RH1924-1GP11 | |
| 3TX4180-3F | 3RH1924-1GP11 | |
| 3TX4180-3G | 3RH1924-1GP11 | |
| 3TX4185-0A | SEE 3RH1911-1GA** | |
| 3TX4185-0BC1 | SEE SIRIUS 3R | |
| 3TX4185-0BD1 | SEE SIRIUS 3R | |
| 3TX4185-0BK6 | SEE SIRIUS 3R | |
| 3TX4185-0BM1 | SEE SIRIUS 3R | |
| 3TX4185-0BN1 | SEE SIRIUS 3R | |
| 3TX4185-0BP1 | SEE SIRIUS 3R | |
| 3TX4185-0BP6 | SEE SIRIUS 3R | |
| 3TX4185-1BW8 | SEE SIRIUS 3R | |
| 3TX4210-0A | NO DIRECT REPLACEMENT | |
| 3TX4210-0B | NO DIRECT REPLACEMENT | |
| 3TX4210-0D | SEE 3RT1916-1**00 OR 3RT1926-1**00 | |
| 3TX4210-0E | SEE SIRIUS 3RT1916-2C** OR 3RT1926-2C** | |
| 3TX4210-0H | 3RT1900-1SB20 | |
| 3TX4210-0M | SEE 3RT1916-1**00 OR 3RT1926-1**00 | |
| 3TX4210-0P | NO DIRECT REPLACEMENT | |
| 3TX4210-0R | 3RT1900-1SB20 | |
| 3TX4401-1A | 3RH1911-1HA01 | |
| 3TX4401-1B | 3RH1911-2HA01 | |
| 3TX4401-2B | 3RH1911-2HA01 | |
| 3TX4402-2A | 3RH1911-1FA02 | |
| 3TX4402-2B | 3RH1911-2FA02 | |
| 3TX4404-0A | SEE SIRIUS 3RH | |
| 3TX4404-0B | SEE SIRIUS 3RH | |
| 3TX4411-2A | 3RH1911-1FA11 | |
| 3TX4411-2B | 3RH1911-2FA11 | |
| 3TX4412-1A | 3RH1911-1HA12 | |
| 3TX4412-1B | 3RH1911-2HA12 | |
| 3TX4412-2B | 3RH1911-2FA11 | |
| 3TX4413-0A | 3RH1911-1HA13 | |
| 3TX4413-0B | 3RH1911-2HA13 | |
| 3TX4413-1A | 3RH1911-1HA13 | |
| 3TX4420-2A | 3RH1911-1FA20 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TX4420-2B | 3RH1911-2FA20 | |
| 3TX4422-0A | 3RH1911-1HA22 | |
| 3TX4422-0B | 3RH1911-2HA22 | |
| 3TX4422-1A | 3RH1911-1HA22 | |
| 3TX4422-2A | 3RH1911-1FA22 | |
| 3TX4422-2B | 3RH1911-2FA22 | |
| 3TX4422-2G | 3RH1911-1FC22 | |
| 3TX4431-0A | 3RH1911-2FC22 | |
| 3TX4431-0B | 3RH1911-1FA31 | |
| 3TX4431-2A | 3RH1911-1FA31 | |
| 3TX4431-2B | 3RH1911-2FA31 | |
| 3TX4440-0A | 3RH1911-1FA40 | |
| 3TX4440-0B | 3RH1911-2FA40 | |
| 3TX4440-2A | 3RH1911-1FA40 | |
| 3TX4440-2B | 3RH1911-2FA40 | |
| 3TX4490-0C | 3RT1916-1DG00 | |
| 3TX4490-0D | 3RT1916-1BB00 | |
| 3TX4490-0E | 3RT1916-1BC00 | |
| 3TX4490-0F | 3RT1916-1BD00 | |
| 3TX4490-0R | 3RT1916-1CC00 | |
| 3TX4490-0S | 3RT1916-1CD00 | |
| 3TX4490-0V | 3RT1916-1BB00 | |
| 3TX4490-0W | 3RT1916-1BD00 | |
| 3TX4490-1A | 3RT1916-2FK11 | |
| 3TX4490-2A | SEE 3RV1915-*** | |
| 3TX4490-2F | 3RA1922-1A | |
| 3TX4490-3A | 3RT1916-1DG00 | |
| 3TX4490-3AZ0E | NO DIRECT REPLACEMENT | |
| 3TX4490-3B | 3RT1916-1EH00 | |
| 3TX4490-3G | 3RT1916-1BB00 | |
| 3TX4490-3H | 3RT1916-1BC00 | |
| 3TX4490-3HZ0E | NO DIRECT REPLACEMENT | |
| 3TX4490-3J | 3RT1916-1BD00 | |
| 3TX4490-3L | 3RT1916-1BF00 | |
| 3TX4490-3R | 3RT1916-1CB00 | |
| 3TX4490-3S | 3RT1916-1CC00 | |
| 3TX4490-3T | 3RT1916-1CD00 | |
| 3TX4490-3TZ0E | NO DIRECT REPLACEMENT | |
| 3TX4490-3TZOE | NO DIRECT REPLACEMENT | |
| 3TX4490-4A | 3RT1916-1LM00 | |
| 3TX4490-4G | 3RT1916-1JJ00 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TX4490-4H | 3RT1916-1JK00 | |
| 3TX4491-2A | 3RT1916-4KA1 | |
| 3TX4491-2AZ0E | NO DIRECT REPLACEMENT | |
| 3TX4701-0AN1 | 3RT1916-2DH21 | |
| 3TX4701-0BB4 | 3RT1916-2DG21 | |
| 3TX6346-3B | NO DIRECT REPLACEMENT | |
| 3TX6404-1AA11 | SEE PILOT DEVICES | |
| 3TX6406-0B | 3RT1926-1CE00 | |
| 3TX6406-0C | 3RT1926-1CC00 | |
| 3TX6406-0D | 3RT1926-1CB00 | |
| 3TX6406-0H | 3RT1926-1ES00 | |
| 3TX6406-1A | 3RT1926-1BB00 | |
| 3TX6406-1B | 3RT1926-1BC00 | |
| 3TX6406-1C | 3RT1926-1BD00 | |
| 3TX6426-0A | 3RA1922-1A | |
| 3TX6446-0A | 3RA1932-1A | |
| 3TX6446-0B | 3RT1926-1CE00 | |
| 3TX6446-0C | 3RA1924-2B | |
| 3TX6446-1A | 3RT1926-1BB00 | |
| 3TX6446-1B | 3RT1926-1BC00 | |
| 3TX6446-3B | NO DIRECT REPLACEMENT | |
| 3TX6461-0A | NO DIRECT REPLACEMENT | |
| 3TX6461-1A | CMR2 | |
| 3TX6461-1B | CMR3 | |
| 3TX6476-3C | NO DIRECT REPLACEMENT | |
| 3TX6481-0A | NO DIRECT REPLACEMENT | |
| 3TX6486-3B | 3RT1946-4EA2 | |
| 3TX6506-0B | 3RA1924-2B | |
| 3TX6506-0C | 3RT1936-1CE00 | |
| 3TX6506-3B | 3RT1946-4EA2 | |
| 3TX6506-3C | PRODUCT STILL AVAILABLE | |
| 3TX6516-3C | PRODUCT STILL AVAILABLE | |
| 3TX6526-0C | 3RT1936-1CC00 | |
| 3TX6526-1A | PRODUCT STILL AVAILABLE | |
| 3TX6526-1B | PRODUCT STILL AVAILABLE | |
| 3TX6526-1C | PRODUCT STILL AVAILABLE | |
| 3TX6526-1F | PRODUCT STILL AVAILABLE | |
| 3TX6526-3B | PRODUCT STILL AVAILABLE | |
| 3TX6526-3BZ0E | NO DIRECT REPLACEMENT | |
| 3TX6526-3C | PRODUCT STILL AVAILABLE | |
| 3TX6526-3CTS | PRODUCT STILL AVAILABLE | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TX6526ES429 | PRODUCT STILL AVAILABLE | |
| 3TX6546-0B | 3RA1924-2B | |
| 3TX6546-3B | PRODUCT STILL AVAILABLE | |
| 3TX6546-3C | PRODUCT STILL AVAILABLE | |
| 3TX6546-3CTS | PRODUCT STILL AVAILABLE | |
| 3TX6546ES431 | PRODUCT STILL AVAILABLE | |
| 3TX6566-0C | SEE 3TX7522-3T | |
| 3TX6566-0D | SEE 3TX7522-3U | |
| 3TX6566-3C | PRODUCT STILL AVAILABLE | |
| 3TX6576-3C | PRODUCT STILL AVAILABLE | |
| 3TX6586-3C | PRODUCT STILL AVAILABLE | |
| 3TX7002-1AB00 | NO DIRECT REPLACEMENT | |
| 3TX7002-1AB02 | NO DIRECT REPLACEMENT | |
| 3TX7002-1BB00 | NO DIRECT REPLACEMENT | |
| 3TX7002-1BF00 | NO DIRECT REPLACEMENT | |
| 3TX7002-1CB00 | NO DIRECT REPLACEMENT | |
| 3TX7002-1FB02 | NO DIRECT REPLACEMENT | |
| 3TX7002-2AB00 | NO DIRECT REPLACEMENT | |
| 3TX7002-2AE00 | NO DIRECT REPLACEMENT | |
| 3TX7002-2AF00 | NO DIRECT REPLACEMENT | |
| 3TX7002-3AB00 | NO DIRECT REPLACEMENT | |
| 3TX7002-3AB01 | NO DIRECT REPLACEMENT | |
| 3TX7002-4AB00 | NO DIRECT REPLACEMENT | |
| 3TX7002-4AG00 | NO DIRECT REPLACEMENT | |
| 3TX7004-1AM00 | NO DIRECT REPLACEMENT | |
| 3TX7004-1BB00 | NO DIRECT REPLACEMENT | |
| 3TX7004-1LB00 | NO DIRECT REPLACEMENT | |
| 3TX7004-1LB02 | NO DIRECT REPLACEMENT | |
| 3TX7004-1MB00 | NO DIRECT REPLACEMENT | |
| 3TX7004-2ME02 | NO DIRECT REPLACEMENT | |
| 3TX7004-3AB04 | NO DIRECT REPLACEMENT | |
| 3TX7004-3AC04 | NO DIRECT REPLACEMENT | |
| 3TX7004-4AB04 | NO DIRECT REPLACEMENT | |
| 3TX7004-8AA00 | NO DIRECT REPLACEMENT | |
| 3TX7004-8BA00 | NO DIRECT REPLACEMENT | |
| 3TX7005-1LB00 | NO DIRECT REPLACEMENT | |
| 3TX7005-1LB02 | NO DIRECT REPLACEMENT | |
| 3TX7005-3AC04 | NO DIRECT REPLACEMENT | |
| 3TX7090-0D | NO DIRECT REPLACEMENT | |
| 3TX7090-0DB00 | NO DIRECT REPLACEMENT | |
| 3TX7402-2A | 3RT1926-1CB00 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TX7402-2B | 3RT1926-1CC00 | |
| 3TX7402-2C | 3RT1926-1CD00 | |
| 3TX7402-2D | 3RT1926-1CE00 | |
| 3TX7402-3A | 3RT1926-1ES00 | |
| 3TX7402-3D | 3RT1936-1TS00 | |
| 3TX7402-3G | 3RT1926-1BB00 | |
| 3TX7402-3H | 3RT1926-1BC00 | |
| 3TX7402-3J | 3RT1926-1BD00 | |
| 3TX7402-3K | 3RT1926-1BE00 | |
| 3TX7402-3L | 3RT1926-1BF00 | |
| 3TX7402-3R | 3RT1926-1CB00 | |
| 3TX7402-3S | 3RT1926-1CC00 | |
| 3TX7402-3T | 3RT1926-1CD00 | |
| 3TX7402-3U | 3RT1926-1CE00 | |
| 3TX7402-3V | 3RT1926-1CF00 | |
| 3TX7441-1D | NO DIRECT REPLACEMENT | |
| 3TX7446-0A | NO DIRECT REPLACEMENT | |
| 3TX7460-0E | 3RT1936-4EA2 | |
| 3TX7462-2B | 3RT1936-1CC00 | |
| 3TX7462-2C | 3RT1936-1CD00 | |
| 3TX7462-2E | 3RT1936-1CC00 | |
| 3TX7462-2F | 3RT1936-1CD00 | |
| 3TX7462-2G | 3RT1936-1CE00 | |
| 3TX7462-3D | 3RT1936-1ES00 | |
| 3TX7462-3G | PRODUCT STILL AVAILABLE | |
| 3TX7462-3H | PRODUCT STILL AVAILABLE | |
| 3TX7462-3J | PRODUCT STILL AVAILABLE | |
| 3TX7462-3K | PRODUCT STILL AVAILABLE | |
| 3TX7462-3L | PRODUCT STILL AVAILABLE | |
| 3TX7462-3R | 3RT1936-1CB00 | |
| 3TX7462-3S | 3RT1936-1CC00 | |
| 3TX7462-3SZ0E | NO DIRECT REPLACEMENT | |
| 3TX7462-3T | 3RT1936-1CD00 | |
| 3TX7462-3U | 3RT1936-1CE00 | |
| 3TX7462-3V | 3RT1936-1CF00 | |
| 3TX7465-0DB4 | NO DIRECT REPLACEMENT | |
| 3TX7465-0DG4 | NO DIRECT REPLACEMENT | |
| 3TX7466-0A | 3RT1946-4EA2 | |
| 3TX7466-0E | 3RT1946-4EA2 | |
| 3TX7466-1A | 3RA1924-2B | |
| 3TX7466-2A | SEE 3TX7522-3G | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TX7466-2B | SEE 3TX7462-3H | |
| 3TX7466-2C | SEE 3TX7462-3J | |
| 3TX7466-2D | SEE 3TX7462-3K | |
| 3TX7466-2E | SEE 3TX7462-3L | |
| 3TX7485-0DB4 | NO DIRECT REPLACEMENT | |
| 3TX7500-0A | NO DIRECT REPLACEMENT | |
| 3TX7500-0AB | NO DIRECT REPLACEMENT | |
| 3TX7500-0B | PRODUCT STILL AVAILABLE | |
| 3TX7500-0D | PRODUCT STILL AVAILABLE | |
| 3TX7500-0E | PRODUCT STILL AVAILABLE | |
| 3TX7505-0DB4 | NO DIRECT REPLACEMENT | |
| 3TX7506-0A | PRODUCT STILL AVAILABLE | |
| 3TX7506-0B | PRODUCT STILL AVAILABLE | |
| 3TX7510-1F | PRODUCT STILL AVAILABLE | |
| 3TX7520-0B | PRODUCT STILL AVAILABLE | |
| 3TX7522-2B | SEE 3TX7522-3S | |
| 3TX7522-2C | PRODUCT STILL AVAILABLE | |
| 3TX7522-3G | PRODUCT STILL AVAILABLE | |
| 3TX7522-3H | PRODUCT STILL AVAILABLE | |
| 3TX7522-3R | PRODUCT STILL AVAILABLE | |
| 3TX7522-3S | PRODUCT STILL AVAILABLE | |
| 3TX7522-3T | PRODUCT STILL AVAILABLE | |
| 3TX7522-3TZ0E | PRODUCT STILL AVAILABLE | |
| 3TX7522-3U | PRODUCT STILL AVAILABLE | |
| 3TX7522-3V | PRODUCT STILL AVAILABLE | |
| 3TX7530-1E | PRODUCT STILL AVAILABLE | |
| 3TX7530-1F | PRODUCT STILL AVAILABLE | |
| 3TX7536-0A | PRODUCT STILL AVAILABLE | |
| 3TX7536-0B | PRODUCT STILL AVAILABLE | |
| 3TX7561-1A | PRODUCT STILL AVAILABLE | |
| 3TX7561-1B | PRODUCT STILL AVAILABLE | |
| 3TX7566-1A | PRODUCT STILL AVAILABLE | |
| 3TX7566-1B | PRODUCT STILL AVAILABLE | |
| 3TX7570-1E | PRODUCT STILL AVAILABLE | |
| 3TX7570-1F | PRODUCT STILL AVAILABLE | |
| 3TX7586-0A | PRODUCT STILL AVAILABLE | |
| 3TX7680-1A | PRODUCT STILL AVAILABLE | |
| 3TX7681-1A | PRODUCT STILL AVAILABLE | |
| 3TX7686-0A | PRODUCT STILL AVAILABLE | |
| 3TX7686-0B | PRODUCT STILL AVAILABLE | |
| 3TX7686-1A | PRODUCT STILL AVAILABLE | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TX7686-1B | PRODUCT STILL AVAILABLE | |
| 3TX7690-1F | PRODUCT STILL AVAILABLE | |
| 3TX7696-0A | PRODUCT STILL AVAILABLE | |
| 3TX7696-0B | PRODUCT STILL AVAILABLE | |
| 3TY1223-0J | NO DIRECT REPLACEMENT | |
| 3TY2440-0A | PRODUCT STILL AVAILABLE | |
| 3TY2442-0A | PRODUCT STILL AVAILABLE | |
| 3TY2480-0A | PRODUCT STILL AVAILABLE | |
| 3TY2482-0A | PRODUCT STILL AVAILABLE | |
| 3TY2520-0A | PRODUCT STILL AVAILABLE | |
| 3TY2522-0A | PRODUCT STILL AVAILABLE | |
| 3TY2560-0A | PRODUCT STILL AVAILABLE | |
| 3TY2562-0A | PRODUCT STILL AVAILABLE | |
| 3TY2740-0E | PRODUCT STILL AVAILABLE | |
| 3TY2741-2J | PRODUCT STILL AVAILABLE | |
| 3TY2742-0C | PRODUCT STILL AVAILABLE | |
| 3TY2744-1A | PRODUCT STILL AVAILABLE | |
| 3TY2744-1G | PRODUCT STILL AVAILABLE | |
| 3TY2746-6B | PRODUCT STILL AVAILABLE | |
| 3TY2781-2C | PRODUCT STILL AVAILABLE | |
| 3TY2781-2D | PRODUCT STILL AVAILABLE | |
| 3TY4803-0AB0 | 3RT1924-5AC21 | |
| 3TY4803-0AC0 | NO DIRECT REPLACEMENT | |
| 3TY4803-0AC1 | 3RT1924-5AC21 | |
| 3TY4803-0AD0 | 3RT1924-5AD01 | |
| 3TY4803-0AD1 | 3RT1924-5AD01 | |
| 3TY4803-0AE0 | NO DIRECT REPLACEMENT | |
| 3TY4803-0AF0 | 3RT1924-5AF01 | |
| 3TY4803-0AG0 | NO DIRECT REPLACEMENT | |
| 3TY4803-0AG1 | 3RT1924-5AG21 | |
| 3TY4803-0AH0 | 3RT1924-5AH01 | |
| 3TY4803-0AJ1 | 3RT1924-5AK61 | |
| 3TY4803-0AK1 | 3RT1924-5AK61 | |
| 3TY4803-0AK6 | 3RT1924-5AK61 | |
| 3TY4803-0AL0 | NO DIRECT REPLACEMENT | |
| 3TY4803-0AM0 | 3RT1924-5AP01 | |
| 3TY4803-0AM1 | 3RT1924-5AM21 | |
| 3TY4803-0AN1 | 3RT1924-5AP61 | |
| 3TY4803-0AP0 | 3RT1924-5AP01 | |
| 3TY4803-0AP1 | 3RT1924-5AP61 | |
| 3TY4803-0AP6 | 3RT1924-5AP61 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TY4803-0AQ0 | 3RT1924-5AV01 | |
| 3TY4803-0AR0 | 3RT1924-5AV01 | |
| 3TY4803-0AR1 | 3RT1924-5AV61 | |
| 3TY4803-0AS0 | 3RT1924-5AT61 | |
| 3TY4803-0AU0 | 3RT1924-5AP61 | |
| 3TY4803-0AU1 | 3RT1924-5AU61 | |
| 3TY4803-0AV0 | 3RT1924-5AV01 | |
| 3TY4803-0BA4 | NO DIRECT REPLACEMENT | |
| 3TY4803-0BB4 | NO DIRECT REPLACEMENT | |
| 3TY4803-0BC4 | NO DIRECT REPLACEMENT | |
| 3TY4803-0BD4 | NO DIRECT REPLACEMENT | |
| 3TY4803-0BE4 | NO DIRECT REPLACEMENT | |
| 3TY4803-0BE8 | NO DIRECT REPLACEMENT | |
| 3TY4803-0BF4 | NO DIRECT REPLACEMENT | |
| 3TY4803-0BG4 | NO DIRECT REPLACEMENT | |
| 3TY4803-0BK4 | NO DIRECT REPLACEMENT | |
| 3TY4803-0BM4 | NO DIRECT REPLACEMENT | |
| 3TY4803-0BN4 | NO DIRECT REPLACEMENT | |
| 3TY4803-0BP4 | NO DIRECT REPLACEMENT | |
| 3TY4803-0BQ4 | NO DIRECT REPLACEMENT | |
| 3TY4803-0BU4 | NO DIRECT REPLACEMENT | |
| 3TY4803-0BV4 | NO DIRECT REPLACEMENT | |
| 3TY4803-0BW4 | NO DIRECT REPLACEMENT | |
| 3TY4803-0BZ74 | NO DIRECT REPLACEMENT | |
| 3TY4803-0BZ80 | NO DIRECT REPLACEMENT | |
| 3TY4803-1AB8 | NO DIRECT REPLACEMENT | |
| 3TY4803-1AX8 | NO DIRECT REPLACEMENT | |
| 3TY4803-1BB4 | NO DIRECT REPLACEMENT | |
| 3TY6326-5AQ0 | NO DIRECT REPLACEMENT | |
| 3TY6344-0AF0 | NO DIRECT REPLACEMENT | |
| 3TY6344-0AM0 | NO DIRECT REPLACEMENT | |
| 3TY6344-0AQ0 | NO DIRECT REPLACEMENT | |
| 3TY6344-0AS0 | NO DIRECT REPLACEMENT | |
| 3TY6440-0A | 3RT1934-6A | |
| 3TY6442-0B | NO DIRECT REPLACEMENT | |
| 3TY6443-0BB4 | PRODUCT STILL AVAILABLE | |
| 3TY6443-0BC4 | PRODUCT STILL AVAILABLE | |
| 3TY6443-0BD4 | PRODUCT STILL AVAILABLE | |
| 3TY6443-0BE4 | PRODUCT STILL AVAILABLE | |
| 3TY6443-0BF4 | PRODUCT STILL AVAILABLE | |
| 3TY6443-0BG4 | PRODUCT STILL AVAILABLE | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TY6443-0BK4 | PRODUCT STILL AVAILABLE | |
| 3TY6443-0BM4 | PRODUCT STILL AVAILABLE | |
| 3TY6443-0BN4 | PRODUCT STILL AVAILABLE | |
| 3TY6443-0BP4 | PRODUCT STILL AVAILABLE | |
| 3TY6443-0BQ4 | PRODUCT STILL AVAILABLE | |
| 3TY6443-0BV4 | PRODUCT STILL AVAILABLE | |
| 3TY6443-0BW4 | PRODUCT STILL AVAILABLE | |
| 3TY6443-0BZ74 | PRODUCT STILL AVAILABLE | |
| 3TY6443-0BZ80 | PRODUCT STILL AVAILABLE | |
| 3TY6460-0A | 3RT1936-6A | |
| 3TY6462-0A | 3RT1936-7A | |
| 3TY6463-0AC1 | 3RT1935-5AC21 | |
| 3TY6463-0AD0 | 3RT1935-5AD01 | |
| 3TY6463-0AH0 | 3RT1935-5AH01 | |
| 3TY6463-0AK6 | 3RT1935-5AK61 | |
| 3TY6463-0AM0 | 3RT1935-5AP01 | |
| 3TY6463-0AM1 | 3RT1935-5AM21 | |
| 3TY6463-0AN1 | 3RT1935-5AP61 | |
| 3TY6463-0AP0 | 3RT1935-5AP01 | |
| 3TY6463-0AP6 | 3RT1935-5AP61 | |
| 3TY6463-0AQ0 | 3RT1935-5AV01 | |
| 3TY6463-0AS0 | 3RT1935-5AT61 | |
| 3TY6463-0BB4 | 3RT1934-5BB41 | |
| 3TY6463-0BE4 | 3RT1934-5BE41 | |
| 3TY6463-0BG4 | NO DIRECT REPLACEMENT | |
| 3TY6465-0AA8 | 3RT1944-5AK61 | |
| 3TY6465-0AB8 | 3RT1944-5AM21 | |
| 3TY6465-0AC8 | 3RT1944-5AP61 | |
| 3TY6465-0AD8 | 3RT1944-5AV61 | |
| 3TY6465-0AE8 | 3RT1944-5AT61 | |
| 3TY6465-0AF8 | 3RT1944-5AC21 | |
| 3TY6465-0AG8 | 3RT1944-5AU61 | |
| 3TY6470-0A | 3RT1944-6A | |
| 3TY6472-0A | 3RT1946-7A | |
| 3TY6480-0A | 3RT1945-6A | |
| 3TY6482-0A | 3RT1946-7A | |
| 3TY6483-0AC1 | 3RT1944-5AC21 OR 3RT1945-5AC21 | |
| 3TY6483-0AK6 | 3RT1944-5AK61 OR 3RT1945-5AK61 | |
| 3TY6483-0AM0 | 3RT1944-5AP01 OR 3RT1945-5AP01 | |
| 3TY6483-0AM1 | 3RT1944-5AM21 OR 3RT1945-5AM21 | |
| 3TY6483-0AN1 | 3RT1944-5AP61 OR 3RT1945-5AP61 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TY6483-0AP0 | 3RT1944-5AP01 OR 3RT1945-5AP01 | |
| 3TY6483-0AP1 | 3RT1944-5AP61 OR 3RT1945-5AP61 | |
| 3TY6483-0AP6 | 3RT1944-5AP61 OR 3RT1945-5AP61 | |
| 3TY6483-0AQ0 | 3RT1944-5AV01 OR 3RT1945-5AV01 | |
| 3TY6483-0AR0 | 3RT1944-5AV01 OR 3RT1945-5AV01 | |
| 3TY6483-0AR1 | 3RT1944-5AV61 OR 3RT1945-5AV61 | |
| 3TY6483-0AS0 | 3RT1944-5AT61 OR 3RT1945-5AT61 | |
| 3TY6483-0BB4 | 3RT1944-5BB41 | |
| 3TY6483-0BC4 | NO DIRECT REPLACEMENT | |
| 3TY6483-0BF4 | 3RT1944-5BF41 | |
| 3TY6483-0BG4 | NO DIRECT REPLACEMENT | |
| 3TY6483-0BK4 | NO DIRECT REPLACEMENT | |
| 3TY6483-0BM4 | 3RT1944-5BM41 | |
| 3TY6483-0BP4 | 3RT1944-5BP41 | |
| 3TY6483-0BQ4 | NO DIRECT REPLACEMENT | |
| 3TY6483-0BV4 | NO DIRECT REPLACEMENT | |
| 3TY6483-0BW4 | 3RT1944-5BW41 | |
| 3TY6485-0AA8 | 3RT1944-5AK61 OR 3RT1945-5AK61 | |
| 3TY6485-0AB8 | 3RT1944-5AM21 OR 3RT1945-5AM21 | |
| 3TY6485-0AC8 | 3RT1944-5AP61 OR 3RT1945-5AP61 | |
| 3TY6485-0AD8 | 3RT1944-5AV61 OR 3RT1945-5AV61 | |
| 3TY6485-0AE8 | 3RT1944-5AT61 OR 3RT1945-5AT61 | |
| 3TY6485-0AF8 | 3RT1944-5AC21 OR 3RT1945-5AC21 | |
| 3TY6485-0AG8 | 3RT1944-5AP01 OR 3RT1945-5AP01 | |
| 3TY6500-0A | SEE 3TY7500-0A | |
| 3TY6501-1A | 3RH1921-1EA11 | |
| 3TY6501-1B | 3RH1921-1EA11 | |
| 3TY6501-1E | 3RH1921-1CD01 | |
| 3TY6501-1K | 3RH1921-1KA11 | |
| 3TY6501-1L | 3RH1921-1KA11 | |
| 3TY6502-0A | SEE 3TY7500-0A | |
| 3TY6503-0AC1 | SEE 3TY7503-0AC2 | |
| 3TY6503-0AK6 | SEE 3TY7503-0AK6 | |
| 3TY6503-0AL1 | SEE 3TY7503-0AP6 | |
| 3TY6503-0AM1 | SEE 3TY7503-0AM1 | |
| 3TY6503-0AP0 | SEE 3TY7503-0AU1 | |
| 3TY6503-0AP6 | SEE 3TY7503-0AP6 | |
| 3TY6503-0AQ0 | SEE 3TY7503-0AV0 | |
| 3TY6503-0AS0 | SEE 3TY7503-0AS0 | |
| 3TY6503-0AV0 | SEE 3TY7503-0AV0 | |
| 3TY6503-0BB4 | SEE 3TY7503-0DB4 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TY6503-0BE4 | SEE 3TY7503-0DE4 | |
| 3TY6503-0BG4 | SEE 3TY7503-0DG4 | |
| 3TY6505-0AA8 | SEE 3TY7503-0AK6 | |
| 3TY6505-0AB8 | SEE 3TY7503-0AM1 | |
| 3TY6505-0AC8 | SEE 3TY7503-0AP6 | |
| 3TY6505-0AD8 | SEE 3TY7503-0AV0 | |
| 3TY6505-0AE8 | SEE 3TY7503-0AS0 | |
| 3TY6505-0AF8 | SEE 3TY7503-0AC2 | |
| 3TY6505-0AG8 | SEE 3TY7503-0AU1 | |
| 3TY6520-0A | SEE 3TY7520-0A | |
| 3TY6522-0A | SEE 3TY7522-0A | |
| 3TY6523-0AC1 | SEE 3TY7523-0AC2 | |
| 3TY6523-0AF0 | SEE 3TY7523-0AK6 | |
| 3TY6523-0AK6 | SEE 3TY7523-0AK6 | |
| 3TY6523-0AM1 | SEE 3TY7523-0AM1 | |
| 3TY6523-0AP0 | SEE 3TY7523-0AU1 | |
| 3TY6523-0AP1 | SEE 3TY7523-0AP6 | |
| 3TY6523-0AP6 | SEE 3TY7523-0AP6 | |
| 3TY6523-0AQ0 | SEE 3TY7523-0AV0 | |
| 3TY6523-0AS0 | SEE 3TY7523-0AS0 | |
| 3TY6523-0AV0 | SEE 3TY7523-0AV0 | |
| 3TY6523-0BB4 | SEE 3TY7523-0DB4 | |
| 3TY6523-0BF4 | SEE 3TY7523-0DF4 | |
| 3TY6523-0BG4 | SEE 3TY7523-0DG4 | |
| 3TY6523-0BK4 | SEE 3TY7523-0DK4 | |
| 3TY6523-0BM4 | SEE 3TY7523-0DM4 | |
| 3TY6523-0BN4 | NO DIRECT REPLACEMENT | |
| 3TY6523-0BP4 | SEE 3TY7523-0DP4 | |
| 3TY6523-0BV4 | SEE 3TY7523-0DV4 | |
| 3TY6523-0BW4 | SEE 3TY7523-0DW4 | |
| 3TY6525-0AA8 | SEE 3TY7523-0AK6 | |
| 3TY6525-0AB8 | SEE 3TY7523-0AM1 | |
| 3TY6525-0AC8 | SEE 3TY7523-0AP6 | |
| 3TY6525-0AD8 | SEE 3TY7523-0AV0 | |
| 3TY6525-0AE8 | SEE 3TY7523-0AS0 | |
| 3TY6525-0AF8 | SEE 3TY7523-0AC2 | |
| 3TY6525-0AG8 | SEE 3TY7523-0AU1 | |
| 3TY6525-0AH8 | NO DIRECT REPLACEMENT | |
| 3TY6540-0A | SEE 3TY7540-0A | |
| 3TY6542-0A | SEE 3TY7542-0A | |
| 3TY6543-0AC1 | SEE 3TY7543-0AC2 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TY6543-0AF0 | SEE 3TY7543-0AK6 | |
| 3TY6543-0AG1 | SEE 3TY7543-0AG1 | |
| 3TY6543-0AJ1 | SEE 3TY7543-0AJ1 | |
| 3TY6543-0AK6 | SEE 3TY7543-0AK6 | |
| 3TY6543-0AM1 | SEE 3TY7543-0AM1 | |
| 3TY6543-0AP0 | SEE 3TY7543-0AU1 | |
| 3TY6543-0AP6 | SEE 3TY7543-0AP6 | |
| 3TY6543-0AQ0 | SEE 3TY7543-0AV0 | |
| 3TY6543-0AS0 | SEE 3TY7543-0AS0 | |
| 3TY6543-0AV0 | SEE 3TY7543-0AV0 | |
| 3TY6543-0BB4 | SEE 3TY7543-0DB4 | |
| 3TY6543-0BG4 | SEE 3TY7543-0DG4 | |
| 3TY6545-0AA8 | SEE 3TY7543-0AK6 | |
| 3TY6545-0AB8 | SEE 3TY7543-0AM1 | |
| 3TY6545-0AC8 | SEE 3TY7543-0AP6 | |
| 3TY6545-0AD8 | SEE 3TY7543-0AV0 | |
| 3TY6545-0AE8 | SEE 3TY7543-0AS0 | |
| 3TY6545-0AF8 | SEE 3TY7543-0AC2 | |
| 3TY6545-0AG8 | SEE 3TY7543-0AU1 | |
| 3TY6560-0A | SEE 3TY7560-0A | |
| 3TY6561-1A | SEE 3TY7561-1AA00 | |
| 3TY6561-1B | SEE 3TY7561-1AA00 | |
| 3TY6561-1E | SEE 3TY7561-1EA00 | |
| 3TY6561-1K | SEE 3TY7561-1KA00 | |
| 3TY6561-1L | SEE 3TY7561-1KA00 | |
| 3TY6562-0A | SEE 3TY7560-0A | |
| 3TY6563-0AP6 | SEE 3TY7563-0AC2 | |
| 3TY6563-0AQ0 | SEE 3TY7563-0AV0 | |
| 3TY6563-0BB4 | SEE 3TY7563-0DB4 | |
| 3TY6563-0BE4 | SEE 3TY7563-0DE4 | |
| 3TY6563-0BG4 | SEE 3TY7563-0D | |
| 3TY6563-0BK4 | SEE 3TY7563-0DK4 | |
| 3TY6563-0BV4 | SEE 3TY7563-0DV4 | |
| 3TY6563-0BW4 | SEE 3TY7563-0DW4 | |
| 3TY6565-0AA8 | SEE 3TY7563-0AK6 | |
| 3TY6565-0AB8 | SEE 3TY7563-0AM1 | |
| 3TY6565-0AC8 | SEE 3TY7563-0AP6 | |
| 3TY6565-0AD8 | SEE 3TY7563-0AV0 | |
| 3TY6565-0AE8 | SEE 3TY7563-0AS0 | |
| 3TY6565-0AF8 | SEE 3TY7563-0AC2 | |
| 3TY6565-0AG8 | SEE 3TY7563-0AU1 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TY6566-0AC1 | SEE 3TY7563-0AC2 | |
| 3TY6566-0AJ1 | SEE 3TY7563-0AJ1 | |
| 3TY6566-0AK6 | SEE 3TY7563-0AK6 | |
| 3TY6566-0AM1 | SEE 3TY7563-0AM1 | |
| 3TY6566-0AP0 | SEE 3TY7563-0AU1 | |
| 3TY6566-0AP1 | SEE 3TY7563-0AP6 | |
| 3TY6566-0AP6 | SEE 3TY7563-0AP6 | |
| 3TY6566-0AQ0 | SEE 3TY7563-0AV0 | |
| 3TY6566-0AS0 | SEE 3TY7563-0AS0 | |
| 3TY6566-0AV0 | SEE 3TY7563-0AV0 | |
| 3TY6580-0A | SEE 3TY7570-0A | |
| 3TY6581-1D | SEE 3TY7561-1AA00 + 3TY7561-1KA00 | |
| 3TY6581-1E | SEE 3TY7561-1AA00 + 3TY7561-1KA00 | |
| 3TY6581-1F | SEE 3TY7561-1AA00 + 3TY7561-1KA00 | |
| 3TY6582-0A | SEE 3TY7572-0A | |
| 3TY6583-0AF0 | SEE 3TY7573-0CF7 | |
| 3TY6583-0AM0 | SEE 3TY7573-0CM7 | |
| 3TY6583-0AR1 | SEE 3TY7573-0CQ7 | |
| 3TY6583-0AS0 | SEE 3TY7573-0CS7 | |
| 3TY6584-0C | NO DIRECT REPLACEMENT | |
| 3TY6586-5DB4 | SEE 3TY7573-0BB4 | |
| 3TY6586-5DG4 | SEE 3TY7573-0BG4 | |
| 3TY7403-0AB0 | 3RT1924-5AC21 | |
| 3TY7403-0AC0 | NO DIRECT REPLACEMENT | |
| 3TY7403-0AC1 | 3RT1924-5AC21 | |
| 3TY7403-0AC2 | 3RT1924-5AC21 | |
| 3TY7403-0AD0 | 3RT1924-5AD01 | |
| 3TY7403-0AD2 | 3RT1924-5AD21 | |
| 3TY7403-0AE0 | NO DIRECT REPLACEMENT | |
| 3TY7403-0AF0 | 3RT1924-5AF01 | |
| 3TY7403-0AG0 | NO DIRECT REPLACEMENT | |
| 3TY7403-0AG1 | 3RT1924-5AG21 | |
| 3TY7403-0AG2 | 3RT1924-5AG21 | |
| 3TY7403-0AG6 | NO DIRECT REPLACEMENT | |
| 3TY7403-0AH0 | 3RT1924-5AH01 | |
| 3TY7403-0AJ1 | 3RT1924-5AK61 | |
| 3TY7403-0AJ2 | 3RT1924-5AK61 | |
| 3TY7403-0AK2 | 3RT1924-5AK61 | |
| 3TY7403-0AK6 | 3RT1924-5AK61 | |
| 3TY7403-0AL2 | 3RT1924-5AL21 | |
| 3TY7403-0AM0 | 3RT1924-5AP01 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TY7403-0AM1 | 3RT1924-5AM21 | |
| 3TY7403-0AM2 | 3RT1924-5AM21 | |
| 3TY7403-0AN1 | 3RT1924-5AP61 | |
| 3TY7403-0AN2 | 3RT1924-5AN21 | |
| 3TY7403-0AP0 | 3RT1924-5AP01 | |
| 3TY7403-0AP2 | 3RT1924-5AP61 | |
| 3TY7403-0AP6 | 3RT1924-5AP61 | |
| 3TY7403-0AQ0 | 3RT1924-5AV01 | |
| 3TY7403-0AR1 | 3RT1924-5AV61 | |
| 3TY7403-0AR2 | 3RT1924-5AV61 | |
| 3TY7403-0AS0 | 3RT1924-5AT61 | |
| 3TY7403-0AS2 | 3RT1924-5AT61 | |
| 3TY7403-0AU1 | 3RT1924-5AU61 | |
| 3TY7403-0AV0 | 3RT1924-5AV01 | |
| 3TY7403-0BB4 | NO DIRECT REPLACEMENT | |
| 3TY7403-0BD4 | NO DIRECT REPLACEMENT | |
| 3TY7403-0BE4 | NO DIRECT REPLACEMENT | |
| 3TY7403-0BE8 | NO DIRECT REPLACEMENT | |
| 3TY7403-0BF4 | NO DIRECT REPLACEMENT | |
| 3TY7403-0BM4 | NO DIRECT REPLACEMENT | |
| 3TY7403-0BN4 | NO DIRECT REPLACEMENT | |
| 3TY7403-6CC8 | NO DIRECT REPLACEMENT | |
| 3TY7440-0A | 3RT1934-6A | |
| 3TY7442-0A | 3RT1936-7A | |
| 3TY7443-0AC2 | 3RT1934-5AC21 OR 3RT1935-5AC21 | |
| 3TY7443-0AD0 | 3RT1934-5AD01 OR 3RT1935-5AD01 | |
| 3TY7443-0AD2 | 3RT1934-5AD21 OR 3RT1935-5AD21 | |
| 3TY7443-0AE0 | NO DIRECT REPLACEMENT | |
| 3TY7443-0AF0 | 3RT1934-5AF01 OR 3RT1935-5AF01 | |
| 3TY7443-0AG0 | NO DIRECT REPLACEMENT | |
| 3TY7443-0AG1 | 3RT1934-5AG21 OR 3RT1935-5AG21 | |
| 3TY7443-0AG2 | 3RT1934-5AG21 OR 3RT1935-5AG21 | |
| 3TY7443-0AH0 | 3RT1934-5AH01 OR 3RT1935-5AH01 | |
| 3TY7443-0AJ1 | 3RT1934-5AK61 OR 3RT1935-5AK61 | |
| 3TY7443-0AK2 | 3RT1934-5AK61 OR 3RT1935-5AK61 | |
| 3TY7443-0AK6 | 3RT1934-5AK61 OR 3RT1935-5AK61 | |
| 3TY7443-0AM0 | 3RT1934-5AP01 OR 3RT1935-5AP01 | |
| 3TY7443-0AM1 | 3RT1934-5AM21 OR 3RT1935-5AM21 | |
| 3TY7443-0AM2 | 3RT1934-5AM21 OR 3RT1935-5AM21 | |
| 3TY7443-0AN1 | 3RT1934-5AP61 OR 3RT1935-5AP61 | |
| 3TY7443-0AP0 | 3RT1934-5AP01 OR 3RT1935-5AP01 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TY7443-0AP6 | 3RT1934-5AP61 OR 3RT1935-5AP61 | |
| 3TY7443-0AQ0 | 3RT1934-5AV01 OR 3RT1935-5AV01 | |
| 3TY7443-0AR1 | 3RT1934-5AV61 OR 3RT1935-5AV61 | |
| 3TY7443-0AR2 | 3RT1934-5AV61 OR 3RT1935-5AV61 | |
| 3TY7443-0AS0 | 3RT1934-5AT61 OR 3RT1935-5AT61 | |
| 3TY7443-0AS2 | 3RT1934-5AT61 OR 3RT1935-5AT61 | |
| 3TY7443-0AU1 | 3RT1934-5AU61 OR 3RT1935-5AU61 | |
| 3TY7443-0AV0 | 3RT1934-5AV01 OR 3RT1935-5AV01 | |
| 3TY7443-0BA4 | NO DIRECT REPLACEMENT | |
| 3TY7443-0BB4 | 3RT1934-5BB41 | |
| 3TY7443-0BD4 | NO DIRECT REPLACEMENT | |
| 3TY7443-0BE4 | 3RT1934-5BE41 | |
| 3TY7443-0BE8 | NO DIRECT REPLACEMENT | |
| 3TY7443-0BF4 | 3RT1934-5BF41 | |
| 3TY7443-0BG4 | NO DIRECT REPLACEMENT | |
| 3TY7443-0BM4 | 3RT1934-5BM41 | |
| 3TY7443-0BN4 | NO DIRECT REPLACEMENT | |
| 3TY7443-0BQ4 | NO DIRECT REPLACEMENT | |
| 3TY7443-0BV4 | NO DIRECT REPLACEMENT | |
| 3TY7443-0BW4 | 3RT1934-5BW41 | |
| 3TY7450-0A | 3RT1935-6A | |
| 3TY7452-0A | 3RT1936-7A | |
| 3TY7460-0A | 3RT1936-6A | |
| 3TY7461-1F | 3RH1921-1CD01 | |
| 3TY7462-0A | 3RT1936-7A | |
| 3TY7463-0AC1 | 3RT1935-5AC21 OR 3RT1944-5AC21 | |
| 3TY7463-0AC2 | 3RT1935-5AC21 OR 3RT1944-5AC21 | |
| 3TY7463-0AD0 | 3RT1935-5AD01 OR 3RT1944-5AD01 | |
| 3TY7463-0AD2 | 3RT1935-5AD21 OR 3RT1944-5AD21 | |
| 3TY7463-0AG1 | 3RT1935-5AG21 OR 3RT1944-5AG21 | |
| 3TY7463-0AH0 | 3RT1935-5AH01 OR 3RT1944-5AH01 | |
| 3TY7463-0AJ1 | 3RT1935-5AK61 OR 3RT1944-5AK61 | |
| 3TY7463-0AJ2 | 3RT1935-5AK61 OR 3RT1944-5AK61 | |
| 3TY7463-0AK6 | 3RT1935-5AK61 OR 3RT1944-5AK61 | |
| 3TY7463-0AL2 | 3RT1935-5AL21 OR 3RT1944-5AL21 | |
| 3TY7463-0AM0 | 3RT1935-5AP01 OR 3RT1944-5AP01 | |
| 3TY7463-0AM1 | 3RT1935-5AM21 OR 3RT1944-5AM21 | |
| 3TY7463-0AM2 | 3RT1935-5AM21 OR 3RT1944-5AM21 | |
| 3TY7463-0AN1 | 3RT1935-5AP61 OR 3RT1944-5AP61 | |
| 3TY7463-0AP0 | 3RT1935-5AP01 OR 3RT1944-5AP01 | |
| 3TY7463-0AP1 | 3RT1935-5AP61 OR 3RT1944-5AP61 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TY7463-0AP6 | 3RT1935-5AP61 OR 3RT1944-5AP61 | |
| 3TY7463-0AQ0 | 3RT1935-5AV01 OR 3RT1944-5AV01 | |
| 3TY7463-0AR0 | 3RT1935-5AV01 OR 3RT1944-5AV01 | |
| 3TY7463-0AR1 | 3RT1935-5AV61 OR 3RT1944-5AV61 | |
| 3TY7463-0AS0 | 3RT1935-5AT61 OR 3RT1944-5AT61 | |
| 3TY7463-0AU1 | 3RT1935-5AU61 OR 3RT1944-5AU61 | |
| 3TY7463-0AV0 | 3RT1935-5AV01 OR 3RT1944-5AV01 | |
| 3TY7463-0BB4 | 3RT1935-5BB41 OR 3RT1935-5BB41 | |
| 3TY7463-0BF4 | 3RT1935-5BF41 OR 3RT1935-5BF41 | |
| 3TY7463-0BW4 | 3RT1935-5BW41 OR 3RT1935-5BW41 | |
| 3TY7463-0DB4 | 3RT1935-5BB41 OR 3RT1935-5BB41 | |
| 3TY7463-0DD4 | NO DIRECT REPLACEMENT | |
| 3TY7463-0DG4 | NO DIRECT REPLACEMENT | |
| 3TY7463-0DV4 | NO DIRECT REPLACEMENT | |
| 3TY7470-0A | 3RT1944-6A | |
| 3TY7472-0A | 3RT1946-7A | |
| 3TY7480-0A | 3RT1945-6A | |
| 3TY7480-0B | 3RT1945-6A | |
| 3TY7481-1F | 3RH1921-1CD01 | |
| 3TY7482-0A | 3RT1946-7A | |
| 3TY7483-0AB0 | 3RT1945-5AC21 | |
| 3TY7483-0AC1 | 3RT1945-5AC21 | |
| 3TY7483-0AC2 | 3RT1945-5AC21 | |
| 3TY7483-0AD\ | 3RT1945-5AD21 | |
| 3TY7483-0AD0 | 3RT1945-5AD01 | |
| 3TY7483-0AD2 | 3RT1945-5AD21 | |
| 3TY7483-0AF0 | 3RT1945-5AF01 | |
| 3TY7483-0AG1 | 3RT1945-5AG21 | |
| 3TY7483-0AG2 | 3RT1945-5AG21 | |
| 3TY7483-0AJ1 | 3RT1945-5AK61 | |
| 3TY7483-0AJ2 | 3RT1945-5AK61 | |
| 3TY7483-0AK1 | 3RT1945-5AK61 | |
| 3TY7483-0AK6 | 3RT1945-5AK61 | |
| 3TY7483-0AM0 | 3RT1945-5AP01 | |
| 3TY7483-0AM1 | 3RT1945-5AM21 | |
| 3TY7483-0AN1 | 3RT1945-5AP61 | |
| 3TY7483-0AP0 | 3RT1945-5AP01 | |
| 3TY7483-0AP6 | 3RT1945-5AP61 | |
| 3TY7483-0AQ0 | 3RT1945-5AV01 | |
| 3TY7483-0AR1 | 3RT1945-5AV61 | |
| 3TY7483-0AS0 | 3RT1945-5AT61 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TY7483-0AU1 | 3RT1945-5AU61 | |
| 3TY7483-0AV0 | 3RT1945-5AV01 | |
| 3TY7483-0DB4 | 3RT1944-5BB41 | |
| 3TY7483-0DG4 | NO DIRECT REPLACEMENT | |
| 3TY7483-0DV4 | NO DIRECT REPLACEMENT | |
| 3TY7490-0A | 3RT1946-6A | |
| 3TY7492-0A | 3RT1946-7A | |
| 3TY7500-0A | PRODUCT STILL AVAILABLE | |
| 3TY7500-0B | PRODUCT STILL AVAILABLE | |
| 3TY7502-0A | PRODUCT STILL AVAILABLE | |
| 3TY7503-0AB0 | PRODUCT STILL AVAILABLE | |
| 3TY7503-0AC1 | PRODUCT STILL AVAILABLE | |
| 3TY7503-0AC2 | PRODUCT STILL AVAILABLE | |
| 3TY7503-0AD0 | PRODUCT STILL AVAILABLE | |
| 3TY7503-0AJ1 | PRODUCT STILL AVAILABLE | |
| 3TY7503-0AJ2 | PRODUCT STILL AVAILABLE | |
| 3TY7503-0AK6 | PRODUCT STILL AVAILABLE | |
| 3TY7503-0AM1 | PRODUCT STILL AVAILABLE | |
| 3TY7503-0AN1 | PRODUCT STILL AVAILABLE | |
| 3TY7503-0AP0 | PRODUCT STILL AVAILABLE | |
| 3TY7503-0AP6 | PRODUCT STILL AVAILABLE | |
| 3TY7503-0AQ0 | SEE 3TY7503-0AV0 | |
| 3TY7503-0AR1 | PRODUCT STILL AVAILABLE | |
| 3TY7503-0AS0 | PRODUCT STILL AVAILABLE | |
| 3TY7503-0AU1 | PRODUCT STILL AVAILABLE | |
| 3TY7503-0AV0 | PRODUCT STILL AVAILABLE | |
| 3TY7503-0DB4 | PRODUCT STILL AVAILABLE | |
| 3TY7510-0A | PRODUCT STILL AVAILABLE | |
| 3TY7512-0A | PRODUCT STILL AVAILABLE | |
| 3TY7520-0A | PRODUCT STILL AVAILABLE | |
| 3TY7520-0B | PRODUCT STILL AVAILABLE | |
| 3TY7522-0A | PRODUCT STILL AVAILABLE | |
| 3TY7523-0AC1 | PRODUCT STILL AVAILABLE | |
| 3TY7523-0AD0 | PRODUCT STILL AVAILABLE | |
| 3TY7523-0AF0 | PRODUCT STILL AVAILABLE | |
| 3TY7523-0AG1 | PRODUCT STILL AVAILABLE | |
| 3TY7523-0AG2 | PRODUCT STILL AVAILABLE | |
| 3TY7523-0AJ1 | PRODUCT STILL AVAILABLE | |
| 3TY7523-0AK6 | PRODUCT STILL AVAILABLE | |
| 3TY7523-0AM0 | PRODUCT STILL AVAILABLE | |
| 3TY7523-0AM1 | PRODUCT STILL AVAILABLE | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TY7523-0AM2 | PRODUCT STILL AVAILABLE | |
| 3TY7523-0AN1 | PRODUCT STILL AVAILABLE | |
| 3TY7523-0AP0 | PRODUCT STILL AVAILABLE | |
| 3TY7523-0AP2 | PRODUCT STILL AVAILABLE | |
| 3TY7523-0AP6 | PRODUCT STILL AVAILABLE | |
| 3TY7523-0AQ0 | SEE 3TY7523-0AV0 | |
| 3TY7523-0AR0 | PRODUCT STILL AVAILABLE | |
| 3TY7523-0AR1 | PRODUCT STILL AVAILABLE | |
| 3TY7523-0AS0 | PRODUCT STILL AVAILABLE | |
| 3TY7523-0AU1 | PRODUCT STILL AVAILABLE | |
| 3TY7523-0AV0 | PRODUCT STILL AVAILABLE | |
| 3TY7523-0DB4 | PRODUCT STILL AVAILABLE | |
| 3TY7530-0A | PRODUCT STILL AVAILABLE | |
| 3TY7540-0A | PRODUCT STILL AVAILABLE | |
| 3TY7542-0A | PRODUCT STILL AVAILABLE | |
| 3TY7543-0AF0 | PRODUCT STILL AVAILABLE | |
| 3TY7543-0AG1 | PRODUCT STILL AVAILABLE | |
| 3TY7543-0AG2 | PRODUCT STILL AVAILABLE | |
| 3TY7543-0AJ1 | PRODUCT STILL AVAILABLE | |
| 3TY7543-0AK6 | PRODUCT STILL AVAILABLE | |
| 3TY7543-0AM1 | PRODUCT STILL AVAILABLE | |
| 3TY7543-0AN1 | PRODUCT STILL AVAILABLE | |
| 3TY7543-0AP0 | PRODUCT STILL AVAILABLE | |
| 3TY7543-0AP6 | PRODUCT STILL AVAILABLE | |
| 3TY7543-0AQ0 | SEE 3TY7543-0AV0 | |
| 3TY7543-0AR0 | PRODUCT STILL AVAILABLE | |
| 3TY7543-0AR1 | PRODUCT STILL AVAILABLE | |
| 3TY7543-0AS0 | PRODUCT STILL AVAILABLE | |
| 3TY7543-0AU1 | PRODUCT STILL AVAILABLE | |
| 3TY7543-0AV0 | PRODUCT STILL AVAILABLE | |
| 3TY7543-0DB4 | PRODUCT STILL AVAILABLE | |
| 3TY7543-0DF4 | PRODUCT STILL AVAILABLE | |
| 3TY7550-0A | PRODUCT STILL AVAILABLE | |
| 3TY7552-0A | PRODUCT STILL AVAILABLE | |
| 3TY7560-0A | PRODUCT STILL AVAILABLE | |
| 3TY7560-0B | PRODUCT STILL AVAILABLE | |
| 3TY7561-1A | SEE 3TY7561-1AA00 | |
| 3TY7561-1AA00 | PRODUCT STILL AVAILABLE | |
| 3TY7561-1B | SEE 3TY7561-1AA00 | |
| 3TY7561-1E | PRODUCT STILL AVAILABLE | |
| 3TY7561-1K | SEE 3TY7561-1KA00 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TY7561-1KA00 | PRODUCT STILL AVAILABLE | |
| 3TY7561-1L | SEE 3TY7561-1KA00 | |
| 3TY7561-1N | PRODUCT STILL AVAILABLE | |
| 3TY7561-1P | PRODUCT STILL AVAILABLE | |
| 3TY7561-1U | PRODUCT STILL AVAILABLE | |
| 3TY7561-1V | PRODUCT STILL AVAILABLE | |
| 3TY7562-0A | PRODUCT STILL AVAILABLE | |
| 3TY7563-0AG1 | PRODUCT STILL AVAILABLE | |
| 3TY7563-0AG2 | PRODUCT STILL AVAILABLE | |
| 3TY7563-0AJ1 | PRODUCT STILL AVAILABLE | |
| 3TY7563-0AK6 | PRODUCT STILL AVAILABLE | |
| 3TY7563-0AM1 | PRODUCT STILL AVAILABLE | |
| 3TY7563-0AM2 | PRODUCT STILL AVAILABLE | |
| 3TY7563-0AN1 | PRODUCT STILL AVAILABLE | |
| 3TY7563-0AP0 | PRODUCT STILL AVAILABLE | |
| 3TY7563-0AP1 | PRODUCT STILL AVAILABLE | |
| 3TY7563-0AP6 | PRODUCT STILL AVAILABLE | |
| 3TY7563-0AQ0 | SEE 3TY7563-0AV0 | |
| 3TY7563-0AR0 | PRODUCT STILL AVAILABLE | |
| 3TY7563-0AR1 | PRODUCT STILL AVAILABLE | |
| 3TY7563-0AS0 | PRODUCT STILL AVAILABLE | |
| 3TY7563-0AU1 | PRODUCT STILL AVAILABLE | |
| 3TY7563-0AV0 | PRODUCT STILL AVAILABLE | |
| 3TY7563-0DF4 | PRODUCT STILL AVAILABLE | |
| 3TY7570-0A | PRODUCT STILL AVAILABLE | |
| 3TY7573-0CF7 | PRODUCT STILL AVAILABLE | |
| 3TY7573-0CM7 | PRODUCT STILL AVAILABLE | |
| 3TY7573-0CQ7 | PRODUCT STILL AVAILABLE | |
| 3TY7573-0CS7 | PRODUCT STILL AVAILABLE | |
| 3TY7680-0A | SEE 3TY7680-0B | |
| 3TY7680-0B | PRODUCT STILL AVAILABLE | |
| 3TY7683-0AJ1 | NO DIRECT REPLACEMENT | |
| 3TY7683-0AK1 | SEE 3TY7683-0CF7 | |
| 3TY7683-0AN1 | SEE 3TY7683-0CM7 | |
| 3TY7683-0AP1 | SEE 3TY7683-0CM7 | |
| 3TY7683-0AQ0 | SEE 3TY7683-0CQ7 | |
| 3TY7683-0AS0 | SEE 3TY7683-0CS7 | |
| 3TY7683-0AS1 | NO DIRECT REPLACEMENT | |
| 3TY7683-0CF7 | PRODUCT STILL AVAILABLE | |
| 3TY7683-0CM7 | PRODUCT STILL AVAILABLE | |
| 3TY7683-0CQ7 | PRODUCT STILL AVAILABLE | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3TY7690-0B | PRODUCT STILL AVAILABLE | |
| 3TY7693-0CF7 | PRODUCT STILL AVAILABLE | |
| 3TY7693-0CQ7 | PRODUCT STILL AVAILABLE | |
| 3UA3300-1G | PRODUCT STILL AVAILABLE | |
| 3UA5000-0A | 3RU1116-0AB0 | |
| 3UA5000-0C | 3RU1116-0CB0 OR 3RU1116-0BB0 | |
| 3UA5000-0E | 3RU1116-0EB0 OR 3RU1116-0DB0 | |
| 3UA5000-0G | 3RU1116-0GB0 OR 3RU1116-0FB0 | |
| 3UA5000-0J | 3RU1116-0JB0 OR 3RU1116-0HB0 | |
| 3UA5000-0K | 3RU1116-0JB0 OR 3RU1116-0KB0 | |
| 3UA5000-1A | 3RU1116-0KB0 OR 3RU1116-1AB0 | |
| 3UA5000-1B | 3RU1116-1AB0 OR 3RU1116-1BB0 | |
| 3UA5000-1C | 3RU1116-1BB0 OR 3RU1116-1CB0 | |
| 3UA5000-1D | 3RU1116-1CB0 OR 3RU1116-1DB0 | |
| 3UA5000-1E | 3RU1116-1DB0 OR 3RU1116-1EB0 | |
| 3UA5000-1F | 3RU1116-1EB0 OR 3RU1116-1FB0 | |
| 3UA5000-1G | 3RU1116-1FB0 OR 3RU1116-1GB0 | |
| 3UA5000-1H | 3RU1116-1GB0 OR 3RU1116-1HB0 | |
| 3UA5000-1J | 3RU1116-1HB0 OR 3RU1116-1JB0 | |
| 3UA5000-1K | 3RU1116-1JB0 OR 3RU1116-1KB0 | |
| 3UA5000-2S | 3RU1116-1KB0 OR 3RU1126-4AB0 | |
| 3UA5200-0A | 3RU1116-0AB0 | |
| 3UA5200-0C | 3RU1116-0CB0 OR 3RU1116-0BB0 | |
| 3UA5200-0E | 3RU1116-0EB0 OR 3RU1116-0DB0 | |
| 3UA5200-0G | 3RU1116-0GB0 OR 3RU1116-0FB0 | |
| 3UA5200-0J | 3RU1116-0JB0 OR 3RU1116-0HB0 | |
| 3UA5200-0K | 3RU1116-0JB0 OR 3RU1116-0KB0 | |
| 3UA5200-1A | 3RU1116-0KB0 OR 3RU1116-1AB0 | |
| 3UA5200-1B | 3RU1116-1AB0 OR 3RU1116-1BB0 | |
| 3UA5200-1C | 3RU1116-1BB0 OR 3RU1116-1CB0 | |
| 3UA5200-1D | 3RU1116-1CB0 OR 3RU1116-1DB0 | |
| 3UA5200-1E | 3RU1116-1DB0 OR 3RU1116-1EB0 | |
| 3UA5200-1F | 3RU1116-1EB0 OR 3RU1116-1FB0 | |
| 3UA5200-1G | 3RU1116-1FB0 OR 3RU1116-1GB0 | |
| 3UA5200-1H | 3RU1116-1GB0 OR 3RU1116-1HB0 | |
| 3UA5200-1J | 3RU1116-1HB0 OR 3RU1116-1JB0 | |
| 3UA5200-1K | 3RU1116-1JB0 OR 3RU1116-1KB0 | |
| 3UA5200-2A | 3RU1126-4AB0 OR 3RU1126-1KB0 | |
| 3UA5200-2B | 3RU1126-4AB0 OR 3RU1126-4BB0 | |
| 3UA5200-2C | 3RU1126-4BB0 OR 3RU1126-4DB0 | |
| 3UA5400-0A | 3RU1116-0AB0 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3UA5400-0C | 3RU1116-0CB0 OR 3RU1116-0BB0 | |
| 3UA5400-0E | 3RU1116-0EB0 OR 3RU1116-0DB0 | |
| 3UA5400-0G | 3RU1116-0GB0 OR 3RU1116-0FB0 | |
| 3UA5400-0J | 3RU1116-0JB0 OR 3RU1116-0HB0 | |
| 3UA5400-0K | 3RU1116-0JB0 OR 3RU1116-0KB0 | |
| 3UA5400-1A | 3RU1116-0KB0 OR 3RU1116-1AB0 | |
| 3UA5400-1B | 3RU1116-1AB0 OR 3RU1116-1BB0 | |
| 3UA5400-1C | 3RU1116-1BB0 OR 3RU1116-1CB0 | |
| 3UA5400-1D | 3RU1116-1CB0 OR 3RU1116-1DB0 | |
| 3UA5400-1E | 3RU1116-1DB0 OR 3RU1116-1EB0 | |
| 3UA5400-1F | 3RU1116-1EB0 OR 3RU1116-1FB0 | |
| 3UA5400-1G | 3RU1116-1FB0 OR 3RU1116-1GB0 | |
| 3UA5400-1H | 3RU1116-1GB0 OR 3RU1116-1HB0 | |
| 3UA5400-1J | 3RU1116-1HB0 OR 3RU1116-1JB0 | |
| 3UA5400-1K | 3RU1116-1JB0 OR 3RU1116-1KB0 | |
| 3UA5400-2A | 3RU1126-4AB0 OR 3RU1126-1KB0 | |
| 3UA5400-2B | 3RU1126-4AB0 OR 3RU1126-4BB0 | |
| 3UA5400-2C | 3RU1126-4BB0 OR 3RU1126-4DB0 | |
| 3UA5400-2D | 3RU1126-4DB0 OR 3RU1136-4EB0 | |
| 3UA5400-2Q | 3RU1136-4EB0 OR 3RU1136-4FB0 | |
| 3UA5500-0A | 3RU1116-0AB0 | |
| 3UA5500-0C | 3RU1116-0CB0 OR 3RU1116-0BB0 | |
| 3UA5500-0E | 3RU1116-0EB0 OR 3RU1116-0DB0 | |
| 3UA5500-0G | 3RU1116-0GB0 OR 3RU1116-0FB0 | |
| 3UA5500-0J | 3RU1116-0JB0 OR 3RU1116-0HB0 | |
| 3UA5500-0K | 3RU1116-0JB0 OR 3RU1116-0KB0 | |
| 3UA5500-1A | 3RU1116-0KB0 OR 3RU1116-1AB0 | |
| 3UA5500-1B | 3RU1116-1AB0 OR 3RU1116-1BB0 | |
| 3UA5500-1C | 3RU1116-1BB0 OR 3RU1116-1CB0 | |
| 3UA5500-1D | 3RU1116-1CB0 OR 3RU1116-1DB0 | |
| 3UA5500-1E | 3RU1116-1DB0 OR 3RU1116-1EB0 | |
| 3UA5500-1F | 3RU1116-1EB0 OR 3RU1116-1FB0 | |
| 3UA5500-1G | 3RU1116-1FB0 OR 3RU1116-1GB0 | |
| 3UA5500-1H | 3RU1116-1GB0 OR 3RU1116-1HB0 | |
| 3UA5500-1J | 3RU1116-1HB0 OR 3RU1116-1JB0 | |
| 3UA5500-1K | 3RU1116-1JB0 OR 3RU1116-1KB0 | |
| 3UA5500-2A | 3RU1126-4AB0 OR 3RU1126-1KB0 | |
| 3UA5500-2B | 3RU1126-4AB0 OR 3RU1126-4BB0 | |
| 3UA5500-2C | 3RU1126-4BB0 OR 3RU1126-4DB0 | |
| 3UA5500-2D | 3RU1126-4DB0 OR 3RU1136-4EB0 | |
| 3UA5500-2Q | 3RU1136-4EB0 OR 3RU1136-4FB0 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3UA5500-2R | 3RU1136-4FB0 | |
| 3UA5500-8M | 3RU1136-4GB0 OR 3RU1136-4FB0 | |
| 3UA5800-16 | NO DIRECT REPLACEMENT | |
| 3UA5800-1G | 3RU1116-1FB0 OR 3RU1116-1GB0 | |
| 3UA5800-2B | 3RU1126-4AB0 OR 3RU1126-4BB0 | |
| 3UA5800-2C | 3RU1126-4BB0 OR 3RU1126-4DB0 | |
| 3UA5800-2D | 3RU1126-4DB0 OR 3RU1136-4EB0 | |
| 3UA5800-2E | 3RU1136-4FB0 OR 3RU1136-4EB0 | |
| 3UA5800-2F | 3RU1136-4HB0 OR 3RU1136-4GB0 | |
| 3UA5800-2P | 3RU1146-4JB0 | |
| 3UA5800-2T | 3RU1146-4JB0 | |
| 3UA5800-2TS21 | NO DIRECT REPLACEMENT | |
| 3UA5800-2U | 3RU1146-4LB0 OR 3RU1146-4KB0 | |
| 3UA5800-2US21 | NO DIRECT REPLACEMENT | |
| 3UA5800-2V | 3RU1146-4KB0 OR 3RU1146-4JB0 | |
| 3UA5800-8A | 3RU1136-4AB0 OR 3RU1136-4BB0 | |
| 3UA5800-8W | 3RU1146-4LB0 OR 3RU1146-4MB0 | |
| 3UA5900-0A | 3RU1116-0AB0 | |
| 3UA5900-0C | 3RU1116-0CB0 OR 3RU1116-0BB0 | |
| 3UA5900-0E | 3RU1116-0EB0 OR 3RU1116-0DB0 | |
| 3UA5900-0G | 3RU1116-0GB0 OR 3RU1116-0FB0 | |
| 3UA5900-0J | 3RU1116-0JB0 OR 3RU1116-0HB0 | |
| 3UA5900-0K | 3RU1116-0JB0 OR 3RU1116-0KB0 | |
| 3UA5900-1A | 3RU1116-0KB0 OR 3RU1116-1AB0 | |
| 3UA5900-1B | 3RU1116-1AB0 OR 3RU1116-1BB0 | |
| 3UA5900-1C | 3RU1116-1BB0 OR 3RU1116-1CB0 | |
| 3UA5900-1D | 3RU1116-1CB0 OR 3RU1116-1DB0 | |
| 3UA5900-1E | 3RU1116-1DB0 OR 3RU1116-1EB0 | |
| 3UA5900-1F | 3RU1116-1EB0 OR 3RU1116-1FB0 | |
| 3UA5900-1G | 3RU1116-1FB0 OR 3RU1116-1GB0 | |
| 3UA5900-1H | 3RU1116-1GB0 OR 3RU1116-1HB0 | |
| 3UA5900-1J | 3RU1116-1HB0 OR 3RU1116-1JB0 | |
| 3UA5900-1JZ0E | NO DIRECT REPLACEMENT | |
| 3UA5900-1K | 3RU1116-1JB0 OR 3RU1116-1KB0 | |
| 3UA5900-1KZ0E | NO DIRECT REPLACEMENT | |
| 3UA5900-2A | 3RU1126-4AB0 OR 3RU1126-1KB0 | |
| 3UA5900-2AZ0E | NO DIRECT REPLACEMENT | |
| 3UA5900-2B | 3RU1126-4AB0 OR 3RU1126-4BB0 | |
| 3UA5900-2BZ0E | NO DIRECT REPLACEMENT | |
| 3UA5900-2C | 3RU1126-4BB0 OR 3RU1126-4DB0 | |
| 3UA5900-2CZ0E | NO DIRECT REPLACEMENT | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3UA5900-2D | 3RU1126-4DB0 OR 3RU1136-4EB0 | |
| 3UA5900-2DZ0E | NO DIRECT REPLACEMENT | |
| 3UA5900-2E | 3RU1136-4FB0 OR 3RU1136-4EB0 | |
| 3UA5900-2EZ0E | NO DIRECT REPLACEMENT | |
| 3UA5900-2M | 3RU1136-4GB0 OR 3RU1136-4FB0 | |
| 3UA5900-2MZ0E | NO DIRECT REPLACEMENT | |
| 3UA5900-2P | 3RU1146-4JB0 OR 3RU1146-4KB0 | |
| 3UA5900-2T | 3RU1146-4JB0 OR 3RU1146-4HB0 | |
| 3UA6000-2H | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RB1056-1FG0 |
| 3UA6000-2W | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RB1056-1FG0 |
| 3UA6000-2X | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RB1056-1FG0 |
| 3UA6000-3H | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RB1056-1FG0 |
| 3UA6000-3J | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RB1056-1FG0 |
| 3UA6001-2H | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RB1056-1FG0 |
| 3UA6001-2W | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RB1056-1FG0 |
| 3UA6001-2X | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RB1056-1FG0 |
| 3UA6001-3H | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RB1056-1FG0 |
| 3UA6001-3J | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RB1056-1FG0 |
| 3UA6100-2H | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RB1056-1FG0 |
| 3UA6100-2W | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RB1056-1FG0 |
| 3UA6100-2X | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RB1056-1FG0 |
| 3UA6100-3H | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RB1056-1FG0 |
| 3UA6100-3J | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RB1056-1FG0 |
| 3UA6100-3K | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RB1056-1FG0 |
| 3UA6101-2H | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RB1056-1FG0 |
| 3UA6101-2W | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RB1056-1FG0 |
| 3UA6101-2X | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RB1056-1FG0 |
| 3UA6101-3H | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RB1056-1FG0 |
| 3UA6101-3J | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RB1056-1FG0 |
| 3UA6101-3K | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RB1056-1FG0 |
| 3UA6200-2H | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RB1056-1FG0, 3RB1066-1GG0 OR 3RB1066-1K( |
| 3UA6200-2W | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RB1056-1FG0, 3RB1066-1GG0 OR 3RB1066-1K( |
| 3UA6200-2WZ0E | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | NO DIRECT REPLACEMENT |
| 3UA6200-2X | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RB1056-1FG0, 3RB1066-1GG0 OR 3RB1066-1K( |
| 3UA6200-2XZ0E | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | NO DIRECT REPLACEMENT |
| 3UA6200-3H | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RB1056-1FG0, 3RB1066-1GG0 OR 3RB1066-1K( |
| 3UA6200-3J | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RB1056-1FG0, 3RB1066-1GG0 OR 3RB1066-1K( |
| 3UA6200-3K | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RB1056-1FG0, 3RB1066-1GG0 OR 3RB1066-1K( |
| 3UA6200-3L | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RB1056-1FG0, 3RB1066-1GG0 OR 3RB1066-1K( |
| 3UA6200-3M | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RB1056-1FG0, 3RB1066-1GG0 OR 3RB1066-1K( |
| 3UA6201-2H | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RB1056-1FG0, 3RB1066-1GG0 OR 3RB1066-1K( |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3UA6201-2W | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RB1056-1FG0, 3RB1066-1GG0 OR 3RB1066-1K( |
| 3UA6201-2X | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RB1056-1FG0, 3RB1066-1GG0 OR 3RB1066-1K( |
| 3UA6201-3H | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RB1056-1FG0, 3RB1066-1GG0 OR 3RB1066-1K( |
| 3UA6201-3J | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RB1056-1FG0, 3RB1066-1GG0 OR 3RB1066-1K( |
| 3UA6201-3K | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RB1056-1FG0, 3RB1066-1GG0 OR 3RB1066-1K( |
| 3UA6201-3L | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RB1056-1FG0, 3RB1066-1GG0 OR 3RB1066-1K( |
| 3UA6201-3M | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RB1056-1FG0, 3RB1066-1GG0 OR 3RB1066-1K( |
| 3UA6201-3N | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RB1056-1FG0, 3RB1066-1GG0 OR 3RB1066-1K( |
| 3UA62-2H | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RB1056-1FG0, 3RB1066-1GG0 OR 3RB1066-1K( |
| 3UA62-2W | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RB1056-1FG0, 3RB1066-1GG0 OR 3RB1066-1K( |
| 3UA62-2X | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RB1056-1FG0, 3RB1066-1GG0 OR 3RB1066-1K( |
| 3UA62-3H | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RB1056-1FG0, 3RB1066-1GG0 OR 3RB1066-1K( |
| 3UA62-3J | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RB1056-1FG0, 3RB1066-1GG0 OR 3RB1066-1K( |
| 3UA62-3K | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RB1056-1FG0, 3RB1066-1GG0 OR 3RB1066-1K( |
| 3UA62-3L | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RB1056-1FG0, 3RB1066-1GG0 OR 3RB1066-1K( |
| 3UA62-3M | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RB1056-1FG0, 3RB1066-1GG0 OR 3RB1066-1K( |
| 3UA6600-2K | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RB1056-1FG0, 3RB1066-1GG0 OR 3RB1066-1K( |
| 3UA6600-3B | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RB1056-1FG0, 3RB1066-1GG0 OR 3RB1066-1K( |
| 3UA6600-3C | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RB1056-1FG0, 3RB1066-1GG0 OR 3RB1066-1K( |
| 3UA6600-3D | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RB1056-1FG0, 3RB1066-1GG0 OR 3RB1066-1K( |
| 3UA6600-3E | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RB1056-1FG0, 3RB1066-1GG0 OR 3RB1066-1K( |
| 3UA66-2K | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RB1056-1FG0, 3RB1066-1GG0 OR 3RB1066-1K( |
| 3UA66-3B | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RB1056-1FG0, 3RB1066-1GG0 OR 3RB1066-1K( |
| 3UA66-3C | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RB1056-1FG0, 3RB1066-1GG0 OR 3RB1066-1K( |
| 3UA66-3D | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RB1056-1FG0, 3RB1066-1GG0 OR 3RB1066-1K( |
| 3UA66-3E | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | AFTER SEPTEMBER 2001, ORDER 3RB1056-1FG0, 3RB1066-1GG0 OR 3RB1066-1K( |
| 3UA6800-3F | PRODUCT STILL AVAILABLE | |
| 3UA6800-3G | PRODUCT STILL AVAILABLE | |
| 3UA7010-0A | 3RU1116-0AB0 | |
| 3UA7010-0C | 3RU1116-0CB0 OR 3RU1116-0BB0 | |
| 3UA7010-0E | 3RU1116-0EB0 OR 3RU1116-0DB0 | |
| 3UA7010-0G | 3RU1116-0GB0 OR 3RU1116-0FB0 | |
| 3UA7010-0J | 3RU1116-0JB0 OR 3RU1116-0HB0 | |
| 3UA7010-0K | 3RU1116-0JB0 OR 3RU1116-0KB0 | |
| 3UA7010-1A | 3RU1116-0KB0 OR 3RU1116-1AB0 | |
| 3UA7010-1B | 3RU1116-1AB0 OR 3RU1116-1BB0 | |
| 3UA7010-1C | 3RU1116-1BB0 OR 3RU1116-1CB0 | |
| 3UA7010-1D | 3RU1116-1CB0 OR 3RU1116-1DB0 | |
| 3UA7010-1E | 3RU1116-1DB0 OR 3RU1116-1EB0 | |
| 3UA7010-1F | 3RU1116-1EB0 OR 3RU1116-1FB0 | |
| 3UA7010-1G | 3RU1116-1FB0 OR 3RU1116-1GB0 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3UA7010-1H | 3RU1116-1GB0 OR 3RU1116-1HB0 | |
| 3UA7010-1J | 3RU1116-1HB0 OR 3RU1116-1JB0 | |
| 3UA7010-1K | 3RU1116-1JB0 OR 3RU1116-1KB0 | |
| 3UA7011-0A | 3RU1116-0AB0 | |
| 3UA7011-0C | 3RU1116-0CB0 OR 3RU1116-0BB0 | |
| 3UA7011-0E | 3RU1116-0EB0 OR 3RU1116-0DB0 | |
| 3UA7011-0G | 3RU1116-0GB0 OR 3RU1116-0FB0 | |
| 3UA7011-0J | 3RU1116-0JB0 OR 3RU1116-0HB0 | |
| 3UA7011-0K | 3RU1116-0JB0 OR 3RU1116-0KB0 | |
| 3UA7011-1A | 3RU1116-0KB0 OR 3RU1116-1AB0 | |
| 3UA7011-1B | 3RU1116-1AB0 OR 3RU1116-1BB0 | |
| 3UA7011-1C | 3RU1116-1BB0 OR 3RU1116-1CB0 | |
| 3UA7011-1D | 3RU1116-1CB0 OR 3RU1116-1DB0 | |
| 3UA7011-1E | 3RU1116-1DB0 OR 3RU1116-1EB0 | |
| 3UA7011-1F | 3RU1116-1EB0 OR 3RU1116-1FB0 | |
| 3UA7011-1G | 3RU1116-1FB0 OR 3RU1116-1GB0 | |
| 3UA7011-1H | 3RU1116-1GB0 OR 3RU1116-1HB0 | |
| 3UA7011-1J | 3RU1116-1HB0 OR 3RU1116-1JB0 | |
| 3UA7011-1K | 3RU1116-1JB0 OR 3RU1116-1KB0 | |
| 3UA7020-0A | 3RU1116-0AB0 | |
| 3UA7020-0C | 3RU1116-0CB0 OR 3RU1116-0BB0 | |
| 3UA7020-0E | 3RU1116-0EB0 OR 3RU1116-0DB0 | |
| 3UA7020-0G | 3RU1116-0GB0 OR 3RU1116-0FB0 | |
| 3UA7020-0J | 3RU1116-0JB0 OR 3RU1116-0HB0 | |
| 3UA7020-0K | 3RU1116-0JB0 OR 3RU1116-0KB0 | |
| 3UA7020-1A | 3RU1116-0KB0 OR 3RU1116-1AB0 | |
| 3UA7020-1B | 3RU1116-1AB0 OR 3RU1116-1BB0 | |
| 3UA7020-1C | 3RU1116-1BB0 OR 3RU1116-1CB0 | |
| 3UA7020-1D | 3RU1116-1CB0 OR 3RU1116-1DB0 | |
| 3UA7020-1E | 3RU1116-1DB0 OR 3RU1116-1EB0 | |
| 3UA7020-1F | 3RU1116-1EB0 OR 3RU1116-1FB0 | |
| 3UA7020-1G | 3RU1116-1FB0 OR 3RU1116-1GB0 | |
| 3UA7020-1H | 3RU1116-1GB0 OR 3RU1116-1HB0 | |
| 3UA7020-1J | 3RU1116-1HB0 OR 3RU1116-1JB0 | |
| 3UA7021-0A | 3RU1116-0AB0 | |
| 3UA7021-0C | 3RU1116-0CB0 OR 3RU1116-0BB0 | |
| 3UA7021-0E | 3RU1116-0EB0 OR 3RU1116-0DB0 | |
| 3UA7021-0G | 3RU1116-0GB0 OR 3RU1116-0FB0 | |
| 3UA7021-0J | 3RU1116-0JB0 OR 3RU1116-0HB0 | |
| 3UA7021-0K | 3RU1116-0JB0 OR 3RU1116-0KB0 | |
| 3UA7021-1A | 3RU1116-0KB0 OR 3RU1116-1AB0 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3UA7021-1B | 3RU1116-1AB0 OR 3RU1116-1BB0 | |
| 3UA7021-1C | 3RU1116-1BB0 OR 3RU1116-1CB0 | |
| 3UA7021-1D | 3RU1116-1CB0 OR 3RU1116-1DB0 | |
| 3UA7021-1E | 3RU1116-1DB0 OR 3RU1116-1EB0 | |
| 3UA7021-1F | 3RU1116-1EB0 OR 3RU1116-1FB0 | |
| 3UA7021-1G | 3RU1116-1FB0 OR 3RU1116-1GB0 | |
| 3UA7021-1H | 3RU1116-1GB0 OR 3RU1116-1HB0 | |
| 3UA7021-1J | 3RU1116-1HB0 OR 3RU1116-1JB0 | |
| 3UA7900-0A | 3RU1916-3AA01 | |
| 3UA7900-0B | NO DIRECT REPLACEMENT | |
| 3UA7900-0C | NO DIRECT REPLACEMENT | |
| 3UA7900-0E | NO DIRECT REPLACEMENT | |
| 3UA7901-0A | NO DIRECT REPLACEMENT | |
| 3UA7901-1A | 3RU1900-2AB71 | |
| 3UA7901-1B | 3RU1900-2AM71 OR 3RU1900-2AF71 | |
| 3UA7901-1C | 3RU1900-2AM71 | |
| 3UA7901-1D | 3RU1900-2AF71 | |
| 3UA7901-1E | 3RU1900-2AF71 | |
| 3UA7921-1A | 3RU1900-2AB71 | |
| 3UA7921-1C | 3RU1900-2AM71 | |
| 3UA7921-1D | 3RU1900-2AF71 | |
| 3UA7921-1E | 3RU1900-2AF71 | |
| 3UX1010 | 3RU1900-1A | |
| 3UX1011 | 3RU1900-1A | |
| 3UX1012 | 3RU1900-1A | |
| 3UX1013 | SEE 3RU1900-1A | |
| 3UX1015 | 3RU1900-1B | |
| 3UX1016 | 3RU1900-1C | |
| 3UX1104 | NO DIRECT REPLACEMENT | |
| 3UX1110 | PRODUCT STILL AVAILABLE | |
| 3UX1111 | 3RT1936-4EA2 | |
| 3UX1120 | 3RT1936-4EA2 | |
| 3UX1121 | 3RT1946-4EA2 | |
| 3UX1206 | NO DIRECT REPLACEMENT | |
| 3UX1210 | NO DIRECT REPLACEMENT | |
| 3UX1211 | PRODUCT STILL AVAILABLE | |
| 3UX1215 | PRODUCT STILL AVAILABLE | |
| 3UX1217 | PRODUCT STILL AVAILABLE | |
| 3UX1218 | PRODUCT STILL AVAILABLE | |
| 3UX1221 | PRODUCT STILL AVAILABLE | |
| 3UX1222 | PRODUCT STILL AVAILABLE | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3UX1410 | NO DIRECT REPLACEMENT | |
| 3UX1411 | NO DIRECT REPLACEMENT | |
| 3UX1412 | NO DIRECT REPLACEMENT | |
| 3UX1418 | 3RU1916-3AA01 | |
| 3UX1420 | 3RU1926-3AA01 | |
| 3UX1421 | 3RU1946-3AA01 | |
| 3UX1423 | PRODUCT STILL AVAILABLE | |
| 3UX1424 | PRODUCT STILL AVAILABLE | |
| 3UX1425 | 3RU1936-3AA01 | |
| 3UX1426 | PRODUCT STILL AVAILABLE | |
| 3UX1427 | PRODUCT STILL AVAILABLE | |
| 3UX1428 | PRODUCT STILL AVAILABLE | |
| 3UX1430 | NO DIRECT REPLACEMENT | |
| 3VH1320-1MG10-1BB4 | NO DIRECT REPLACEMENT | |
| 3VH1320-1MG17-4BB4 | 3RA1115-1AA15-1BB4 OR 3RA1115-0KA15-1BB4 | 3RA1125-1AA23-1BB4 OR 3RA1125-0KA23-1BB4 |
| 3VH1320-1MH17-4AP0 | 3RA1115-1CA15-1AP6 OR 3RA1115-1BA15-1AP6 | 3RA1125-1CA23-1AP6 OR 3RA1125-1BA23-1AP6 |
| 3VH1320-1MJ10-4BB4 | NO DIRECT REPLACEMENT | |
| 3VH1320-1MJ17-4BB4 | 3RA1115-1EA15-1BB4 OR 3RA1115-1DA15-1BB4 | 3RA1125-1EA23-1BB4 OR 3RA1125-1DA23-1BB4 |
| 3VH1320-1ML17-4BB4 | 3RA1125-1JA24-1BB4 OR 3RA1115-1HA16-1BB4 | |
| 3VH1330-1MB10A4 | 3RA1115-0AA15-1BA4 | 3RA1125-0AA23-1BA4 |
| 3VH1330-1MB10B4 | 3RA1115-0AA15-1BB4 | 3RA1125-0AA23-1BB4 |
| 3VH1330-1MB10C2 | 3RA1115-0AA15-1AC2 | 3RA1125-0AA23-1AC2 |
| 3VH1330-1MB10G4 | 3RA1115-0AA15-1BG4 | 3RA1125-0AA23-1BG4 |
| 3VH1330-1MB10K6 | 3RA1115-0AA15-1AK6 | 3RA1125-0AA23-1AK6 |
| 3VH1330-1MB10M1 | 3RA1115-0AA15-1AM2 | 3RA1125-0AA23-1AM2 |
| 3VH1330-1MB10P6 | 3RA1115-0AA15-1AP6 | 3RA1125-0AA23-1AP6 |
| 3VH1330-1MB10Q0 | 3RA1115-0AA15-1AV0 | 3RA1125-0AA23-1AV0 |
| 3VH1330-1MB10Q4 | 3RA1115-0AA15-1BP4 | 3RA1125-0AA23-1BP4 |
| 3VH1330-1MB10S0 | 3RA1115-0AA15-1AT6 | 3RA1125-0AA23-1AT6 |
| 3VH1330-1MB10U1 | 3RA1115-0AA15-1AU6 | 3RA1125-0AA23-1AU6 |
| 3VH1330-1MB10W4 | 3RA1115-0AA15-1BW4 | 3RA1125-0AA23-1BW4 |
| 3VH1330-1MC10A4 | 3RA1115-0CA15-1BA4 OR 3RA1115-0BA15-1BA4 | 3RA1125-0CA23-1BA4 OR 3RA1125-0BA23-1BA4 |
| 3VH1330-1MC10B4 | 3RA1115-0CA15-1BB4 OR 3RA1115-0BA15-1BB4 | 3RA1125-0CA23-1BB4 OR 3RA1125-0BA23-1BB4 |
| 3VH1330-1MC10C2 | 3RA1115-0CA15-1AC2 OR 3RA1115-0BA15-1AC2 | 3RA1125-0CA23-1AC2 OR 3RA1125-0BA23-1AC2 |
| 3VH1330-1MC10G4 | 3RA1115-0CA15-1BG4 OR 3RA1115-0BA15-1BG4 | 3RA1125-0CA23-1BG4 OR 3RA1125-0BA23-1BG4 |
| 3VH1330-1MC10K6 | 3RA1115-0CA15-1AK6 OR 3RA1115-0BA15-1AK6 | 3RA1125-0CA23-1AK6 OR 3RA1125-0BA23-1AK6 |
| 3VH1330-1MC10M1 | 3RA1115-0CA15-1AM2 OR 3RA1115-0BA15-1AM2 | 3RA1125-0CA23-1AM2 OR 3RA1125-0BA23-1AM2 |
| 3VH1330-1MC10P6 | 3RA1115-0CA15-1AP6 OR 3RA1115-0BA15-1AP6 | 3RA1125-0CA23-1AP6 OR 3RA1125-0BA23-1AP6 |
| 3VH1330-1MC10Q0 | 3RA1115-0CA15-1AV0 OR 3RA1115-0BA15-1AV0 | 3RA1125-0CA23-1AV0 OR 3RA1125-0BA23-1AV0 |
| 3VH1330-1MC10Q4 | 3RA1115-0CA15-1BP4 OR 3RA1115-0BA15-1BP4 | 3RA1125-0CA23-1BP4 OR 3RA1125-0BA23-1BP4 |
| 3VH1330-1MC10S0 | 3RA1115-0CA15-1AT6 OR 3RA1115-0BA15-1AT6 | 3RA1125-0CA23-1AT6 OR 3RA1125-0BA23-1AT6 |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3VH1330-1MC10U1 | 3RA1115-0CA15-1AU6 OR 3RA1115-0BA15-1AU6 | 3RA1125-0CA23-1AU6 OR 3RA1125-0BA23-1AU6 |
| 3VH1330-1MC10W4 | 3RA1115-0CA15-1BW4 OR 3RA1115-0BA15-1BW4 | 3RA1125-0CA23-1BW4 OR 3RA1125-0BA23-1BW4 |
| 3VH1330-1MD10A4 | 3RA1115-0EA15-1BA4 OR 3RA1115-0DA15-1BA4 | 3RA1125-0EA23-1BA4 OR 3RA1125-0DA23-1BA4 |
| 3VH1330-1MD10B4 | 3RA1115-0EA15-1BB4 OR 3RA1115-0DA15-1BB4 | 3RA1125-0EA23-1BB4 OR 3RA1125-0DA23-1BB4 |
| 3VH1330-1MD10C2 | 3RA1115-0EA15-1AC2 OR 3RA1115-0DA15-1AC2 | 3RA1125-0EA23-1AC2 OR 3RA1125-0DA23-1AC2 |
| 3VH1330-1MD10G4 | 3RA1115-0EA15-1BG4 OR 3RA1115-0DA15-1BG4 | 3RA1125-0EA23-1BG4 OR 3RA1125-0DA23-1BG4 |
| 3VH1330-1MD10K6 | 3RA1115-0EA15-1AK6 OR 3RA1115-0DA15-1AK6 | 3RA1125-0EA23-1AK6 OR 3RA1125-0DA23-1AK6 |
| 3VH1330-1MD10M1 | 3RA1115-0EA15-1AM2 OR 3RA1115-0DA15-1AM2 | 3RA1125-0EA23-1AM2 OR 3RA1125-0DA23-1AM2 |
| 3VH1330-1MD10P6 | 3RA1115-0EA15-1AP6 OR 3RA1115-0DA15-1AP6 | 3RA1125-0EA23-1AP6 OR 3RA1125-0DA23-1AP6 |
| 3VH1330-1MD10Q0 | 3RA1115-0EA15-1AV0 OR 3RA1115-0DA15-1AV0 | 3RA1125-0EA23-1AV0 OR 3RA1125-0DA23-1AV0 |
| 3VH1330-1MD10Q4 | 3RA1115-0EA15-1BP4 OR 3RA1115-0DA15-1BP4 | 3RA1125-0EA23-1BP4 OR 3RA1125-0DA23-1BP4 |
| 3VH1330-1MD10S0 | 3RA1115-0EA15-1AT6 OR 3RA1115-0DA15-1AT6 | 3RA1125-0EA23-1AT6 OR 3RA1125-0DA23-1AT6 |
| 3VH1330-1MD10U1 | 3RA1115-0EA15-1AU6 OR 3RA1115-0DA15-1AU6 | 3RA1125-0EA23-1AU6 OR 3RA1125-0DA23-1AU6 |
| 3VH1330-1MD10W4 | 3RA1115-0EA15-1BW4 OR 3RA1115-0DA15-1BW4 | 3RA1125-0EA23-1BW4 OR 3RA1125-0DA23-1BW4 |
| 3VH1330-1ME10A4 | 3RA1115-0GA15-1BA4 OR 3RA1115-0FA15-1BA4 | 3RA1125-0GA23-1BA4 OR 3RA1125-0FA23-1BA4 |
| 3VH1330-1ME10B4 | 3RA1115-0GA15-1BB4 OR 3RA1115-0FA15-1BB4 | 3RA1125-0GA23-1BB4 OR 3RA1125-0FA23-1BB4 |
| 3VH1330-1ME10C2 | 3RA1115-0GA15-1AC2 OR 3RA1115-0FA15-1AC2 | 3RA1125-0GA23-1AC2 OR 3RA1125-0FA23-1AC2 |
| 3VH1330-1ME10G4 | 3RA1115-0GA15-1BG4 OR 3RA1115-0FA15-1BG4 | 3RA1125-0GA23-1BG4 OR 3RA1125-0FA23-1BG4 |
| 3VH1330-1ME10K6 | 3RA1115-0GA15-1AK6 OR 3RA1115-0FA15-1AK6 | 3RA1125-0GA23-1AK6 OR 3RA1125-0FA23-1AK6 |
| 3VH1330-1ME10M1 | 3RA1115-0GA15-1AM2 OR 3RA1115-0FA15-1AM2 | 3RA1125-0GA23-1AM2 OR 3RA1125-0FA23-1AM2 |
| 3VH1330-1ME10P6 | 3RA1115-0GA15-1AP6 OR 3RA1115-0FA15-1AP6 | 3RA1125-0GA23-1AP6 OR 3RA1125-0FA23-1AP6 |
| 3VH1330-1ME10Q0 | 3RA1115-0GA15-1AV0 OR 3RA1115-0FA15-1AV0 | 3RA1125-0GA23-1AV0 OR 3RA1125-0FA23-1AV0 |
| 3VH1330-1ME10Q4 | 3RA1115-0GA15-1BP4 OR 3RA1115-0FA15-1BP4 | 3RA1125-0GA23-1BP4 OR 3RA1125-0FA23-1BP4 |
| 3VH1330-1ME10S0 | 3RA1115-0GA15-1AT6 OR 3RA1115-0FA15-1AT6 | 3RA1125-0GA23-1AT6 OR 3RA1125-0FA23-1AT6 |
| 3VH1330-1ME10U1 | 3RA1115-0GA15-1AU6 OR 3RA1115-0FA15-1AU6 | 3RA1125-0GA23-1AU6 OR 3RA1125-0FA23-1AU6 |
| 3VH1330-1ME10W4 | 3RA1115-0GA15-1BW4 OR 3RA1115-0FA15-1BW4 | 3RA1125-0GA23-1BW4 OR 3RA1125-0FA23-1BW4 |
| 3VH1330-1MF10A4 | 3RA1115-0JA15-1BA4 OR 3RA1115-0HA15-1BA4 | 3RA1125-0JA23-1BA4 OR 3RA1125-0HA23-1BA4 |
| 3VH1330-1MF10B4 | 3RA1115-0JA15-1BB4 OR 3RA1115-0HA15-1BB4 | 3RA1125-0JA23-1BB4 OR 3RA1125-0HA23-1BB4 |
| 3VH1330-1MF10C2 | 3RA1115-0JA15-1AC2 OR 3RA1115-0HA15-1AC2 | 3RA1125-0JA23-1AC2 OR 3RA1125-0HA23-1AC2 |
| 3VH1330-1MF10G4 | 3RA1115-0JA15-1BG4 OR 3RA1115-0HA15-1BG4 | 3RA1125-0JA23-1BG4 OR 3RA1125-0HA23-1BG4 |
| 3VH1330-1MF10K6 | 3RA1115-0JA15-1AK6 OR 3RA1115-0HA15-1AK6 | 3RA1125-0JA23-1AK6 OR 3RA1125-0HA23-1AK6 |
| 3VH1330-1MF10M1 | 3RA1115-0JA15-1AM2 OR 3RA1115-0HA15-1AM2 | 3RA1125-0JA23-1AM2 OR 3RA1125-0HA23-1AM2 |
| 3VH1330-1MF10P6 | 3RA1115-0JA15-1AP6 OR 3RA1115-0HA15-1AP6 | 3RA1125-0JA23-1AP6 OR 3RA1125-0HA23-1AP6 |
| 3VH1330-1MF10Q0 | 3RA1115-0JA15-1AV0 OR 3RA1115-0HA15-1AV0 | 3RA1125-0JA23-1AV0 OR 3RA1125-0HA23-1AV0 |
| 3VH1330-1MF10Q4 | 3RA1115-0JA15-1BP4 OR 3RA1115-0HA15-1BP4 | 3RA1125-0JA23-1BP4 OR 3RA1125-0HA23-1BP4 |
| 3VH1330-1MF10S0 | 3RA1115-0JA15-1AT6 OR 3RA1115-0HA15-1AT6 | 3RA1125-0JA23-1AT6 OR 3RA1125-0HA23-1AT6 |
| 3VH1330-1MF10U1 | 3RA1115-0JA15-1AU6 OR 3RA1115-0HA15-1AU6 | 3RA1125-0JA23-1AU6 OR 3RA1125-0HA23-1AU6 |
| 3VH1330-1MF10W4 | 3RA1115-0JA15-1BW4 OR 3RA1115-0HA15-1BW4 | 3RA1125-0JA23-1BW4 OR 3RA1125-0HA23-1BW4 |
| 3VH1330-1MG10A4 | 3RA1115-1AA15-1BA4 OR 3RA1115-0KA15-1BA4 | 3RA1125-1AA23-1BA4 OR 3RA1125-0KA23-1BA4 |
| 3VH1330-1MG10B4 | 3RA1115-1AA15-1BB4 OR 3RA1115-0KA15-1BB4 | 3RA1125-1AA23-1BB4 OR 3RA1125-0KA23-1BB4 |
| 3VH1330-1MG10C2 | 3RA1115-1AA15-1AC2 OR 3RA1115-0KA15-1AC2 | 3RA1125-1AA23-1AC2 OR 3RA1125-0KA23-1AC2 |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3VH1330-1MG10G4 | 3RA1115-1AA15-1BG4 OR 3RA1115-0KA15-1BG4 | 3RA1125-1AA23-1BG4 OR 3RA1125-0KA23-1BG4 |
| 3VH1330-1MG10K6 | 3RA1115-1AA15-1AK6 OR 3RA1115-0KA15-1AK6 | 3RA1125-1AA23-1AK6 OR 3RA1125-0KA23-1AK6 |
| 3VH1330-1MG10M1 | 3RA1115-1AA15-1AM2 OR 3RA1115-0KA15-1AM2 | 3RA1125-1AA23-1AM2 OR 3RA1125-0KA23-1AM2 |
| 3VH1330-1MG10P6 | 3RA1115-1AA15-1AP6 OR 3RA1115-0KA15-1AP6 | 3RA1125-1AA23-1AP6 OR 3RA1125-0KA23-1AP6 |
| 3VH1330-1MG10Q0 | 3RA1115-1AA15-1AV0 OR 3RA1115-0KA15-1AV0 | 3RA1125-1AA23-1AV0 OR 3RA1125-0KA23-1AV0 |
| 3VH1330-1MG10Q4 | 3RA1115-1AA15-1BP4 OR 3RA1115-0KA15-1BP4 | 3RA1125-1AA23-1BP4 OR 3RA1125-0KA23-1BP4 |
| 3VH1330-1MG10S0 | 3RA1115-1AA15-1AT6 OR 3RA1115-0KA15-1AT6 | 3RA1125-1AA23-1AT6 OR 3RA1125-0KA23-1AT6 |
| 3VH1330-1MG10U1 | 3RA1115-1AA15-1AU6 OR 3RA1115-0KA15-1AU6 | 3RA1125-1AA23-1AU6 OR 3RA1125-0KA23-1AU6 |
| 3VH1330-1MG10W4 | 3RA1115-1AA15-1BW4 OR 3RA1115-0KA15-1BW4 | 3RA1125-1AA23-1BW4 OR 3RA1125-0KA23-1BW4 |
| 3VH1330-1MG19K6 | 3RA1115-1AA15-1AK6 OR 3RA1115-0KA15-1AK6 | 3RA1125-1AA23-1AK6 OR 3RA1125-0KA23-1AK6 |
| 3VH1330-1MH10A4 | 3RA1115-1CA15-1BA4 OR 3RA1115-1BA15-1BA4 | 3RA1125-1CA23-1BA4 OR 3RA1125-1BA23-1BA4 |
| 3VH1330-1MH10B4 | 3RA1115-1CA15-1BB4 OR 3RA1115-1BA15-1BB4 | 3RA1125-1CA23-1BB4 OR 3RA1125-1BA23-1BB4 |
| 3VH1330-1MH10C2 | 3RA1115-1CA15-1AC2 OR 3RA1115-1BA15-1AC2 | 3RA1125-1CA23-1AC2 OR 3RA1125-1BA23-1AC2 |
| 3VH1330-1MH10G4 | 3RA1115-1CA15-1BG4 OR 3RA1115-1BA15-1BG4 | 3RA1125-1CA23-1BG4 OR 3RA1125-1BA23-1BG4 |
| 3VH1330-1MH10K6 | 3RA1115-1CA15-1AK6 OR 3RA1115-1BA15-1AK6 | 3RA1125-1CA23-1AK6 OR 3RA1125-1BA23-1AK6 |
| 3VH1330-1MH10M1 | 3RA1115-1CA15-1AM2 OR 3RA1115-1BA15-1AM2 | 3RA1125-1CA23-1AM2 OR 3RA1125-1BA23-1AM2 |
| 3VH1330-1MH10P6 | 3RA1115-1CA15-1AP6 OR 3RA1115-1BA15-1AP6 | 3RA1125-1CA23-1AP6 OR 3RA1125-1BA23-1AP6 |
| 3VH1330-1MH10Q0 | 3RA1115-1CA15-1AV0 OR 3RA1115-1BA15-1AV0 | 3RA1125-1CA23-1AV0 OR 3RA1125-1BA23-1AV0 |
| 3VH1330-1MH10Q4 | 3RA1115-1CA15-1BP4 OR 3RA1115-1BA15-1BP4 | 3RA1125-1CA23-1BP4 OR 3RA1125-1BA23-1BP4 |
| 3VH1330-1MH10S0 | 3RA1115-1CA15-1AT6 OR 3RA1115-1BA15-1AT6 | 3RA1125-1CA23-1AT6 OR 3RA1125-1BA23-1AT6 |
| 3VH1330-1MH10U1 | 3RA1115-1CA15-1AU6 OR 3RA1115-1BA15-1AU6 | 3RA1125-1CA23-1AU6 OR 3RA1125-1BA23-1AU6 |
| 3VH1330-1MH10W4 | 3RA1115-1CA15-1BW4 OR 3RA1115-1BA15-1BW4 | 3RA1125-1CA23-1BW4 OR 3RA1125-1BA23-1BW4 |
| 3VH1330-1MH19K6 | 3RA1115-1CA15-1AK6 OR 3RA1115-1BA15-1AK6 | 3RA1125-1CA23-1AK6 OR 3RA1125-1BA23-1AK6 |
| 3VH1330-1MJ10A4 | 3RA1115-1EA15-1BA4 OR 3RA1115-1DA15-1BA4 | 3RA1125-1EA23-1BA4 OR 3RA1125-1DA23-1BA4 |
| 3VH1330-1MJ10B4 | 3RA1115-1EA15-1BB4 OR 3RA1115-1DA15-1BB4 | 3RA1125-1EA23-1BB4 OR 3RA1125-1DA23-1BB4 |
| 3VH1330-1MJ10C2 | 3RA1115-1EA15-1AC2 OR 3RA1115-1DA15-1AC2 | 3RA1125-1EA23-1AC2 OR 3RA1125-1DA23-1AC2 |
| 3VH1330-1MJ10G4 | 3RA1115-1EA15-1BG4 OR 3RA1115-1DA15-1BG4 | 3RA1125-1EA23-1BG4 OR 3RA1125-1DA23-1BG4 |
| 3VH1330-1MJ10K6 | 3RA1115-1EA15-1AK6 OR 3RA1115-1DA15-1AK6 | 3RA1125-1EA23-1AK6 OR 3RA1125-1DA23-1AK6 |
| 3VH1330-1MJ10M1 | 3RA1115-1EA15-1AM2 OR 3RA1115-1DA15-1AM2 | 3RA1125-1EA23-1AM2 OR 3RA1125-1DA23-1AM2 |
| 3VH1330-1MJ10P6 | 3RA1115-1EA15-1AP6 OR 3RA1115-1DA15-1AP6 | 3RA1125-1EA23-1AP6 OR 3RA1125-1DA23-1AP6 |
| 3VH1330-1MJ10Q0 | 3RA1115-1EA15-1AV0 OR 3RA1115-1DA15-1AV0 | 3RA1125-1EA23-1AV0 OR 3RA1125-1DA23-1AV0 |
| 3VH1330-1MJ10Q4 | 3RA1115-1EA15-1BP4 OR 3RA1115-1DA15-1BP4 | 3RA1125-1EA23-1BP4 OR 3RA1125-1DA23-1BP4 |
| 3VH1330-1MJ10S0 | 3RA1115-1EA15-1AT6 OR 3RA1115-1DA15-1AT6 | 3RA1125-1EA23-1AT6 OR 3RA1125-1DA23-1AT6 |
| 3VH1330-1MJ10U1 | 3RA1115-1EA15-1AU6 OR 3RA1115-1DA15-1AU6 | 3RA1125-1EA23-1AU6 OR 3RA1125-1DA23-1AU6 |
| 3VH1330-1MJ10W4 | 3RA1115-1EA15-1BW4 OR 3RA1115-1DA15-1BW4 | 3RA1125-1EA23-1BW4 OR 3RA1125-1DA23-1BW4 |
| 3VH1330-1MJ19B4 | 3RA1115-1EA15-1BB4 OR 3RA1115-1DA15-1BB4 | 3RA1125-1EA23-1BB4 OR 3RA1125-1DA23-1BB4 |
| 3VH1330-1MJ19K6 | 3RA1115-1EA15-1AK6 OR 3RA1115-1DA15-1AK6 | 3RA1125-1EA23-1AK6 OR 3RA1125-1DA23-1AK6 |
| 3VH1330-1MK10A4 | 3RA1115-1GA15-1BA4 OR 3RA1115-1FA15-1BA4 | 3RA1125-1GA23-1BA4 OR 3RA1125-1FA23-1BA4 |
| 3VH1330-1MK10B4 | 3RA1115-1GA15-1BB4 OR 3RA1115-1FA15-1BB4 | 3RA1125-1GA23-1BB4 OR 3RA1125-1FA23-1BB4 |
| 3VH1330-1MK10C2 | 3RA1115-1GA15-1AC2 OR 3RA1115-1FA15-1AC2 | 3RA1125-1GA23-1AC2 OR 3RA1125-1FA23-1AC2 |
| 3VH1330-1MK10G4 | 3RA1115-1GA15-1BG4 OR 3RA1115-1FA15-1BG4 | 3RA1125-1GA23-1BG4 OR 3RA1125-1FA23-1BG4 |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3VH1330-1MK10K6 | 3RA1115-1GA15-1AK6 OR 3RA1115-1FA15-1AK6 | 3RA1125-1GA23-1AK6 OR 3RA1125-1FA23-1AK6 |
| 3VH1330-1MK10M1 | 3RA1115-1GA15-1AM2 OR 3RA1115-1FA15-1AM2 | 3RA1125-1GA23-1AM2 OR 3RA1125-1FA23-1AM2 |
| 3VH1330-1MK10P6 | 3RA1115-1GA15-1AP6 OR 3RA1115-1FA15-1AP6 | 3RA1125-1GA23-1AP6 OR 3RA1125-1FA23-1AP6 |
| 3VH1330-1MK10Q0 | 3RA1115-1GA15-1AV0 OR 3RA1115-1FA15-1AV0 | 3RA1125-1GA23-1AV0 OR 3RA1125-1FA23-1AV0 |
| 3VH1330-1MK10Q4 | 3RA1115-1GA15-1BP4 OR 3RA1115-1FA15-1BP4 | 3RA1125-1GA23-1BP4 OR 3RA1125-1FA23-1BP4 |
| 3VH1330-1MK10S0 | 3RA1115-1GA15-1AT6 OR 3RA1115-1FA15-1AT6 | 3RA1125-1GA23-1AT6 OR 3RA1125-1FA23-1AT6 |
| 3VH1330-1MK10U1 | 3RA1115-1GA15-1AU6 OR 3RA1115-1FA15-1AU6 | 3RA1125-1GA23-1AU6 OR 3RA1125-1FA23-1AU6 |
| 3VH1330-1MK10W4 | 3RA1115-1GA15-1BW4 OR 3RA1115-1FA15-1BW4 | 3RA1125-1GA23-1BW4 OR 3RA1125-1FA23-1BW4 |
| 3VH1330-1MK19B4 | 3RA1115-1GA15-1BB4 OR 3RA1115-1FA15-1BB4 | 3RA1125-1GA23-1BB4 OR 3RA1125-1FA23-1BB4 |
| 3VH1330-1MK19K6 | 3RA1115-1GA15-1AK6 OR 3RA1115-1FA15-1AK6 | 3RA1125-1GA23-1AK6 OR 3RA1125-1FA23-1AK6 |
| 3VH1330-1ML10A4 | 3RA1125-1JA24-1BA4 OR 3RA1115-1HA16-1BA4 | |
| 3VH1330-1ML10B4 | 3RA1125-1JA24-1BB4 OR 3RA1115-1HA16-1BB4 | |
| 3VH1330-1ML10C2 | 3RA1125-1JA24-1AC2 OR 3RA1115-1HA16-1AC2 | |
| 3VH1330-1ML10G4 | 3RA1125-1JA24-1BG4 OR 3RA1115-1HA16-1BG4 | |
| 3VH1330-1ML10K6 | 3RA1125-1JA24-1AK6 OR 3RA1115-1HA16-1AK6 | |
| 3VH1330-1ML10M1 | 3RA1125-1JA24-1AM2 OR 3RA1115-1HA16-1AM2 | |
| 3VH1330-1ML10P6 | 3RA1125-1JA24-1AP6 OR 3RA1115-1HA16-1AP6 | |
| 3VH1330-1ML10Q0 | 3RA1125-1JA24-1AV0 OR 3RA1115-1HA16-1AV0 | |
| 3VH1330-1ML10Q4 | 3RA1125-1JA24-1BP4 OR 3RA1115-1HA16-1BP4 | |
| 3VH1330-1ML10S0 | 3RA1125-1JA24-1AT6 OR 3RA1115-1HA16-1AT6 | |
| 3VH1330-1ML10U1 | 3RA1125-1JA24-1AU6 OR 3RA1115-1HA16-1AU6 | |
| 3VH1330-1ML10W4 | 3RA1125-1JA24-1BW4 OR 3RA1115-1HA16-1BW4 | |
| 3VH1330-1ML19K6 | 3RA1125-1JA24-1AK6 OR 3RA1115-1HA16-1AK6 | |
| 3VH1330-1NH10C2 | 3RA1115-1DA15-1AC2 OR 3RA1115-1CA15-1AC2 | 3RA1125-1DA23-1AC2 OR 3RA1125-1CA23-1AC2 |
| 3VH1330-1NH10K6 | 3RA1115-1DA15-1AK6 OR 3RA1115-1CA15-1AK6 | 3RA1125-1DA23-1AK6 OR 3RA1125-1CA23-1AK6 |
| 3VH1330-1NJ10C2 | 3RA1115-1FA15-1AC2 OR 3RA1115-1EA15-1AC2 | 3RA1125-1FA23-1AC2 OR 3RA1125-1EA23-1AC2 |
| 3VH1330-1NJ10K6 | 3RA1115-1FA15-1AK6 OR 3RA1115-1EA15-1AK6 | 3RA1125-1FA23-1AK6 OR 3RA1125-1EA23-1AK6 |
| 3VH1330-1NK10C2 | 3RA1115-1HA16-1AC2 OR 3RA1115-1GA15-1AC2 | 3RA1125-1HA23-1AC2 OR 3RA1125-1GA23-1AC2 |
| 3VH1330-1NK10K6 | 3RA1115-1HA16-1AK6 OR 3RA1115-1GA15-1AK6 | 3RA1125-1HA23-1AK6 OR 3RA1125-1GA23-1AK6 |
| 3VH1332-1MF10K6 | 3RA1115-0JA15-1AK6 OR 3RA1115-0HA15-1AK6 | 3RA1125-0JA23-1AK6 OR 3RA1125-0HA23-1AK6 |
| 3VH1332-1MG10A4 | 3RA1115-1AA15-1BA4 OR 3RA1115-0KA15-1BA4 | 3RA1125-1AA23-1BA4 OR 3RA1125-0KA23-1BA4 |
| 3VH1332-1MG10B4 | 3RA1115-1AA15-1BB4 OR 3RA1115-0KA15-1BB4 | 3RA1125-1AA23-1BB4 OR 3RA1125-0KA23-1BB4 |
| 3VH1332-1MG10C2 | 3RA1115-1AA15-1AC2 OR 3RA1115-0KA15-1AC2 | 3RA1125-1AA23-1AC2 OR 3RA1125-0KA23-1AC2 |
| 3VH1332-1MG10G4 | 3RA1115-1AA15-1BG4 OR 3RA1115-0KA15-1BG4 | 3RA1125-1AA23-1BG4 OR 3RA1125-0KA23-1BG4 |
| 3VH1332-1MG10K6 | 3RA1115-1AA15-1AK6 OR 3RA1115-0KA15-1AK6 | 3RA1125-1AA23-1AK6 OR 3RA1125-0KA23-1AK6 |
| 3VH1332-1MG10M1 | 3RA1115-1AA15-1AM2 OR 3RA1115-0KA15-1AM2 | 3RA1125-1AA23-1AM2 OR 3RA1125-0KA23-1AM2 |
| 3VH1332-1MG10P6 | 3RA1115-1AA15-1AP6 OR 3RA1115-0KA15-1AP6 | 3RA1125-1AA23-1AP6 OR 3RA1125-0KA23-1AP6 |
| 3VH1332-1MG10Q0 | 3RA1115-1AA15-1AV0 OR 3RA1115-0KA15-1AV0 | 3RA1125-1AA23-1AV0 OR 3RA1125-0KA23-1AV0 |
| 3VH1332-1MG10Q4 | 3RA1115-1AA15-1BP4 OR 3RA1115-0KA15-1BP4 | 3RA1125-1AA23-1BP4 OR 3RA1125-0KA23-1BP4 |
| 3VH1332-1MG10S0 | 3RA1115-1AA15-1AT6 OR 3RA1115-0KA15-1AT6 | 3RA1125-1AA23-1AT6 OR 3RA1125-0KA23-1AT6 |
| 3VH1332-1MG10U1 | 3RA1115-1AA15-1AU6 OR 3RA1115-0KA15-1AU6 | 3RA1125-1AA23-1AU6 OR 3RA1125-0KA23-1AU6 |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3VH1332-1MG10W4 | 3RA1115-1AA15-1BW4 OR 3RA1115-0KA15-1BW4 | 3RA1125-1AA23-1BW4 OR 3RA1125-0KA23-1BW4 |
| 3VH1332-1MH10A4 | 3RA1115-1CA15-1BA4 OR 3RA1115-1BA15-1BA4 | 3RA1125-1CA23-1BA4 OR 3RA1125-1BA23-1BA4 |
| 3VH1332-1MH10B4 | 3RA1115-1CA15-1BB4 OR 3RA1115-1BA15-1BB4 | 3RA1125-1CA23-1BB4 OR 3RA1125-1BA23-1BB4 |
| 3VH1332-1MH10C2 | 3RA1115-1CA15-1AC2 OR 3RA1115-1BA15-1AC2 | 3RA1125-1CA23-1AC2 OR 3RA1125-1BA23-1AC2 |
| 3VH1332-1MH10G4 | 3RA1115-1CA15-1BG4 OR 3RA1115-1BA15-1BG4 | 3RA1125-1CA23-1BG4 OR 3RA1125-1BA23-1BG4 |
| 3VH1332-1MH10K6 | 3RA1115-1CA15-1AK6 OR 3RA1115-1BA15-1AK6 | 3RA1125-1CA23-1AK6 OR 3RA1125-1BA23-1AK6 |
| 3VH1332-1MH10M1 | 3RA1115-1CA15-1AM2 OR 3RA1115-1BA15-1AM2 | 3RA1125-1CA23-1AM2 OR 3RA1125-1BA23-1AM2 |
| 3VH1332-1MH10P6 | 3RA1115-1CA15-1AP6 OR 3RA1115-1BA15-1AP6 | 3RA1125-1CA23-1AP6 OR 3RA1125-1BA23-1AP6 |
| 3VH1332-1MH10Q0 | 3RA1115-1CA15-1AV0 OR 3RA1115-1BA15-1AV0 | 3RA1125-1CA23-1AV0 OR 3RA1125-1BA23-1AV0 |
| 3VH1332-1MH10Q4 | 3RA1115-1CA15-1BP4 OR 3RA1115-1BA15-1BP4 | 3RA1125-1CA23-1BP4 OR 3RA1125-1BA23-1BP4 |
| 3VH1332-1MH10S0 | 3RA1115-1CA15-1AT6 OR 3RA1115-1BA15-1AT6 | 3RA1125-1CA23-1AT6 OR 3RA1125-1BA23-1AT6 |
| 3VH1332-1MH10U1 | 3RA1115-1CA15-1AU6 OR 3RA1115-1BA15-1AU6 | 3RA1125-1CA23-1AU6 OR 3RA1125-1BA23-1AU6 |
| 3VH1332-1MH10W4 | 3RA1115-1CA15-1BW4 OR 3RA1115-1BA15-1BW4 | 3RA1125-1CA23-1BW4 OR 3RA1125-1BA23-1BW4 |
| 3VH1332-1MJ10A4 | 3RA1115-1EA15-1BA4 OR 3RA1115-1DA15-1BA4 | 3RA1125-1EA23-1BA4 OR 3RA1125-1DA23-1BA4 |
| 3VH1332-1MJ10B4 | 3RA1115-1EA15-1BB4 OR 3RA1115-1DA15-1BB4 | 3RA1125-1EA23-1BB4 OR 3RA1125-1DA23-1BB4 |
| 3VH1332-1MJ10C2 | 3RA1115-1EA15-1AC2 OR 3RA1115-1DA15-1AC2 | 3RA1125-1EA23-1AC2 OR 3RA1125-1DA23-1AC2 |
| 3VH1332-1MJ10G4 | 3RA1115-1EA15-1BG4 OR 3RA1115-1DA15-1BG4 | 3RA1125-1EA23-1BG4 OR 3RA1125-1DA23-1BG4 |
| 3VH1332-1MJ10K6 | 3RA1115-1EA15-1AK6 OR 3RA1115-1DA15-1AK6 | 3RA1125-1EA23-1AK6 OR 3RA1125-1DA23-1AK6 |
| 3VH1332-1MJ10M1 | 3RA1115-1EA15-1AM2 OR 3RA1115-1DA15-1AM2 | 3RA1125-1EA23-1AM2 OR 3RA1125-1DA23-1AM2 |
| 3VH1332-1MJ10P6 | 3RA1115-1EA15-1AP6 OR 3RA1115-1DA15-1AP6 | 3RA1125-1EA23-1AP6 OR 3RA1125-1DA23-1AP6 |
| 3VH1332-1MJ10Q0 | 3RA1115-1EA15-1AV0 OR 3RA1115-1DA15-1AV0 | 3RA1125-1EA23-1AV0 OR 3RA1125-1DA23-1AV0 |
| 3VH1332-1MJ10Q4 | 3RA1115-1EA15-1BP4 OR 3RA1115-1DA15-1BP4 | 3RA1125-1EA23-1BP4 OR 3RA1125-1DA23-1BP4 |
| 3VH1332-1MJ10S0 | 3RA1115-1EA15-1AT6 OR 3RA1115-1DA15-1AT6 | 3RA1125-1EA23-1AT6 OR 3RA1125-1DA23-1AT6 |
| 3VH1332-1MJ10U1 | 3RA1115-1EA15-1AU6 OR 3RA1115-1DA15-1AU6 | 3RA1125-1EA23-1AU6 OR 3RA1125-1DA23-1AU6 |
| 3VH1332-1MJ10W4 | 3RA1115-1EA15-1BW4 OR 3RA1115-1DA15-1BW4 | 3RA1125-1EA23-1BW4 OR 3RA1125-1DA23-1BW4 |
| 3VH1332-1MK10A4 | 3RA1115-1GA15-1BA4 OR 3RA1115-1FA15-1BA4 | 3RA1125-1GA23-1BA4 OR 3RA1125-1FA23-1BA4 |
| 3VH1332-1MK10B4 | 3RA1115-1GA15-1BB4 OR 3RA1115-1FA15-1BB4 | 3RA1125-1GA23-1BB4 OR 3RA1125-1FA23-1BB4 |
| 3VH1332-1MK10C2 | 3RA1115-1GA15-1AC2 OR 3RA1115-1FA15-1AC2 | 3RA1125-1GA23-1AC2 OR 3RA1125-1FA23-1AC2 |
| 3VH1332-1MK10G4 | 3RA1115-1GA15-1BG4 OR 3RA1115-1FA15-1BG4 | 3RA1125-1GA23-1BG4 OR 3RA1125-1FA23-1BG4 |
| 3VH1332-1MK10K6 | 3RA1115-1GA15-1AK6 OR 3RA1115-1FA15-1AK6 | 3RA1125-1GA23-1AK6 OR 3RA1125-1FA23-1AK6 |
| 3VH1332-1MK10M1 | 3RA1115-1GA15-1AM2 OR 3RA1115-1FA15-1AM2 | 3RA1125-1GA23-1AM2 OR 3RA1125-1FA23-1AM2 |
| 3VH1332-1MK10P6 | 3RA1115-1GA15-1AP6 OR 3RA1115-1FA15-1AP6 | 3RA1125-1GA23-1AP6 OR 3RA1125-1FA23-1AP6 |
| 3VH1332-1MK10Q0 | 3RA1115-1GA15-1AV0 OR 3RA1115-1FA15-1AV0 | 3RA1125-1GA23-1AV0 OR 3RA1125-1FA23-1AV0 |
| 3VH1332-1MK10Q4 | 3RA1115-1GA15-1BP4 OR 3RA1115-1FA15-1BP4 | 3RA1125-1GA23-1BP4 OR 3RA1125-1FA23-1BP4 |
| 3VH1332-1MK10S0 | 3RA1115-1GA15-1AT6 OR 3RA1115-1FA15-1AT6 | 3RA1125-1GA23-1AT6 OR 3RA1125-1FA23-1AT6 |
| 3VH1332-1MK10U1 | 3RA1115-1GA15-1AU6 OR 3RA1115-1FA15-1AU6 | 3RA1125-1GA23-1AU6 OR 3RA1125-1FA23-1AU6 |
| 3VH1332-1MK10W4 | 3RA1115-1GA15-1BW4 OR 3RA1115-1FA15-1BW4 | 3RA1125-1GA23-1BW4 OR 3RA1125-1FA23-1BW4 |
| 3VH1332-1ML10B4 | 3RA1125-1JA24-1BB4 OR 3RA1115-1HA16-1BB4 | |
| 3VH1332-1ML10K6 | 3RA1125-1JA24-1AK6 OR 3RA1115-1HA16-1AK6 | |
| 3VH1332-1ML10P6 | 3RA1125-1JA24-1AP6 OR 3RA1115-1HA16-1AP6 | |
| 3VH1332-1MM10A4 | 3RA1125-4AA25-1BA4 OR 3RA1125-1KA23-1BA4 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3VH1332-1MM10B4 | 3RA1125-4AA25-1BB4 OR 3RA1125-1KA23-1BB4 | |
| 3VH1332-1MM10C2 | 3RA1125-4AA25-1AC2 OR 3RA1125-1KA23-1AC2 | |
| 3VH1332-1MM10G4 | 3RA1125-4AA25-1BG4 OR 3RA1125-1KA23-1BG4 | |
| 3VH1332-1MM10K6 | 3RA1125-4AA25-1AK6 OR 3RA1125-1KA23-1AK6 | |
| 3VH1332-1MM10M1 | 3RA1125-4AA25-1AM2 OR 3RA1125-1KA23-1AM2 | |
| 3VH1332-1MM10P6 | 3RA1125-4AA25-1AP6 OR 3RA1125-1KA23-1AP6 | |
| 3VH1332-1MM10Q0 | 3RA1125-4AA25-1AV0 OR 3RA1125-1KA23-1AV0 | |
| 3VH1332-1MM10Q4 | 3RA1125-4AA25-1BP4 OR 3RA1125-1KA23-1BP4 | |
| 3VH1332-1MM10S0 | 3RA1125-4AA25-1AT6 OR 3RA1125-1KA23-1AT6 | |
| 3VH1332-1MM10U1 | 3RA1125-4AA25-1AU6 OR 3RA1125-1KA23-1AU6 | |
| 3VH1332-1MM10W4 | 3RA1125-4AA25-1BW4 OR 3RA1125-1KA23-1BW4 | |
| 3VH1332-1NL10C2 | 3RA1125-1KA25-1AC2 OR 3RA1125-1JA24-1AC2 | |
| 3VH1332-1NL10K6 | 3RA1125-1KA25-1AK6 OR 3RA1125-1JA24-1AK6 | |
| 3VH1333-1MN10A4 | 3RA1125-4BA26-1BA4 | |
| 3VH1333-1MN10B4 | 3RA1125-4BA26-1BB4 | |
| 3VH1333-1MN10C2 | 3RA1125-4BA26-1AC2 | |
| 3VH1333-1MN10G4 | 3RA1125-4BA26-1BG4 | |
| 3VH1333-1MN10K6 | 3RA1125-4BA26-1AK6 | |
| 3VH1333-1MN10M1 | 3RA1125-4BA26-1AM2 | |
| 3VH1333-1MN10P6 | 3RA1125-4BA26-1AP6 | |
| 3VH1333-1MN10Q0 | 3RA1125-4BA26-1AV0 | |
| 3VH1333-1MN10Q4 | 3RA1125-4BA26-1BP4 | |
| 3VH1333-1MN10S0 | 3RA1125-4BA26-1AT6 | |
| 3VH1333-1MN10U1 | 3RA1125-4BA26-1AU6 | |
| 3VH1333-1MN10W4 | 3RA1125-4BA26-1BW4 | |
| 3VH1334-1MM10K6 | 3RA1125-4AA25-1AK6 OR 3RA1125-1KA23-1AK6 | |
| 3VH1334-1MN10A4 | 3RA1125-4BA26-1BA4 | |
| 3VH1334-1MN10B4 | 3RA1125-4BA26-1BB4 | |
| 3VH1334-1MN10C2 | 3RA1125-4BA26-1AC2 | |
| 3VH1334-1MN10G4 | 3RA1125-4BA26-1BG4 | |
| 3VH1334-1MN10K6 | 3RA1125-4BA26-1AK6 | |
| 3VH1334-1MN10M1 | 3RA1125-4BA26-1AM2 | |
| 3VH1334-1MN10P6 | 3RA1125-4BA26-1AP6 | |
| 3VH1334-1MN10Q0 | 3RA1125-4BA26-1AV0 | |
| 3VH1334-1MN10Q4 | 3RA1125-4BA26-1BP4 | |
| 3VH1334-1MN10S0 | 3RA1125-4BA26-1AT6 | |
| 3VH1334-1MN10U1 | 3RA1125-4BA26-1AU6 | |
| 3VH1334-1MN10W4 | 3RA1125-4BA26-1BW4 | |
| 3VH1334-1MP10A4 | 3RA1135-4DB33-1BA4 OR 3RA1125-4CA26-1BA4 | |
| 3VH1334-1MP10B4 | 3RA1135-4DB33-1BB4 OR 3RA1125-4CA26-1BB4 | |
| 3VH1334-1MP10C2 | 3RA1135-4DB33-1AC2 OR 3RA1125-4CA26-1AC2 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3VH1334-1MP10G4 | 3RA1135-4DB33-1BG4 OR 3RA1125-4CA26-1BG4 | |
| 3VH1334-1MP10K6 | 3RA1135-4DB33-1AK6 OR 3RA1125-4CA26-1AK6 | |
| 3VH1334-1MP10M1 | 3RA1135-4DB33-1AM2 OR 3RA1125-4CA26-1AM2 | |
| 3VH1334-1MP10P6 | 3RA1135-4DB33-1AP6 OR 3RA1125-4CA26-1AP6 | |
| 3VH1334-1MP10Q0 | 3RA1135-4DB33-1AV0 OR 3RA1125-4CA26-1AV0 | |
| 3VH1334-1MP10Q4 | 3RA1135-4DB33-1BP4 OR 3RA1125-4CA26-1BP4 | |
| 3VH1334-1MP10S0 | 3RA1135-4DB33-1AT6 OR 3RA1125-4CA26-1AT6 | |
| 3VH1334-1MP10U1 | 3RA1135-4DB33-1AU6 OR 3RA1125-4CA26-1AU6 | |
| 3VH1334-1MP10W4 | 3RA1135-4DB33-1BW4 OR 3RA1125-4CA26-1BW4 | |
| 3VH1340-1ML10-1BB4 | 3RA1125-1JA24-1BB4 OR 3RA1115-1HA16-1BB4 | |
| 3VH1632-3MQ11-0BB4 | NO DIRECT REPLACEMENT | |
| 3VH1633-1MN10-0BB4 | 3RA1135-4DB33-1BB4 OR 3RA1135-4BB33-1BB4 | |
| 3VH1634-1MP10A4 | 3RA1135-4EB34-1BA4 | |
| 3VH1634-1MP10B4 | 3RA1135-4EB34-1BB4 | |
| 3VH1634-1MP10C2 | 3RA1135-4EB34-1AC2 | |
| 3VH1634-1MP10G4 | 3RA1135-4EB34-1BG4 | |
| 3VH1634-1MP10K6 | 3RA1135-4EB34-1AK6 | |
| 3VH1634-1MP10M1 | 3RA1135-4EB34-1AM2 | |
| 3VH1634-1MP10P6 | 3RA1135-4EB34-1AP6 | |
| 3VH1634-1MP10Q0 | 3RA1135-4EB34-1AV0 | |
| 3VH1634-1MP10Q4 | 3RA1135-4EB34-1BP4 | |
| 3VH1634-1MP10S0 | 3RA1135-4EB34-1AT6 | |
| 3VH1634-1MP10U1 | 3RA1135-4EB34-1AU6 | |
| 3VH1634-1MP10W4 | 3RA1135-4EB34-1BW4 | |
| 3VH1634-1MP19B4 | 3RA1135-4EB34-1BB4 | |
| 3VH1635-1MQ10A4 | 3RA1135-4FB35-1BA4 | |
| 3VH1635-1MQ10B4 | 3RA1135-4FB35-1BB4 | |
| 3VH1635-1MQ10C2 | 3RA1135-4FB35-1AC2 | |
| 3VH1635-1MQ10G4 | 3RA1135-4FB35-1BG4 | |
| 3VH1635-1MQ10K6 | 3RA1135-4FB35-1AK6 | |
| 3VH1635-1MQ10M1 | 3RA1135-4FB35-1AM2 | |
| 3VH1635-1MQ10P6 | 3RA1135-4FB35-1AP6 | |
| 3VH1635-1MQ10Q0 | 3RA1135-4FB35-1AV0 | |
| 3VH1635-1MQ10Q4 | 3RA1135-4FB35-1BP4 | |
| 3VH1635-1MQ10S0 | 3RA1135-4FB35-1AT6 | |
| 3VH1635-1MQ10U1 | 3RA1135-4FB35-1AU6 | |
| 3VH1635-1MQ10W4 | 3RA1135-4FB35-1BW4 | |
| 3VH1642-1MM10-1BB4 | 3RA1125-4AA25-1BB4 OR 3RA1125-1KA25-1BB4 | |
| 3VHES001 | NO DIRECT REPLACEMENT | |
| 3VHR330-1MB10A4 | 3RA1215-0AA15-1BA4 | 3RA1225-0AA23-1BA4 |
| 3VHR330-1MB10B4 | 3RA1215-0AA15-1BB4 | 3RA1225-0AA23-1BB4 |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3VHR330-1MB10C2 | 3RA1215-0AA15-1AC2 | 3RA1225-0AA23-1AC2 |
| 3VHR330-1MB10G4 | 3RA1215-0AA15-1BG4 | 3RA1225-0AA23-1BG4 |
| 3VHR330-1MB10K6 | 3RA1215-0AA15-1AK6 | 3RA1225-0AA23-1AK6 |
| 3VHR330-1MB10M1 | 3RA1215-0AA15-1AM2 | 3RA1225-0AA23-1AM2 |
| 3VHR330-1MB10P6 | 3RA1215-0AA15-1AP6 | 3RA1225-0AA23-1AP6 |
| 3VHR330-1MB10Q0 | 3RA1215-0AA15-1AV0 | 3RA1225-0AA23-1AV0 |
| 3VHR330-1MB10Q4 | 3RA1215-0AA15-1BP4 | 3RA1225-0AA23-1BP4 |
| 3VHR330-1MB10S0 | 3RA1215-0AA15-1AT6 | 3RA1225-0AA23-1AT6 |
| 3VHR330-1MB10U1 | 3RA1215-0AA15-1AU6 | 3RA1225-0AA23-1AU6 |
| 3VHR330-1MB10W4 | 3RA1215-0AA15-1BW4 | 3RA1225-0AA23-1BW4 |
| 3VHR330-1MC10A4 | 3RA1215-0CA15-1BA4 OR 3RA1215-0BA15-1BA4 | 3RA1225-0CA23-1BA4 OR 3RA1225-0BA23-1BA4 |
| 3VHR330-1MC10B4 | 3RA1215-0CA15-1BB4 OR 3RA1215-0BA15-1BB4 | 3RA1225-0CA23-1BB4 OR 3RA1225-0BA23-1BB4 |
| 3VHR330-1MC10C2 | 3RA1215-0CA15-1AC2 OR 3RA1215-0BA15-1AC2 | 3RA1225-0CA23-1AC2 OR 3RA1225-0BA23-1AC2 |
| 3VHR330-1MC10G4 | 3RA1215-0CA15-1BG4 OR 3RA1215-0BA15-1BG4 | 3RA1225-0CA23-1BG4 OR 3RA1225-0BA23-1BG4 |
| 3VHR330-1MC10K6 | 3RA1215-0CA15-1AK6 OR 3RA1215-0BA15-1AK6 | 3RA1225-0CA23-1AK6 OR 3RA1225-0BA23-1AK6 |
| 3VHR330-1MC10M1 | 3RA1215-0CA15-1AM2 OR 3RA1215-0BA15-1AM2 | 3RA1225-0CA23-1AM2 OR 3RA1225-0BA23-1AM2 |
| 3VHR330-1MC10P6 | 3RA1215-0CA15-1AP6 OR 3RA1215-0BA15-1AP6 | 3RA1225-0CA23-1AP6 OR 3RA1225-0BA23-1AP6 |
| 3VHR330-1MC10Q0 | 3RA1215-0CA15-1AV0 OR 3RA1215-0BA15-1AV0 | 3RA1225-0CA23-1AV0 OR 3RA1225-0BA23-1AV0 |
| 3VHR330-1MC10Q4 | 3RA1215-0CA15-1BP4 OR 3RA1215-0BA15-1BP4 | 3RA1225-0CA23-1BP4 OR 3RA1225-0BA23-1BP4 |
| 3VHR330-1MC10S0 | 3RA1215-0CA15-1AT6 OR 3RA1215-0BA15-1AT6 | 3RA1225-0CA23-1AT6 OR 3RA1225-0BA23-1AT6 |
| 3VHR330-1MC10U1 | 3RA1215-0CA15-1AU6 OR 3RA1215-0BA15-1AU6 | 3RA1225-0CA23-1AU6 OR 3RA1225-0BA23-1AU6 |
| 3VHR330-1MC10W4 | 3RA1215-0CA15-1BW4 OR 3RA1215-0BA15-1BW4 | 3RA1225-0CA23-1BW4 OR 3RA1225-0BA23-1BW4 |
| 3VHR330-1MD10A4 | 3RA1215-0EA15-1BA4 OR 3RA1215-0DA15-1BA4 | 3RA1225-0EA23-1BA4 OR 3RA1225-0DA23-1BA4 |
| 3VHR330-1MD10B4 | 3RA1215-0EA15-1BB4 OR 3RA1215-0DA15-1BB4 | 3RA1225-0EA23-1BB4 OR 3RA1225-0DA23-1BB4 |
| 3VHR330-1MD10C2 | 3RA1215-0EA15-1AC2 OR 3RA1215-0DA15-1AC2 | 3RA1225-0EA23-1AC2 OR 3RA1225-0DA23-1AC2 |
| 3VHR330-1MD10G4 | 3RA1215-0EA15-1BG4 OR 3RA1215-0DA15-1BG4 | 3RA1225-0EA23-1BG4 OR 3RA1225-0DA23-1BG4 |
| 3VHR330-1MD10K6 | 3RA1215-0EA15-1AK6 OR 3RA1215-0DA15-1AK6 | 3RA1225-0EA23-1AK6 OR 3RA1225-0DA23-1AK6 |
| 3VHR330-1MD10M1 | 3RA1215-0EA15-1AM2 OR 3RA1215-0DA15-1AM2 | 3RA1225-0EA23-1AM2 OR 3RA1225-0DA23-1AM2 |
| 3VHR330-1MD10P6 | 3RA1215-0EA15-1AP6 OR 3RA1215-0DA15-1AP6 | 3RA1225-0EA23-1AP6 OR 3RA1225-0DA23-1AP6 |
| 3VHR330-1MD10Q0 | 3RA1215-0EA15-1AV0 OR 3RA1215-0DA15-1AV0 | 3RA1225-0EA23-1AV0 OR 3RA1225-0DA23-1AV0 |
| 3VHR330-1MD10Q4 | 3RA1215-0EA15-1BP4 OR 3RA1215-0DA15-1BP4 | 3RA1225-0EA23-1BP4 OR 3RA1225-0DA23-1BP4 |
| 3VHR330-1MD10S0 | 3RA1215-0EA15-1AT6 OR 3RA1215-0DA15-1AT6 | 3RA1225-0EA23-1AT6 OR 3RA1225-0DA23-1AT6 |
| 3VHR330-1MD10U1 | 3RA1215-0EA15-1AU6 OR 3RA1215-0DA15-1AU6 | 3RA1225-0EA23-1AU6 OR 3RA1225-0DA23-1AU6 |
| 3VHR330-1MD10W4 | 3RA1215-0EA15-1BW4 OR 3RA1215-0DA15-1BW4 | 3RA1225-0EA23-1BW4 OR 3RA1225-0DA23-1BW4 |
| 3VHR330-1ME10A4 | 3RA1215-0GA15-1BA4 OR 3RA1215-0FA15-1BA4 | 3RA1225-0GA23-1BA4 OR 3RA1225-0FA23-1BA4 |
| 3VHR330-1ME10B4 | 3RA1215-0GA15-1BB4 OR 3RA1215-0FA15-1BB4 | 3RA1225-0GA23-1BB4 OR 3RA1225-0FA23-1BB4 |
| 3VHR330-1ME10C2 | 3RA1215-0GA15-1AC2 OR 3RA1215-0FA15-1AC2 | 3RA1225-0GA23-1AC2 OR 3RA1225-0FA23-1AC2 |
| 3VHR330-1ME10G4 | 3RA1215-0GA15-1BG4 OR 3RA1215-0FA15-1BG4 | 3RA1225-0GA23-1BG4 OR 3RA1225-0FA23-1BG4 |
| 3VHR330-1ME10K6 | 3RA1215-0GA15-1AK6 OR 3RA1215-0FA15-1AK6 | 3RA1225-0GA23-1AK6 OR 3RA1225-0FA23-1AK6 |
| 3VHR330-1ME10M1 | 3RA1215-0GA15-1AM2 OR 3RA1215-0FA15-1AM2 | 3RA1225-0GA23-1AM2 OR 3RA1225-0FA23-1AM2 |
| 3VHR330-1ME10P6 | 3RA1215-0GA15-1AP6 OR 3RA1215-0FA15-1AP6 | 3RA1225-0GA23-1AP6 OR 3RA1225-0FA23-1AP6 |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3VHR330-1ME10Q0 | 3RA1215-0GA15-1AV0 OR 3RA1215-0FA15-1AV0 | 3RA1225-0GA23-1AV0 OR 3RA1225-0FA23-1AV0 |
| 3VHR330-1ME10Q4 | 3RA1215-0GA15-1BP4 OR 3RA1215-0FA15-1BP4 | 3RA1225-0GA23-1BP4 OR 3RA1225-0FA23-1BP4 |
| 3VHR330-1ME10S0 | 3RA1215-0GA15-1AT6 OR 3RA1215-0FA15-1AT6 | 3RA1225-0GA23-1AT6 OR 3RA1225-0FA23-1AT6 |
| 3VHR330-1ME10U1 | 3RA1215-0GA15-1AU6 OR 3RA1215-0FA15-1AU6 | 3RA1225-0GA23-1AU6 OR 3RA1225-0FA23-1AU6 |
| 3VHR330-1ME10W4 | 3RA1215-0GA15-1BW4 OR 3RA1215-0FA15-1BW4 | 3RA1225-0GA23-1BW4 OR 3RA1225-0FA23-1BW4 |
| 3VHR330-1MF10A4 | 3RA1215-0JA15-1BA4 OR 3RA1215-0HA15-1BA4 | 3RA1225-0JA23-1BA4 OR 3RA1225-0HA23-1BA4 |
| 3VHR330-1MF10B4 | 3RA1215-0JA15-1BB4 OR 3RA1215-0HA15-1BB4 | 3RA1225-0JA23-1BB4 OR 3RA1225-0HA23-1BB4 |
| 3VHR330-1MF10C2 | 3RA1215-0JA15-1AC2 OR 3RA1215-0HA15-1AC2 | 3RA1225-0JA23-1AC2 OR 3RA1225-0HA23-1AC2 |
| 3VHR330-1MF10G4 | 3RA1215-0JA15-1BG4 OR 3RA1215-0HA15-1BG4 | 3RA1225-0JA23-1BG4 OR 3RA1225-0HA23-1BG4 |
| 3VHR330-1MF10K6 | 3RA1215-0JA15-1AK6 OR 3RA1215-0HA15-1AK6 | 3RA1225-0JA23-1AK6 OR 3RA1225-0HA23-1AK6 |
| 3VHR330-1MF10M1 | 3RA1215-0JA15-1AM2 OR 3RA1215-0HA15-1AM2 | 3RA1225-0JA23-1AM2 OR 3RA1225-0HA23-1AM2 |
| 3VHR330-1MF10P6 | 3RA1215-0JA15-1AP6 OR 3RA1215-0HA15-1AP6 | 3RA1225-0JA23-1AP6 OR 3RA1225-0HA23-1AP6 |
| 3VHR330-1MF10Q0 | 3RA1215-0JA15-1AV0 OR 3RA1215-0HA15-1AV0 | 3RA1225-0JA23-1AV0 OR 3RA1225-0HA23-1AV0 |
| 3VHR330-1MF10Q4 | 3RA1215-0JA15-1BP4 OR 3RA1215-0HA15-1BP4 | 3RA1225-0JA23-1BP4 OR 3RA1225-0HA23-1BP4 |
| 3VHR330-1MF10S0 | 3RA1215-0JA15-1AT6 OR 3RA1215-0HA15-1AT6 | 3RA1225-0JA23-1AT6 OR 3RA1225-0HA23-1AT6 |
| 3VHR330-1MF10U1 | 3RA1215-0JA15-1AU6 OR 3RA1215-0HA15-1AU6 | 3RA1225-0JA23-1AU6 OR 3RA1225-0HA23-1AU6 |
| 3VHR330-1MF10W4 | 3RA1215-0JA15-1BW4 OR 3RA1215-0HA15-1BW4 | 3RA1225-0JA23-1BW4 OR 3RA1225-0HA23-1BW4 |
| 3VHR330-1MG10A4 | 3RA1215-1AA15-1BA4 OR 3RA1215-0AK15-1BA4 | 3RA1225-1AA23-1BA4 OR 3RA1225-0AK23-1BA4 |
| 3VHR330-1MG10B4 | 3RA1215-1AA15-1BB4 OR 3RA1215-0AK15-1BB4 | 3RA1225-1AA23-1BB4 OR 3RA1225-0AK23-1BB4 |
| 3VHR330-1MG10C2 | 3RA1215-1AA15-1AC2 OR 3RA1215-0AK15-1AC2 | 3RA1225-1AA23-1AC2 OR 3RA1225-0AK23-1AC2 |
| 3VHR330-1MG10G4 | 3RA1215-1AA15-1BG4 OR 3RA1215-0AK15-1BG4 | 3RA1225-1AA23-1BG4 OR 3RA1225-0AK23-1BG4 |
| 3VHR330-1MG10K6 | 3RA1215-1AA15-1AK6 OR 3RA1215-0AK15-1AK6 | 3RA1225-1AA23-1AK6 OR 3RA1225-0AK23-1AK6 |
| 3VHR330-1MG10M1 | 3RA1215-1AA15-1AM2 OR 3RA1215-0AK15-1AM2 | 3RA1225-1AA23-1AM2 OR 3RA1225-0AK23-1AM2 |
| 3VHR330-1MG10P6 | 3RA1215-1AA15-1AP6 OR 3RA1215-0AK15-1AP6 | 3RA1225-1AA23-1AP6 OR 3RA1225-0AK23-1AP6 |
| 3VHR330-1MG10Q0 | 3RA1215-1AA15-1AV0 OR 3RA1215-0AK15-1AV0 | 3RA1225-1AA23-1AV0 OR 3RA1225-0AK23-1AV0 |
| 3VHR330-1MG10Q4 | 3RA1215-1AA15-1BP4 OR 3RA1215-0AK15-1BP4 | 3RA1225-1AA23-1BP4 OR 3RA1225-0AK23-1BP4 |
| 3VHR330-1MG10S0 | 3RA1215-1AA15-1AT6 OR 3RA1215-0AK15-1AT6 | 3RA1225-1AA23-1AT6 OR 3RA1225-0AK23-1AT6 |
| 3VHR330-1MG10U1 | 3RA1215-1AA15-1AU6 OR 3RA1215-0AK15-1AU6 | 3RA1225-1AA23-1AU6 OR 3RA1225-0AK23-1AU6 |
| 3VHR330-1MG10W4 | 3RA1215-1AA15-1BW4 OR 3RA1215-0AK15-1BW4 | 3RA1225-1AA23-1BW4 OR 3RA1225-0AK23-1BW4 |
| 3VHR330-1MH10A4 | 3RA1215-1CA15-1BA4 OR 3RA1215-1BA15-1BA4 | 3RA1225-1CA23-1BA4 OR 3RA1225-1BA23-1BA4 |
| 3VHR330-1MH10B4 | 3RA1215-1CA15-1BB4 OR 3RA1215-1BA15-1BB4 | 3RA1225-1CA23-1BB4 OR 3RA1225-1BA23-1BB4 |
| 3VHR330-1MH10C2 | 3RA1215-1CA15-1AC2 OR 3RA1215-1BA15-1AC2 | 3RA1225-1CA23-1AC2 OR 3RA1225-1BA23-1AC2 |
| 3VHR330-1MH10G4 | 3RA1215-1CA15-1BG4 OR 3RA1215-1BA15-1BG4 | 3RA1225-1CA23-1BG4 OR 3RA1225-1BA23-1BG4 |
| 3VHR330-1MH10K6 | 3RA1215-1CA15-1AK6 OR 3RA1215-1BA15-1AK6 | 3RA1225-1CA23-1AK6 OR 3RA1225-1BA23-1AK6 |
| 3VHR330-1MH10M1 | 3RA1215-1CA15-1AM2 OR 3RA1215-1BA15-1AM2 | 3RA1225-1CA23-1AM2 OR 3RA1225-1BA23-1AM2 |
| 3VHR330-1MH10P6 | 3RA1215-1CA15-1AP6 OR 3RA1215-1BA15-1AP6 | 3RA1225-1CA23-1AP6 OR 3RA1225-1BA23-1AP6 |
| 3VHR330-1MH10Q0 | 3RA1215-1CA15-1AV0 OR 3RA1215-1BA15-1AV0 | 3RA1225-1CA23-1AV0 OR 3RA1225-1BA23-1AV0 |
| 3VHR330-1MH10Q4 | 3RA1215-1CA15-1BP4 OR 3RA1215-1BA15-1BP4 | 3RA1225-1CA23-1BP4 OR 3RA1225-1BA23-1BP4 |
| 3VHR330-1MH10S0 | 3RA1215-1CA15-1AT6 OR 3RA1215-1BA15-1AT6 | 3RA1225-1CA23-1AT6 OR 3RA1225-1BA23-1AT6 |
| 3VHR330-1MH10U1 | 3RA1215-1CA15-1AU6 OR 3RA1215-1BA15-1AU6 | 3RA1225-1CA23-1AU6 OR 3RA1225-1BA23-1AU6 |
| 3VHR330-1MH10W4 | 3RA1215-1CA15-1BW4 OR 3RA1215-1BA15-1BW4 | 3RA1225-1CA23-1BW4 OR 3RA1225-1BA23-1BW4 |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3VHR330-1MJ10A4 | 3RA1215-1EA15-1BA4 OR 3RA1215-1DA15-1BA4 | 3RA1225-1EA23-1BA4 OR 3RA1225-1DA23-1BA4 |
| 3VHR330-1MJ10B4 | 3RA1215-1EA15-1BB4 OR 3RA1215-1DA15-1BB4 | 3RA1225-1EA23-1BB4 OR 3RA1225-1DA23-1BB4 |
| 3VHR330-1MJ10C2 | 3RA1215-1EA15-1AC2 OR 3RA1215-1DA15-1AC2 | 3RA1225-1EA23-1AC2 OR 3RA1225-1DA23-1AC2 |
| 3VHR330-1MJ10G4 | 3RA1215-1EA15-1BG4 OR 3RA1215-1DA15-1BG4 | 3RA1225-1EA23-1BG4 OR 3RA1225-1DA23-1BG4 |
| 3VHR330-1MJ10K6 | 3RA1215-1EA15-1AK6 OR 3RA1215-1DA15-1AK6 | 3RA1225-1EA23-1AK6 OR 3RA1225-1DA23-1AK6 |
| 3VHR330-1MJ10M1 | 3RA1215-1EA15-1AM2 OR 3RA1215-1DA15-1AM2 | 3RA1225-1EA23-1AM2 OR 3RA1225-1DA23-1AM2 |
| 3VHR330-1MJ10P6 | 3RA1215-1EA15-1AP6 OR 3RA1215-1DA15-1AP6 | 3RA1225-1EA23-1AP6 OR 3RA1225-1DA23-1AP6 |
| 3VHR330-1MJ10Q0 | 3RA1215-1EA15-1AV0 OR 3RA1215-1DA15-1AV0 | 3RA1225-1EA23-1AV0 OR 3RA1225-1DA23-1AV0 |
| 3VHR330-1MJ10Q4 | 3RA1215-1EA15-1BP4 OR 3RA1215-1DA15-1BP4 | 3RA1225-1EA23-1BP4 OR 3RA1225-1DA23-1BP4 |
| 3VHR330-1MJ10S0 | 3RA1215-1EA15-1AT6 OR 3RA1215-1DA15-1AT6 | 3RA1225-1EA23-1AT6 OR 3RA1225-1DA23-1AT6 |
| 3VHR330-1MJ10U1 | 3RA1215-1EA15-1AU6 OR 3RA1215-1DA15-1AU6 | 3RA1225-1EA23-1AU6 OR 3RA1225-1DA23-1AU6 |
| 3VHR330-1MJ10W4 | 3RA1215-1EA15-1BW4 OR 3RA1215-1DA15-1BW4 | 3RA1225-1EA23-1BW4 OR 3RA1225-1DA23-1BW4 |
| 3VHR330-1MK10A4 | 3RA1215-1GA15-1BA4 OR 3RA1215-1FA15-1BA4 | 3RA1225-1GA23-1BA4 OR 3RA1225-1FA23-1BA4 |
| 3VHR330-1MK10B4 | 3RA1215-1GA15-1BB4 OR 3RA1215-1FA15-1BB4 | 3RA1225-1GA23-1BB4 OR 3RA1225-1FA23-1BB4 |
| 3VHR330-1MK10C2 | 3RA1215-1GA15-1AC2 OR 3RA1215-1FA15-1AC2 | 3RA1225-1GA23-1AC2 OR 3RA1225-1FA23-1AC2 |
| 3VHR330-1MK10G4 | 3RA1215-1GA15-1BG4 OR 3RA1215-1FA15-1BG4 | 3RA1225-1GA23-1BG4 OR 3RA1225-1FA23-1BG4 |
| 3VHR330-1MK10K6 | 3RA1215-1GA15-1AK6 OR 3RA1215-1FA15-1AK6 | 3RA1225-1GA23-1AK6 OR 3RA1225-1FA23-1AK6 |
| 3VHR330-1MK10M1 | 3RA1215-1GA15-1AM2 OR 3RA1215-1FA15-1AM2 | 3RA1225-1GA23-1AM2 OR 3RA1225-1FA23-1AM2 |
| 3VHR330-1MK10P6 | 3RA1215-1GA15-1AP6 OR 3RA1215-1FA15-1AP6 | 3RA1225-1GA23-1AP6 OR 3RA1225-1FA23-1AP6 |
| 3VHR330-1MK10Q0 | 3RA1215-1GA15-1AV0 OR 3RA1215-1FA15-1AV0 | 3RA1225-1GA23-1AV0 OR 3RA1225-1FA23-1AV0 |
| 3VHR330-1MK10Q4 | 3RA1215-1GA15-1BP4 OR 3RA1215-1FA15-1BP4 | 3RA1225-1GA23-1BP4 OR 3RA1225-1FA23-1BP4 |
| 3VHR330-1MK10S0 | 3RA1215-1GA15-1AT6 OR 3RA1215-1FA15-1AT6 | 3RA1225-1GA23-1AT6 OR 3RA1225-1FA23-1AT6 |
| 3VHR330-1MK10U1 | 3RA1215-1GA15-1AU6 OR 3RA1215-1FA15-1AU6 | 3RA1225-1GA23-1AU6 OR 3RA1225-1FA23-1AU6 |
| 3VHR330-1MK10W4 | 3RA1215-1GA15-1BW4 OR 3RA1215-1FA15-1BW4 | 3RA1225-1GA23-1BW4 OR 3RA1225-1FA23-1BW4 |
| 3VHR330-1ML10A4 | 3RA1225-1JA24-1BA4 OR 3RA1215-1HA16-1BA4 | |
| 3VHR330-1ML10B4 | 3RA1225-1JA24-1BB4 OR 3RA1215-1HA16-1BB4 | |
| 3VHR330-1ML10C2 | 3RA1225-1JA24-1AC2 OR 3RA1215-1HA16-1AC2 | |
| 3VHR330-1ML10G4 | 3RA1225-1JA24-1BG4 OR 3RA1215-1HA16-1BG4 | |
| 3VHR330-1ML10K6 | 3RA1225-1JA24-1AK6 OR 3RA1215-1HA16-1AK6 | |
| 3VHR330-1ML10M1 | 3RA1225-1JA24-1AM2 OR 3RA1215-1HA16-1AM2 | |
| 3VHR330-1ML10P6 | 3RA1225-1JA24-1AP6 OR 3RA1215-1HA16-1AP6 | |
| 3VHR330-1ML10Q0 | 3RA1225-1JA24-1AV0 OR 3RA1215-1HA16-1AV0 | |
| 3VHR330-1ML10Q4 | 3RA1225-1JA24-1BP4 OR 3RA1215-1HA16-1BP4 | |
| 3VHR330-1ML10S0 | 3RA1225-1JA24-1AT6 OR 3RA1215-1HA16-1AT6 | |
| 3VHR330-1ML10U1 | 3RA1225-1JA24-1AU6 OR 3RA1215-1HA16-1AU6 | |
| 3VHR330-1ML10W4 | 3RA1225-1JA24-1BW4 OR 3RA1215-1HA16-1BW4 | |
| 3VHR332-1MG10A4 | 3RA1215-1AA15-1BA4 OR 3RA1215-0AK15-1BA4 | 3RA1225-1AA23-1BA4 OR 3RA1225-0AK23-1BA4 |
| 3VHR332-1MG10B4 | 3RA1215-1AA15-1BB4 OR 3RA1215-0AK15-1BB4 | 3RA1225-1AA23-1BB4 OR 3RA1225-0AK23-1BB4 |
| 3VHR332-1MG10C2 | 3RA1215-1AA15-1AC2 OR 3RA1215-0AK15-1AC2 | 3RA1225-1AA23-1AC2 OR 3RA1225-0AK23-1AC2 |
| 3VHR332-1MG10G4 | 3RA1215-1AA15-1BG4 OR 3RA1215-0AK15-1BG4 | 3RA1225-1AA23-1BG4 OR 3RA1225-0AK23-1BG4 |
| 3VHR332-1MG10K6 | 3RA1215-1AA15-1AK6 OR 3RA1215-0AK15-1AK6 | 3RA1225-1AA23-1AK6 OR 3RA1225-0AK23-1AK6 |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3VHR332-1MG10M1 | 3RA1215-1AA15-1AM2 OR 3RA1215-0AK15-1AM2 | 3RA1225-1AA23-1AM2 OR 3RA1225-0AK23-1AM2 |
| 3VHR332-1MG10P6 | 3RA1215-1AA15-1AP6 OR 3RA1215-0AK15-1AP6 | 3RA1225-1AA23-1AP6 OR 3RA1225-0AK23-1AP6 |
| 3VHR332-1MG10Q0 | 3RA1215-1AA15-1AV0 OR 3RA1215-0AK15-1AV0 | 3RA1225-1AA23-1AV0 OR 3RA1225-0AK23-1AV0 |
| 3VHR332-1MG10Q4 | 3RA1215-1AA15-1BP4 OR 3RA1215-0AK15-1BP4 | 3RA1225-1AA23-1BP4 OR 3RA1225-0AK23-1BP4 |
| 3VHR332-1MG10S0 | 3RA1215-1AA15-1AT6 OR 3RA1215-0AK15-1AT6 | 3RA1225-1AA23-1AT6 OR 3RA1225-0AK23-1AT6 |
| 3VHR332-1MG10U1 | 3RA1215-1AA15-1AU6 OR 3RA1215-0AK15-1AU6 | 3RA1225-1AA23-1AU6 OR 3RA1225-0AK23-1AU6 |
| 3VHR332-1MG10W4 | 3RA1215-1AA15-1BW4 OR 3RA1215-0AK15-1BW4 | 3RA1225-1AA23-1BW4 OR 3RA1225-0AK23-1BW4 |
| 3VHR332-1MH10A4 | 3RA1215-1CA15-1BA4 OR 3RA1215-1BA15-1BA4 | 3RA1225-1CA23-1BA4 OR 3RA1225-1BA23-1BA4 |
| 3VHR332-1MH10B4 | 3RA1215-1CA15-1BB4 OR 3RA1215-1BA15-1BB4 | 3RA1225-1CA23-1BB4 OR 3RA1225-1BA23-1BB4 |
| 3VHR332-1MH10C2 | 3RA1215-1CA15-1AC2 OR 3RA1215-1BA15-1AC2 | 3RA1225-1CA23-1AC2 OR 3RA1225-1BA23-1AC2 |
| 3VHR332-1MH10G4 | 3RA1215-1CA15-1BG4 OR 3RA1215-1BA15-1BG4 | 3RA1225-1CA23-1BG4 OR 3RA1225-1BA23-1BG4 |
| 3VHR332-1MH10K6 | 3RA1215-1CA15-1AK6 OR 3RA1215-1BA15-1AK6 | 3RA1225-1CA23-1AK6 OR 3RA1225-1BA23-1AK6 |
| 3VHR332-1MH10M1 | 3RA1215-1CA15-1AM2 OR 3RA1215-1BA15-1AM2 | 3RA1225-1CA23-1AM2 OR 3RA1225-1BA23-1AM2 |
| 3VHR332-1MH10P6 | 3RA1215-1CA15-1AP6 OR 3RA1215-1BA15-1AP6 | 3RA1225-1CA23-1AP6 OR 3RA1225-1BA23-1AP6 |
| 3VHR332-1MH10Q0 | 3RA1215-1CA15-1AV0 OR 3RA1215-1BA15-1AV0 | 3RA1225-1CA23-1AV0 OR 3RA1225-1BA23-1AV0 |
| 3VHR332-1MH10Q4 | 3RA1215-1CA15-1BP4 OR 3RA1215-1BA15-1BP4 | 3RA1225-1CA23-1BP4 OR 3RA1225-1BA23-1BP4 |
| 3VHR332-1MH10S0 | 3RA1215-1CA15-1AT6 OR 3RA1215-1BA15-1AT6 | 3RA1225-1CA23-1AT6 OR 3RA1225-1BA23-1AT6 |
| 3VHR332-1MH10U1 | 3RA1215-1CA15-1AU6 OR 3RA1215-1BA15-1AU6 | 3RA1225-1CA23-1AU6 OR 3RA1225-1BA23-1AU6 |
| 3VHR332-1MH10W4 | 3RA1215-1CA15-1BW4 OR 3RA1215-1BA15-1BW4 | 3RA1225-1CA23-1BW4 OR 3RA1225-1BA23-1BW4 |
| 3VHR332-1MJ10A4 | 3RA1215-1EA15-1BA4 OR 3RA1215-1DA15-1BA4 | 3RA1225-1EA23-1BA4 OR 3RA1225-1DA23-1BA4 |
| 3VHR332-1MJ10B4 | 3RA1215-1EA15-1BB4 OR 3RA1215-1DA15-1BB4 | 3RA1225-1EA23-1BB4 OR 3RA1225-1DA23-1BB4 |
| 3VHR332-1MJ10C2 | 3RA1215-1EA15-1AC2 OR 3RA1215-1DA15-1AC2 | 3RA1225-1EA23-1AC2 OR 3RA1225-1DA23-1AC2 |
| 3VHR332-1MJ10G4 | 3RA1215-1EA15-1BG4 OR 3RA1215-1DA15-1BG4 | 3RA1225-1EA23-1BG4 OR 3RA1225-1DA23-1BG4 |
| 3VHR332-1MJ10K6 | 3RA1215-1EA15-1AK6 OR 3RA1215-1DA15-1AK6 | 3RA1225-1EA23-1AK6 OR 3RA1225-1DA23-1AK6 |
| 3VHR332-1MJ10M1 | 3RA1215-1EA15-1AM2 OR 3RA1215-1DA15-1AM2 | 3RA1225-1EA23-1AM2 OR 3RA1225-1DA23-1AM2 |
| 3VHR332-1MJ10P6 | 3RA1215-1EA15-1AP6 OR 3RA1215-1DA15-1AP6 | 3RA1225-1EA23-1AP6 OR 3RA1225-1DA23-1AP6 |
| 3VHR332-1MJ10Q0 | 3RA1215-1EA15-1AV0 OR 3RA1215-1DA15-1AV0 | 3RA1225-1EA23-1AV0 OR 3RA1225-1DA23-1AV0 |
| 3VHR332-1MJ10Q4 | 3RA1215-1EA15-1BP4 OR 3RA1215-1DA15-1BP4 | 3RA1225-1EA23-1BP4 OR 3RA1225-1DA23-1BP4 |
| 3VHR332-1MJ10S0 | 3RA1215-1EA15-1AT6 OR 3RA1215-1DA15-1AT6 | 3RA1225-1EA23-1AT6 OR 3RA1225-1DA23-1AT6 |
| 3VHR332-1MJ10U1 | 3RA1215-1EA15-1AU6 OR 3RA1215-1DA15-1AU6 | 3RA1225-1EA23-1AU6 OR 3RA1225-1DA23-1AU6 |
| 3VHR332-1MJ10W4 | 3RA1215-1EA15-1BW4 OR 3RA1215-1DA15-1BW4 | 3RA1225-1EA23-1BW4 OR 3RA1225-1DA23-1BW4 |
| 3VHR332-1MK10A4 | 3RA1215-1GA15-1BA4 OR 3RA1215-1FA15-1BA4 | 3RA1225-1GA23-1BA4 OR 3RA1225-1FA23-1BA4 |
| 3VHR332-1MK10B4 | 3RA1215-1GA15-1BB4 OR 3RA1215-1FA15-1BB4 | 3RA1225-1GA23-1BB4 OR 3RA1225-1FA23-1BB4 |
| 3VHR332-1MK10C2 | 3RA1215-1GA15-1AC2 OR 3RA1215-1FA15-1AC2 | 3RA1225-1GA23-1AC2 OR 3RA1225-1FA23-1AC2 |
| 3VHR332-1MK10G4 | 3RA1215-1GA15-1BG4 OR 3RA1215-1FA15-1BG4 | 3RA1225-1GA23-1BG4 OR 3RA1225-1FA23-1BG4 |
| 3VHR332-1MK10K6 | 3RA1215-1GA15-1AK6 OR 3RA1215-1FA15-1AK6 | 3RA1225-1GA23-1AK6 OR 3RA1225-1FA23-1AK6 |
| 3VHR332-1MK10M1 | 3RA1215-1GA15-1AM2 OR 3RA1215-1FA15-1AM2 | 3RA1225-1GA23-1AM2 OR 3RA1225-1FA23-1AM2 |
| 3VHR332-1MK10P6 | 3RA1215-1GA15-1AP6 OR 3RA1215-1FA15-1AP6 | 3RA1225-1GA23-1AP6 OR 3RA1225-1FA23-1AP6 |
| 3VHR332-1MK10Q0 | 3RA1215-1GA15-1AV0 OR 3RA1215-1FA15-1AV0 | 3RA1225-1GA23-1AV0 OR 3RA1225-1FA23-1AV0 |
| 3VHR332-1MK10Q4 | 3RA1215-1GA15-1BP4 OR 3RA1215-1FA15-1BP4 | 3RA1225-1GA23-1BP4 OR 3RA1225-1FA23-1BP4 |
| 3VHR332-1MK10S0 | 3RA1215-1GA15-1AT6 OR 3RA1215-1FA15-1AT6 | 3RA1225-1GA23-1AT6 OR 3RA1225-1FA23-1AT6 |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3VHR332-1MK10U1 | 3RA1215-1GA15-1AU6 OR 3RA1215-1FA15-1AU6 | 3RA1225-1GA23-1AU6 OR 3RA1225-1FA23-1AU6 |
| 3VHR332-1MK10W4 | 3RA1215-1GA15-1BW4 OR 3RA1215-1FA15-1BW4 | 3RA1225-1GA23-1BW4 OR 3RA1225-1FA23-1BW4 |
| 3VHR332-1MM10A4 | 3RA1225-4AA25-1BA4 OR 3RA1225-1KA23-1BA4 | |
| 3VHR332-1MM10B4 | 3RA1225-4AA25-1BB4 OR 3RA1225-1KA23-1BB4 | |
| 3VHR332-1MM10C2 | 3RA1225-4AA25-1AC2 OR 3RA1225-1KA23-1AC2 | |
| 3VHR332-1MM10G4 | 3RA1225-4AA25-1BG4 OR 3RA1225-1KA23-1BG4 | |
| 3VHR332-1MM10K6 | 3RA1225-4AA25-1AK6 OR 3RA1225-1KA23-1AK6 | |
| 3VHR332-1MM10M1 | 3RA1225-4AA25-1AM2 OR 3RA1225-1KA23-1AM2 | |
| 3VHR332-1MM10P6 | 3RA1225-4AA25-1AP6 OR 3RA1225-1KA23-1AP6 | |
| 3VHR332-1MM10Q0 | 3RA1225-4AA25-1AV0 OR 3RA1225-1KA23-1AV0 | |
| 3VHR332-1MM10Q4 | 3RA1225-4AA25-1BP4 OR 3RA1225-1KA23-1BP4 | |
| 3VHR332-1MM10S0 | 3RA1225-4AA25-1AT6 OR 3RA1225-1KA23-1AT6 | |
| 3VHR332-1MM10U1 | 3RA1225-4AA25-1AU6 OR 3RA1225-1KA23-1AU6 | |
| 3VHR332-1MM10W4 | 3RA1225-4AA25-1BW4 OR 3RA1225-1KA23-1BW4 | |
| 3VHR333-1MN10A4 | 3RA1225-4BA26-1BA4 | |
| 3VHR333-1MN10B4 | 3RA1225-4BA26-1BB4 | |
| 3VHR333-1MN10C2 | 3RA1225-4BA26-1AC2 | |
| 3VHR333-1MN10G4 | 3RA1225-4BA26-1BG4 | |
| 3VHR333-1MN10K6 | 3RA1225-4BA26-1AK6 | |
| 3VHR333-1MN10M1 | 3RA1225-4BA26-1AM2 | |
| 3VHR333-1MN10P6 | 3RA1225-4BA26-1AP6 | |
| 3VHR333-1MN10Q0 | 3RA1225-4BA26-1AV0 | |
| 3VHR333-1MN10Q4 | 3RA1225-4BA26-1BP4 | |
| 3VHR333-1MN10S0 | 3RA1225-4BA26-1AT6 | |
| 3VHR333-1MN10U1 | 3RA1225-4BA26-1AU6 | |
| 3VHR333-1MN10W4 | 3RA1225-4BA26-1BW4 | |
| 3VHR334-1MN10A4 | 3RA1225-4BA26-1BA4 | |
| 3VHR334-1MN10B4 | 3RA1225-4BA26-1BB4 | |
| 3VHR334-1MN10C2 | 3RA1225-4BA26-1AC2 | |
| 3VHR334-1MN10G4 | 3RA1225-4BA26-1BG4 | |
| 3VHR334-1MN10K6 | 3RA1225-4BA26-1AK6 | |
| 3VHR334-1MN10M1 | 3RA1225-4BA26-1AM2 | |
| 3VHR334-1MN10P6 | 3RA1225-4BA26-1AP6 | |
| 3VHR334-1MN10Q0 | 3RA1225-4BA26-1AV0 | |
| 3VHR334-1MN10Q4 | 3RA1225-4BA26-1BP4 | |
| 3VHR334-1MN10S0 | 3RA1225-4BA26-1AT6 | |
| 3VHR334-1MN10U1 | 3RA1225-4BA26-1AU6 | |
| 3VHR334-1MN10W4 | 3RA1225-4BA26-1BW4 | |
| 3VHR334-1MP10A4 | 3RA1235-4DB33-1BA4 OR 3RA1225-4CA26-1BA4 | |
| 3VHR334-1MP10B4 | 3RA1235-4DB33-1BB4 OR 3RA1225-4CA26-1BB4 | |
| 3VHR334-1MP10C2 | 3RA1235-4DB33-1AC2 OR 3RA1225-4CA26-1AC2 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3VHR334-1MP10G4 | 3RA1235-4DB33-1BG4 OR 3RA1225-4CA26-1BG4 | |
| 3VHR334-1MP10K6 | 3RA1235-4DB33-1AK6 OR 3RA1225-4CA26-1AK6 | |
| 3VHR334-1MP10M1 | 3RA1235-4DB33-1AM2 OR 3RA1225-4CA26-1AM2 | |
| 3VHR334-1MP10P6 | 3RA1235-4DB33-1AP6 OR 3RA1225-4CA26-1AP6 | |
| 3VHR334-1MP10Q0 | 3RA1235-4DB33-1AV0 OR 3RA1225-4CA26-1AV0 | |
| 3VHR334-1MP10Q4 | 3RA1235-4DB33-1BP4 OR 3RA1225-4CA26-1BP4 | |
| 3VHR334-1MP10S0 | 3RA1235-4DB33-1AT6 OR 3RA1225-4CA26-1AT6 | |
| 3VHR334-1MP10U1 | 3RA1235-4DB33-1AU6 OR 3RA1225-4CA26-1AU6 | |
| 3VHR334-1MP10W4 | 3RA1235-4DB33-1BW4 OR 3RA1225-4CA26-1BW4 | |
| 3VHR634-1MP10A4 | 3RA1235-4EB34-1BA4 | |
| 3VHR634-1MP10B4 | 3RA1235-4EB34-1BB4 | |
| 3VHR634-1MP10C2 | 3RA1235-4EB34-1AC2 | |
| 3VHR634-1MP10G4 | 3RA1235-4EB34-1BG4 | |
| 3VHR634-1MP10K6 | 3RA1235-4EB34-1AK6 | |
| 3VHR634-1MP10M1 | 3RA1235-4EB34-1AM2 | |
| 3VHR634-1MP10P6 | 3RA1235-4EB34-1AP6 | |
| 3VHR634-1MP10Q0 | 3RA1235-4EB34-1AV0 | |
| 3VHR634-1MP10Q4 | 3RA1235-4EB34-1BP4 | |
| 3VHR634-1MP10S0 | 3RA1235-4EB34-1AT6 | |
| 3VHR634-1MP10U1 | 3RA1235-4EB34-1AU6 | |
| 3VHR634-1MP10W4 | 3RA1235-4EB34-1BW4 | |
| 3VHR635-1MQ10A4 | 3RA1235-4FB35-1BA4 | |
| 3VHR635-1MQ10B4 | 3RA1235-4FB35-1BB4 | |
| 3VHR635-1MQ10C2 | 3RA1235-4FB35-1AC2 | |
| 3VHR635-1MQ10G4 | 3RA1235-4FB35-1BG4 | |
| 3VHR635-1MQ10K6 | 3RA1235-4FB35-1AK6 | |
| 3VHR635-1MQ10M1 | 3RA1235-4FB35-1AM2 | |
| 3VHR635-1MQ10P6 | 3RA1235-4FB35-1AP6 | |
| 3VHR635-1MQ10Q0 | 3RA1235-4FB35-1AV0 | |
| 3VHR635-1MQ10Q4 | 3RA1235-4FB35-1BP4 | |
| 3VHR635-1MQ10S0 | 3RA1235-4FB35-1AT6 | |
| 3VHR635-1MQ10U1 | 3RA1235-4FB35-1AU6 | |
| 3VHR635-1MQ10W4 | 3RA1235-4FB35-1BW4 | |
| 3VU1300-0MB00 | 3RV1011-0AA10 + AUX | 3RV1021-0AA10 + AUX |
| 3VU1300-0MC00 | 3RV1011-0CA10 OR 3RV1011-0BA10 (+ AUX) | 3RV1021-0CA10 OR 3RV1021-0BA10 (+ AUX) |
| 3VU1300-0MD00 | 3RV1011-0EA10 OR 3RV1011-0DA10 (+ AUX) | 3RV1021-0EA10 OR 3RV1021-0DA10 (+ AUX) |
| 3VU1300-0ME00 | 3RV1011-0GA10 OR 3RV1011-0FA10 (+ AUX) | 3RV1021-0GA10 OR 3RV1021-0FA10 (+ AUX) |
| 3VU1300-0MF00 | 3RV1011-0JA10 OR 3RV1011-0HA10 (+ AUX) | 3RV1021-0JA10 OR 3RV1021-0HA10 (+ AUX) |
| 3VU1300-0MG00 | 3RV1011-1AA10 OR 3RV1011-0KA10 (+ AUX) | 3RV1021-1AA10 OR 3RV1021-0KA10 (+ AUX) |
| 3VU1300-0MH00 | 3RV1011-1CA10 OR 3RV1011-1BA10 (+ AUX) | 3RV1021-1CA10 OR 3RV1021-1BA10 (+ AUX) |
| 3VU1300-0MJ00 | 3RV1011-1EA10 OR 3RV1011-1DA10 (+ AUX) | 3RV1021-1EA10 OR 3RV1021-1DA10 (+ AUX) |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3VU1300-0MJ00ZEF | 3RV1011-1EA10 OR 3RV1011-1DA10 (+ AUX) | 3RV1021-1EA10 OR 3RV1021-1DA10 (+ AUX) |
| 3VU1300-0MK00 | 3RV1011-1GA10 OR 3RV1011-1FA10 (+ AUX) | 3RV1021-1GA10 OR 3RV1021-1FA10 (+ AUX) |
| 3VU1300-0MK00ZEF | 3RV1011-1GA10 OR 3RV1011-1FA10 (+ AUX) | 3RV1021-1GA10 OR 3RV1021-1FA10 (+ AUX) |
| 3VU1300-0ML00 | 3RV1021-1JA10 OR 3RV1011-1HA10 (+ AUX) | |
| 3VU1300-0MM00 | 3RV1021-4AA10 OR 3RV1021-1KA10 (+ AUX) | |
| 3VU1300-0MN00 | 3RV1021-4BA10 + AUX | |
| 3VU1300-0MN00ZEF | 3RV1021-4BA10 + AUX | |
| 3VU1300-0MP00 | 3RV1031-4DA10 OR 3RV1021-4CA10 (+ AUX) | |
| 3VU1300-0NH00 | 3RV1011-1DA10 OR 3RV1011-1CA10 (+ AUX) | 3RV1021-1DA10 OR 3RV1021-1CA10 (+ AUX) |
| 3VU1300-0NJ00 | 3RV1011-1FA10 OR 3RV1011-1EA10 (+ AUX) | 3RV1021-1FA10 OR 3RV1021-1EA10 (+ AUX) |
| 3VU1300-0NK00 | 3RV1011-1HA10 OR 3RV1011-1GA10 (+ AUX) | 3RV1021-1HA10 OR 3RV1021-1GA10 (+ AUX) |
| 3VU1300-0NL00 | 3RV1021-1KA10 OR 3RV1021-1JA10 (+ AUX) | |
| 3VU1300-1MB00 | 3RV1011-0AA10 + AUX | 3RV1021-0AA10 + AUX |
| 3VU1300-1MC00 | 3RV1011-0CA10 OR 3RV1011-0BA10 (+ AUX) | 3RV1021-0CA10 OR 3RV1021-0BA10 (+ AUX) |
| 3VU1300-1MD00 | 3RV1011-0EA10 OR 3RV1011-0DA10 (+ AUX) | 3RV1021-0EA10 OR 3RV1021-0DA10 (+ AUX) |
| 3VU1300-1ME00 | 3RV1011-0GA10 OR 3RV1011-0FA10 (+ AUX) | 3RV1021-0GA10 OR 3RV1021-0FA10 (+ AUX) |
| 3VU1300-1MF00 | 3RV1011-0JA10 OR 3RV1011-0HA10 (+ AUX) | 3RV1021-0JA10 OR 3RV1021-0HA10 (+ AUX) |
| 3VU1300-1MG00 | 3RV1011-1AA10 OR 3RV1011-0KA10 (+ AUX) | 3RV1021-1AA10 OR 3RV1021-0KA10 (+ AUX) |
| 3VU1300-1MH00 | 3RV1011-1CA10 OR 3RV1011-1BA10 (+ AUX) | 3RV1021-1CA10 OR 3RV1021-1BA10 (+ AUX) |
| 3VU1300-1MJ00 | 3RV1011-1EA10 OR 3RV1011-1DA10 (+ AUX) | 3RV1021-1EA10 OR 3RV1021-1DA10 (+ AUX) |
| 3VU1300-1MJ00ZEF | 3RV1011-1EA10 OR 3RV1011-1DA10 (+ AUX) | 3RV1021-1EA10 OR 3RV1021-1DA10 (+ AUX) |
| 3VU1300-1MJ00ZQR | 3RV1011-1EA10 OR 3RV1011-1DA10 (+ AUX) | 3RV1021-1EA10 OR 3RV1021-1DA10 (+ AUX) |
| 3VU1300-1MK00 | 3RV1011-1GA10 OR 3RV1011-1FA10 (+ AUX) | 3RV1021-1GA10 OR 3RV1021-1FA10 (+ AUX) |
| 3VU1300-1MK00ZEF | 3RV1011-1GA10 OR 3RV1011-1FA10 (+ AUX) | 3RV1021-1GA10 OR 3RV1021-1FA10 (+ AUX) |
| 3VU1300-1ML00 | 3RV1021-1JA10 OR 3RV1011-1HA10 (+ AUX) | |
| 3VU1300-1MM00 | 3RV1021-4AA10 OR 3RV1021-1KA10 (+ AUX) | |
| 3VU1300-1MN00 | 3RV1021-4BA10 + AUX | |
| 3VU1300-1MN00ZEF | 3RV1021-4BA10 + AUX | |
| 3VU1300-1MP00 | 3RV1031-4DA10 OR 3RV1021-4CA10 (+ AUX) | |
| 3VU1300-1MS00 | 3RV1611-0BD10 | |
| 3VU1300-1NH00 | 3RV1011-1DA10 OR 3RV1011-1CA10 (+ AUX) | 3RV1021-1DA10 OR 3RV1021-1CA10 (+ AUX) |
| 3VU1300-1NJ00 | 3RV1011-1FA10 OR 3RV1011-1EA10 (+ AUX) | 3RV1021-1FA10 OR 3RV1021-1EA10 (+ AUX) |
| 3VU1300-1NK00 | 3RV1011-1HA10 OR 3RV1011-1GA10 (+ AUX) | 3RV1021-1HA10 OR 3RV1021-1GA10 (+ AUX) |
| 3VU1300-1NL00 | 3RV1021-1KA10 OR 3RV1021-1JA10 (+ AUX) | |
| 3VU1300-1TC00 | 3RV1421-0CA10 | |
| 3VU1300-1TD00 | 3RV1421-0EA10 | |
| 3VU1300-1TE00 | 3RV1421-0GA10 | |
| 3VU1300-1TF00 | 3RV1421-0JA10 | |
| 3VU1300-1TG00 | 3RV1421-1AA10 | |
| 3VU1300-1TH00 | 3RV1421-1CA10 | |
| 3VU1300-1TJ00 | 3RV1421-1EA10 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3VU1300-1TK00 | 3RV1421-1GA10 | |
| 3VU1300-1TL00 | 3RV1421-1JA10 | |
| 3VU1300-1TM00 | 3RV1421-4AA10 | |
| 3VU1300-1TN00 | 3RV1421-4BA10 | |
| 3VU1300-2MB00 | 3RV1011-0AA10 + AUX | 3RV1021-0AA10 + AUX |
| 3VU1300-2MC00 | 3RV1011-0CA10 OR 3RV1011-0BA10 (+ AUX) | 3RV1021-0CA10 OR 3RV1021-0BA10 (+ AUX) |
| 3VU1300-2MD00 | 3RV1011-0EA10 OR 3RV1011-0DA10 (+ AUX) | 3RV1021-0EA10 OR 3RV1021-0DA10 (+ AUX) |
| 3VU1300-2ME00 | 3RV1011-0GA10 OR 3RV1011-0FA10 (+ AUX) | 3RV1021-0GA10 OR 3RV1021-0FA10 (+ AUX) |
| 3VU1300-2MF00 | 3RV1011-0JA10 OR 3RV1011-0HA10 (+ AUX) | 3RV1021-0JA10 OR 3RV1021-0HA10 (+ AUX) |
| 3VU1300-2MG00 | 3RV1011-1AA10 OR 3RV1011-0KA10 (+ AUX) | 3RV1021-1AA10 OR 3RV1021-0KA10 (+ AUX) |
| 3VU1300-2MH00 | 3RV1011-1CA10 OR 3RV1011-1BA10 (+ AUX) | 3RV1021-1CA10 OR 3RV1021-1BA10 (+ AUX) |
| 3VU1300-2MJ00 | 3RV1011-1EA10 OR 3RV1011-1DA10 (+ AUX) | 3RV1021-1EA10 OR 3RV1021-1DA10 (+ AUX) |
| 3VU1300-2MK00 | 3RV1011-1GA10 OR 3RV1011-1FA10 (+ AUX) | 3RV1021-1GA10 OR 3RV1021-1FA10 (+ AUX) |
| 3VU1300-2ML00 | 3RV1021-1JA10 OR 3RV1011-1HA10 (+ AUX) | |
| 3VU1300-2MM00 | 3RV1021-4AA10 OR 3RV1021-1KA10 (+ AUX) | |
| 3VU1300-2MN00 | 3RV1021-4BA10 + AUX | |
| 3VU1300-2MP00 | 3RV1031-4DA10 OR 3RV1021-4CA10 (+ AUX) | |
| 3VU1300-2NJ00 | 3RV1011-1FA10 OR 3RV1011-1EA10 (+ AUX) | 3RV1021-1FA10 OR 3RV1021-1EA10 (+ AUX) |
| 3VU1300-2NK00 | 3RV1011-1HA10 OR 3RV1011-1GA10 (+ AUX) | 3RV1021-1HA10 OR 3RV1021-1GA10 (+ AUX) |
| 3VU1300-2NL00 | 3RV1021-1KA10 OR 3RV1021-1JA10 (+ AUX) | |
| 3VU1300-3MD00 | 3RV1011-0EA10 OR 3RV1011-0DA10 (+ AUX) | 3RV1021-0EA10 OR 3RV1021-0DA10 (+ AUX) |
| 3VU1300-3ME00 | 3RV1011-0GA10 OR 3RV1011-0FA10 (+ AUX) | 3RV1021-0GA10 OR 3RV1021-0FA10 (+ AUX) |
| 3VU1300-3MG00 | 3RV1011-1AA10 OR 3RV1011-0KA10 (+ AUX) | 3RV1021-1AA10 OR 3RV1021-0KA10 (+ AUX) |
| 3VU1300-3MH00 | 3RV1011-1CA10 OR 3RV1011-1BA10 (+ AUX) | 3RV1021-1CA10 OR 3RV1021-1BA10 (+ AUX) |
| 3VU1300-3NH00 | 3RV1011-1DA10 OR 3RV1011-1CA10 (+ AUX) | 3RV1021-1DA10 OR 3RV1021-1CA10 (+ AUX) |
| 3VU1301-1MC00 | 3RV1011-0CA10 OR 3RV1011-0BA10 (+ AUX) | 3RV1021-0CA10 OR 3RV1021-0BA10 (+ AUX) |
| 3VU1301-1MH00 | 3RV1011-1CA10 OR 3RV1011-1BA10 (+ AUX) | 3RV1021-1CA10 OR 3RV1021-1BA10 (+ AUX) |
| 3VU1301-1MJ00 | 3RV1011-1EA10 OR 3RV1011-1DA10 (+ AUX) | 3RV1021-1EA10 OR 3RV1021-1DA10 (+ AUX) |
| 3VU1301-1MK00 | 3RV1011-1GA10 OR 3RV1011-1FA10 (+ AUX) | 3RV1021-1GA10 OR 3RV1021-1FA10 (+ AUX) |
| 3VU1301-1MM00 | 3RV1021-4AA10 OR 3RV1021-1KA10 (+ AUX) | |
| 3VU1311-6JR00 | NO DIRECT REPLACEMENT | |
| 3VU1600-0CK00 | 3RV1321-1GC10 | |
| 3VU1600-0LS00 | 3RV1041-4JA10 OR 3RV1041-4KA10 (+ AUX) | |
| 3VU1600-0MG00 | 3RV1011-1AA10 OR 3RV1011-0KA10 (+ AUX) | 3RV1021-1AA10 OR 3RV1021-0KA10 (+ AUX) |
| 3VU1600-0MH00 | 3RV1011-1CA10 OR 3RV1011-1BA10 (+ AUX) | 3RV1021-1CA10 OR 3RV1021-1BA10 (+ AUX) |
| 3VU1600-0MJ00 | 3RV1011-1EA10 OR 3RV1011-1DA10 (+ AUX) | 3RV1021-1EA10 OR 3RV1021-1DA10 (+ AUX) |
| 3VU1600-0MK00 | 3RV1011-1GA10 OR 3RV1011-1FA10 (+ AUX) | 3RV1021-1GA10 OR 3RV1021-1FA10 (+ AUX) |
| 3VU1600-0ML00 | 3RV1021-1JA10 OR 3RV1011-1HA10 (+ AUX) | |
| 3VU1600-0MM00 | 3RV1021-4AA10 OR 3RV1021-1KA10 (+ AUX) | |
| 3VU1600-0MN00 | 3RV1021-4BA10 + AUX | |
| 3VU1600-0MP00 | 3RV1031-4EA10 + AUX | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3VU1600-0MQ00 | 3RV1031-4FA10 + AUX | |
| 3VU1600-0MR00 | 3RV1031-4GA10 OR 3RV1031-4HA10 (+ AUX) | |
| 3VU1600-1LS00 | 3RV1041-4JA10 OR 3RV1041-4KA10 (+ AUX) | |
| 3VU1600-1MG00 | 3RV1011-1AA10 OR 3RV1011-0KA10 (+ AUX) | 3RV1021-1AA10 OR 3RV1021-0KA10 (+ AUX) |
| 3VU1600-1MH00 | 3RV1011-1CA10 OR 3RV1011-1BA10 (+ AUX) | 3RV1021-1CA10 OR 3RV1021-1BA10 (+ AUX) |
| 3VU1600-1MJ00 | 3RV1011-1EA10 OR 3RV1011-1DA10 (+ AUX) | 3RV1021-1EA10 OR 3RV1021-1DA10 (+ AUX) |
| 3VU1600-1MK00 | 3RV1011-1GA10 OR 3RV1011-1FA10 (+ AUX) | 3RV1021-1GA10 OR 3RV1021-1FA10 (+ AUX) |
| 3VU1600-1ML00 | 3RV1021-1JA10 OR 3RV1011-1HA10 (+ AUX) | |
| 3VU1600-1MM00 | 3RV1021-4AA10 OR 3RV1021-1KA10 (+ AUX) | |
| 3VU1600-1MN00 | 3RV1021-4BA10 + AUX | |
| 3VU1600-1MP00 | 3RV1031-4EA10 + AUX | |
| 3VU1600-1MQ00 | 3RV1031-4FA10 + AUX | |
| 3VU1600-1MR00 | 3RV1031-4GA10 OR 3RV1031-4HA10 (+ AUX) | |
| 3VU1600-2MG00 | 3RV1011-1AA10 OR 3RV1011-0KA10 (+ AUX) | 3RV1021-1AA10 OR 3RV1021-0KA10 (+ AUX) |
| 3VU1600-2MH00 | 3RV1011-1CA10 OR 3RV1011-1BA10 (+ AUX) | 3RV1021-1CA10 OR 3RV1021-1BA10 (+ AUX) |
| 3VU1600-2MJ00 | 3RV1011-1EA10 OR 3RV1011-1DA10 (+ AUX) | 3RV1021-1EA10 OR 3RV1021-1DA10 (+ AUX) |
| 3VU1600-2MK00 | 3RV1011-1GA10 OR 3RV1011-1FA10 (+ AUX) | 3RV1021-1GA10 OR 3RV1021-1FA10 (+ AUX) |
| 3VU1600-2ML00 | 3RV1021-1JA10 OR 3RV1011-1HA10 (+ AUX) | |
| 3VU1600-2MM00 | 3RV1021-4AA10 OR 3RV1021-1KA10 (+ AUX) | |
| 3VU1600-3MQ00 | 3RV1031-4FA10 + AUX | |
| 3VU9131-3AA00 | 3RV1901-1A | |
| 3VU9131-4AA00 | 3RV1901-1D | |
| 3VU9131-7AA00 | 3RV1921-1M | |
| 3VU9132-0AA14 | 3RV1902-1AP0 | |
| 3VU9132-0AA16 | 3RV1902-1AV1 | |
| 3VU9132-0AA23 | 3RV1902-1AF0 | |
| 3VU9132-0AA24 | 3RV1902-1AM1 | |
| 3VU9132-0AA34 | 3RV1922-1CP0 | |
| 3VU9132-0AA36 | 3RV1922-1CV1 | |
| 3VU9132-0AA43 | 3RV1902-1AF0 | |
| 3VU9132-0AA44 | 3RV1902-1AM1 | |
| 3VU9132-0AA50 | 3RV1902-1DB0 | |
| 3VU9132-0AA54 | 3RV1902-1DP0 | |
| 3VU9132-0AA56 | 3RV1902-1DS0 | |
| 3VU9132-0AA63 | 3RV1902-1DF0 | |
| 3VU9132-0AA64 | 3RV1902-1DP0 | |
| 3VU9132-0AB15 | 3RV1902-1AP0 | |
| 3VU9132-0AB17 | 3RV1902-1AV0 | |
| 3VU9132-0AB18 | 3RV1902-1AV1 | |
| 3VU9132-0AB19 | NO DIRECT REPLACEMENT | |
| 3VU9132-0AB23 | 3RV1902-1AF0 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3VU9132-0AB24 | 3RV1902-1AM1 | |
| 3VU9132-0AB26 | 3RV1902-1AP0 | |
| 3VU9132-0AB35 | 3RV1902-1AP0 | |
| 3VU9132-0AB37 | 3RV1902-1AV0 | |
| 3VU9132-0AB38 | 3RV1902-1AV1 | |
| 3VU9132-0AB43 | 3RV1902-1AF0 | |
| 3VU9132-0AB44 | 3RV1902-1AM1 | |
| 3VU9132-0AB46 | 3RV1922-1CV1 | |
| 3VU9132-0AB50 | 3RV1902-1DB0 | |
| 3VU9132-0AB57 | 3RV1902-1DV0 | |
| 3VU9132-0AB58 | 3RV1902-1DS0 | |
| 3VU9132-0AB63 | 3RV1902-1DF0 | |
| 3VU9132-0AB64 | 3RV1902-1DP0 | |
| 3VU9132-0AB66 | 3RV1902-1DP0 | |
| 3VU9132-0AB73 | 3RV1902-1DF0 OR 3RV1902-1DP0 | |
| 3VU9133-0AA00 | 3RV1913-1C | |
| 3VU9133-0CA00 | 3RV1913-1D | |
| 3VU9133-0DA00 | CONTACT SALES OFFICE | |
| 3VU9133-0EA00 | 3RV1913-1D | |
| 3VU9133-0FA00 | 3RV1913-2D | |
| 3VU9133-0MA00 | 3RV1926-0B | |
| 3VU9133-1AA00 | 3RV1913-7D | |
| 3VU9133-1CA00 | 3RV1913-7E | |
| 3VU9133-1KA00 | 3RV1913-6B | |
| 3VU9133-1LA01 | CONTACT SALES OFFICE | |
| 3VU9133-1MC00 | 3RV1926-0B | |
| 3VU9133-1MD00 | 3RV1926-0C | |
| 3VU9133-1PA01 | 3RV1926-0B | |
| 3VU9133-1PA02 | 3RV1926-0C | |
| 3VU9133-2CA00 | 3RV1913-1C | |
| 3VU9133-2DA00 | CONTACT SALES OFFICE | |
| 3VU9133-2EA00 | 3RV1913-1C | |
| 3VU9133-2GA00 | 3RV1913-1D | |
| 3VU9133-2HB00 | 3RV1913-4C | |
| 3VU9133-2JB00 | 3RV1913-4C | |
| 3VU9133-2KB00 | 3RV1913-4C | |
| 3VU9133-2LA00 | CONTACT SALES OFFICE | |
| 3VU9133-2LA01 | CONTACT SALES OFFICE | |
| 3VU9133-2LB00 | 3RV1913-4C | |
| 3VU9133-2MB01 | 3RV1923-4B | |
| 3VU9133-2NB00 | 3RV1923-4B + 3RV1923-4G | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3VU9133-2QA00 | 3RV1923-1C | |
| 3VU9133-2UA00 | 3RV1923-1D | |
| 3VU9133-3AA00 | 3RV1913-7D | |
| 3VU9133-3AA01 | 3RV1913-7D | |
| 3VU9133-3EA00 | 3RV1913-7D | |
| 3VU9133-3KA00 | 3RV1913-6B | |
| 3VU9135-0AA00 | SEE FASTBUS BUS BAR ADAPTERS | |
| 3VU9135-0BA00 | NO DIRECT REPLACEMENT | |
| 3VU9135-0FA00 | SEE FASTBUS BUS BAR ADAPTERS | |
| 3VU9135-1AA00 | 3RV1915-1DB | |
| 3VU9135-1AB02 | 3RV1915-1AB | |
| 3VU9135-1AB03 | 3RV1915-1BB | |
| 3VU9135-1AB04 | 3RV1915-1CB | |
| 3VU9135-1AB05 | 3RV1915-1DB | |
| 3VU9135-1BA00 | 3RV1915-5A | |
| 3VU9135-1BB00 | 3RV1915-5A | |
| 3VU9135-1BB01 | 3RV1915-5A | |
| 3VU9135-1BB03 | 3RV1915-5B | |
| 3VU9135-1CA00 | NO DIRECT REPLACEMENT | |
| 3VU9135-1FA00 | NO DIRECT REPLACEMENT | |
| 3VU9135-1GA00 | 3RV1915-6AB | |
| 3VU9135-1GB00 | 3RV1915-6AB | |
| 3VU9135-1KA02 | 3RV1915-2AB | |
| 3VU9135-1KA04 | 3RV1915-2CB | |
| 3VU9138-0AA00 | 3RB1900-0B | |
| 3VU9138-0BA00 | 3RV1908-0P | |
| 3VU9138-1AA14 | NO DIRECT REPLACEMENT | |
| 3VU9138-2AA00 | NO DIRECT REPLACEMENT | |
| 3VU9138-2AB00 | NO DIRECT REPLACEMENT | |
| 3VU9138-3AA00 | 3RV1928-1A | |
| 3VU9138-3BB00 | NO DIRECT REPLACEMENT | |
| 3VU9161-4AA00 | 3RV1901-1D | |
| 3VU9163-1PA01 | 3RV1926-0B | |
| 3VU9163-1PA02 | 3RV1926-0C | |
| 3VU9163-2BB00 | CONTACT SALES OFFICE | |
| 3VU9165-1AB02 | 3RV1915-1AB | |
| 3VU9165-1AB03 | 3RV1915-1BB | |
| 3VU9165-1BB01 | 3RV1925-5AB | |
| 3VU9165-1GB00 | 3RV1915-6AB | |
| 3VU9168-0KA00 | NO DIRECT REPLACEMENT | |
| 3VUES164 | NO DIRECT REPLACEMENT | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3VUPLHSP | NO DIRECT REPLACEMENT | |
| 3VX1530-0A | SEE SIRIUS 3RV ACCESSORIES | |
| 3VX1540-0B | NO DIRECT REPLACEMENT | |
| 3VX1700-2T | NO DIRECT REPLACEMENT | |
| 3VX1700-2U | NO DIRECT REPLACEMENT | |
| 3VX1700-3A | NO DIRECT REPLACEMENT | |
| 3VX1700-3C | NO DIRECT REPLACEMENT | |
| 3VX3100-1F | NO DIRECT REPLACEMENT | |
| 3VX3100-1X | NO DIRECT REPLACEMENT | |
| 3VX4210-3B | SEE SIRIUS 3RV ACCESSORIES | |
| 3VX4210-3C | NO DIRECT REPLACEMENT | |
| 3VX4210-4B | SEE SIRIUS 3RV ACCESSORIES | |
| 3VX4210-5B | SEE SIRIUS 3RV ACCESSORIES | |
| 3VX4220-3B | NO DIRECT REPLACEMENT | |
| 3VX4220-3C | SEE SIRIUS 3RV ACCESSORIES | |
| 3VX4220-4B | SEE SIRIUS 3RV ACCESSORIES | |
| 3VX4220-5B | SEE SIRIUS 3RV ACCESSORIES | |
| 3VX4230-0A | SEE SIRIUS 3RV ACCESSORIES | |
| 3VX4260-0A | SEE SIRIUS 3RV ACCESSORIES | |
| 3VX4260-0B | SEE SIRIUS 3RV ACCESSORIES | |
| 3VX4260-0D | SEE SIRIUS 3RV ACCESSORIES | |
| 3VX4270-0A | SEE SIRIUS 3RV ACCESSORIES | |
| 3VX4270-0B | SEE SIRIUS 3RV ACCESSORIES | |
| 3VX4270-0C | SEE SIRIUS 3RV ACCESSORIES | |
| 3VX4270-0D | SEE SIRIUS 3RV ACCESSORIES | |
| 3VX4280-0B | NO DIRECT REPLACEMENT | |
| 3VX4280-0J | NO DIRECT REPLACEMENT | |
| 3VX4280-0P | SEE SIRIUS 3RV ACCESSORIES | |
| 3VX4280-0Q | NO DIRECT REPLACEMENT | |
| 3VX4280-0S | SEE PILOT DEVICES | |
| 3VX4280-0V | SEE FASTBUS | |
| 3VX4280-1B | SEE SIRIUS 3RV ACCESSORIES | |
| 3VX4280-1C | SEE SIRIUS 3RV ACCESSORIES | |
| 3VX4280-1E | SEE SIRIUS 3RV ACCESSORIES | |
| 3VX4280-1G | SEE SIRIUS 3RV ACCESSORIES | |
| 3VX4280-1V | SEE FASTBUS | |
| 3VX4280-2R | SEE FASTBUS | |
| 3VX4280-2S | SEE FASTBUS | |
| 3VX5357-3HE00 | SEE SIRIUS 3RV ACCESSORIES | |
| 3VX5857-3TE00 | SEE SIRIUS 3RV ACCESSORIES | |
| 3VX7521-1AB00 | SEE SIRIUS 3RV ACCESSORIES | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3VX7522-0AA08 | SEE SIRIUS 3RV ACCESSORIES | |
| 3VX7522-0AA11 | NO DIRECT REPLACEMENT | |
| 3VX7522-0AA51 | SEE SIRIUS 3RV ACCESSORIES | |
| 3VX7522-0AA70 | SEE SIRIUS 3RV ACCESSORIES | |
| 3VX7524-0AB00 | SEE SIRIUS 3RV ACCESSORIES | |
| 3VX7524-0AC00 | SEE SIRIUS 3RV ACCESSORIES | |
| 3VX7524-0AE00 | SEE SIRIUS 3RV ACCESSORIES | |
| 3VX7524-0AF00 | SEE SIRIUS 3RV ACCESSORIES | |
| 3VX7524-0AH00 | SEE SIRIUS 3RV ACCESSORIES | |
| 3VX7524-1AB00 | SEE SIRIUS 3RV ACCESSORIES | |
| 3VX7524-2AB00 | SEE SIRIUS 3RV ACCESSORIES | |
| 3VX7524-2AE00 | SEE SIRIUS 3RV ACCESSORIES | |
| 3VX7524-2AF00 | SEE SIRIUS 3RV ACCESSORIES | |
| 3VX7524-5AA00 | SEE SIRIUS 3RV ACCESSORIES | |
| 3VX7525-2AA00 | SEE SIRIUS 3RV ACCESSORIES | |
| 3VX7525-3AA00 | NO DIRECT REPLACEMENT | |
| 3VX7527-1AA00 | SEE SIRIUS 3RV ACCESSORIES | |
| 3VX7621-5AB00 | SEE SIRIUS 3RV ACCESSORIES | |
| 3VX7622-0AA08 | NO DIRECT REPLACEMENT | |
| 3VX7622-0AA14 | SEE SIRIUS 3RV ACCESSORIES | |
| 3VX7622-0AA50 | SEE SIRIUS 3RV ACCESSORIES | |
| 3VX7622-0AA70 | SEE SIRIUS 3RV ACCESSORIES | |
| 3VX7624-0AC00 | SEE SIRIUS 3RV ACCESSORIES | |
| 3VX7624-0AE00 | SEE SIRIUS 3RV ACCESSORIES | |
| 3VX7624-0AF00 | SEE SIRIUS 3RV ACCESSORIES | |
| 3VX7624-1AB00 | SEE SIRIUS 3RV ACCESSORIES | |
| 3VX7624-2AE00 | SEE SIRIUS 3RV ACCESSORIES | |
| 3VX7624-2AF00 | SEE SIRIUS 3RV ACCESSORIES | |
| 3VX7625-2AA00 | NO DIRECT REPLACEMENT | |
| 3VX7627-1AA00 | SEE SIRIUS 3RV ACCESSORIES | |
| 3VX7627-4AA00 | NO DIRECT REPLACEMENT | |
| 3VX7715-1CA00 | NO DIRECT REPLACEMENT | |
| 3VX7721-5AA00 | SEE SIRIUS 3RV ACCESSORIES | |
| 3VX7722-0AA04 | SEE SIRIUS 3RV ACCESSORIES | |
| 3VX7722-0AA11 | SEE SIRIUS 3RV ACCESSORIES | |
| 3VX7722-0AA28 | SEE SIRIUS 3RV ACCESSORIES | |
| 3VX7722-0AA30 | SEE SIRIUS 3RV ACCESSORIES | |
| 3VX7722-0AA50 | SEE SIRIUS 3RV ACCESSORIES | |
| 3VX7724-0AE01 | SEE SIRIUS 3RV ACCESSORIES | |
| 3VX7724-0AF01 | SEE SIRIUS 3RV ACCESSORIES | |
| 3VX7724-0BA05 | SEE SIRIUS 3RV ACCESSORIES | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 3VX7724-2AF01 | SEE SIRIUS 3RV ACCESSORIES | |
| 3VX7724-5AA01 | SEE SIRIUS 3RV ACCESSORIES | |
| 3VX7725-2CA00 | NO DIRECT REPLACEMENT | |
| 3VX7725-3AA00 | SEE FASTBUS | |
| 3VX7725-4BA00 | NO DIRECT REPLACEMENT | |
| 3VX7727-1BA00 | NO DIRECT REPLACEMENT | |
| 3VX7727-5AA00 | NO DIRECT REPLACEMENT | |
| 7PU1040-1AB30 | 3RP1020-1AQ30 | |
| 7PU1040-1AE30 | NO DIRECT REPLACEMENT | |
| 7PU1040-1AF30 | NO DIRECT REPLACEMENT | |
| 7PU1040-1AJ20 | 3RP1020-1AQ30 | |
| 7PU1040-1AN20 | 3RP1020-1AP30 | |
| 7PU1040-2AB30 | 3RP1020-1AQ30 | |
| 7PU1040-2AE30 | NO DIRECT REPLACEMENT | |
| 7PU1040-2AF30 | NO DIRECT REPLACEMENT | |
| 7PU1040-2AJ20 | 3RP1020-1AQ30 | |
| 7PU1040-2AN20 | 3RP1020-1AP30 | |
| 7PU1140-0AB30 | 3RP1020-1AQ30 | |
| 7PU1140-0AE30 | NO DIRECT REPLACEMENT | |
| 7PU1140-0AF30 | NO DIRECT REPLACEMENT | |
| 7PU1140-0AJ20 | 3RP1020-1AQ30 | |
| 7PU1140-0AN20 | 3RP1020-1AP30 | |
| 7PU1140-1AB30 | 3RP1020-1AQ30 | |
| 7PU1140-1AE30 | NO DIRECT REPLACEMENT | |
| 7PU1140-1AF30 | NO DIRECT REPLACEMENT | |
| 7PU1140-1AJ20 | 3RP1020-1AQ30 | |
| 7PU1140-1AN20 | 3RP1020-1AP30 | |
| 7PU1140-2AB30 | 3RP1020-1AQ30 | |
| 7PU1140-2AE30 | NO DIRECT REPLACEMENT | |
| 7PU1140-2AF30 | NO DIRECT REPLACEMENT | |
| 7PU1140-2AJ20 | 3RP1020-1AQ30 | |
| 7PU1140-2AN20 | 3RP1020-1AP30 | |
| 7PU1140-31B30 | 3RP1020-1AQ30 | |
| 7PU1140-3AB30 | 3RP1020-1AQ30 | |
| 7PU1140-3AE30 | NO DIRECT REPLACEMENT | |
| 7PU1140-3AF30 | NO DIRECT REPLACEMENT | |
| 7PU1140-3AJ20 | 3RP1020-1AQ30 | |
| 7PU1140-3AN20 | 3RP1020-1AP30 | |
| 7PU1140-4AB30 | 3RP1020-1AQ30 | |
| 7PU1140-4AE30 | NO DIRECT REPLACEMENT | |
| 7PU1140-4AF30 | NO DIRECT REPLACEMENT | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 7PU1140-4AJ20 | 3RP1020-1AQ30 | |
| 7PU1140-4AN20 | 3RP1020-1AP30 | |
| 7PU1140-7AB30 | 3RP1020-1AQ30 | |
| 7PU1140-7AE30 | NO DIRECT REPLACEMENT | |
| 7PU1140-7AEA30 | NO DIRECT REPLACEMENT | |
| 7PU1140-7AF30 | NO DIRECT REPLACEMENT | |
| 7PU1140-7AJ20 | 3RP1020-1AQ30 | |
| 7PU1140-7AN20 | 3RP1020-1AP30 | |
| 7PU1540-0AB30 | 3RP1540-1AB30 | |
| 7PU1540-0AB33 | 3RP1540-1AB30 | |
| 7PU1540-0AC20 | NO DIRECT REPLACEMENT | |
| 7PU1540-0AC23 | NO DIRECT REPLACEMENT | |
| 7PU1540-0AD20 | NO DIRECT REPLACEMENT | |
| 7PU1540-0AD23 | NO DIRECT REPLACEMENT | |
| 7PU1540-0AF20 | NO DIRECT REPLACEMENT | |
| 7PU1540-0AF23 | NO DIRECT REPLACEMENT | |
| 7PU1540-0AG20 | 3RP1540-1AJ30 | |
| 7PU1540-0AG23 | 3RP1540-1AJ30 | |
| 7PU1540-0AK20 | 3RP1540-1AJ30 | |
| 7PU1540-0AK23 | 3RP1540-1AJ30 | |
| 7PU1540-0AM20 | 3RP1540-1AP30 | |
| 7PU1540-0AM23 | 3RP1540-1AP30 | |
| 7PU1540-0AP20 | 3RP1540-1AP30 | |
| 7PU1540-0AP23 | 3RP1540-1AP30 | |
| 7PU1540-1AB30 | 3RP1540-1AB30 | |
| 7PU1540-1AB33 | 3RP1540-1AB30 | |
| 7PU1540-1AC20 | NO DIRECT REPLACEMENT | |
| 7PU1540-1AC23 | NO DIRECT REPLACEMENT | |
| 7PU1540-1AD20 | NO DIRECT REPLACEMENT | |
| 7PU1540-1AD23 | NO DIRECT REPLACEMENT | |
| 7PU1540-1AF20 | NO DIRECT REPLACEMENT | |
| 7PU1540-1AF23 | NO DIRECT REPLACEMENT | |
| 7PU1540-1AG20 | 3RP1540-1AJ30 | |
| 7PU1540-1AG23 | 3RP1540-1AJ30 | |
| 7PU1540-1AK20 | 3RP1540-1AJ30 | |
| 7PU1540-1AK23 | 3RP1540-1AJ30 | |
| 7PU1540-1AM20 | 3RP1540-1AP30 | |
| 7PU1540-1AM23 | 3RP1540-1AP30 | |
| 7PU1540-1AP20 | 3RP1540-1AP30 | |
| 7PU1540-1AP23 | 3RP1540-1AP30 | |
| 7PU1540-8AB30 | 3RP1540-1AB30 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 7PU1540-8AB33 | 3RP1540-1AB30 | |
| 7PU1540-8AC20 | NO DIRECT REPLACEMENT | |
| 7PU1540-8AC23 | NO DIRECT REPLACEMENT | |
| 7PU1540-8AD20 | NO DIRECT REPLACEMENT | |
| 7PU1540-8AD23 | NO DIRECT REPLACEMENT | |
| 7PU1540-8AF20 | NO DIRECT REPLACEMENT | |
| 7PU1540-8AF23 | NO DIRECT REPLACEMENT | |
| 7PU1540-8AG20 | 3RP1540-1AJ30 | |
| 7PU1540-8AG23 | 3RP1540-1AJ30 | |
| 7PU1540-8AK20 | 3RP1540-1AJ30 | |
| 7PU1540-8AK23 | 3RP1540-1AJ30 | |
| 7PU1540-8AM20 | 3RP1540-1AP30 | |
| 7PU1540-8AM23 | 3RP1540-1AP30 | |
| 7PU1540-8AP20 | 3RP1540-1AP30 | |
| 7PU1540-8AP23 | 3RP1540-1AP30 | |
| 7PU1640-0AB30 | 3RP1540-1AB30 | |
| 7PU1640-0AF30 | NO DIRECT REPLACEMENT | |
| 7PU1640-0AJ30 | 3RP1540-1AJ30 | |
| 7PU1640-0AN30 | 3RP1540-1AN30 | |
| 7PU1640-1AB30 | 3RP1540-1AB30 | |
| 7PU1640-1AF30 | NO DIRECT REPLACEMENT | |
| 7PU1640-1AJ30 | 3RP1540-1AJ30 | |
| 7PU1640-1AN30 | 3RP1540-1AN30 | |
| 7PU1640-2AB30 | 3RP1540-1AB30 | |
| 7PU1640-2AF30 | NO DIRECT REPLACEMENT | |
| 7PU1640-2AJ30 | 3RP1540-1AJ30 | |
| 7PU1640-2AN30 | 3RP1540-1AN30 | |
| 7PU1640-7AB30 | 3RP1540-1AB30 | |
| 7PU1640-7AF30 | NO DIRECT REPLACEMENT | |
| 7PU1640-7AJ30 | 3RP1540-1AJ30 | |
| 7PU1640-7AN30 | 3RP1540-1AN30 | |
| 7PU2020-0AB30 | 3RP1525-1BQ30 | |
| 7PU2020-0AE30 | 3RP1525-1BR30 | |
| 7PU2020-0AF30 | 3RP1525-1BR30 | |
| 7PU2020-0AJ20 | 3RP1525-1BQ30 | |
| 7PU2020-0AN20 | 3RP1525-1BW30 | |
| 7PU2020-1AB30 | 3RP1525-1BQ30 | |
| 7PU2020-1AE30 | 3RP1525-1BR30 | |
| 7PU2020-1AF30 | 3RP1525-1BR30 | |
| 7PU2020-1AJ20 | 3RP1525-1BQ30 | |
| 7PU2020-1AN20 | 3RP1525-1BW30 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 7PU2020-2AB30 | 3RP1525-1BQ30 | |
| 7PU2020-2AE30 | 3RP1525-1BR30 | |
| 7PU2020-2AF30 | 3RP1525-1BR30 | |
| 7PU2020-2AJ20 | 3RP1525-1BQ30 | |
| 7PU2020-2AN20 | 3RP1525-1BW30 | |
| 7PU2020-3AB30 | 3RP1525-1BQ30 | |
| 7PU2020-3AE30 | 3RP1525-1BR30 | |
| 7PU2020-3AF30 | 3RP1525-1BR30 | |
| 7PU2020-3AJ20 | 3RP1525-1BQ30 | |
| 7PU2020-3AN20 | 3RP1525-1BW30 | |
| 7PU2020-4AB30 | 3RP1525-1BQ30 | |
| 7PU2020-4AE30 | 3RP1525-1BR30 | |
| 7PU2020-4AF30 | 3RP1525-1BR30 | |
| 7PU2020-4AJ20 | 3RP1525-1BQ30 | |
| 7PU2020-4AN20 | 3RP1525-1BW30 | |
| 7PU2020-5AB30 | 3RP1525-1BQ30 | |
| 7PU2020-7AB30 | 3RP1525-1BQ30 | |
| 7PU2020-7AE30 | 3RP1525-1BR30 | |
| 7PU2020-7AF30 | 3RP1525-1BR30 | |
| 7PU2020-7AJ20 | 3RP1525-1BQ30 | |
| 7PU2020-7AN20 | 3RP1525-1BW30 | |
| 7PU2040-0AB30 | NO DIRECT REPLACEMENT | |
| 7PU2040-0AB33 | NO DIRECT REPLACEMENT | |
| 7PU2040-0AE30 | NO DIRECT REPLACEMENT | |
| 7PU2040-0AE33 | NO DIRECT REPLACEMENT | |
| 7PU2040-0AF30 | NO DIRECT REPLACEMENT | |
| 7PU2040-0AF33 | NO DIRECT REPLACEMENT | |
| 7PU2040-0AJ30 | NO DIRECT REPLACEMENT | |
| 7PU2040-0AJ33 | NO DIRECT REPLACEMENT | |
| 7PU2040-0AN20 | NO DIRECT REPLACEMENT | |
| 7PU2040-0AN23 | NO DIRECT REPLACEMENT | |
| 7PU2040-0AN40 | NO DIRECT REPLACEMENT | |
| 7PU2040-0AN43 | NO DIRECT REPLACEMENT | |
| 7PU2040-0AT20 | NO DIRECT REPLACEMENT | |
| 7PU2040-0AT23 | NO DIRECT REPLACEMENT | |
| 7PU2040-0BB30 | NO DIRECT REPLACEMENT | |
| 7PU2040-0BB33 | NO DIRECT REPLACEMENT | |
| 7PU2040-0BE30 | NO DIRECT REPLACEMENT | |
| 7PU2040-0BE33 | NO DIRECT REPLACEMENT | |
| 7PU2040-0BF30 | NO DIRECT REPLACEMENT | |
| 7PU2040-0BF33 | NO DIRECT REPLACEMENT | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 7PU2040-0BJ30 | NO DIRECT REPLACEMENT | |
| 7PU2040-0BJ33 | NO DIRECT REPLACEMENT | |
| 7PU2040-0BN20 | NO DIRECT REPLACEMENT | |
| 7PU2040-0BN23 | NO DIRECT REPLACEMENT | |
| 7PU2040-0BT20 | NO DIRECT REPLACEMENT | |
| 7PU2040-0BT23 | NO DIRECT REPLACEMENT | |
| 7PU2040-1AB30 | NO DIRECT REPLACEMENT | |
| 7PU2040-1AB33 | NO DIRECT REPLACEMENT | |
| 7PU2040-1AE30 | NO DIRECT REPLACEMENT | |
| 7PU2040-1AE33 | NO DIRECT REPLACEMENT | |
| 7PU2040-1AF30 | NO DIRECT REPLACEMENT | |
| 7PU2040-1AF33 | NO DIRECT REPLACEMENT | |
| 7PU2040-1AJ30 | NO DIRECT REPLACEMENT | |
| 7PU2040-1AJ33 | NO DIRECT REPLACEMENT | |
| 7PU2040-1AN20 | NO DIRECT REPLACEMENT | |
| 7PU2040-1AN23 | NO DIRECT REPLACEMENT | |
| 7PU2040-1AN40 | NO DIRECT REPLACEMENT | |
| 7PU2040-1AN43 | NO DIRECT REPLACEMENT | |
| 7PU2040-1AT20 | NO DIRECT REPLACEMENT | |
| 7PU2040-1AT23 | NO DIRECT REPLACEMENT | |
| 7PU2040-1BB30 | NO DIRECT REPLACEMENT | |
| 7PU2040-1BB33 | NO DIRECT REPLACEMENT | |
| 7PU2040-1BE30 | NO DIRECT REPLACEMENT | |
| 7PU2040-1BE33 | NO DIRECT REPLACEMENT | |
| 7PU2040-1BF30 | NO DIRECT REPLACEMENT | |
| 7PU2040-1BF33 | NO DIRECT REPLACEMENT | |
| 7PU2040-1BJ30 | NO DIRECT REPLACEMENT | |
| 7PU2040-1BJ33 | NO DIRECT REPLACEMENT | |
| 7PU2040-1BN20 | NO DIRECT REPLACEMENT | |
| 7PU2040-1BN23 | NO DIRECT REPLACEMENT | |
| 7PU2040-1BT20 | NO DIRECT REPLACEMENT | |
| 7PU2040-1BT23 | NO DIRECT REPLACEMENT | |
| 7PU2040-2AB30 | NO DIRECT REPLACEMENT | |
| 7PU2040-2AB33 | NO DIRECT REPLACEMENT | |
| 7PU2040-2AE30 | NO DIRECT REPLACEMENT | |
| 7PU2040-2AE33 | NO DIRECT REPLACEMENT | |
| 7PU2040-2AF30 | NO DIRECT REPLACEMENT | |
| 7PU2040-2AF33 | NO DIRECT REPLACEMENT | |
| 7PU2040-2AJ30 | NO DIRECT REPLACEMENT | |
| 7PU2040-2AJ33 | NO DIRECT REPLACEMENT | |
| 7PU2040-2AN20 | NO DIRECT REPLACEMENT | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 7PU2040-2AN23 | NO DIRECT REPLACEMENT | |
| 7PU2040-2AN40 | NO DIRECT REPLACEMENT | |
| 7PU2040-2AN43 | NO DIRECT REPLACEMENT | |
| 7PU2040-2AT20 | NO DIRECT REPLACEMENT | |
| 7PU2040-2AT23 | NO DIRECT REPLACEMENT | |
| 7PU2040-2BB30 | NO DIRECT REPLACEMENT | |
| 7PU2040-2BB33 | NO DIRECT REPLACEMENT | |
| 7PU2040-2BE30 | NO DIRECT REPLACEMENT | |
| 7PU2040-2BE33 | NO DIRECT REPLACEMENT | |
| 7PU2040-2BF30 | NO DIRECT REPLACEMENT | |
| 7PU2040-2BF33 | NO DIRECT REPLACEMENT | |
| 7PU2040-2BJ30 | NO DIRECT REPLACEMENT | |
| 7PU2040-2BJ33 | NO DIRECT REPLACEMENT | |
| 7PU2040-2BN20 | NO DIRECT REPLACEMENT | |
| 7PU2040-2BN23 | NO DIRECT REPLACEMENT | |
| 7PU2040-2BT20 | NO DIRECT REPLACEMENT | |
| 7PU2040-2BT23 | NO DIRECT REPLACEMENT | |
| 7PU2040-3AB30 | NO DIRECT REPLACEMENT | |
| 7PU2040-3AB33 | NO DIRECT REPLACEMENT | |
| 7PU2040-3AE30 | NO DIRECT REPLACEMENT | |
| 7PU2040-3AE33 | NO DIRECT REPLACEMENT | |
| 7PU2040-3AF30 | NO DIRECT REPLACEMENT | |
| 7PU2040-3AF33 | NO DIRECT REPLACEMENT | |
| 7PU2040-3AJ30 | NO DIRECT REPLACEMENT | |
| 7PU2040-3AJ33 | NO DIRECT REPLACEMENT | |
| 7PU2040-3AN20 | NO DIRECT REPLACEMENT | |
| 7PU2040-3AN23 | NO DIRECT REPLACEMENT | |
| 7PU2040-3AN40 | NO DIRECT REPLACEMENT | |
| 7PU2040-3AN43 | NO DIRECT REPLACEMENT | |
| 7PU2040-3AT20 | NO DIRECT REPLACEMENT | |
| 7PU2040-3AT23 | NO DIRECT REPLACEMENT | |
| 7PU2040-3BB30 | NO DIRECT REPLACEMENT | |
| 7PU2040-3BB33 | NO DIRECT REPLACEMENT | |
| 7PU2040-3BE30 | NO DIRECT REPLACEMENT | |
| 7PU2040-3BE33 | NO DIRECT REPLACEMENT | |
| 7PU2040-3BF30 | NO DIRECT REPLACEMENT | |
| 7PU2040-3BF33 | NO DIRECT REPLACEMENT | |
| 7PU2040-3BJ30 | NO DIRECT REPLACEMENT | |
| 7PU2040-3BJ33 | NO DIRECT REPLACEMENT | |
| 7PU2040-3BN20 | NO DIRECT REPLACEMENT | |
| 7PU2040-3BN23 | NO DIRECT REPLACEMENT | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 7PU2040-3BT20 | NO DIRECT REPLACEMENT | |
| 7PU2040-3BT23 | NO DIRECT REPLACEMENT | |
| 7PU2040-4AB30 | NO DIRECT REPLACEMENT | |
| 7PU2040-4AB33 | NO DIRECT REPLACEMENT | |
| 7PU2040-4AE30 | NO DIRECT REPLACEMENT | |
| 7PU2040-4AE33 | NO DIRECT REPLACEMENT | |
| 7PU2040-4AF30 | NO DIRECT REPLACEMENT | |
| 7PU2040-4AF33 | NO DIRECT REPLACEMENT | |
| 7PU2040-4AJ30 | NO DIRECT REPLACEMENT | |
| 7PU2040-4AJ33 | NO DIRECT REPLACEMENT | |
| 7PU2040-4AN20 | NO DIRECT REPLACEMENT | |
| 7PU2040-4AN23 | NO DIRECT REPLACEMENT | |
| 7PU2040-4AN40 | NO DIRECT REPLACEMENT | |
| 7PU2040-4AN43 | NO DIRECT REPLACEMENT | |
| 7PU2040-4AT20 | NO DIRECT REPLACEMENT | |
| 7PU2040-4AT23 | NO DIRECT REPLACEMENT | |
| 7PU2040-4BB30 | NO DIRECT REPLACEMENT | |
| 7PU2040-4BB33 | NO DIRECT REPLACEMENT | |
| 7PU2040-4BE30 | NO DIRECT REPLACEMENT | |
| 7PU2040-4BE33 | NO DIRECT REPLACEMENT | |
| 7PU2040-4BF30 | NO DIRECT REPLACEMENT | |
| 7PU2040-4BF33 | NO DIRECT REPLACEMENT | |
| 7PU2040-4BJ30 | NO DIRECT REPLACEMENT | |
| 7PU2040-4BJ33 | NO DIRECT REPLACEMENT | |
| 7PU2040-4BN20 | NO DIRECT REPLACEMENT | |
| 7PU2040-4BN23 | NO DIRECT REPLACEMENT | |
| 7PU2040-4BT20 | NO DIRECT REPLACEMENT | |
| 7PU2040-4BT23 | NO DIRECT REPLACEMENT | |
| 7PU2040-7AB30 | NO DIRECT REPLACEMENT | |
| 7PU2040-7AB33 | NO DIRECT REPLACEMENT | |
| 7PU2040-7AE30 | NO DIRECT REPLACEMENT | |
| 7PU2040-7AE33 | NO DIRECT REPLACEMENT | |
| 7PU2040-7AF30 | NO DIRECT REPLACEMENT | |
| 7PU2040-7AF33 | NO DIRECT REPLACEMENT | |
| 7PU2040-7AJ30 | NO DIRECT REPLACEMENT | |
| 7PU2040-7AJ33 | NO DIRECT REPLACEMENT | |
| 7PU2040-7AN23 | NO DIRECT REPLACEMENT | |
| 7PU2040-7AN40 | NO DIRECT REPLACEMENT | |
| 7PU2040-7AN43 | NO DIRECT REPLACEMENT | |
| 7PU2040-7AT20 | NO DIRECT REPLACEMENT | |
| 7PU2040-7AT23 | NO DIRECT REPLACEMENT | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 7PU2040-7BB30 | NO DIRECT REPLACEMENT | |
| 7PU2040-7BB33 | NO DIRECT REPLACEMENT | |
| 7PU2040-7BE30 | NO DIRECT REPLACEMENT | |
| 7PU2040-7BE33 | NO DIRECT REPLACEMENT | |
| 7PU2040-7BF30 | NO DIRECT REPLACEMENT | |
| 7PU2040-7BF33 | NO DIRECT REPLACEMENT | |
| 7PU2040-7BJ30 | NO DIRECT REPLACEMENT | |
| 7PU2040-7BJ33 | NO DIRECT REPLACEMENT | |
| 7PU2040-7BN20 | NO DIRECT REPLACEMENT | |
| 7PU2040-7BN23 | NO DIRECT REPLACEMENT | |
| 7PU2040-7BT20 | NO DIRECT REPLACEMENT | |
| 7PU2040-7BT23 | NO DIRECT REPLACEMENT | |
| 7PU2040-7QJ20 | NO DIRECT REPLACEMENT | |
| 7PU2220-1AN20 | 3RP1525-1AW30 | |
| 7PU2220-2AN20 | 3RP1525-1AW30 | |
| 7PU2240-0BE30 | 3RP1525-1BR30 | |
| 7PU2240-3QB30 | 3RP1525-1BQ30 | |
| 7PU2240-4BJ30 | 3RP1525-1BQ30 | |
| 7PU2520-1AJ20 | 3RP1505-1AQ30 | |
| 7PU2520-3AJ20 | 3RP1505-1AQ30 | |
| 7PU2540-0AB30 | 3RP1505-1AQ30 | |
| 7PU2540-0AB33 | 3RP1505-1AQ30 | |
| 7PU2540-0AE30 | 3RP1505-1AW30 | |
| 7PU2540-0AF30 | 3RP1505-1AW30 | |
| 7PU2540-0AJ20 | 3RP1505-1AQ30 | |
| 7PU2540-0AJ40 | 3RP1505-1AW30 | |
| 7PU2540-0AN20 | 3RP1505-1AP30 | |
| 7PU2540-0AN40 | 3RP1505-1AW30 | |
| 7PU2540-0BB30 | 3RP1505-1AQ30 | |
| 7PU2540-0BE30 | 3RP1505-1AW30 | |
| 7PU2540-0BF30 | 3RP1505-1AW30 | |
| 7PU2540-0BJ20 | 3RP1505-1AQ30 | |
| 7PU2540-0BN20 | 3RP1505-1AP30 | |
| 7PU2540-1AB30 | 3RP1505-1AQ30 | |
| 7PU2540-1AB33 | 3RP1505-1AQ30 | |
| 7PU2540-1AE30 | 3RP1505-1AW30 | |
| 7PU2540-1AF30 | 3RP1505-1AW30 | |
| 7PU2540-1AJ20 | 3RP1505-1AQ30 | |
| 7PU2540-1AJ23 | 3RP1505-1AQ30 | |
| 7PU2540-1AJ40 | 3RP1505-1AW30 | |
| 7PU2540-1AN20 | 3RP1505-1AP30 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 7PU2540-1AN40 | 3RP1505-1AW30 | |
| 7PU2540-1BB30 | 3RP1505-1AQ30 | |
| 7PU2540-1BE30 | 3RP1505-1AW30 | |
| 7PU2540-1BF30 | 3RP1505-1AW30 | |
| 7PU2540-1BJ20 | 3RP1505-1AQ30 | |
| 7PU2540-1BN20 | 3RP1505-1AP30 | |
| 7PU2540-1BN40 | 3RP1505-1AW30 | |
| 7PU2540-2AB30 | 3RP1505-1AQ30 | |
| 7PU2540-2AE30 | 3RP1505-1AW30 | |
| 7PU2540-2AF30 | 3RP1505-1AW30 | |
| 7PU2540-2AJ20 | 3RP1505-1AQ30 | |
| 7PU2540-2AJ23 | 3RP1505-1AQ30 | |
| 7PU2540-2AJ40 | 3RP1505-1AW30 | |
| 7PU2540-2AN20 | 3RP1505-1AP30 | |
| 7PU2540-2AN40 | 3RP1505-1AW30 | |
| 7PU2540-2BB30 | 3RP1505-1AQ30 | |
| 7PU2540-2BE30 | 3RP1505-1AW30 | |
| 7PU2540-2BF30 | 3RP1505-1AW30 | |
| 7PU2540-2BJ20 | 3RP1505-1AQ30 | |
| 7PU2540-2BN20 | 3RP1505-1AP30 | |
| 7PU2540-3A720 | NO DIRECT REPLACEMENT | |
| 7PU2540-3AB30 | 3RP1505-1AQ30 | |
| 7PU2540-3AE30 | 3RP1505-1AW30 | |
| 7PU2540-3AF30 | 3RP1505-1AW30 | |
| 7PU2540-3AJ20 | 3RP1505-1AQ30 | |
| 7PU2540-3AJ23 | 3RP1505-1AQ30 | |
| 7PU2540-3AJ40 | 3RP1505-1AW30 | |
| 7PU2540-3AN23 | 3RP1505-1AP30 | |
| 7PU2540-3AN40 | 3RP1505-1AW30 | |
| 7PU2540-3BB30 | 3RP1505-1AQ30 | |
| 7PU2540-3BE30 | 3RP1505-1AW30 | |
| 7PU2540-3BF30 | 3RP1505-1AW30 | |
| 7PU2540-3BJ20 | 3RP1505-1AQ30 | |
| 7PU2540-3BN20 | 3RP1505-1AP30 | |
| 7PU2540-4AB30 | 3RP1505-1AQ30 | |
| 7PU2540-4AB33 | 3RP1505-1AQ30 | |
| 7PU2540-4AE30 | 3RP1505-1AW30 | |
| 7PU2540-4AF30 | 3RP1505-1AW30 | |
| 7PU2540-4AJ20 | 3RP1505-1AQ30 | |
| 7PU2540-4AJ23 | 3RP1505-1AQ30 | |
| 7PU2540-4AJ40 | 3RP1505-1AW30 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 7PU2540-4AN20 | 3RP1505-1AP30 | |
| 7PU2540-4AN23 | 3RP1505-1AP30 | |
| 7PU2540-4AN40 | 3RP1505-1AW30 | |
| 7PU2540-4BB30 | 3RP1505-1AQ30 | |
| 7PU2540-4BE30 | 3RP1505-1AW30 | |
| 7PU2540-4BF30 | 3RP1505-1AW30 | |
| 7PU2540-4BJ20 | 3RP1505-1AQ30 | |
| 7PU2540-4BN20 | 3RP1505-1AP30 | |
| 7PU2540-7AB30 | 3RP1505-1AQ30 | |
| 7PU2540-7AE30 | 3RP1505-1AW30 | |
| 7PU2540-7AF30 | 3RP1505-1AW30 | |
| 7PU2540-7AJ20 | 3RP1505-1AQ30 | |
| 7PU2540-7AJ40 | 3RP1505-1AW30 | |
| 7PU2540-7AN20 | 3RP1505-1AP30 | |
| 7PU2540-7AN23 | 3RP1505-1AP30 | |
| 7PU2540-7AN43 | 3RP1505-1AW30 | |
| 7PU2540-7BB30 | 3RP1505-1AQ30 | |
| 7PU2540-7BE30 | 3RP1505-1AW30 | |
| 7PU2540-7BF30 | 3RP1505-1AW30 | |
| 7PU2540-7BJ20 | 3RP1505-1AQ30 | |
| 7PU2540-7BN20 | 3RP1505-1AP30 | |
| 7PU2540-7BN40 | 3RP1505-1AW30 | |
| 7PU2640-0AB30 | 3RP1505-1AQ30 | |
| 7PU2640-0AE30 | 3RP1505-1AW30 | |
| 7PU2640-0AF30 | 3RP1505-1AW30 | |
| 7PU2640-0AJ20 | 3RP1505-1AQ30 | |
| 7PU2640-0AN20 | 3RP1505-1AP30 | |
| 7PU2640-1AB30 | 3RP1505-1AQ30 | |
| 7PU2640-1AE30 | 3RP1505-1AW30 | |
| 7PU2640-1AF30 | 3RP1505-1AW30 | |
| 7PU2640-1AJ20 | 3RP1505-1AQ30 | |
| 7PU2640-1AN20 | 3RP1505-1AP30 | |
| 7PU2640-2AB30 | 3RP1505-1AQ30 | |
| 7PU2640-2AE30 | 3RP1505-1AW30 | |
| 7PU2640-2AF30 | 3RP1505-1AW30 | |
| 7PU2640-2AJ20 | 3RP1505-1AQ30 | |
| 7PU2640-2AN20 | 3RP1505-1AP30 | |
| 7PU2640-3AB30 | 3RP1505-1AQ30 | |
| 7PU2640-3AE30 | 3RP1505-1AW30 | |
| 7PU2640-3AF30 | 3RP1505-1AW30 | |
| 7PU2640-3AJ20 | 3RP1505-1AQ30 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 7PU2640-3AN20 | 3RP1505-1AP30 | |
| 7PU2640-4AB30 | 3RP1505-1AQ30 | |
| 7PU2640-4AE30 | 3RP1505-1AW30 | |
| 7PU2640-4AF30 | 3RP1505-1AW30 | |
| 7PU2640-4AJ20 | 3RP1505-1AQ30 | |
| 7PU2640-4AN20 | 3RP1505-1AP30 | |
| 7PU2640-7AB30 | 3RP1505-1AQ30 | |
| 7PU2640-7AE30 | 3RP1505-1AW30 | |
| 7PU2640-7AF30 | 3RP1505-1AW30 | |
| 7PU2640-7AJ20 | 3RP1505-1AQ30 | |
| 7PU2640-7AN20 | 3RP1505-1AP30 | |
| 7PU3040-33J20 | 3RP1525-1AQ30 | |
| 7PU3040-3AB30 | 3RP1525-1AQ30 | |
| 7PU3040-3AB34 | 3RP1525-1AQ30 | |
| 7PU3040-3AE30 | 3RP1525-1BW30 | |
| 7PU3040-3AE34 | 3RP1525-1BW30 | |
| 7PU3040-3AF30 | 3RP1525-1BW30 | |
| 7PU3040-3AF34 | 3RP1525-1BW30 | |
| 7PU3040-3AJ20 | 3RP1525-1AQ30 | |
| 7PU3040-3AJ24 | 3RP1525-1AQ30 | |
| 7PU3040-3AJ44 | 3RP1525-1BW30 | |
| 7PU3040-3AN20 | 3RP1525-1AP30 | |
| 7PU3040-3AN24 | 3RP1525-1AP30 | |
| 7PU3040-3AN40 | 3RP1525-1BW30 | |
| 7PU3040-3AN44 | 3RP1525-1BW30 | |
| 7PU3040-3BB30 | 3RP1525-1AQ30 | |
| 7PU3040-3BB34 | 3RP1525-1AQ30 | |
| 7PU3040-3BE30 | 3RP1525-1BW30 | |
| 7PU3040-3BE34 | 3RP1525-1BW30 | |
| 7PU3040-3BF30 | 3RP1525-1BW30 | |
| 7PU3040-3BF34 | 3RP1525-1BW30 | |
| 7PU3040-3BJ20 | 3RP1525-1AQ30 | |
| 7PU3040-3BJ24 | 3RP1525-1AQ30 | |
| 7PU3040-3BN20 | 3RP1525-1AP30 | |
| 7PU3040-3BN24 | 3RP1525-1AP30 | |
| 7PU3040-3FB30 | 3RP1525-1AQ30 | |
| 7PU3040-3FB34 | 3RP1525-1AQ30 | |
| 7PU3040-3FE30 | 3RP1525-1BW30 | |
| 7PU3040-3FE34 | 3RP1525-1BW30 | |
| 7PU3040-3FF30 | 3RP1525-1BW30 | |
| 7PU3040-3FF34 | 3RP1525-1BW30 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 7PU3040-3FJ20 | 3RP1525-1AQ30 | |
| 7PU3040-3FJ24 | 3RP1525-1AQ30 | |
| 7PU3040-3FN20 | 3RP1525-1AP30 | |
| 7PU3040-3FN24 | 3RP1525-1AP30 | |
| 7PU3120-3AJ20 | SEE 3RP15**-***** | |
| 7PU3120-3AN20 | SEE 3RP15**-***** | |
| 7PU3120-3BB30 | SEE 3RP15**-***** | |
| 7PU3120-3BJ20 | SEE 3RP15**-***** | |
| 7PU3140-2BB34 | SEE 3RP15**-***** | |
| 7PU3140-2BJ34 | SEE 3RP15**-***** | |
| 7PU3140-2BN24 | SEE 3RP15**-***** | |
| 7PU3140-3AB30 | SEE 3RP15**-***** | |
| 7PU3140-3AB34 | SEE 3RP15**-***** | |
| 7PU3140-3AE30 | SEE 3RP15**-***** | |
| 7PU3140-3AE34 | SEE 3RP15**-***** | |
| 7PU3140-3AF30 | SEE 3RP15**-***** | |
| 7PU3140-3AF34 | SEE 3RP15**-***** | |
| 7PU3140-3AJ20 | SEE 3RP15**-***** | |
| 7PU3140-3AJ24 | SEE 3RP15**-***** | |
| 7PU3140-3AJ30 | SEE 3RP15**-***** | |
| 7PU3140-3AJ44 | SEE 3RP15**-***** | |
| 7PU3140-3AN20 | SEE 3RP15**-***** | |
| 7PU3140-3AN24 | SEE 3RP15**-***** | |
| 7PU3140-3AN40 | SEE 3RP15**-***** | |
| 7PU3140-3AN44 | SEE 3RP15**-***** | |
| 7PU3140-3BB30 | SEE 3RP15**-***** | |
| 7PU3140-3BB34 | SEE 3RP15**-***** | |
| 7PU3140-3BE30 | SEE 3RP15**-***** | |
| 7PU3140-3BE34 | SEE 3RP15**-***** | |
| 7PU3140-3BF30 | SEE 3RP15**-***** | |
| 7PU3140-3BF34 | SEE 3RP15**-***** | |
| 7PU3140-3BJ20 | SEE 3RP15**-***** | |
| 7PU3140-3BJ24 | SEE 3RP15**-***** | |
| 7PU3140-3BN20 | SEE 3RP15**-***** | |
| 7PU3140-3BN24 | SEE 3RP15**-***** | |
| 7PU3140-3FB24 | SEE 3RP15**-***** | |
| 7PU3140-3FB30 | SEE 3RP15**-***** | |
| 7PU3140-3FB34 | SEE 3RP15**-***** | |
| 7PU3140-3FE30 | SEE 3RP15**-***** | |
| 7PU3140-3FE34 | SEE 3RP15**-***** | |
| 7PU3140-3FF30 | SEE 3RP15**-***** | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 7PU3140-3FF34 | SEE 3RP15**-***** | |
| 7PU3140-3FJ20 | SEE 3RP15**-***** | |
| 7PU3140-3FJ24 | SEE 3RP15**-***** | |
| 7PU3140-3FN20 | SEE 3RP15**-***** | |
| 7PU3140-3FN24 | SEE 3RP15**-***** | |
| 7PU3240-0AB30 | 3RP1505-1AQ30 | |
| 7PU3240-0AE30 | 3RP1505-1AW30 | |
| 7PU3240-0AF30 | 3RP1505-1AW30 | |
| 7PU3240-0AJ20 | 3RP1505-1AQ30 | |
| 7PU3240-0AN20 | 3RP1505-1AP30 | |
| 7PU3320-2BC40 | NO DIRECT REPLACEMENT | |
| 7PU3320-2BC40-Z | NO DIRECT REPLACEMENT | |
| 7PU3320-2BJ20 | 3RP1505-1BQ30 | |
| 7PU3340-2BJ34 | 3RP1505-1BQ30 | |
| 7PU3340-2BN24 | 3RP1505-1BP30 | |
| 7PU3910-0A | NO DIRECT REPLACEMENT | |
| 7PU3910-1A | NO DIRECT REPLACEMENT | |
| 7PU3910-2A | NO DIRECT REPLACEMENT | |
| 7PU3910-3A | NO DIRECT REPLACEMENT | |
| 7PU3911-0A | NO DIRECT REPLACEMENT | |
| 7PU3911-1A | NO DIRECT REPLACEMENT | |
| 7PU3911-2A | NO DIRECT REPLACEMENT | |
| 7PU3911-3A | NO DIRECT REPLACEMENT | |
| 7PU3913-1A | NO DIRECT REPLACEMENT | |
| 7PU3914-0A | NO DIRECT REPLACEMENT | |
| 7PU3914-1A | NO DIRECT REPLACEMENT | |
| 7PU3914-2A | NO DIRECT REPLACEMENT | |
| 7PU3914-3A | NO DIRECT REPLACEMENT | |
| 7PU3915-1A | NO DIRECT REPLACEMENT | |
| 7PU3918-8A | NO DIRECT REPLACEMENT | |
| 7PU4020 | NO DIRECT REPLACEMENT | |
| 7PU4020-0AB30 | 3RP1525-1AQ30 | |
| 7PU4020-0AJ20 | 3RP1525-1AQ30 | |
| 7PU4020-0AN20 | 3RP1525-1AP30 | |
| 7PU4020-0BB30 | 3RP1525-1BQ30 | |
| 7PU4020-0BJ20 | 3RP1525-1BQ30 | |
| 7PU4020-1AB30 | 3RP1525-1AQ30 | |
| 7PU4020-1AJ20 | 3RP1525-1AQ30 | |
| 7PU4020-1AN20 | 3RP1525-1AP30 | |
| 7PU4020-1AZ90-K03 | NO DIRECT REPLACEMENT | |
| 7PU4020-1AZ90-K0J | NO DIRECT REPLACEMENT | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 7PU4020-1BB30 | 3RP1525-1BQ30 | |
| 7PU4020-1BJ20 | 3RP1525-1BQ30 | |
| 7PU4020-2AB30 | 3RP1525-1AQ30 | |
| 7PU4020-2AJ20 | 3RP1525-1AQ30 | |
| 7PU4020-2AN20 | 3RP1525-1AP30 | |
| 7PU4020-3AB30 | 3RP1525-1AQ30 | |
| 7PU4020-3AJ20 | 3RP1525-1AQ30 | |
| 7PU4020-3AN20 | 3RP1525-1AP30 | |
| 7PU4020-3BB30 | 3RP1525-1BQ30 | |
| 7PU4020-3BJ20 | 3RP1525-1BQ30 | |
| 7PU4020-4AB30 | 3RP1525-1AQ30 | |
| 7PU4020-4AJ20 | 3RP1525-1AQ30 | |
| 7PU4020-4AN20 | 3RP1525-1AP30 | |
| 7PU4020-4AZ90-K03 | NO DIRECT REPLACEMENT | |
| 7PU4020-4AZ90-K0J | NO DIRECT REPLACEMENT | |
| 7PU4020-5AB30 | 3RP1525-1AQ30 | |
| 7PU4020-5AJ20 | 3RP1525-1AQ30 | |
| 7PU4020-5AN20 | 3RP1525-1AP30 | |
| 7PU4040-0AJ30 | 3RP1525-1AQ30 | |
| 7PU4040-0AN20 | 3RP1525-1AP30 | |
| 7PU4040-0BB30 | 3RP1525-1BQ30 | |
| 7PU4040-0BB33 | 3RP1525-1BQ30 | |
| 7PU4040-0BN20 | 3RP1525-1BP30 | |
| 7PU4040-1AB30 | 3RP1525-1AQ30 | |
| 7PU4040-1AJ30 | 3RP1525-1AQ30 | |
| 7PU4040-1AN20 | 3RP1525-1AP30 | |
| 7PU4040-1BB30 | 3RP1525-1BQ30 | |
| 7PU4040-1BJ30 | 3RP1525-1BQ30 | |
| 7PU4040-2AB30 | 3RP1525-1AQ30 | |
| 7PU4040-2AJ30 | 3RP1525-1AQ30 | |
| 7PU4040-2AN20 | 3RP1525-1AP30 | |
| 7PU4040-2BB30 | 3RP1525-1BQ30 | |
| 7PU4040-2BJ30 | 3RP1525-1BQ30 | |
| 7PU4040-3AB30 | 3RP1525-1AQ30 | |
| 7PU4040-3AJ30 | 3RP1525-1AQ30 | |
| 7PU4040-3BB30 | 3RP1525-1BQ30 | |
| 7PU4040-3BJ30 | 3RP1525-1BQ30 | |
| 7PU4040-4AN20 | 3RP1525-1AP30 | |
| 7PU4040-4BB30 | 3RP1525-1BQ30 | |
| 7PU4040-4BJ30 | 3RP1525-1BQ30 | |
| 7PU4040-4BN20 | 3RP1525-1BP30 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 7PU4040-5AJ30 | 3RP1525-1AQ30 | |
| 7PU4120-2AF30 | 3RP1525-1AW30 | |
| 7PU4120-2AF30-Z | NO DIRECT REPLACEMENT | |
| 7PU4120-2AJ20 | 3RP1525-1AQ30 | |
| 7PU4120-2AN20 | 3RP1525-1AP30 | |
| 7PU4120-2BJ20 | 3RP1525-1BQ30 | |
| 7PU4120-2BJ30 | 3RP1525-1BQ30 | |
| 7PU4140-2BB30 | 3RP1525-1BQ30 | |
| 7PU4140-2BE30 | 3RP1525-1BW30 | |
| 7PU4140-2BF30 | 3RP1525-1BW30 | |
| 7PU4140-2BJ30 | 3RP1525-1BQ30 | |
| 7PU4140-2BN20 | 3RP1525-1BP30 | |
| 7PU4140-2BN40 | 3RP1525-1BW30 | |
| 7PU4140-2BT20 | 3RP1525-1BW30 | |
| 7PU4140-2QJ20 | 3RP1525-1BQ30 | |
| 7PU4140-2QN20 | 3RP1525-1BP30 | |
| 7PU4220-2BF30 | 3RP1505-1BW30 | |
| 7PU4220-2BF30-Z | NO DIRECT REPLACEMENT | |
| 7PU4220-2BJ20 | 3RP1505-1BQ30 | |
| 7PU4220-2BN20 | 3RP1505-1BP30 | |
| 7PU4320-0BJ20 | 3RP1505-1BQ30 | |
| 7PU4320-2AJ20 | 3RP1505-1AQ30 | |
| 7PU4320-2AN20 | 3RP1505-1AP30 | |
| 7PU4320-2BF30-Z | NO DIRECT REPLACEMENT | |
| 7PU4320-2BF40-Z | NO DIRECT REPLACEMENT | |
| 7PU4320-2BJ20 | 3RP1505-1BQ30 | |
| 7PU4320-2BN20 | 3RP1505-1BP30 | |
| 7PU4340-2AJ30 | 3RP1505-1BW30 | |
| 7PU4440-0AB30 | 3RP1505-1AQ30 | |
| 7PU4440-0AJ30 | 3RP1505-1AW30 | |
| 7PU4440-1AJ30 | 3RP1505-1AW30 | |
| 7PU4440-2AJ30 | 3RP1505-1AW30 | |
| 7PU4440-2BB30 | 3RP1505-1BQ30 | |
| 7PU4440-2BE30 | 3RP1505-1BW30 | |
| 7PU4440-2BF30 | 3RP1505-1BW30 | |
| 7PU4440-2BJ30 | 3RP1505-1BW30 | |
| 7PU4440-2BN20 | 3RP1505-1BP30 | |
| 7PU4440-2BN40 | 3RP1505-1BW30 | |
| 7PU4440-2BT20 | NO DIRECT REPLACEMENT | |
| 7PU4440-3AJ30 | 3RP1505-1AW30 | |
| 7PU4440-3AN20 | 3RP1505-1AP30 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 7PU4440-4AB30 | 3RP1505-1AQ30 | |
| 7PU4440-4AJ30 | 3RP1505-1AW30 | |
| 7PU4440-8RB30 | 3RP1505-1BQ30 | |
| 7PU4520-2AB30 | 3RP1540-1BQ30 | |
| 7PU4520-2AJ30 | 3RP1540-1BJ30 | |
| 7PU4520-2AN30 | 3RP1540-1BN30 | |
| 7PU4520-2BJ30 | 3RP1540-1BJ30 | |
| 7PU4520-2BZ90-K9Y | NO DIRECT REPLACEMENT | |
| 7PU4540-2BB30 | 3RP1540-1BQ30 | |
| 7PU4540-2BJ30 | 3RP1540-1BJ30 | |
| 7PU4540-2BN30 | 3RP1540-1BN30 | |
| 7PU4620-0BJ20 | 3RP1505-1RW30 | |
| 7PU4620-0BN20 | 3RP1505-1RW30 | |
| 7PU4620-2AF30 | 3RP1505-1RW30 | |
| 7PU4620-2AJ20 | 3RP1505-1RW30 | |
| 7PU4620-2AN20 | 3RP1505-1RW30 | |
| 7PU4620-2AZ90-K03 | NO DIRECT REPLACEMENT | |
| 7PU4620-2AZ90-K0J | NO DIRECT REPLACEMENT | |
| 7PU4620-2AZ90-K0M | NO DIRECT REPLACEMENT | |
| 7PU4620-2BF30-Z | NO DIRECT REPLACEMENT | |
| 7PU4620-2BJ20 | 3RP1505-1RW30 | |
| 7PU4620-2BN20 | 3RP1505-1RW30 | |
| 7PU4640-0RJ20 | 3RP1505-1RW30 | |
| 7PU4720-0AJ20 | 3RP1555-1AQ30 | |
| 7PU4720-1AB30 | 3RP1555-1AP30 | |
| 7PU4720-1AJ20 | 3RP1555-1AQ30 | |
| 7PU5020-0AB30 | 3RP1505-1AQ30 | |
| 7PU5020-0AE30 | 3RP1505-1AW30 | |
| 7PU5020-0AF30 | 3RP1505-1AW30 | |
| 7PU5020-0AN20 | 3RP1505-1AP30 | |
| 7PU5020-1AB30 | 3RP1505-1AQ30 | |
| 7PU5020-1AE30 | 3RP1505-1AW30 | |
| 7PU5020-1AF30 | 3RP1505-1AW30 | |
| 7PU5020-1AJ20 | 3RP1505-1AQ30 | |
| 7PU5020-1AN20 | 3RP1505-1AP30 | |
| 7PU5020-2AB30 | 3RP1505-1AQ30 | |
| 7PU5020-2AE30 | 3RP1505-1AW30 | |
| 7PU5020-2AF30 | 3RP1505-1AW30 | |
| 7PU5020-2AJ20 | 3RP1505-1AQ30 | |
| 7PU5020-2AN20 | 3RP1505-1AP30 | |
| 7PU5020-3AB30 | 3RP1505-1AQ30 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 7PU5020-3AE30 | 3RP1505-1AW30 | |
| 7PU5020-3AF30 | 3RP1505-1AW30 | |
| 7PU5020-3AJ20 | 3RP1505-1AQ30 | |
| 7PU5020-3AN20 | 3RP1505-1AP30 | |
| 7PU5020-4AB30 | 3RP1505-1AQ30 | |
| 7PU5020-4AE30 | 3RP1505-1AW30 | |
| 7PU5020-4AF30 | 3RP1505-1AW30 | |
| 7PU5020-4AJ20 | 3RP1505-1AQ30 | |
| 7PU5020-4AN20 | 3RP1505-1AP30 | |
| 7PU5020-5AB30 | 3RP1505-1AQ30 | |
| 7PU5020-5AE30 | 3RP1505-1AW30 | |
| 7PU5020-5AF30 | 3RP1505-1AW30 | |
| 7PU5020-5AJ20 | 3RP1505-1AQ30 | |
| 7PU5020-5AN20 | 3RP1505-1AP30 | |
| 7PU5020-6AB30 | 3RP1505-1AQ30 | |
| 7PU5020-6AE30 | 3RP1505-1AW30 | |
| 7PU5020-6AF30 | 3RP1505-1AW30 | |
| 7PU5020-6AJ20 | 3RP1505-1AQ30 | |
| 7PU5020-6AN20 | 3RP1505-1AP30 | |
| 7PU5020-7AB30 | 3RP1505-1AQ30 | |
| 7PU5020-7AE30 | 3RP1505-1AW30 | |
| 7PU5020-7AF30 | 3RP1505-1AW30 | |
| 7PU5020-7AJ20 | 3RP1505-1AQ30 | |
| 7PU5020-7AN20 | 3RP1505-1AP30 | |
| 7PU5120-6CB30 | 3RP1555-1AQ30 | |
| 7PU5120-6CJ20 | 3RP1555-1AQ30 | |
| 7PU5120-6CN20 | 3RP1555-1AP30 | |
| 7PU5220-0AB30 | 3RP1555-1AQ30 | |
| 7PU5220-0AE30 | 3RP1555-1AR30 | |
| 7PU5220-0AF30 | 3RP1555-1AR30 | |
| 7PU5220-0AJ20 | 3RP1555-1AQ30 | |
| 7PU5220-0AN20 | 3RP1555-1AP30 | |
| 7PU5220-1AB30 | 3RP1555-1AQ30 | |
| 7PU5220-1AE30 | 3RP1555-1AR30 | |
| 7PU5220-1AF30 | 3RP1555-1AR30 | |
| 7PU5220-1AJ20 | 3RP1555-1AQ30 | |
| 7PU5220-1AN20 | 3RP1555-1AP30 | |
| 7PU5220-2AB30 | 3RP1555-1AQ30 | |
| 7PU5220-2AE30 | 3RP1555-1AR30 | |
| 7PU5220-2AF30 | 3RP1555-1AR30 | |
| 7PU5220-2AJ20 | 3RP1555-1AQ30 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 7PU5220-2AN20 | 3RP1555-1AP30 | |
| 7PU5220-3AB30 | 3RP1555-1AQ30 | |
| 7PU5220-3AE30 | 3RP1555-1AR30 | |
| 7PU5220-3AF30 | 3RP1555-1AR30 | |
| 7PU5220-3AJ20 | 3RP1555-1AQ30 | |
| 7PU5220-3AN20 | 3RP1555-1AP30 | |
| 7PU5220-4AB30 | 3RP1555-1AQ30 | |
| 7PU5220-4AE30 | 3RP1555-1AR30 | |
| 7PU5220-4AF30 | 3RP1555-1AR30 | |
| 7PU5220-4AJ20 | 3RP1555-1AQ30 | |
| 7PU5220-4AN20 | 3RP1555-1AP30 | |
| 7PU5220-7AB30 | 3RP1555-1AQ30 | |
| 7PU5220-7AE30 | 3RP1555-1AR30 | |
| 7PU5220-7AF30 | 3RP1555-1AR30 | |
| 7PU5220-7AJ20 | 3RP1555-1AQ30 | |
| 7PU5220-7AN20 | 3RP1555-1AP30 | |
| 7PU5340-0AB30 | 3RP1555-1AQ30 | |
| 7PU5340-0AE30 | 3RP1555-1AR30 | |
| 7PU5340-0AF30 | 3RP1555-1AR30 | |
| 7PU5340-0AJ20 | 3RP1555-1AQ30 | |
| 7PU5340-0AN20 | 3RP1555-1AP30 | |
| 7PU5340-1AB30 | 3RP1555-1AQ30 | |
| 7PU5340-1AE30 | 3RP1555-1AW30 | |
| 7PU5340-1AF30 | 3RP1555-1AW30 | |
| 7PU5340-1AJ20 | 3RP1555-1AQ30 | |
| 7PU5340-1AN20 | 3RP1555-1AP30 | |
| 7PU5340-2AB30 | 3RP1555-1AQ30 | |
| 7PU5340-2AE30 | 3RP1555-1AW30 | |
| 7PU5340-2AF30 | 3RP1555-1AW30 | |
| 7PU5340-2AJ20 | 3RP1555-1AQ30 | |
| 7PU5340-2AN20 | 3RP1555-1AP30 | |
| 7PU5340-3AB20 | 3RP1555-1AP30 | |
| 7PU5340-3AB30 | 3RP1555-1AQ30 | |
| 7PU5340-3AE30 | 3RP1555-1AW30 | |
| 7PU5340-3AF30 | 3RP1555-1AW30 | |
| 7PU5340-3AJ20 | 3RP1555-1AQ30 | |
| 7PU5340-3AN20 | 3RP1555-1AP30 | |
| 7PU5340-4AB30 | 3RP1555-1AQ30 | |
| 7PU5340-4AE30 | 3RP1555-1AW30 | |
| 7PU5340-4AF30 | 3RP1555-1AW30 | |
| 7PU5340-4AJ20 | 3RP1555-1AQ30 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 7PU5340-4AN20 | 3RP1555-1AP30 | |
| 7PU5340-7AB30 | 3RP1555-1AQ30 | |
| 7PU5340-7AE30 | 3RP1555-1AW30 | |
| 7PU5340-7AF30 | 3RP1555-1AW30 | |
| 7PU5340-7AJ20 | 3RP1555-1AQ30 | |
| 7PU5340-7AN20 | 3RP1555-1AP30 | |
| 7PU5720-0AB30 | 3RP1505-1AQ30 | |
| 7PU5720-0AE30 | 3RP1505-1AW30 | |
| 7PU5720-0AF30 | 3RP1505-1AW30 | |
| 7PU5720-0AJ20 | 3RP1505-1AQ30 | |
| 7PU5720-0AN20 | 3RP1505-1AP30 | |
| 7PU5720-0AZ90-K0M | NO DIRECT REPLACEMENT | |
| 7PU6020-2NB30 | 3RP1576-1NQ30 | |
| 7PU6020-2NE30 | 3RP1505-1BW30 | |
| 7PU6020-2NF30 | 3RP1505-1BW30 | |
| 7PU6020-2NJ20 | 3RP1576-1NQ30 | |
| 7PU6020-2NN20 | 3RP1576-1NP30 | |
| 7PU6020-2NT20 | NO DIRECT REPLACEMENT | |
| 7PU6020-7NB30 | 3RP1574-1NQ30 | |
| 7PU6020-7NE30 | 3RP1505-1BW30 | |
| 7PU6020-7NF30 | 3RP1505-1BW30 | |
| 7PU6020-7NJ20 | 3RP1574-1NQ30 | |
| 7PU6020-7NJ40 | 3RP1505-1BW30 | |
| 7PU6020-7NN20 | 3RP1574-1NP30 | |
| 7PU6020-7NT20 | NO DIRECT REPLACEMENT | |
| 7PU6040-2NB30 | 3RP1576-1NQ30 | |
| 7PU6040-2NE30 | 3RP1505-1BW30 | |
| 7PU6040-2NF30 | 3RP1505-1BW30 | |
| 7PU6040-2NJ20 | 3RP1576-1NQ30 | |
| 7PU6040-2NN20 | 3RP1576-1NP30 | |
| 7PU6040-2NT20 | NO DIRECT REPLACEMENT | |
| 7PU6040-7NB30 | 3RP1574-1NQ30 | |
| 7PU6040-7NE30 | 3RP1505-1BW30 | |
| 7PU6040-7NF30 | 3RP1505-1BW30 | |
| 7PU6040-7NJ20 | 3RP1574-1NQ30 | |
| 7PU6040-7NN20 | 3RP1574-1NP30 | |
| 7PU6040-7NT20 | NO DIRECT REPLACEMENT | |
| 7PU6220-2NB30 | 3RP1576-1NQ30 | |
| 7PU6220-2NJ20 | 3RP1576-1NQ30 | |
| 7PU6220-7NB30 | 3RP1574-1NQ30 | |
| 7PU6220-7NE30 | 3RP1505-1BW30 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 7PU6220-7NJ20 | 3RP1574-1NQ30 | |
| 7PU6220-7NN20 | 3RP1574-1NP30 | |
| 7PU7020-0CB30 | 3RP1527-1EC30 | |
| 7PU7020-0CM30 | 3RP1527-1EM30 | |
| 7PU7020-1CB30 | 3RP1527-1EC30 | |
| 7PU7020-1CM30 | 3RP1527-1EM30 | |
| 7PU7020-2CB30 | 3RP1527-1EC30 | |
| 7PU7020-2CM30 | 3RP1527-1EM30 | |
| 7PU7020-3CB30 | 3RP1527-1EC30 | |
| 7PU7020-3CM30 | 3RP1527-1EM30 | |
| 7PU7020-4CB30 | 3RP1527-1EC30 | |
| 7PU7020-4CM30 | 3RP1527-1EM30 | |
| 7PU7020-7CB30 | 3RP1527-1EC30 | |
| 7PU7020-7CM30 | 3RP1527-1EM30 | |
| 7PU7243-0CB40 | NO DIRECT REPLACEMENT | |
| 7PU8040-0AB30 | 3RP020-1AQ30 | |
| 7PU8040-0AJ20 | 3RP020-1AQ30 | |
| 7PU8040-0AN20 | 3RP020-1AP30 | |
| 7PU8040-1AB30 | 3RP020-1AQ30 | |
| 7PU8040-1AJ20 | 3RP020-1AQ30 | |
| 7PU8040-1AN20 | 3RP020-1AP30 | |
| 7PU8040-2AB30 | 3RP020-1AQ30 | |
| 7PU8040-2AJ20 | 3RP020-1AQ30 | |
| 7PU8040-2AN20 | 3RP020-1AP30 | |
| 7PU8040-3AB30 | 3RP020-1AQ30 | |
| 7PU8040-3AJ20 | 3RP020-1AQ30 | |
| 7PU8040-3AN20 | 3RP020-1AP30 | |
| 7PU8140-2AB30 | 3RP020-1AQ30 | |
| 7PU8140-2AJ20 | 3RP020-1AQ30 | |
| 7PU8143-2AB30 | NO DIRECT REPLACEMENT | |
| 7PU8143-2AJ20 | NO DIRECT REPLACEMENT | |
| 7PU8143-2AN20 | NO DIRECT REPLACEMENT | |
| 7PU8340-2AB30 | 3RP1000-1AQ30 | |
| 7PU8340-2AJ20 | 3RP1000-1AQ30 | |
| 7PU8540-2AB30 | 3RP1540-1AB30 | |
| 7PU8540-2AJ30 | 3RP1540-1AJ30 | |
| 7PU8540-2AN30 | 3RP1540-1AN30 | |
| 7PU8543-2AB30 | NO DIRECT REPLACEMENT | |
| 7PU8543-2AJ30 | NO DIRECT REPLACEMENT | |
| 7PU8640-0AJ20 | 3RP1000-1AQ30 | |
| 7PU8640-2AB30 | 3RP1000-1AP30 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 7PU8640-2AE30 | 3RP1505-1BW30 | |
| 7PU8640-2AF30 | 3RP1505-1BW30 | |
| 7PU8640-2AJ20 | 3RP1000-1AQ30 | |
| 7PU8640-2AN20 | 3RP1000-1AP30 | |
| 7PU8643-2AB30 | NO DIRECT REPLACEMENT | |
| 7PU8643-2AE30 | NO DIRECT REPLACEMENT | |
| 7PU8643-2AF30 | NO DIRECT REPLACEMENT | |
| 7PU8643-2AJ20 | NO DIRECT REPLACEMENT | |
| 7PU8643-2AN20 | NO DIRECT REPLACEMENT | |
| 7PU8740-0AB30 | 3RP1555-1AQ30 | |
| 7PU8740-0AE30-Z | NO DIRECT REPLACEMENT | |
| 7PU8740-0AJ20 | 3RP1555-1AQ30 | |
| 7PX1040-0AB30 | 3RT1916-2EJ11 OR 3RT1926-2EJ11 | |
| 7PX1040-0AE30 | SEE SIRIUS 3RP | |
| 7PX1040-0AF30 | SEE SIRIUS 3RP | |
| 7PX1040-0AJ20 | 3RT1916-2EC11 OR 3RT1926-2EC11 | |
| 7PX1040-0AN20 | 3RT1916-2ED11 OR 3RT1926-2ED11 | |
| 7PX1040-1AB30 | 3RT1916-2EJ21 OR 3RT1926-2EJ21 | |
| 7PX1040-1AE30 | SEE SIRIUS 3RP | |
| 7PX1040-1AF30 | SEE SIRIUS 3RP | |
| 7PX1040-1AJ20 | 3RT1916-2EC21 OR 3RT1926-2EC21 | |
| 7PX1040-1AJ22 | 3RT1916-2EC21 OR 3RT1926-2EC21 | |
| 7PX1040-1AN20 | 3RT1916-2ED21 OR 3RT1926-2ED21 | |
| 7PX1040-2AB30 | 3RT1916-2EJ31 OR 3RT1926-2EJ31 | |
| 7PX1040-2AE30 | SEE SIRIUS 3RP | |
| 7PX1040-2AF30 | SEE SIRIUS 3RP | |
| 7PX1040-2AJ20 | 3RT1916-2EC31 OR 3RT1926-2EC31 | |
| 7PX1040-2AN20 | 3RT1916-2ED41 OR 3RT1926-2ED41 | |
| 7PX1040-2AZ90 | SEE SIRIUS 3RP | |
| 7PX1040-3AB30 | SEE SIRIUS 3RP | |
| 7PX1040-3AE30 | SEE SIRIUS 3RP | |
| 7PX1040-3AF30 | SEE SIRIUS 3RP | |
| 7PX1040-3AJ20 | SEE SIRIUS 3RP | |
| 7PX1040-3AN20 | SEE SIRIUS 3RP | |
| 7PX1040-4AB30 | SEE SIRIUS 3RP | |
| 7PX1040-4AE30 | SEE SIRIUS 3RP | |
| 7PX1040-4AF30 | SEE SIRIUS 3RP | |
| 7PX1040-4AJ20 | SEE SIRIUS 3RP | |
| 7PX1040-4AN20 | SEE SIRIUS 3RP | |
| 7PX1040-7AB30 | SEE SIRIUS 3RP | |
| 7PX1040-7AE30 | SEE SIRIUS 3RP | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 7PX1040-7AF30 | SEE SIRIUS 3RP | |
| 7PX1040-7AJ20 | SEE SIRIUS 3RP | |
| 7PX1040-7AN20 | SEE SIRIUS 3RP | |
| 7PX1050-1AB30 | 3RT1916-2EJ21 OR 3RT1926-2EJ21 | |
| 7PX1050-1AE30 | SEE SIRIUS 3RP | |
| 7PX1050-1AF30 | SEE SIRIUS 3RP | |
| 7PX1050-1AJ20 | 3RT1916-2EC21 OR 3RT1926-2EC21 | |
| 7PX1050-1AN20 | 3RT1916-2ED21 OR 3RT1926-2ED21 | |
| 7PX1050-2AB30 | 3RT1916-2EJ31 OR 3RT1926-2EJ31 | |
| 7PX1050-2AE30 | SEE SIRIUS 3RP | |
| 7PX1050-2AF30 | SEE SIRIUS 3RP | |
| 7PX1050-2AJ20 | 3RT1916-2EC31 OR 3RT1926-2EC31 | |
| 7PX1050-2AN20 | 3RT1916-2ED41 OR 3RT1926-2ED41 | |
| 7PX1540-0AB30 | 3RT1916-2FJ11 OR 3RT1926-2FJ11 | |
| 7PX1540-0AF30 | SEE SIRIUS 3RP | |
| 7PX1540-0AJ30 | 3RT1916-2FK11 OR 3RT1926-2FK11 | |
| 7PX1540-0AN30 | 3RT1916-2FL11 OR 3RT1926-2FL11 | |
| 7PX1540-1AB30 | 3RT1916-2FJ21 OR 3RT1926-2FJ21 | |
| 7PX1540-1AF30 | SEE SIRIUS 3RP | |
| 7PX1540-1AJ30 | 3RT1916-2FK21 OR 3RT1926-2FK21 | |
| 7PX1540-1AN30 | 3RT1916-2FL21 OR 3RT1926-2FL21 | |
| 7PX1540-2AB30 | 3RT1916-2FJ31 OR 3RT1926-2FJ31 | |
| 7PX1540-2AF30 | SEE SIRIUS 3RP | |
| 7PX1540-2AJ30 | 3RT1916-2FK31 OR 3RT1926-2FK31 | |
| 7PX1540-2AN30 | 3RT1916-2FL31 OR 3RT1926-2FL31 | |
| 7PX1540-7AB30 | SEE SIRIUS 3RP | |
| 7PX1540-7AF30 | SEE SIRIUS 3RP | |
| 7PX1540-7AJ30 | SEE SIRIUS 3RP | |
| 7PX1540-7AN30 | SEE SIRIUS 3RP | |
| 7PX7040-0CF30 | 3RT1926-2CG11 | |
| 7PX7040-0CJ30 | 3RT1926-2CH11 | |
| 7PX7040-0CN20 | 3RT1926-2CH11 | |
| 7PX7040-0CN40 | 3RT1926-2CH11 | |
| 7PX7040-1CF30 | 3RT1926-2CG21 | |
| 7PX7040-1CJ30 | 3RT1926-2CH21 | |
| 7PX7040-1CN20 | 3RT1926-2CH21 | |
| 7PX7040-1CN40 | 3RT1926-2CH21 | |
| 7PX7040-2CF30 | 3RT1926-2CG31 | |
| 7PX7040-2CJ30 | 3RT1926-2CH31 | |
| 7PX7040-2CN20 | 3RT1926-2CH31 | |
| 7PX7040-2CN40 | 3RT1926-2CH31 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 7PX7040-7CF30 | 3RT1926-2CG31 | |
| 7PX7040-7CJ30 | 3RT1926-2CH31 | |
| 7PX7040-7CN20 | 3RT1926-2CH31 | |
| 7PX7040-7CN40 | 3RT1926-2CH31 | |
| 7PX7040-7CZ90 | NO DIRECT REPLACEMENT | |
| 7PX7140-0CF30 | CONTACT SALES OFFICE | |
| 7PX7140-0CJ30 | CONTACT SALES OFFICE | |
| 7PX7140-0CN20 | CONTACT SALES OFFICE | |
| 7PX7140-0CN40 | CONTACT SALES OFFICE | |
| 7PX7340-0CM30 | 3RT1916-2CH11 | |
| 7PX7340-1CB30 | 3RT1916-2CG21 | |
| 7PX8040-0A | NO DIRECT REPLACEMENT | |
| 7PX8141-0Q | NO DIRECT REPLACEMENT | |
| 7PX8170-0Q | NO DIRECT REPLACEMENT | |
| 7PX8170-0R | SEE SIRIUS 3RP | |
| 7PX8170-0T | SEE SIRIUS 3RP | |
| 7PX8170-1Q | SEE SIRIUS 3RP | |
| 7PX8170-1R | SEE SIRIUS 3RP | |
| 7PX8170-1T | SEE SIRIUS 3RP | |
| 7PX8170-2QB | SEE SIRIUS 3RP | |
| 7PX8170-2QK | SEE SIRIUS 3RP | |
| 7PX8170-2RB | SEE SIRIUS 3RP | |
| 7PX8170-2TJ | SEE SIRIUS 3RP | |
| 7PX8170-2TK | SEE SIRIUS 3RP | |
| 7PX8170-3A | SEE SIRIUS 3RP | |
| 7PX8170-4A | SEE SIRIUS 3RP | |
| 7PX8171-0Q | SEE SIRIUS 3RP | |
| 7PX8171-0R | SEE SIRIUS 3RP | |
| 7PX8171-0T | SEE SIRIUS 3RP | |
| 7PX8171-1Q | SEE SIRIUS 3RP | |
| 7PX8171-1R | SEE SIRIUS 3RP | |
| 7PX8171-1T | SEE SIRIUS 3RP | |
| 7PX8171-2QB | SEE SIRIUS 3RP | |
| 7PX8171-2QJ | SEE SIRIUS 3RP | |
| 7PX8171-2QK | SEE SIRIUS 3RP | |
| 7PX8171-2RB | SEE SIRIUS 3RP | |
| 7PX8171-2TJ | SEE SIRIUS 3RP | |
| 7PX8171-2TK | SEE SIRIUS 3RP | |
| 7PX8220-0AB30 | NO DIRECT REPLACEMENT | |
| 7PX8220-0AE30 | NO DIRECT REPLACEMENT | |
| 7PX8220-0AF30 | NO DIRECT REPLACEMENT | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| 7PX8220-0AJ20 | NO DIRECT REPLACEMENT | |
| 7PX8220-0AN20 | NO DIRECT REPLACEMENT | |
| 7PX9001 | NO DIRECT REPLACEMENT | |
| 7PX9002 | NO DIRECT REPLACEMENT | |
| 7PX9003 | NO DIRECT REPLACEMENT | |
| 7PX9004 | NO DIRECT REPLACEMENT | |
| 7PX9901 | 3RP1902 | |
| 7PX9902 | 3RP1902 | |
| 7PX9904 | PRODUCT STILL AVAILABLE | |
| 7PX9905 | NO DIRECT REPLACEMENT | |
| 7PX9906 | 3RP1903 | |
| 7PX9907 | NO DIRECT REPLACEMENT | |
| 7PX9911 | NO DIRECT REPLACEMENT | |
| 7PX9912 | NO DIRECT REPLACEMENT | |
| 7PX9914 | 3RP1901-0B | |
| CRL0F3011C1 | 3RA1316-8XB30-1AC2 + AUX | |
| CRL0F3011K6 | 3RA1316-8XB30-1AK6 + AUX | |
| CRL0F3011M1 | 3RA1316-8XB30-1AM2 + AUX | |
| CRL0F3011P0 | 3RA1316-8XB30-1AP6 + AUX | |
| CRL0F3011P6 | 3RA1316-8XB30-1AP6 + AUX | |
| CRL0F3011Q0 | 3RA1316-8XB30-1AV0 + AUX | |
| CRL0F3011S0 | 3RA1316-8XB30-1AT6 + AUX | |
| CRL0F3022B4 | 3RA1316-8XB30-1BB4 + AUX | |
| CRL0F3022B41 | 3RA1316-8XB30-1BB4 + AUX | |
| CRL0F3022C1 | 3RA1316-8XB30-1AC2 + AUX | |
| CRL0F3022C2 | 3RA1316-8XB30-1AC2 + AUX | |
| CRL0F3022C21 | 3RA1316-8XB30-1AC2 + AUX | |
| CRL0F3022E4 | 3RA1316-8XB30-1BE4 + AUX | |
| CRL0F3022E41 | 3RA1316-8XB30-1BE4 + AUX | |
| CRL0F3022G4 | 3RA1316-8XB30-1BG4 + AUX | |
| CRL0F3022G41 | 3RA1316-8XB30-1BG4 + AUX | |
| CRL0F3022K6 | 3RA1316-8XB30-1AK6 + AUX | |
| CRL0F3022K61 | 3RA1316-8XB30-1AK6 + AUX | |
| CRL0F3022M1 | 3RA1316-8XB30-1AM2 + AUX | |
| CRL0F3022M11 | 3RA1316-8XB30-1AM2 + AUX | |
| CRL0F3022P6 | 3RA1316-8XB30-1AP6 + AUX | |
| CRL0F3022P61 | 3RA1316-8XB30-1AP6 + AUX | |
| CRL0F3022Q0 | 3RA1316-8XB30-1AV0 + AUX | |
| CRL0F3022Q01 | 3RA1316-8XB30-1AV0 + AUX | |
| CRL0F3022S0 | 3RA1316-8XB30-1AT6 + AUX | |
| CRL0F3022S01 | 3RA1316-8XB30-1AT6 + AUX | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| CRL0F3022S2 | 3RA1316-8XB30-1AT6 + AUX | |
| CRL0F3022S21 | 3RA1316-8XB30-1AT6 + AUX | |
| CRL0F3022U1 | 3RA1316-8XB30-1AU6 + AUX | |
| CRL0F3022U11 | 3RA1316-8XB30-1AU6 + AUX | |
| CRL0F3022W4 | 3RA1316-8XB30-1BW4 + AUX | |
| CRL0F3022W41 | 3RA1316-8XB30-1BW4 + AUX | |
| CRL0F3111C1 | 3RA1317-8XB30-1AC2 + AUX | |
| CRL0F3111K6 | 3RA1317-8XB30-1AK6 + AUX | |
| CRL0F3111M1 | 3RA1317-8XB30-1AM2 + AUX | |
| CRL0F3111P0 | 3RA1317-8XB30-1AP6 + AUX | |
| CRL0F3111P6 | 3RA1317-8XB30-1AP6 + AUX | |
| CRL0F3111Q0 | 3RA1317-8XB30-1AV0 + AUX | |
| CRL0F3111S0 | 3RA1317-8XB30-1AT6 + AUX | |
| CRL0F3122B4 | 3RA1317-8XB30-1BB4 + AUX | |
| CRL0F3122B41 | 3RA1317-8XB30-1BB4 + AUX | |
| CRL0F3122C1 | 3RA1317-8XB30-1AC2 + AUX | |
| CRL0F3122C2 | 3RA1317-8XB30-1AC2 + AUX | |
| CRL0F3122C21 | 3RA1317-8XB30-1AC2 + AUX | |
| CRL0F3122E4 | 3RA1317-8XB30-1BE4 + AUX | |
| CRL0F3122E41 | 3RA1317-8XB30-1BE4 + AUX | |
| CRL0F3122G4 | 3RA1317-8XB30-1BG4 + AUX | |
| CRL0F3122G41 | 3RA1317-8XB30-1BG4 + AUX | |
| CRL0F3122K6 | 3RA1317-8XB30-1AK6 + AUX | |
| CRL0F3122K61 | 3RA1317-8XB30-1AK6 + AUX | |
| CRL0F3122M1 | 3RA1317-8XB30-1AM2 + AUX | |
| CRL0F3122M11 | 3RA1317-8XB30-1AM2 + AUX | |
| CRL0F3122P6 | 3RA1317-8XB30-1AP6 + AUX | |
| CRL0F3122P61 | 3RA1317-8XB30-1AP6 + AUX | |
| CRL0F3122Q0 | 3RA1317-8XB30-1AV0 + AUX | |
| CRL0F3122Q01 | 3RA1317-8XB30-1AV0 + AUX | |
| CRL0F3122S0 | 3RA1317-8XB30-1AT6 + AUX | |
| CRL0F3122S01 | 3RA1317-8XB30-1AT6 + AUX | |
| CRL0F3122S2 | 3RA1317-8XB30-1AT6 + AUX | |
| CRL0F3122S21 | 3RA1317-8XB30-1AT6 + AUX | |
| CRL0F3122U1 | 3RA1317-8XB30-1AU6 + AUX | |
| CRL0F3122U11 | 3RA1317-8XB30-1AU6 + AUX | |
| CRL0F3122W4 | 3RA1317-8XB30-1BW4 + AUX | |
| CRL0F3122W41 | 3RA1317-8XB30-1BW4 + AUX | |
| CRL0F3211C1 | 3RA1325-8XB30-1AC2 + AUX | |
| CRL0F3211K6 | 3RA1325-8XB30-1AK6 + AUX | |
| CRL0F3211M1 | 3RA1325-8XB30-1AM2 + AUX | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| CRL0F3211P0 | 3RA1325-8XB30-1AP6 + AUX | |
| CRL0F3211P6 | 3RA1325-8XB30-1AP6 + AUX | |
| CRL0F3211Q0 | 3RA1325-8XB30-1AV0 + AUX | |
| CRL0F3211S0 | 3RA1325-8XB30-1AT6 + AUX | |
| CRL0F3221B4 | 3RA1325-8XB30-1BB4 + AUX | |
| CRL0F3221B41 | 3RA1325-8XB30-1BB4 + AUX | |
| CRL0F3221C1 | 3RA1325-8XB30-1AC2 + AUX | |
| CRL0F3221C2 | 3RA1325-8XB30-1AC2 + AUX | |
| CRL0F3221C21 | 3RA1325-8XB30-1AC2 + AUX | |
| CRL0F3221E4 | 3RA1325-8XB30-1BE4 + AUX | |
| CRL0F3221E41 | 3RA1325-8XB30-1BE4 + AUX | |
| CRL0F3221G4 | 3RA1325-8XB30-1BG4 + AUX | |
| CRL0F3221G41 | 3RA1325-8XB30-1BG4 + AUX | |
| CRL0F3221K6 | 3RA1325-8XB30-1AK6 + AUX | |
| CRL0F3221K61 | 3RA1325-8XB30-1AK6 + AUX | |
| CRL0F3221M1 | 3RA1325-8XB30-1AM2 + AUX | |
| CRL0F3221M11 | 3RA1325-8XB30-1AM2 + AUX | |
| CRL0F3221P6 | 3RA1325-8XB30-1AP6 + AUX | |
| CRL0F3221P61 | 3RA1325-8XB30-1AP6 + AUX | |
| CRL0F3221Q0 | 3RA1325-8XB30-1AV0 + AUX | |
| CRL0F3221Q01 | 3RA1325-8XB30-1AV0 + AUX | |
| CRL0F3221S0 | 3RA1325-8XB30-1AT6 + AUX | |
| CRL0F3221S01 | 3RA1325-8XB30-1AT6 + AUX | |
| CRL0F3221S2 | 3RA1325-8XB30-1AT6 + AUX | |
| CRL0F3221S21 | 3RA1325-8XB30-1AT6 + AUX | |
| CRL0F3221U1 | 3RA1325-8XB30-1AU6 + AUX | |
| CRL0F3221U11 | 3RA1325-8XB30-1AU6 + AUX | |
| CRL0F3221W4 | 3RA1325-8XB30-1BW4 + AUX | |
| CRL0F3221W41 | 3RA1325-8XB30-1BW4 + AUX | |
| CRL0F3222C1 | 3RA1325-8XB30-1AC2 + AUX | |
| CRL0F3222K6 | 3RA1325-8XB30-1AK6 + AUX | |
| CRL0F3222M1 | 3RA1325-8XB30-1AM2 + AUX | |
| CRL0F3222P6 | 3RA1325-8XB30-1AP6 + AUX | |
| CRL0F3222Q0 | 3RA1325-8XB30-1AV0 + AUX | |
| CRL0F3222S0 | 3RA1325-8XB30-1AT6 + AUX | |
| CRL0F3222U1 | 3RA1325-8XB30-1AU6 + AUX | |
| CRL0F3311C1 | 3RA1326-8XB30-1AC2 + AUX | |
| CRL0F3311K6 | 3RA1326-8XB30-1AK6 + AUX | |
| CRL0F3311M1 | 3RA1326-8XB30-1AM2 + AUX | |
| CRL0F3311P0 | 3RA1326-8XB30-1AP6 + AUX | |
| CRL0F3311P6 | 3RA1326-8XB30-1AP6 + AUX | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| CRL0F3311Q0 | 3RA1326-8XB30-1AV0 + AUX | |
| CRL0F3311S0 | 3RA1326-8XB30-1AT6 + AUX | |
| CRL0F3321A4 | 3RA1326-8XB30-1BA4 + AUX | |
| CRL0F3321B4 | 3RA1326-8XB30-1BB4 + AUX | |
| CRL0F3321B41 | 3RA1326-8XB30-1BB4 + AUX | |
| CRL0F3321C1 | 3RA1326-8XB30-1AC2 + AUX | |
| CRL0F3321C2 | 3RA1326-8XB30-1AC2 + AUX | |
| CRL0F3321C21 | 3RA1326-8XB30-1AC2 + AUX | |
| CRL0F3321E4 | 3RA1326-8XB30-1BE4 + AUX | |
| CRL0F3321E41 | 3RA1326-8XB30-1BE4 + AUX | |
| CRL0F3321G4 | 3RA1326-8XB30-1BG4 + AUX | |
| CRL0F3321G41 | 3RA1326-8XB30-1BG4 + AUX | |
| CRL0F3321K6 | 3RA1326-8XB30-1AK6 + AUX | |
| CRL0F3321K61 | 3RA1326-8XB30-1AK6 + AUX | |
| CRL0F3321M1 | 3RA1326-8XB30-1AM2 + AUX | |
| CRL0F3321M11 | 3RA1326-8XB30-1AM2 + AUX | |
| CRL0F3321P6 | 3RA1326-8XB30-1AP6 + AUX | |
| CRL0F3321P61 | 3RA1326-8XB30-1AP6 + AUX | |
| CRL0F3321Q0 | 3RA1326-8XB30-1AV0 + AUX | |
| CRL0F3321Q01 | 3RA1326-8XB30-1AV0 + AUX | |
| CRL0F3321S0 | 3RA1326-8XB30-1AT6 + AUX | |
| CRL0F3321S01 | 3RA1326-8XB30-1AT6 + AUX | |
| CRL0F3321S2 | 3RA1326-8XB30-1AT6 + AUX | |
| CRL0F3321S21 | 3RA1326-8XB30-1AT6 + AUX | |
| CRL0F3321U1 | 3RA1326-8XB30-1AU6 + AUX | |
| CRL0F3321U11 | 3RA1326-8XB30-1AU6 + AUX | |
| CRL0F3321W4 | 3RA1326-8XB30-1BW4 + AUX | |
| CRL0F3321W41 | 3RA1326-8XB30-1BW4 + AUX | |
| CRL0F3322C1 | 3RA1326-8XB30-1AC2 + AUX | |
| CRL0F3322K6 | 3RA1326-8XB30-1AK6 + AUX | |
| CRL0F3322M1 | 3RA1326-8XB30-1AM2 + AUX | |
| CRL0F3322P6 | 3RA1326-8XB30-1AP6 + AUX | |
| CRL0F3322Q0 | 3RA1326-8XB30-1AV0 + AUX | |
| CRL0F3322S0 | 3RA1326-8XB30-1AT6 + AUX | |
| CRL0F3322U1 | 3RA1326-8XB30-1AU6 + AUX | |
| CRL0F3411C1 | 3RA1334-8XB30-1AC2 + AUX | |
| CRL0F3411K6 | 3RA1334-8XB30-1AK6 + AUX | |
| CRL0F3411M1 | 3RA1334-8XB30-1AM2 + AUX | |
| CRL0F3411P0 | 3RA1334-8XB30-1AP6 + AUX | |
| CRL0F3411P6 | 3RA1334-8XB30-1AP6 + AUX | |
| CRL0F3411Q0 | 3RA1334-8XB30-1AV0 + AUX | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| CRL0F3411S0 | 3RA1334-8XB30-1AT6 + AUX | |
| CRL0F3421B4 | 3RA1334-8XB30-1BB4 + AUX | |
| CRL0F3421B41 | 3RA1334-8XB30-1BB4 + AUX | |
| CRL0F3421C1 | 3RA1334-8XB30-1AC2 + AUX | |
| CRL0F3421C2 | 3RA1334-8XB30-1AC2 + AUX | |
| CRL0F3421C21 | 3RA1334-8XB30-1AC2 + AUX | |
| CRL0F3421E4 | 3RA1334-8XB30-1BE4 + AUX | |
| CRL0F3421E41 | 3RA1334-8XB30-1BE4 + AUX | |
| CRL0F3421G4 | 3RA1334-8XB30-1BG4 + AUX | |
| CRL0F3421G41 | 3RA1334-8XB30-1BG4 + AUX | |
| CRL0F3421K6 | 3RA1334-8XB30-1AK6 + AUX | |
| CRL0F3421K61 | 3RA1334-8XB30-1AK6 + AUX | |
| CRL0F3421M1 | 3RA1334-8XB30-1AM2 + AUX | |
| CRL0F3421M11 | 3RA1334-8XB30-1AM2 + AUX | |
| CRL0F3421P6 | 3RA1334-8XB30-1AP6 + AUX | |
| CRL0F3421P61 | 3RA1334-8XB30-1AP6 + AUX | |
| CRL0F3421Q0 | 3RA1334-8XB30-1AV0 + AUX | |
| CRL0F3421Q01 | 3RA1334-8XB30-1AV0 + AUX | |
| CRL0F3421S0 | 3RA1334-8XB30-1AT6 + AUX | |
| CRL0F3421S01 | 3RA1334-8XB30-1AT6 + AUX | |
| CRL0F3421S2 | 3RA1334-8XB30-1AT6 + AUX | |
| CRL0F3421S21 | 3RA1334-8XB30-1AT6 + AUX | |
| CRL0F3421U1 | 3RA1334-8XB30-1AU6 + AUX | |
| CRL0F3421U11 | 3RA1334-8XB30-1AU6 + AUX | |
| CRL0F3421W4 | 3RA1334-8XB30-1BW4 + AUX | |
| CRL0F3421W41 | 3RA1334-8XB30-1BW4 + AUX | |
| CRL0F3422C1 | 3RA1334-8XB30-1AC2 + AUX | |
| CRL0F3422K6 | 3RA1334-8XB30-1AK6 + AUX | |
| CRL0F3422M1 | 3RA1334-8XB30-1AM2 + AUX | |
| CRL0F3422P6 | 3RA1334-8XB30-1AP6 + AUX | |
| CRL0F3422Q0 | 3RA1334-8XB30-1AV0 + AUX | |
| CRL0F3422S0 | 3RA1334-8XB30-1AT6 + AUX | |
| CRL0F3422U1 | 3RA1334-8XB30-1AU6 + AUX | |
| CRL0F3511C1 | 3RA1335-8XB30-1AC2 + AUX | |
| CRL0F3511K6 | 3RA1335-8XB30-1AK6 + AUX | |
| CRL0F3511M1 | 3RA1335-8XB30-1AM2 + AUX | |
| CRL0F3511P0 | 3RA1335-8XB30-1AP6 + AUX | |
| CRL0F3511P6 | 3RA1335-8XB30-1AP6 + AUX | |
| CRL0F3511Q0 | 3RA1335-8XB30-1AV0 + AUX | |
| CRL0F3511S0 | 3RA1335-8XB30-1AT6 + AUX | |
| CRL0F3521K6 | 3RA1335-8XB30-1AK6 + AUX | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| CRL0F3521P6 | 3RA1335-8XB30-1AP6 + AUX | |
| CRL0F4022A4 | 3RA1316-8XB30-1BA4 + AUX | |
| CRL0F4022A41 | 3RA1316-8XB30-1BA4 + AUX | |
| CRL0F4022B4 | 3RA1316-8XB30-1BB4 + AUX | |
| CRL0F4022C2 | 3RA1316-8XB30-1AC2 + AUX | |
| CRL0F4022C21 | 3RA1316-8XB30-1AC2 + AUX | |
| CRL0F4022G4 | 3RA1316-8XB30-1BG4 + AUX | |
| CRL0F4022K6 | 3RA1316-8XB30-1AK6 + AUX | |
| CRL0F4022K61 | 3RA1316-8XB30-1AK6 + AUX | |
| CRL0F4022M1 | 3RA1316-8XB30-1AM2 + AUX | |
| CRL0F4022M11 | 3RA1316-8XB30-1AM2 + AUX | |
| CRL0F4022P6 | 3RA1316-8XB30-1AP6 + AUX | |
| CRL0F4022P61 | 3RA1316-8XB30-1AP6 + AUX | |
| CRL0F4022Q0 | 3RA1316-8XB30-1AV0 + AUX | |
| CRL0F4022Q01 | 3RA1316-8XB30-1AV0 + AUX | |
| CRL0F4022S0 | 3RA1316-8XB30-1AT6 + AUX | |
| CRL0F4022S01 | 3RA1316-8XB30-1AT6 + AUX | |
| CRL0F4022S2 | 3RA1316-8XB30-1AT6 + AUX | |
| CRL0F4022S21 | 3RA1316-8XB30-1AT6 + AUX | |
| CRL0F4022U1 | 3RA1316-8XB30-1AU6 + AUX | |
| CRL0F4022U11 | 3RA1316-8XB30-1AU6 + AUX | |
| CRL0F4022W4 | 3RA1316-8XB30-1BW4 + AUX | |
| CRL0F4022W41 | 3RA1316-8XB30-1BW4 + AUX | |
| CRL0F4122B4 | 3RA1317-8XB30-1BB4 + AUX | |
| CRL0F4122C2 | 3RA1317-8XB30-1AC2 + AUX | |
| CRL0F4122G4 | 3RA1317-8XB30-1BG4 + AUX | |
| CRL0F4122K6 | 3RA1317-8XB30-1AK6 + AUX | |
| CRL0F4122M1 | 3RA1317-8XB30-1AM2 + AUX | |
| CRL0F4122M2 | 3RA1317-8XB30-1AM2 + AUX | |
| CRL0F4122P6 | 3RA1317-8XB30-1AP6 + AUX | |
| CRL0F4122Q0 | 3RA1317-8XB30-1AV0 + AUX | |
| CRL0F4122S0 | 3RA1317-8XB30-1AT6 + AUX | |
| CRL0F4122S2 | 3RA1317-8XB30-1AT6 + AUX | |
| CRL0F4122U1 | 3RA1317-8XB30-1AU6 + AUX | |
| CRL0F4222B4 | 3RA1325-8XB30-1BB4 + AUX | |
| CRL0F4222C2 | 3RA1325-8XB30-1AC2 + AUX | |
| CRL0F4222C21 | 3RA1325-8XB30-1AC2 + AUX | |
| CRL0F4222G4 | 3RA1325-8XB30-1BG4 + AUX | |
| CRL0F4222K6 | 3RA1325-8XB30-1AK6 + AUX | |
| CRL0F4222K61 | 3RA1325-8XB30-1AK6 + AUX | |
| CRL0F4222M1 | 3RA1325-8XB30-1AM2 + AUX | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| CRL0F4222M11 | 3RA1325-8XB30-1AM2 + AUX | |
| CRL0F4222P6 | 3RA1325-8XB30-1AP6 + AUX | |
| CRL0F4222P61 | 3RA1325-8XB30-1AP6 + AUX | |
| CRL0F4222Q0 | 3RA1325-8XB30-1AV0 + AUX | |
| CRL0F4222Q01 | 3RA1325-8XB30-1AV0 + AUX | |
| CRL0F4222Q4 | 3RA1325-8XB30-1BP4 + AUX | |
| CRL0F4222S0 | 3RA1325-8XB30-1AT6 + AUX | |
| CRL0F4222S01 | 3RA1325-8XB30-1AT6 + AUX | |
| CRL0F4222S2 | 3RA1325-8XB30-1AT6 + AUX | |
| CRL0F4222S21 | 3RA1325-8XB30-1AT6 + AUX | |
| CRL0F4222U1 | 3RA1325-8XB30-1AU6 + AUX | |
| CRL0F4222U11 | 3RA1325-8XB30-1AU6 + AUX | |
| CRL0F4222W4 | 3RA1325-8XB30-1BW4 + AUX | |
| CRL0F4322B4 | 3RA1326-8XB30-1BB4 + AUX | |
| CRL0F4322C2 | 3RA1326-8XB30-1AC2 + AUX | |
| CRL0F4322G4 | 3RA1326-8XB30-1BG4 + AUX | |
| CRL0F4322K6 | 3RA1326-8XB30-1AK6 + AUX | |
| CRL0F4322K6ZPC | NO DIRECT REPLACEMENT | |
| CRL0F4322M1 | 3RA1326-8XB30-1AM2 + AUX | |
| CRL0F4322P6 | 3RA1326-8XB30-1AP6 + AUX | |
| CRL0F4322P6ZPC | NO DIRECT REPLACEMENT | |
| CRL0F4322Q0 | 3RA1326-8XB30-1AV0 + AUX | |
| CRL0F4322Q4 | 3RA1326-8XB30-1BP4 + AUX | |
| CRL0F4322S0 | 3RA1326-8XB30-1AT6 + AUX | |
| CRL0F4322S2 | 3RA1326-8XB30-1AT6 + AUX | |
| CRL0F4322U1 | 3RA1326-8XB30-1AU6 + AUX | |
| CRL0F4322W4 | 3RA1326-8XB30-1BW4 + AUX | |
| CRL0F4422B4 | 3RA1334-8XB30-1BB4 + AUX | |
| CRL0F4422C2 | 3RA1334-8XB30-1AC2 + AUX | |
| CRL0F4422C21 | 3RA1334-8XB30-1AC2 + AUX | |
| CRL0F4422G4 | 3RA1334-8XB30-1BG4 + AUX | |
| CRL0F4422J1 | 3RA1334-8XB30-1AK6 + AUX | |
| CRL0F4422K6 | 3RA1334-8XB30-1AK6 + AUX | |
| CRL0F4422K61 | 3RA1334-8XB30-1AK6 + AUX | |
| CRL0F4422K6Z0E | NO DIRECT REPLACEMENT | |
| CRL0F4422K6ZZ0E | NO DIRECT REPLACEMENT | |
| CRL0F4422M1 | 3RA1334-8XB30-1AM2 + AUX | |
| CRL0F4422M11 | 3RA1334-8XB30-1AM2 + AUX | |
| CRL0F4422N4 | NO DIRECT REPLACEMENT | |
| CRL0F4422P6 | 3RA1334-8XB30-1AP6 + AUX | |
| CRL0F4422P61 | 3RA1334-8XB30-1AP6 + AUX | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| CRL0F4422Q0 | 3RA1334-8XB30-1AV0 + AUX | |
| CRL0F4422Q01 | 3RA1334-8XB30-1AV0 + AUX | |
| CRL0F4422Q4 | 3RA1334-8XB30-1BP4 + AUX | |
| CRL0F4422S0 | 3RA1334-8XB30-1AT6 + AUX | |
| CRL0F4422S01 | 3RA1334-8XB30-1AT6 + AUX | |
| CRL0F4422S2 | 3RA1334-8XB30-1AT6 + AUX | |
| CRL0F4422S21 | 3RA1334-8XB30-1AT6 + AUX | |
| CRL0F4422U1 | 3RA1334-8XB30-1AU6 + AUX | |
| CRL0F4422U11 | 3RA1334-8XB30-1AU6 + AUX | |
| CRL0F4422W4 | 3RA1334-8XB30-1BW4 + AUX | |
| CRL0F4522K6 | 3RA1335-8XB30-1AK6 + AUX | |
| CRL0F4522P6 | 3RA1335-8XB30-1AP6 + AUX | |
| CRL0F4622B4 | 3RA1336-8XB30-1BB4 + AUX | |
| CRL0F4622C1 | 3RA1336-8XB30-1AC2 + AUX | |
| CRL0F4622C2 | 3RA1336-8XB30-1AC2 + AUX | |
| CRL0F4622G4 | 3RA1336-8XB30-1BG4 + AUX | |
| CRL0F4622K6 | 3RA1336-8XB30-1AK6 + AUX | |
| CRL0F4622K61 | 3RA1336-8XB30-1AK6 + AUX | |
| CRL0F4622K6Z0E | NO DIRECT REPLACEMENT | |
| CRL0F4622M1 | 3RA1336-8XB30-1AM2 + AUX | |
| CRL0F4622M11 | 3RA1336-8XB30-1AM2 + AUX | |
| CRL0F4622M1ZAE | NO DIRECT REPLACEMENT | |
| CRL0F4622N4 | NO DIRECT REPLACEMENT | |
| CRL0F4622P0 | 3RA1336-8XB30-1AP6 + AUX | |
| CRL0F4622P6 | 3RA1336-8XB30-1AP6 + AUX | |
| CRL0F4622P61 | 3RA1336-8XB30-1AP6 + AUX | |
| CRL0F4622P6ZAE | NO DIRECT REPLACEMENT | |
| CRL0F4622Q0 | 3RA1336-8XB30-1AV0 + AUX | |
| CRL0F4622Q01 | 3RA1336-8XB30-1AV0 + AUX | |
| CRL0F4622S0 | 3RA1336-8XB30-1AT6 + AUX | |
| CRL0F4622S01 | 3RA1336-8XB30-1AT6 + AUX | |
| CRL0F4622U1 | 3RA1336-8XB30-1AU6 + AUX | |
| CRL0F4722B4 | 3RA1344-8XB30-1BB4 + AUX | |
| CRL0F4722C1 | 3RA1344-8XB30-1AC2 + AUX | |
| CRL0F4722K6 | 3RA1344-8XB30-1AK6 + AUX | |
| CRL0F4722K6Z0E | NO DIRECT REPLACEMENT | |
| CRL0F4722M1 | 3RA1344-8XB30-1AM2 + AUX | |
| CRL0F4722M1ZAE | NO DIRECT REPLACEMENT | |
| CRL0F4722P0 | 3RA1344-8XB30-1AP6 + AUX | |
| CRL0F4722P6 | 3RA1344-8XB30-1AP6 + AUX | |
| CRL0F4722Q0 | 3RA1344-8XB30-1AV0 + AUX | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| CRL0F4722S0 | 3RA1344-8XB30-1AT6 + AUX | |
| CRL0F4722U1 | 3RA1344-8XB30-1AU6 + AUX | |
| CRL0F4822B4 | 3RA1345-8XB30-1BB4 + AUX | |
| CRL0F4822C1 | 3RA1345-8XB30-1AC2 + AUX | |
| CRL0F4822K6 | 3RA1345-8XB30-1AK6 + AUX | |
| CRL0F4822K61 | 3RA1345-8XB30-1AK6 + AUX | |
| CRL0F4822K6Z0E | NO DIRECT REPLACEMENT | |
| CRL0F4822M1 | 3RA1345-8XB30-1AM2 + AUX | |
| CRL0F4822M11 | 3RA1345-8XB30-1AM2 + AUX | |
| CRL0F4822M1ZAE | NO DIRECT REPLACEMENT | |
| CRL0F4822P0 | 3RA1345-8XB30-1AP6 + AUX | |
| CRL0F4822P6 | 3RA1345-8XB30-1AP6 + AUX | |
| CRL0F4822P61 | 3RA1345-8XB30-1AP6 + AUX | |
| CRL0F4822P6ZAE | NO DIRECT REPLACEMENT | |
| CRL0F4822Q0 | 3RA1345-8XB30-1AV0 + AUX | |
| CRL0F4822Q01 | 3RA1345-8XB30-1AV0 + AUX | |
| CRL0F4822S0 | 3RA1345-8XB30-1AT6 + AUX | |
| CRL0F4822S01 | 3RA1345-8XB30-1AT6 + AUX | |
| CRL0F4822U1 | 3RA1345-8XB30-1AU6 + AUX | |
| CRL0F4922K6ES1 | NO DIRECT REPLACEMENT | |
| CRL0F5022C1 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | REPLACE WITH SIRIUS 3R COMPONENTS - SEE INDUSTRIAL CATALOG |
| CRL0F5022K6 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | REPLACE WITH SIRIUS 3R COMPONENTS - SEE INDUSTRIAL CATALOG |
| CRL0F5022K6Z0E | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | REPLACE WITH SIRIUS 3R COMPONENTS - SEE INDUSTRIAL CATALOG |
| CRL0F5022M1 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | REPLACE WITH SIRIUS 3R COMPONENTS - SEE INDUSTRIAL CATALOG |
| CRL0F5022M1ZAE | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | REPLACE WITH SIRIUS 3R COMPONENTS - SEE INDUSTRIAL CATALOG |
| CRL0F5022P0 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | REPLACE WITH SIRIUS 3R COMPONENTS - SEE INDUSTRIAL CATALOG |
| CRL0F5022P6 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | REPLACE WITH SIRIUS 3R COMPONENTS - SEE INDUSTRIAL CATALOG |
| CRL0F5022Q0 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | REPLACE WITH SIRIUS 3R COMPONENTS - SEE INDUSTRIAL CATALOG |
| CRL0F5022S0 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | REPLACE WITH SIRIUS 3R COMPONENTS - SEE INDUSTRIAL CATALOG |
| CRL0F5222K6 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | REPLACE WITH SIRIUS 3R COMPONENTS - SEE INDUSTRIAL CATALOG |
| CRL0F5222K61 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | REPLACE WITH SIRIUS 3R COMPONENTS - SEE INDUSTRIAL CATALOG |
| CRL0F5222K6Z0E | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | REPLACE WITH SIRIUS 3R COMPONENTS - SEE INDUSTRIAL CATALOG |
| CRL0F5222K6Z0E1 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | REPLACE WITH SIRIUS 3R COMPONENTS - SEE INDUSTRIAL CATALOG |
| CRL0F5222M1 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | REPLACE WITH SIRIUS 3R COMPONENTS - SEE INDUSTRIAL CATALOG |
| CRL0F5222M11 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | REPLACE WITH SIRIUS 3R COMPONENTS - SEE INDUSTRIAL CATALOG |
| CRL0F5222M1Z0E | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | REPLACE WITH SIRIUS 3R COMPONENTS - SEE INDUSTRIAL CATALOG |
| CRL0F5222P0 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | REPLACE WITH SIRIUS 3R COMPONENTS - SEE INDUSTRIAL CATALOG |
| CRL0F5222P6 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | REPLACE WITH SIRIUS 3R COMPONENTS - SEE INDUSTRIAL CATALOG |
| CRL0F5222P61 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | REPLACE WITH SIRIUS 3R COMPONENTS - SEE INDUSTRIAL CATALOG |
| CRL0F5222P6Z0E | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | REPLACE WITH SIRIUS 3R COMPONENTS - SEE INDUSTRIAL CATALOG |
| CRL0F5222Q0 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | REPLACE WITH SIRIUS 3R COMPONENTS - SEE INDUSTRIAL CATALOG |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| CRL0F5222Q01 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | REPLACE WITH SIRIUS 3R COMPONENTS - SEE INDUSTRIAL CATALOG |
| CRL0F5222S0 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | REPLACE WITH SIRIUS 3R COMPONENTS - SEE INDUSTRIAL CATALOG |
| CRL0F5222S01 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | REPLACE WITH SIRIUS 3R COMPONENTS - SEE INDUSTRIAL CATALOG |
| CRL0F5222S2 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | REPLACE WITH SIRIUS 3R COMPONENTS - SEE INDUSTRIAL CATALOG |
| CRL0F5422K6 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | REPLACE WITH SIRIUS 3R COMPONENTS - SEE INDUSTRIAL CATALOG |
| CRL0F5422K6Z0E | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | REPLACE WITH SIRIUS 3R COMPONENTS - SEE INDUSTRIAL CATALOG |
| CRL0F5422M1 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | REPLACE WITH SIRIUS 3R COMPONENTS - SEE INDUSTRIAL CATALOG |
| CRL0F5422P0 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | REPLACE WITH SIRIUS 3R COMPONENTS - SEE INDUSTRIAL CATALOG |
| CRL0F5422P6 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | REPLACE WITH SIRIUS 3R COMPONENTS - SEE INDUSTRIAL CATALOG |
| CRL0F5422Q0 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | REPLACE WITH SIRIUS 3R COMPONENTS - SEE INDUSTRIAL CATALOG |
| CRL0F5422S0 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | REPLACE WITH SIRIUS 3R COMPONENTS - SEE INDUSTRIAL CATALOG |
| CRL0F561A8ZTS | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | REPLACE WITH SIRIUS 3R COMPONENTS - SEE INDUSTRIAL CATALOG |
| CRL0F5622K6 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | REPLACE WITH SIRIUS 3R COMPONENTS - SEE INDUSTRIAL CATALOG |
| CRL0F5622K61 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | REPLACE WITH SIRIUS 3R COMPONENTS - SEE INDUSTRIAL CATALOG |
| CRL0F5622M1 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | REPLACE WITH SIRIUS 3R COMPONENTS - SEE INDUSTRIAL CATALOG |
| CRL0F5622M11 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | REPLACE WITH SIRIUS 3R COMPONENTS - SEE INDUSTRIAL CATALOG |
| CRL0F5622P0 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | REPLACE WITH SIRIUS 3R COMPONENTS - SEE INDUSTRIAL CATALOG |
| CRL0F5622P6 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | REPLACE WITH SIRIUS 3R COMPONENTS - SEE INDUSTRIAL CATALOG |
| CRL0F5622P61 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | REPLACE WITH SIRIUS 3R COMPONENTS - SEE INDUSTRIAL CATALOG |
| CRL0F5622Q0 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | REPLACE WITH SIRIUS 3R COMPONENTS - SEE INDUSTRIAL CATALOG |
| CRL0F5622Q01 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | REPLACE WITH SIRIUS 3R COMPONENTS - SEE INDUSTRIAL CATALOG |
| CRL0F5622S0 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | REPLACE WITH SIRIUS 3R COMPONENTS - SEE INDUSTRIAL CATALOG |
| CRL0F5622S01 | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | REPLACE WITH SIRIUS 3R COMPONENTS - SEE INDUSTRIAL CATALOG |
| CRL0F5633K6ZTS | PRODUCT STILL AVAILABLE UNTIL SEPTEMBER 2002 | REPLACE WITH SIRIUS 3R COMPONENTS - SEE INDUSTRIAL CATALOG |
| ENC13VU16 | NO DIRECT REPLACEMENT | |
| ENC1B44 | NO DIRECT REPLACEMENT | |
| ENC1B44T | NO DIRECT REPLACEMENT | |
| ENC1B46T | NO DIRECT REPLACEMENT | |
| ENC1CD1 | NO DIRECT REPLACEMENT | |
| ENC1F44 | NO DIRECT REPLACEMENT | |
| ENC1F44ES01 | NO DIRECT REPLACEMENT | |
| ENC1F44T | NO DIRECT REPLACEMENT | |
| ENC1F46 | NO DIRECT REPLACEMENT | |
| ENC1F46T | NO DIRECT REPLACEMENT | |
| ENC1F48 | NO DIRECT REPLACEMENT | |
| ENC1F48T | NO DIRECT REPLACEMENT | |
| ENC1F50 | NO DIRECT REPLACEMENT | |
| ENC1F52T | NO DIRECT REPLACEMENT | |
| ENC1F56T | NO DIRECT REPLACEMENT | |
| ENC2B48T | NO DIRECT REPLACEMENT | |
| ENC2F46T | NO DIRECT REPLACEMENT | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| ENC2F48T | NO DIRECT REPLACEMENT | |
| ENC2F52T | NO DIRECT REPLACEMENT | |
| ENC2F56T | NO DIRECT REPLACEMENT | |
| ENC4F46T | NO DIRECT REPLACEMENT | |
| ENC4F48T | NO DIRECT REPLACEMENT | |
| ENC4F52T | NO DIRECT REPLACEMENT | |
| ENC4F56T | NO DIRECT REPLACEMENT | |
| ENCFCLM20 | NO DIRECT REPLACEMENT | |
| ENCR3VU13 | NO DIRECT REPLACEMENT | |
| ENCR3VU16 | NO DIRECT REPLACEMENT | |
| ENCRCD1 | NO DIRECT REPLACEMENT | |
| ENCSF46T | NO DIRECT REPLACEMENT | |
| ENCSF48T | NO DIRECT REPLACEMENT | |
| ENCSF52T | NO DIRECT REPLACEMENT | |
| ENCSF56T | NO DIRECT REPLACEMENT | |
| FBE1330-1MB10A4 | 3RA1115-0AD15-1BA4 | 3RA1125-0AD23-1BA4 |
| FBE1330-1MB10B4 | 3RA1115-0AD15-1BB4 | 3RA1125-0AD23-1BB4 |
| FBE1330-1MB10C2 | 3RA1115-0AD15-1AC2 | 3RA1125-0AD23-1AC2 |
| FBE1330-1MB10G4 | 3RA1115-0AD15-1BG4 | 3RA1125-0AD23-1BG4 |
| FBE1330-1MB10K6 | 3RA1115-0AD15-1AK6 | 3RA1125-0AD23-1AK6 |
| FBE1330-1MB10M1 | 3RA1115-0AD15-1AM2 | 3RA1125-0AD23-1AM2 |
| FBE1330-1MB10P6 | 3RA1115-0AD15-1AP6 | 3RA1125-0AD23-1AP6 |
| FBE1330-1MB10Q0 | 3RA1115-0AD15-1AV0 | 3RA1125-0AD23-1AV0 |
| FBE1330-1MB10Q4 | 3RA1115-0AD15-1BP4 | 3RA1125-0AD23-1BP4 |
| FBE1330-1MB10U1 | 3RA1115-0AD15-1AU6 | 3RA1125-0AD23-1AU6 |
| FBE1330-1MB10W4 | 3RA1115-0AD15-1BW4 | 3RA1125-0AD23-1BW4 |
| FBE1330-1MC10A4 | 3RA1115-0CD15-1BA4 OR 3RA1115-0BD15-1BA4 | 3RA1125-0CD23-1BA4 OR 3RA1125-0BD23-1BA4 |
| FBE1330-1MC10B4 | 3RA1115-0CD15-1BB4 OR 3RA1115-0BD15-1BB4 | 3RA1125-0CD23-1BB4 OR 3RA1125-0BD23-1BB4 |
| FBE1330-1MC10C2 | 3RA1115-0CD15-1AC2 OR 3RA1115-0BD15-1AC2 | 3RA1125-0CD23-1AC2 OR 3RA1125-0BD23-1AC2 |
| FBE1330-1MC10G4 | 3RA1115-0CD15-1BG4 OR 3RA1115-0BD15-1BG4 | 3RA1125-0CD23-1BG4 OR 3RA1125-0BD23-1BG4 |
| FBE1330-1MC10K6 | 3RA1115-0CD15-1AK6 OR 3RA1115-0BD15-1AK6 | 3RA1125-0CD23-1AK6 OR 3RA1125-0BD23-1AK6 |
| FBE1330-1MC10M1 | 3RA1115-0CD15-1AM2 OR 3RA1115-0BD15-1AM2 | 3RA1125-0CD23-1AM2 OR 3RA1125-0BD23-1AM2 |
| FBE1330-1MC10P6 | 3RA1115-0CD15-1AP6 OR 3RA1115-0BD15-1AP6 | 3RA1125-0CD23-1AP6 OR 3RA1125-0BD23-1AP6 |
| FBE1330-1MC10Q0 | 3RA1115-0CD15-1AV0 OR 3RA1115-0BD15-1AV0 | 3RA1125-0CD23-1AV0 OR 3RA1125-0BD23-1AV0 |
| FBE1330-1MC10Q4 | 3RA1115-0CD15-1BP4 OR 3RA1115-0BD15-1BP4 | 3RA1125-0CD23-1BP4 OR 3RA1125-0BD23-1BP4 |
| FBE1330-1MC10U1 | 3RA1115-0CD15-1AU6 OR 3RA1115-0BD15-1AU6 | 3RA1125-0CD23-1AU6 OR 3RA1125-0BD23-1AU6 |
| FBE1330-1MC10W4 | 3RA1115-0CD15-1BW4 OR 3RA1115-0BD15-1BW4 | 3RA1125-0CD23-1BW4 OR 3RA1125-0BD23-1BW4 |
| FBE1330-1MD10A4 | 3RA1115-0ED15-1BA4 OR 3RA1115-0DD15-1BA4 | 3RA1125-0ED23-1BA4 OR 3RA1125-0DD23-1BA4 |
| FBE1330-1MD10B4 | 3RA1115-0ED15-1BB4 OR 3RA1115-0DD15-1BB4 | 3RA1125-0ED23-1BB4 OR 3RA1125-0DD23-1BB4 |
| FBE1330-1MD10C2 | 3RA1115-0ED15-1AC2 OR 3RA1115-0DD15-1AC2 | 3RA1125-0ED23-1AC2 OR 3RA1125-0DD23-1AC2 |
| FBE1330-1MD10G4 | 3RA1115-0ED15-1BG4 OR 3RA1115-0DD15-1BG4 | 3RA1125-0ED23-1BG4 OR 3RA1125-0DD23-1BG4 |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| FBE1330-1MD10K6 | 3RA1115-0ED15-1AK6 OR 3RA1115-0DD15-1AK6 | 3RA1125-0ED23-1AK6 OR 3RA1125-0DD23-1AK6 |
| FBE1330-1MD10M1 | 3RA1115-0ED15-1AM2 OR 3RA1115-0DD15-1AM2 | 3RA1125-0ED23-1AM2 OR 3RA1125-0DD23-1AM2 |
| FBE1330-1MD10P6 | 3RA1115-0ED15-1AP6 OR 3RA1115-0DD15-1AP6 | 3RA1125-0ED23-1AP6 OR 3RA1125-0DD23-1AP6 |
| FBE1330-1MD10Q0 | 3RA1115-0ED15-1AV0 OR 3RA1115-0DD15-1AV0 | 3RA1125-0ED23-1AV0 OR 3RA1125-0DD23-1AV0 |
| FBE1330-1MD10Q4 | 3RA1115-0ED15-1BP4 OR 3RA1115-0DD15-1BP4 | 3RA1125-0ED23-1BP4 OR 3RA1125-0DD23-1BP4 |
| FBE1330-1MD10U1 | 3RA1115-0ED15-1AU6 OR 3RA1115-0DD15-1AU6 | 3RA1125-0ED23-1AU6 OR 3RA1125-0DD23-1AU6 |
| FBE1330-1MD10W4 | 3RA1115-0ED15-1BW4 OR 3RA1115-0DD15-1BW4 | 3RA1125-0ED23-1BW4 OR 3RA1125-0DD23-1BW4 |
| FBE1330-1ME10A4 | 3RA1115-0GD15-1BA4 OR 3RA1115-0FD15-1BA4 | 3RA1125-0GD23-1BA4 OR 3RA1125-0FD23-1BA4 |
| FBE1330-1ME10B4 | 3RA1115-0GD15-1BB4 OR 3RA1115-0FD15-1BB4 | 3RA1125-0GD23-1BB4 OR 3RA1125-0FD23-1BB4 |
| FBE1330-1ME10C2 | 3RA1115-0GD15-1AC2 OR 3RA1115-0FD15-1AC2 | 3RA1125-0GD23-1AC2 OR 3RA1125-0FD23-1AC2 |
| FBE1330-1ME10G4 | 3RA1115-0GD15-1BG4 OR 3RA1115-0FD15-1BG4 | 3RA1125-0GD23-1BG4 OR 3RA1125-0FD23-1BG4 |
| FBE1330-1ME10K6 | 3RA1115-0GD15-1AK6 OR 3RA1115-0FD15-1AK6 | 3RA1125-0GD23-1AK6 OR 3RA1125-0FD23-1AK6 |
| FBE1330-1ME10M1 | 3RA1115-0GD15-1AM2 OR 3RA1115-0FD15-1AM2 | 3RA1125-0GD23-1AM2 OR 3RA1125-0FD23-1AM2 |
| FBE1330-1ME10P6 | 3RA1115-0GD15-1AP6 OR 3RA1115-0FD15-1AP6 | 3RA1125-0GD23-1AP6 OR 3RA1125-0FD23-1AP6 |
| FBE1330-1ME10Q0 | 3RA1115-0GD15-1AV0 OR 3RA1115-0FD15-1AV0 | 3RA1125-0GD23-1AV0 OR 3RA1125-0FD23-1AV0 |
| FBE1330-1ME10Q4 | 3RA1115-0GD15-1BP4 OR 3RA1115-0FD15-1BP4 | 3RA1125-0GD23-1BP4 OR 3RA1125-0FD23-1BP4 |
| FBE1330-1ME10U1 | 3RA1115-0GD15-1AU6 OR 3RA1115-0FD15-1AU6 | 3RA1125-0GD23-1AU6 OR 3RA1125-0FD23-1AU6 |
| FBE1330-1ME10W4 | 3RA1115-0GD15-1BW4 OR 3RA1115-0FD15-1BW4 | 3RA1125-0GD23-1BW4 OR 3RA1125-0FD23-1BW4 |
| FBE1330-1MF10A4 | 3RA1115-0JD15-1BA4 OR 3RA1115-0HD15-1BA4 | 3RA1125-0JD23-1BA4 OR 3RA1125-0HD23-1BA4 |
| FBE1330-1MF10B4 | 3RA1115-0JD15-1BB4 OR 3RA1115-0HD15-1BB4 | 3RA1125-0JD23-1BB4 OR 3RA1125-0HD23-1BB4 |
| FBE1330-1MF10C2 | 3RA1115-0JD15-1AC2 OR 3RA1115-0HD15-1AC2 | 3RA1125-0JD23-1AC2 OR 3RA1125-0HD23-1AC2 |
| FBE1330-1MF10G4 | 3RA1115-0JD15-1BG4 OR 3RA1115-0HD15-1BG4 | 3RA1125-0JD23-1BG4 OR 3RA1125-0HD23-1BG4 |
| FBE1330-1MF10K6 | 3RA1115-0JD15-1AK6 OR 3RA1115-0HD15-1AK6 | 3RA1125-0JD23-1AK6 OR 3RA1125-0HD23-1AK6 |
| FBE1330-1MF10M1 | 3RA1115-0JD15-1AM2 OR 3RA1115-0HD15-1AM2 | 3RA1125-0JD23-1AM2 OR 3RA1125-0HD23-1AM2 |
| FBE1330-1MF10P6 | 3RA1115-0JD15-1AP6 OR 3RA1115-0HD15-1AP6 | 3RA1125-0JD23-1AP6 OR 3RA1125-0HD23-1AP6 |
| FBE1330-1MF10Q0 | 3RA1115-0JD15-1AV0 OR 3RA1115-0HD15-1AV0 | 3RA1125-0JD23-1AV0 OR 3RA1125-0HD23-1AV0 |
| FBE1330-1MF10Q4 | 3RA1115-0JD15-1BP4 OR 3RA1115-0HD15-1BP4 | 3RA1125-0JD23-1BP4 OR 3RA1125-0HD23-1BP4 |
| FBE1330-1MF10U1 | 3RA1115-0JD15-1AU6 OR 3RA1115-0HD15-1AU6 | 3RA1125-0JD23-1AU6 OR 3RA1125-0HD23-1AU6 |
| FBE1330-1MF10W4 | 3RA1115-0JD15-1BW4 OR 3RA1115-0HD15-1BW4 | 3RA1125-0JD23-1BW4 OR 3RA1125-0HD23-1BW4 |
| FBE1334-1MG10A4 | 3RA1115-1AD15-1BA4 OR 3RA1115-0KD15-1BA4 | 3RA1125-1AD23-1BA4 OR 3RA1125-0KD23-1BA4 |
| FBE1334-1MG10B4 | 3RA1115-1AD15-1BB4 OR 3RA1115-0KD15-1BB4 | 3RA1125-1AD23-1BB4 OR 3RA1125-0KD23-1BB4 |
| FBE1334-1MG10C2 | 3RA1115-1AD15-1AC2 OR 3RA1115-0KD15-1AC2 | 3RA1125-1AD23-1AC2 OR 3RA1125-0KD23-1AC2 |
| FBE1334-1MG10G4 | 3RA1115-1AD15-1BG4 OR 3RA1115-0KD15-1BG4 | 3RA1125-1AD23-1BG4 OR 3RA1125-0KD23-1BG4 |
| FBE1334-1MG10K6 | 3RA1115-1AD15-1AK6 OR 3RA1115-0KD15-1AK6 | 3RA1125-1AD23-1AK6 OR 3RA1125-0KD23-1AK6 |
| FBE1334-1MG10M1 | 3RA1115-1AD15-1AM2 OR 3RA1115-0KD15-1AM2 | 3RA1125-1AD23-1AM2 OR 3RA1125-0KD23-1AM2 |
| FBE1334-1MG10P6 | 3RA1115-1AD15-1AP6 OR 3RA1115-0KD15-1AP6 | 3RA1125-1AD23-1AP6 OR 3RA1125-0KD23-1AP6 |
| FBE1334-1MG10Q0 | 3RA1115-1AD15-1AV0 OR 3RA1115-0KD15-1AV0 | 3RA1125-1AD23-1AV0 OR 3RA1125-0KD23-1AV0 |
| FBE1334-1MG10Q4 | 3RA1115-1AD15-1BP4 OR 3RA1115-0KD15-1BP4 | 3RA1125-1AD23-1BP4 OR 3RA1125-0KD23-1BP4 |
| FBE1334-1MG10U1 | 3RA1115-1AD15-1AU6 OR 3RA1115-0KD15-1AU6 | 3RA1125-1AD23-1AU6 OR 3RA1125-0KD23-1AU6 |
| FBE1334-1MG10W4 | 3RA1115-1AD15-1BW4 OR 3RA1115-0KD15-1BW4 | 3RA1125-1AD23-1BW4 OR 3RA1125-0KD23-1BW4 |
| FBE1334-1MH10A4 | 3RA1115-1CD15-1BA4 OR 3RA1115-1BD15-1BA4 | 3RA1125-1CD23-1BA4 OR 3RA1125-1BD23-1BA4 |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| FBE1334-1MH10B4 | 3RA1115-1CD15-1BB4 OR 3RA1115-1BD15-1BB4 | 3RA1125-1CD23-1BB4 OR 3RA1125-1BD23-1BB4 |
| FBE1334-1MH10C2 | 3RA1115-1CD15-1AC2 OR 3RA1115-1BD15-1AC2 | 3RA1125-1CD23-1AC2 OR 3RA1125-1BD23-1AC2 |
| FBE1334-1MH10G4 | 3RA1115-1CD15-1BG4 OR 3RA1115-1BD15-1BG4 | 3RA1125-1CD23-1BG4 OR 3RA1125-1BD23-1BG4 |
| FBE1334-1MH10K6 | 3RA1115-1CD15-1AK6 OR 3RA1115-1BD15-1AK6 | 3RA1125-1CD23-1AK6 OR 3RA1125-1BD23-1AK6 |
| FBE1334-1MH10M1 | 3RA1115-1CD15-1AM2 OR 3RA1115-1BD15-1AM2 | 3RA1125-1CD23-1AM2 OR 3RA1125-1BD23-1AM2 |
| FBE1334-1MH10P6 | 3RA1115-1CD15-1AP6 OR 3RA1115-1BD15-1AP6 | 3RA1125-1CD23-1AP6 OR 3RA1125-1BD23-1AP6 |
| FBE1334-1MH10Q0 | 3RA1115-1CD15-1AV0 OR 3RA1115-1BD15-1AV0 | 3RA1125-1CD23-1AV0 OR 3RA1125-1BD23-1AV0 |
| FBE1334-1MH10Q4 | 3RA1115-1CD15-1BP4 OR 3RA1115-1BD15-1BP4 | 3RA1125-1CD23-1BP4 OR 3RA1125-1BD23-1BP4 |
| FBE1334-1MH10U1 | 3RA1115-1CD15-1AU6 OR 3RA1115-1BD15-1AU6 | 3RA1125-1CD23-1AU6 OR 3RA1125-1BD23-1AU6 |
| FBE1334-1MH10W4 | 3RA1115-1CD15-1BW4 OR 3RA1115-1BD15-1BW4 | 3RA1125-1CD23-1BW4 OR 3RA1125-1BD23-1BW4 |
| FBE1334-1MJ10A4 | 3RA1115-1ED15-1BA4 OR 3RA1115-1DD15-1BA4 | 3RA1125-1ED23-1BA4 OR 3RA1125-1DD23-1BA4 |
| FBE1334-1MJ10B4 | 3RA1115-1ED15-1BB4 OR 3RA1115-1DD15-1BB4 | 3RA1125-1ED23-1BB4 OR 3RA1125-1DD23-1BB4 |
| FBE1334-1MJ10C2 | 3RA1115-1ED15-1AC2 OR 3RA1115-1DD15-1AC2 | 3RA1125-1ED23-1AC2 OR 3RA1125-1DD23-1AC2 |
| FBE1334-1MJ10G4 | 3RA1115-1ED15-1BG4 OR 3RA1115-1DD15-1BG4 | 3RA1125-1ED23-1BG4 OR 3RA1125-1DD23-1BG4 |
| FBE1334-1MJ10K6 | 3RA1115-1ED15-1AK6 OR 3RA1115-1DD15-1AK6 | 3RA1125-1ED23-1AK6 OR 3RA1125-1DD23-1AK6 |
| FBE1334-1MJ10M1 | 3RA1115-1ED15-1AM2 OR 3RA1115-1DD15-1AM2 | 3RA1125-1ED23-1AM2 OR 3RA1125-1DD23-1AM2 |
| FBE1334-1MJ10P6 | 3RA1115-1ED15-1AP6 OR 3RA1115-1DD15-1AP6 | 3RA1125-1ED23-1AP6 OR 3RA1125-1DD23-1AP6 |
| FBE1334-1MJ10Q0 | 3RA1115-1ED15-1AV0 OR 3RA1115-1DD15-1AV0 | 3RA1125-1ED23-1AV0 OR 3RA1125-1DD23-1AV0 |
| FBE1334-1MJ10Q4 | 3RA1115-1ED15-1BP4 OR 3RA1115-1DD15-1BP4 | 3RA1125-1ED23-1BP4 OR 3RA1125-1DD23-1BP4 |
| FBE1334-1MJ10U1 | 3RA1115-1ED15-1AU6 OR 3RA1115-1DD15-1AU6 | 3RA1125-1ED23-1AU6 OR 3RA1125-1DD23-1AU6 |
| FBE1334-1MJ10W4 | 3RA1115-1ED15-1BW4 OR 3RA1115-1DD15-1BW4 | 3RA1125-1ED23-1BW4 OR 3RA1125-1DD23-1BW4 |
| FBE1334-1MK10A4 | 3RA1115-1GD15-1BA4 OR 3RA1115-1FD15-1BA4 | 3RA1125-1GD23-1BA4 OR 3RA1125-1FD23-1BA4 |
| FBE1334-1MK10B4 | 3RA1115-1GD15-1BB4 OR 3RA1115-1FD15-1BB4 | 3RA1125-1GD23-1BB4 OR 3RA1125-1FD23-1BB4 |
| FBE1334-1MK10C2 | 3RA1115-1GD15-1AC2 OR 3RA1115-1FD15-1AC2 | 3RA1125-1GD23-1AC2 OR 3RA1125-1FD23-1AC2 |
| FBE1334-1MK10G4 | 3RA1115-1GD15-1BG4 OR 3RA1115-1FD15-1BG4 | 3RA1125-1GD23-1BG4 OR 3RA1125-1FD23-1BG4 |
| FBE1334-1MK10K6 | 3RA1115-1GD15-1AK6 OR 3RA1115-1FD15-1AK6 | 3RA1125-1GD23-1AK6 OR 3RA1125-1FD23-1AK6 |
| FBE1334-1MK10M1 | 3RA1115-1GD15-1AM2 OR 3RA1115-1FD15-1AM2 | 3RA1125-1GD23-1AM2 OR 3RA1125-1FD23-1AM2 |
| FBE1334-1MK10P6 | 3RA1115-1GD15-1AP6 OR 3RA1115-1FD15-1AP6 | 3RA1125-1GD23-1AP6 OR 3RA1125-1FD23-1AP6 |
| FBE1334-1MK10Q0 | 3RA1115-1GD15-1AV0 OR 3RA1115-1FD15-1AV0 | 3RA1125-1GD23-1AV0 OR 3RA1125-1FD23-1AV0 |
| FBE1334-1MK10Q4 | 3RA1115-1GD15-1BP4 OR 3RA1115-1FD15-1BP4 | 3RA1125-1GD23-1BP4 OR 3RA1125-1FD23-1BP4 |
| FBE1334-1MK10U1 | 3RA1115-1GD15-1AU6 OR 3RA1115-1FD15-1AU6 | 3RA1125-1GD23-1AU6 OR 3RA1125-1FD23-1AU6 |
| FBE1334-1MK10W4 | 3RA1115-1GD15-1BW4 OR 3RA1115-1FD15-1BW4 | 3RA1125-1GD23-1BW4 OR 3RA1125-1FD23-1BW4 |
| FBE1334-1ML10A4 | 3RA1125-1JD24-1BA4 OR 3RA1115-1HD16-1BA4 | |
| FBE1334-1ML10B4 | 3RA1125-1JD24-1BB4 OR 3RA1115-1HD16-1BB4 | |
| FBE1334-1ML10C2 | 3RA1125-1JD24-1AC2 OR 3RA1115-1HD16-1AC2 | |
| FBE1334-1ML10G4 | 3RA1125-1JD24-1BG4 OR 3RA1115-1HD16-1BG4 | |
| FBE1334-1ML10K6 | 3RA1125-1JD24-1AK6 OR 3RA1115-1HD16-1AK6 | |
| FBE1334-1ML10M1 | 3RA1125-1JD24-1AM2 OR 3RA1115-1HD16-1AM2 | |
| FBE1334-1ML10P6 | 3RA1125-1JD24-1AP6 OR 3RA1115-1HD16-1AP6 | |
| FBE1334-1ML10Q0 | 3RA1125-1JD24-1AV0 OR 3RA1115-1HD16-1AV0 | |
| FBE1334-1ML10Q4 | 3RA1125-1JD24-1BP4 OR 3RA1115-1HD16-1BP4 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| FBE1334-1ML10U1 | 3RA1125-1JD24-1AU6 OR 3RA1115-1HD16-1AU6 | |
| FBE1334-1ML10W4 | 3RA1125-1JD24-1BW4 OR 3RA1115-1HD16-1BW4 | |
| FBE1334-1MM10A4 | 3RA1125-4AD25-1BA4 OR 3RA1125-1KD23-1BA4 | |
| FBE1334-1MM10B4 | 3RA1125-4AD25-1BB4 OR 3RA1125-1KD23-1BB4 | |
| FBE1334-1MM10C2 | 3RA1125-4AD25-1AC2 OR 3RA1125-1KD23-1AC2 | |
| FBE1334-1MM10G4 | 3RA1125-4AD25-1BG4 OR 3RA1125-1KD23-1BG4 | |
| FBE1334-1MM10K6 | 3RA1125-4AD25-1AK6 OR 3RA1125-1KD23-1AK6 | |
| FBE1334-1MM10M1 | 3RA1125-4AD25-1AM2 OR 3RA1125-1KD23-1AM2 | |
| FBE1334-1MM10P6 | 3RA1125-4AD25-1AP6 OR 3RA1125-1KD23-1AP6 | |
| FBE1334-1MM10Q0 | 3RA1125-4AD25-1AV0 OR 3RA1125-1KD23-1AV0 | |
| FBE1334-1MM10Q4 | 3RA1125-4AD25-1BP4 OR 3RA1125-1KD23-1BP4 | |
| FBE1334-1MM10U1 | 3RA1125-4AD25-1AU6 OR 3RA1125-1KD23-1AU6 | |
| FBE1334-1MM10W4 | 3RA1125-4AD25-1BW4 OR 3RA1125-1KD23-1BW4 | |
| FBE1634-1MG10A4 | 3RA1115-1AD15-1BA4 OR 3RA1115-0KD15-1BA4 | 3RA1125-1AD23-1BA4 OR 3RA1125-0KD23-1BA4 |
| FBE1634-1MG10B4 | 3RA1115-1AD15-1BB4 OR 3RA1115-0KD15-1BB4 | 3RA1125-1AD23-1BB4 OR 3RA1125-0KD23-1BB4 |
| FBE1634-1MG10C2 | 3RA1115-1AD15-1AC2 OR 3RA1115-0KD15-1AC2 | 3RA1125-1AD23-1AC2 OR 3RA1125-0KD23-1AC2 |
| FBE1634-1MG10G4 | 3RA1115-1AD15-1BG4 OR 3RA1115-0KD15-1BG4 | 3RA1125-1AD23-1BG4 OR 3RA1125-0KD23-1BG4 |
| FBE1634-1MG10K6 | 3RA1115-1AD15-1AK6 OR 3RA1115-0KD15-1AK6 | 3RA1125-1AD23-1AK6 OR 3RA1125-0KD23-1AK6 |
| FBE1634-1MG10M1 | 3RA1115-1AD15-1AM2 OR 3RA1115-0KD15-1AM2 | 3RA1125-1AD23-1AM2 OR 3RA1125-0KD23-1AM2 |
| FBE1634-1MG10P6 | 3RA1115-1AD15-1AP6 OR 3RA1115-0KD15-1AP6 | 3RA1125-1AD23-1AP6 OR 3RA1125-0KD23-1AP6 |
| FBE1634-1MG10Q0 | 3RA1115-1AD15-1AV0 OR 3RA1115-0KD15-1AV0 | 3RA1125-1AD23-1AV0 OR 3RA1125-0KD23-1AV0 |
| FBE1634-1MG10Q4 | 3RA1115-1AD15-1BP4 OR 3RA1115-0KD15-1BP4 | 3RA1125-1AD23-1BP4 OR 3RA1125-0KD23-1BP4 |
| FBE1634-1MG10U1 | 3RA1115-1AD15-1AU6 OR 3RA1115-0KD15-1AU6 | 3RA1125-1AD23-1AU6 OR 3RA1125-0KD23-1AU6 |
| FBE1634-1MG10W4 | 3RA1115-1AD15-1BW4 OR 3RA1115-0KD15-1BW4 | 3RA1125-1AD23-1BW4 OR 3RA1125-0KD23-1BW4 |
| FBE1634-1MH10A4 | 3RA1115-1CD15-1BA4 OR 3RA1115-1BD15-1BA4 | 3RA1125-1CD23-1BA4 OR 3RA1125-1BD23-1BA4 |
| FBE1634-1MH10B4 | 3RA1115-1CD15-1BB4 OR 3RA1115-1BD15-1BB4 | 3RA1125-1CD23-1BB4 OR 3RA1125-1BD23-1BB4 |
| FBE1634-1MH10C2 | 3RA1115-1CD15-1AC2 OR 3RA1115-1BD15-1AC2 | 3RA1125-1CD23-1AC2 OR 3RA1125-1BD23-1AC2 |
| FBE1634-1MH10G4 | 3RA1115-1CD15-1BG4 OR 3RA1115-1BD15-1BG4 | 3RA1125-1CD23-1BG4 OR 3RA1125-1BD23-1BG4 |
| FBE1634-1MH10K6 | 3RA1115-1CD15-1AK6 OR 3RA1115-1BD15-1AK6 | 3RA1125-1CD23-1AK6 OR 3RA1125-1BD23-1AK6 |
| FBE1634-1MH10M1 | 3RA1115-1CD15-1AM2 OR 3RA1115-1BD15-1AM2 | 3RA1125-1CD23-1AM2 OR 3RA1125-1BD23-1AM2 |
| FBE1634-1MH10P6 | 3RA1115-1CD15-1AP6 OR 3RA1115-1BD15-1AP6 | 3RA1125-1CD23-1AP6 OR 3RA1125-1BD23-1AP6 |
| FBE1634-1MH10Q0 | 3RA1115-1CD15-1AV0 OR 3RA1115-1BD15-1AV0 | 3RA1125-1CD23-1AV0 OR 3RA1125-1BD23-1AV0 |
| FBE1634-1MH10Q4 | 3RA1115-1CD15-1BP4 OR 3RA1115-1BD15-1BP4 | 3RA1125-1CD23-1BP4 OR 3RA1125-1BD23-1BP4 |
| FBE1634-1MH10U1 | 3RA1115-1CD15-1AU6 OR 3RA1115-1BD15-1AU6 | 3RA1125-1CD23-1AU6 OR 3RA1125-1BD23-1AU6 |
| FBE1634-1MH10W4 | 3RA1115-1CD15-1BW4 OR 3RA1115-1BD15-1BW4 | 3RA1125-1CD23-1BW4 OR 3RA1125-1BD23-1BW4 |
| FBE1634-1MJ10A4 | 3RA1115-1ED15-1BA4 OR 3RA1115-1DD15-1BA4 | 3RA1125-1ED23-1BA4 OR 3RA1125-1DD23-1BA4 |
| FBE1634-1MJ10B4 | 3RA1115-1ED15-1BB4 OR 3RA1115-1DD15-1BB4 | 3RA1125-1ED23-1BB4 OR 3RA1125-1DD23-1BB4 |
| FBE1634-1MJ10C2 | 3RA1115-1ED15-1AC2 OR 3RA1115-1DD15-1AC2 | 3RA1125-1ED23-1AC2 OR 3RA1125-1DD23-1AC2 |
| FBE1634-1MJ10G4 | 3RA1115-1ED15-1BG4 OR 3RA1115-1DD15-1BG4 | 3RA1125-1ED23-1BG4 OR 3RA1125-1DD23-1BG4 |
| FBE1634-1MJ10K6 | 3RA1115-1ED15-1AK6 OR 3RA1115-1DD15-1AK6 | 3RA1125-1ED23-1AK6 OR 3RA1125-1DD23-1AK6 |
| FBE1634-1MJ10M1 | 3RA1115-1ED15-1AM2 OR 3RA1115-1DD15-1AM2 | 3RA1125-1ED23-1AM2 OR 3RA1125-1DD23-1AM2 |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| FBE1634-1MJ10P6 | 3RA1115-1ED15-1AP6 OR 3RA1115-1DD15-1AP6 | 3RA1125-1ED23-1AP6 OR 3RA1125-1DD23-1AP6 |
| FBE1634-1MJ10Q0 | 3RA1115-1ED15-1AV0 OR 3RA1115-1DD15-1AV0 | 3RA1125-1ED23-1AV0 OR 3RA1125-1DD23-1AV0 |
| FBE1634-1MJ10Q4 | 3RA1115-1ED15-1BP4 OR 3RA1115-1DD15-1BP4 | 3RA1125-1ED23-1BP4 OR 3RA1125-1DD23-1BP4 |
| FBE1634-1MJ10U1 | 3RA1115-1ED15-1AU6 OR 3RA1115-1DD15-1AU6 | 3RA1125-1ED23-1AU6 OR 3RA1125-1DD23-1AU6 |
| FBE1634-1MJ10W4 | 3RA1115-1ED15-1BW4 OR 3RA1115-1DD15-1BW4 | 3RA1125-1ED23-1BW4 OR 3RA1125-1DD23-1BW4 |
| FBE1634-1MK10A4 | 3RA1115-1GD15-1BA4 OR 3RA1115-1FD15-1BA4 | 3RA1125-1GD23-1BA4 OR 3RA1125-1FD23-1BA4 |
| FBE1634-1MK10B4 | 3RA1115-1GD15-1BB4 OR 3RA1115-1FD15-1BB4 | 3RA1125-1GD23-1BB4 OR 3RA1125-1FD23-1BB4 |
| FBE1634-1MK10C2 | 3RA1115-1GD15-1AC2 OR 3RA1115-1FD15-1AC2 | 3RA1125-1GD23-1AC2 OR 3RA1125-1FD23-1AC2 |
| FBE1634-1MK10G4 | 3RA1115-1GD15-1BG4 OR 3RA1115-1FD15-1BG4 | 3RA1125-1GD23-1BG4 OR 3RA1125-1FD23-1BG4 |
| FBE1634-1MK10K6 | 3RA1115-1GD15-1AK6 OR 3RA1115-1FD15-1AK6 | 3RA1125-1GD23-1AK6 OR 3RA1125-1FD23-1AK6 |
| FBE1634-1MK10M1 | 3RA1115-1GD15-1AM2 OR 3RA1115-1FD15-1AM2 | 3RA1125-1GD23-1AM2 OR 3RA1125-1FD23-1AM2 |
| FBE1634-1MK10P6 | 3RA1115-1GD15-1AP6 OR 3RA1115-1FD15-1AP6 | 3RA1125-1GD23-1AP6 OR 3RA1125-1FD23-1AP6 |
| FBE1634-1MK10Q0 | 3RA1115-1GD15-1AV0 OR 3RA1115-1FD15-1AV0 | 3RA1125-1GD23-1AV0 OR 3RA1125-1FD23-1AV0 |
| FBE1634-1MK10Q4 | 3RA1115-1GD15-1BP4 OR 3RA1115-1FD15-1BP4 | 3RA1125-1GD23-1BP4 OR 3RA1125-1FD23-1BP4 |
| FBE1634-1MK10U1 | 3RA1115-1GD15-1AU6 OR 3RA1115-1FD15-1AU6 | 3RA1125-1GD23-1AU6 OR 3RA1125-1FD23-1AU6 |
| FBE1634-1MK10W4 | 3RA1115-1GD15-1BW4 OR 3RA1115-1FD15-1BW4 | 3RA1125-1GD23-1BW4 OR 3RA1125-1FD23-1BW4 |
| FBE1634-1ML10A4 | 3RA1125-1JD24-1BA4 OR 3RA1115-1HD16-1BA4 | |
| FBE1634-1ML10B4 | 3RA1125-1JD24-1BB4 OR 3RA1115-1HD16-1BB4 | |
| FBE1634-1ML10C2 | 3RA1125-1JD24-1AC2 OR 3RA1115-1HD16-1AC2 | |
| FBE1634-1ML10G4 | 3RA1125-1JD24-1BG4 OR 3RA1115-1HD16-1BG4 | |
| FBE1634-1ML10K6 | 3RA1125-1JD24-1AK6 OR 3RA1115-1HD16-1AK6 | |
| FBE1634-1ML10M1 | 3RA1125-1JD24-1AM2 OR 3RA1115-1HD16-1AM2 | |
| FBE1634-1ML10P6 | 3RA1125-1JD24-1AP6 OR 3RA1115-1HD16-1AP6 | |
| FBE1634-1ML10Q0 | 3RA1125-1JD24-1AV0 OR 3RA1115-1HD16-1AV0 | |
| FBE1634-1ML10Q4 | 3RA1125-1JD24-1BP4 OR 3RA1115-1HD16-1BP4 | |
| FBE1634-1ML10U1 | 3RA1125-1JD24-1AU6 OR 3RA1115-1HD16-1AU6 | |
| FBE1634-1ML10W4 | 3RA1125-1JD24-1BW4 OR 3RA1115-1HD16-1BW4 | |
| FBE1634-1MM10A4 | 3RA1125-4AD25-1BA4 OR 3RA1125-1KD23-1BA4 | |
| FBE1634-1MM10B4 | 3RA1125-4AD25-1BB4 OR 3RA1125-1KD23-1BB4 | |
| FBE1634-1MM10C2 | 3RA1125-4AD25-1AC2 OR 3RA1125-1KD23-1AC2 | |
| FBE1634-1MM10G4 | 3RA1125-4AD25-1BG4 OR 3RA1125-1KD23-1BG4 | |
| FBE1634-1MM10K6 | 3RA1125-4AD25-1AK6 OR 3RA1125-1KD23-1AK6 | |
| FBE1634-1MM10M1 | 3RA1125-4AD25-1AM2 OR 3RA1125-1KD23-1AM2 | |
| FBE1634-1MM10P6 | 3RA1125-4AD25-1AP6 OR 3RA1125-1KD23-1AP6 | |
| FBE1634-1MM10Q0 | 3RA1125-4AD25-1AV0 OR 3RA1125-1KD23-1AV0 | |
| FBE1634-1MM10Q4 | 3RA1125-4AD25-1BP4 OR 3RA1125-1KD23-1BP4 | |
| FBE1634-1MM10U1 | 3RA1125-4AD25-1AU6 OR 3RA1125-1KD23-1AU6 | |
| FBE1634-1MM10W4 | 3RA1125-4AD25-1BW4 OR 3RA1125-1KD23-1BW4 | |
| FBE1634-1MN10A4 | 3RA1125-4BD26-1BA4 | |
| FBE1634-1MN10B4 | 3RA1125-4BD26-1BB4 | |
| FBE1634-1MN10C2 | 3RA1125-4BD26-1AC2 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| FBE1634-1MN10G4 | 3RA1125-4BD26-1BG4 | |
| FBE1634-1MN10K6 | 3RA1125-4BD26-1AK6 | |
| FBE1634-1MN10M1 | 3RA1125-4BD26-1AM2 | |
| FBE1634-1MN10P6 | 3RA1125-4BD26-1AP6 | |
| FBE1634-1MN10Q0 | 3RA1125-4BD26-1AV0 | |
| FBE1634-1MN10Q4 | 3RA1125-4BD26-1BP4 | |
| FBE1634-1MN10U1 | 3RA1125-4BD26-1AU6 | |
| FBE1634-1MN10W4 | 3RA1125-4BD26-1BW4 | |
| FBE1634-1MP10A4 | 3RA1135-4ED34-1BA4 | |
| FBE1634-1MP10B4 | 3RA1135-4ED34-1BB4 | |
| FBE1634-1MP10C2 | 3RA1135-4ED34-1AC2 | |
| FBE1634-1MP10G4 | 3RA1135-4ED34-1BG4 | |
| FBE1634-1MP10K6 | 3RA1135-4ED34-1AK6 | |
| FBE1634-1MP10M1 | 3RA1135-4ED34-1AM2 | |
| FBE1634-1MP10P6 | 3RA1135-4ED34-1AP6 | |
| FBE1634-1MP10Q0 | 3RA1135-4ED34-1AV0 | |
| FBE1634-1MP10Q4 | 3RA1135-4ED34-1BP4 | |
| FBE1634-1MP10U1 | 3RA1135-4ED34-1AU6 | |
| FBE1634-1MP10W4 | 3RA1135-4ED34-1BW4 | |
| FBE9138-2AB10 | NO DIRECT REPLACEMENT | |
| FBEE634-1MM10P6 | NO DIRECT REPLACEMENT | |
| FBER330-1MB10A4 | 3RA1215-0AD15-1BA4 | 3RA1225-0AD23-1BA4 |
| FBER330-1MB10B4 | 3RA1215-0AD15-1BB4 | 3RA1225-0AD23-1BB4 |
| FBER330-1MB10C2 | 3RA1215-0AD15-1AC2 | 3RA1225-0AD23-1AC2 |
| FBER330-1MB10G4 | 3RA1215-0AD15-1BG4 | 3RA1225-0AD23-1BG4 |
| FBER330-1MB10K6 | 3RA1215-0AD15-1AK6 | 3RA1225-0AD23-1AK6 |
| FBER330-1MB10M1 | 3RA1215-0AD15-1AM2 | 3RA1225-0AD23-1AM2 |
| FBER330-1MB10P6 | 3RA1215-0AD15-1AP6 | 3RA1225-0AD23-1AP6 |
| FBER330-1MB10Q0 | 3RA1215-0AD15-1AV0 | 3RA1225-0AD23-1AV0 |
| FBER330-1MB10Q4 | 3RA1215-0AD15-1BP4 | 3RA1225-0AD23-1BP4 |
| FBER330-1MB10U1 | 3RA1215-0AD15-1AU6 | 3RA1225-0AD23-1AU6 |
| FBER330-1MB10W4 | 3RA1215-0AD15-1BW4 | 3RA1225-0AD23-1BW4 |
| FBER330-1MC10A4 | 3RA1215-0CD15-1BA4 OR 3RA1215-0BD15-1BA4 | 3RA1225-0CD23-1BA4 OR 3RA1225-0BD23-1BA4 |
| FBER330-1MC10B4 | 3RA1215-0CD15-1BB4 OR 3RA1215-0BD15-1BB4 | 3RA1225-0CD23-1BB4 OR 3RA1225-0BD23-1BB4 |
| FBER330-1MC10C2 | 3RA1215-0CD15-1AC2 OR 3RA1215-0BD15-1AC2 | 3RA1225-0CD23-1AC2 OR 3RA1225-0BD23-1AC2 |
| FBER330-1MC10G4 | 3RA1215-0CD15-1BG4 OR 3RA1215-0BD15-1BG4 | 3RA1225-0CD23-1BG4 OR 3RA1225-0BD23-1BG4 |
| FBER330-1MC10K6 | 3RA1215-0CD15-1AK6 OR 3RA1215-0BD15-1AK6 | 3RA1225-0CD23-1AK6 OR 3RA1225-0BD23-1AK6 |
| FBER330-1MC10M1 | 3RA1215-0CD15-1AM2 OR 3RA1215-0BD15-1AM2 | 3RA1225-0CD23-1AM2 OR 3RA1225-0BD23-1AM2 |
| FBER330-1MC10P6 | 3RA1215-0CD15-1AP6 OR 3RA1215-0BD15-1AP6 | 3RA1225-0CD23-1AP6 OR 3RA1225-0BD23-1AP6 |
| FBER330-1MC10Q0 | 3RA1215-0CD15-1AV0 OR 3RA1215-0BD15-1AV0 | 3RA1225-0CD23-1AV0 OR 3RA1225-0BD23-1AV0 |
| FBER330-1MC10Q4 | 3RA1215-0CD15-1BP4 OR 3RA1215-0BD15-1BP4 | 3RA1225-0CD23-1BP4 OR 3RA1225-0BD23-1BP4 |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| FBER330-1MC10U1 | 3RA1215-0CD15-1AU6 OR 3RA1215-0BD15-1AU6 | 3RA1225-0CD23-1AU6 OR 3RA1225-0BD23-1AU6 |
| FBER330-1MC10W4 | 3RA1215-0CD15-1BW4 OR 3RA1215-0BD15-1BW4 | 3RA1225-0CD23-1BW4 OR 3RA1225-0BD23-1BW4 |
| FBER330-1MD10A4 | 3RA1215-0ED15-1BA4 OR 3RA1215-0DD15-1BA4 | 3RA1225-0ED23-1BA4 OR 3RA1225-0DD23-1BA4 |
| FBER330-1MD10B4 | 3RA1215-0ED15-1BB4 OR 3RA1215-0DD15-1BB4 | 3RA1225-0ED23-1BB4 OR 3RA1225-0DD23-1BB4 |
| FBER330-1MD10C2 | 3RA1215-0ED15-1AC2 OR 3RA1215-0DD15-1AC2 | 3RA1225-0ED23-1AC2 OR 3RA1225-0DD23-1AC2 |
| FBER330-1MD10G4 | 3RA1215-0ED15-1BG4 OR 3RA1215-0DD15-1BG4 | 3RA1225-0ED23-1BG4 OR 3RA1225-0DD23-1BG4 |
| FBER330-1MD10K6 | 3RA1215-0ED15-1AK6 OR 3RA1215-0DD15-1AK6 | 3RA1225-0ED23-1AK6 OR 3RA1225-0DD23-1AK6 |
| FBER330-1MD10M1 | 3RA1215-0ED15-1AM2 OR 3RA1215-0DD15-1AM2 | 3RA1225-0ED23-1AM2 OR 3RA1225-0DD23-1AM2 |
| FBER330-1MD10P6 | 3RA1215-0ED15-1AP6 OR 3RA1215-0DD15-1AP6 | 3RA1225-0ED23-1AP6 OR 3RA1225-0DD23-1AP6 |
| FBER330-1MD10Q0 | 3RA1215-0ED15-1AV0 OR 3RA1215-0DD15-1AV0 | 3RA1225-0ED23-1AV0 OR 3RA1225-0DD23-1AV0 |
| FBER330-1MD10Q4 | 3RA1215-0ED15-1BP4 OR 3RA1215-0DD15-1BP4 | 3RA1225-0ED23-1BP4 OR 3RA1225-0DD23-1BP4 |
| FBER330-1MD10U1 | 3RA1215-0ED15-1AU6 OR 3RA1215-0DD15-1AU6 | 3RA1225-0ED23-1AU6 OR 3RA1225-0DD23-1AU6 |
| FBER330-1MD10W4 | 3RA1215-0ED15-1BW4 OR 3RA1215-0DD15-1BW4 | 3RA1225-0ED23-1BW4 OR 3RA1225-0DD23-1BW4 |
| FBER330-1ME10A4 | 3RA1215-0GD15-1BA4 OR 3RA1215-0FD15-1BA4 | 3RA1225-0GD23-1BA4 OR 3RA1225-0FD23-1BA4 |
| FBER330-1ME10B4 | 3RA1215-0GD15-1BB4 OR 3RA1215-0FD15-1BB4 | 3RA1225-0GD23-1BB4 OR 3RA1225-0FD23-1BB4 |
| FBER330-1ME10C2 | 3RA1215-0GD15-1AC2 OR 3RA1215-0FD15-1AC2 | 3RA1225-0GD23-1AC2 OR 3RA1225-0FD23-1AC2 |
| FBER330-1ME10G4 | 3RA1215-0GD15-1BG4 OR 3RA1215-0FD15-1BG4 | 3RA1225-0GD23-1BG4 OR 3RA1225-0FD23-1BG4 |
| FBER330-1ME10K6 | 3RA1215-0GD15-1AK6 OR 3RA1215-0FD15-1AK6 | 3RA1225-0GD23-1AK6 OR 3RA1225-0FD23-1AK6 |
| FBER330-1ME10M1 | 3RA1215-0GD15-1AM2 OR 3RA1215-0FD15-1AM2 | 3RA1225-0GD23-1AM2 OR 3RA1225-0FD23-1AM2 |
| FBER330-1ME10P6 | 3RA1215-0GD15-1AP6 OR 3RA1215-0FD15-1AP6 | 3RA1225-0GD23-1AP6 OR 3RA1225-0FD23-1AP6 |
| FBER330-1ME10Q0 | 3RA1215-0GD15-1AV0 OR 3RA1215-0FD15-1AV0 | 3RA1225-0GD23-1AV0 OR 3RA1225-0FD23-1AV0 |
| FBER330-1ME10Q4 | 3RA1215-0GD15-1BP4 OR 3RA1215-0FD15-1BP4 | 3RA1225-0GD23-1BP4 OR 3RA1225-0FD23-1BP4 |
| FBER330-1ME10U1 | 3RA1215-0GD15-1AU6 OR 3RA1215-0FD15-1AU6 | 3RA1225-0GD23-1AU6 OR 3RA1225-0FD23-1AU6 |
| FBER330-1ME10W4 | 3RA1215-0GD15-1BW4 OR 3RA1215-0FD15-1BW4 | 3RA1225-0GD23-1BW4 OR 3RA1225-0FD23-1BW4 |
| FBER330-1MF10A4 | 3RA1215-0JD15-1BA4 OR 3RA1215-0HD15-1BA4 | 3RA1225-0JD23-1BA4 OR 3RA1225-0HD23-1BA4 |
| FBER330-1MF10B4 | 3RA1215-0JD15-1BB4 OR 3RA1215-0HD15-1BB4 | 3RA1225-0JD23-1BB4 OR 3RA1225-0HD23-1BB4 |
| FBER330-1MF10C2 | 3RA1215-0JD15-1AC2 OR 3RA1215-0HD15-1AC2 | 3RA1225-0JD23-1AC2 OR 3RA1225-0HD23-1AC2 |
| FBER330-1MF10G4 | 3RA1215-0JD15-1BG4 OR 3RA1215-0HD15-1BG4 | 3RA1225-0JD23-1BG4 OR 3RA1225-0HD23-1BG4 |
| FBER330-1MF10K6 | 3RA1215-0JD15-1AK6 OR 3RA1215-0HD15-1AK6 | 3RA1225-0JD23-1AK6 OR 3RA1225-0HD23-1AK6 |
| FBER330-1MF10M1 | 3RA1215-0JD15-1AM2 OR 3RA1215-0HD15-1AM2 | 3RA1225-0JD23-1AM2 OR 3RA1225-0HD23-1AM2 |
| FBER330-1MF10P6 | 3RA1215-0JD15-1AP6 OR 3RA1215-0HD15-1AP6 | 3RA1225-0JD23-1AP6 OR 3RA1225-0HD23-1AP6 |
| FBER330-1MF10Q0 | 3RA1215-0JD15-1AV0 OR 3RA1215-0HD15-1AV0 | 3RA1225-0JD23-1AV0 OR 3RA1225-0HD23-1AV0 |
| FBER330-1MF10Q4 | 3RA1215-0JD15-1BP4 OR 3RA1215-0HD15-1BP4 | 3RA1225-0JD23-1BP4 OR 3RA1225-0HD23-1BP4 |
| FBER330-1MF10U1 | 3RA1215-0JD15-1AU6 OR 3RA1215-0HD15-1AU6 | 3RA1225-0JD23-1AU6 OR 3RA1225-0HD23-1AU6 |
| FBER330-1MF10W4 | 3RA1215-0JD15-1BW4 OR 3RA1215-0HD15-1BW4 | 3RA1225-0JD23-1BW4 OR 3RA1225-0HD23-1BW4 |
| FBER334-1MG10A4 | 3RA1215-1AD15-1BA4 OR 3RA1215-0KD15-1BA4 | 3RA1225-1AD23-1BA4 OR 3RA1225-0KD23-1BA4 |
| FBER334-1MG10B4 | 3RA1215-1AD15-1BB4 OR 3RA1215-0KD15-1BB4 | 3RA1225-1AD23-1BB4 OR 3RA1225-0KD23-1BB4 |
| FBER334-1MG10C2 | 3RA1215-1AD15-1AC2 OR 3RA1215-0KD15-1AC2 | 3RA1225-1AD23-1AC2 OR 3RA1225-0KD23-1AC2 |
| FBER334-1MG10G4 | 3RA1215-1AD15-1BG4 OR 3RA1215-0KD15-1BG4 | 3RA1225-1AD23-1BG4 OR 3RA1225-0KD23-1BG4 |
| FBER334-1MG10K6 | 3RA1215-1AD15-1AK6 OR 3RA1215-0KD15-1AK6 | 3RA1225-1AD23-1AK6 OR 3RA1225-0KD23-1AK6 |
| FBER334-1MG10M1 | 3RA1215-1AD15-1AM2 OR 3RA1215-0KD15-1AM2 | 3RA1225-1AD23-1AM2 OR 3RA1225-0KD23-1AM2 |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| FBER334-1MG10P6 | 3RA1215-1AD15-1AP6 OR 3RA1215-0KD15-1AP6 | 3RA1225-1AD23-1AP6 OR 3RA1225-0KD23-1AP6 |
| FBER334-1MG10Q0 | 3RA1215-1AD15-1AV0 OR 3RA1215-0KD15-1AV0 | 3RA1225-1AD23-1AV0 OR 3RA1225-0KD23-1AV0 |
| FBER334-1MG10Q4 | 3RA1215-1AD15-1BP4 OR 3RA1215-0KD15-1BP4 | 3RA1225-1AD23-1BP4 OR 3RA1225-0KD23-1BP4 |
| FBER334-1MG10U1 | 3RA1215-1AD15-1AU6 OR 3RA1215-0KD15-1AU6 | 3RA1225-1AD23-1AU6 OR 3RA1225-0KD23-1AU6 |
| FBER334-1MG10W4 | 3RA1215-1AD15-1BW4 OR 3RA1215-0KD15-1BW4 | 3RA1225-1AD23-1BW4 OR 3RA1225-0KD23-1BW4 |
| FBER334-1MH10A4 | 3RA1215-1CD15-1BA4 OR 3RA1215-1BD15-1BA4 | 3RA1225-1CD23-1BA4 OR 3RA1225-1BD23-1BA4 |
| FBER334-1MH10B4 | 3RA1215-1CD15-1BB4 OR 3RA1215-1BD15-1BB4 | 3RA1225-1CD23-1BB4 OR 3RA1225-1BD23-1BB4 |
| FBER334-1MH10C2 | 3RA1215-1CD15-1AC2 OR 3RA1215-1BD15-1AC2 | 3RA1225-1CD23-1AC2 OR 3RA1225-1BD23-1AC2 |
| FBER334-1MH10G4 | 3RA1215-1CD15-1BG4 OR 3RA1215-1BD15-1BG4 | 3RA1225-1CD23-1BG4 OR 3RA1225-1BD23-1BG4 |
| FBER334-1MH10K6 | 3RA1215-1CD15-1AK6 OR 3RA1215-1BD15-1AK6 | 3RA1225-1CD23-1AK6 OR 3RA1225-1BD23-1AK6 |
| FBER334-1MH10M1 | 3RA1215-1CD15-1AM2 OR 3RA1215-1BD15-1AM2 | 3RA1225-1CD23-1AM2 OR 3RA1225-1BD23-1AM2 |
| FBER334-1MH10P6 | 3RA1215-1CD15-1AP6 OR 3RA1215-1BD15-1AP6 | 3RA1225-1CD23-1AP6 OR 3RA1225-1BD23-1AP6 |
| FBER334-1MH10Q0 | 3RA1215-1CD15-1AV0 OR 3RA1215-1BD15-1AV0 | 3RA1225-1CD23-1AV0 OR 3RA1225-1BD23-1AV0 |
| FBER334-1MH10Q4 | 3RA1215-1CD15-1BP4 OR 3RA1215-1BD15-1BP4 | 3RA1225-1CD23-1BP4 OR 3RA1225-1BD23-1BP4 |
| FBER334-1MH10U1 | 3RA1215-1CD15-1AU6 OR 3RA1215-1BD15-1AU6 | 3RA1225-1CD23-1AU6 OR 3RA1225-1BD23-1AU6 |
| FBER334-1MH10W4 | 3RA1215-1CD15-1BW4 OR 3RA1215-1BD15-1BW4 | 3RA1225-1CD23-1BW4 OR 3RA1225-1BD23-1BW4 |
| FBER334-1MJ10A4 | 3RA1215-1ED15-1BA4 OR 3RA1215-1DD15-1BA4 | 3RA1225-1ED23-1BA4 OR 3RA1225-1DD23-1BA4 |
| FBER334-1MJ10B4 | 3RA1215-1ED15-1BB4 OR 3RA1215-1DD15-1BB4 | 3RA1225-1ED23-1BB4 OR 3RA1225-1DD23-1BB4 |
| FBER334-1MJ10C2 | 3RA1215-1ED15-1AC2 OR 3RA1215-1DD15-1AC2 | 3RA1225-1ED23-1AC2 OR 3RA1225-1DD23-1AC2 |
| FBER334-1MJ10G4 | 3RA1215-1ED15-1BG4 OR 3RA1215-1DD15-1BG4 | 3RA1225-1ED23-1BG4 OR 3RA1225-1DD23-1BG4 |
| FBER334-1MJ10K6 | 3RA1215-1ED15-1AK6 OR 3RA1215-1DD15-1AK6 | 3RA1225-1ED23-1AK6 OR 3RA1225-1DD23-1AK6 |
| FBER334-1MJ10M1 | 3RA1215-1ED15-1AM2 OR 3RA1215-1DD15-1AM2 | 3RA1225-1ED23-1AM2 OR 3RA1225-1DD23-1AM2 |
| FBER334-1MJ10P6 | 3RA1215-1ED15-1AP6 OR 3RA1215-1DD15-1AP6 | 3RA1225-1ED23-1AP6 OR 3RA1225-1DD23-1AP6 |
| FBER334-1MJ10Q0 | 3RA1215-1ED15-1AV0 OR 3RA1215-1DD15-1AV0 | 3RA1225-1ED23-1AV0 OR 3RA1225-1DD23-1AV0 |
| FBER334-1MJ10Q4 | 3RA1215-1ED15-1BP4 OR 3RA1215-1DD15-1BP4 | 3RA1225-1ED23-1BP4 OR 3RA1225-1DD23-1BP4 |
| FBER334-1MJ10U1 | 3RA1215-1ED15-1AU6 OR 3RA1215-1DD15-1AU6 | 3RA1225-1ED23-1AU6 OR 3RA1225-1DD23-1AU6 |
| FBER334-1MJ10W4 | 3RA1215-1ED15-1BW4 OR 3RA1215-1DD15-1BW4 | 3RA1225-1ED23-1BW4 OR 3RA1225-1DD23-1BW4 |
| FBER334-1MK10A4 | 3RA1215-1GD15-1BA4 OR 3RA1215-1FD15-1BA4 | 3RA1225-1GD23-1BA4 OR 3RA1225-1FD23-1BA4 |
| FBER334-1MK10B4 | 3RA1215-1GD15-1BB4 OR 3RA1215-1FD15-1BB4 | 3RA1225-1GD23-1BB4 OR 3RA1225-1FD23-1BB4 |
| FBER334-1MK10C2 | 3RA1215-1GD15-1AC2 OR 3RA1215-1FD15-1AC2 | 3RA1225-1GD23-1AC2 OR 3RA1225-1FD23-1AC2 |
| FBER334-1MK10G4 | 3RA1215-1GD15-1BG4 OR 3RA1215-1FD15-1BG4 | 3RA1225-1GD23-1BG4 OR 3RA1225-1FD23-1BG4 |
| FBER334-1MK10K6 | 3RA1215-1GD15-1AK6 OR 3RA1215-1FD15-1AK6 | 3RA1225-1GD23-1AK6 OR 3RA1225-1FD23-1AK6 |
| FBER334-1MK10M1 | 3RA1215-1GD15-1AM2 OR 3RA1215-1FD15-1AM2 | 3RA1225-1GD23-1AM2 OR 3RA1225-1FD23-1AM2 |
| FBER334-1MK10P6 | 3RA1215-1GD15-1AP6 OR 3RA1215-1FD15-1AP6 | 3RA1225-1GD23-1AP6 OR 3RA1225-1FD23-1AP6 |
| FBER334-1MK10Q0 | 3RA1215-1GD15-1AV0 OR 3RA1215-1FD15-1AV0 | 3RA1225-1GD23-1AV0 OR 3RA1225-1FD23-1AV0 |
| FBER334-1MK10Q4 | 3RA1215-1GD15-1BP4 OR 3RA1215-1FD15-1BP4 | 3RA1225-1GD23-1BP4 OR 3RA1225-1FD23-1BP4 |
| FBER334-1MK10U1 | 3RA1215-1GD15-1AU6 OR 3RA1215-1FD15-1AU6 | 3RA1225-1GD23-1AU6 OR 3RA1225-1FD23-1AU6 |
| FBER334-1MK10W4 | 3RA1215-1GD15-1BW4 OR 3RA1215-1FD15-1BW4 | 3RA1225-1GD23-1BW4 OR 3RA1225-1FD23-1BW4 |
| FBER334-1ML10A4 | 3RA1225-1JD24-1BA4 OR 3RA1215-1HD16-1BA4 | |
| FBER334-1ML10B4 | 3RA1225-1JD24-1BB4 OR 3RA1215-1HD16-1BB4 | |
| FBER334-1ML10C2 | 3RA1225-1JD24-1AC2 OR 3RA1215-1HD16-1AC2 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| FBER334-1ML10G4 | 3RA1225-1JD24-1BG4 OR 3RA1215-1HD16-1BG4 | |
| FBER334-1ML10K6 | 3RA1225-1JD24-1AK6 OR 3RA1215-1HD16-1AK6 | |
| FBER334-1ML10M1 | 3RA1225-1JD24-1AM2 OR 3RA1215-1HD16-1AM2 | |
| FBER334-1ML10P6 | 3RA1225-1JD24-1AP6 OR 3RA1215-1HD16-1AP6 | |
| FBER334-1ML10Q0 | 3RA1225-1JD24-1AV0 OR 3RA1215-1HD16-1AV0 | |
| FBER334-1ML10Q4 | 3RA1225-1JD24-1BP4 OR 3RA1215-1HD16-1BP4 | |
| FBER334-1ML10U1 | 3RA1225-1JD24-1AU6 OR 3RA1215-1HD16-1AU6 | |
| FBER334-1ML10W4 | 3RA1225-1JD24-1BW4 OR 3RA1215-1HD16-1BW4 | |
| FBER334-1MM10A4 | 3RA1225-4AD25-1BA4 OR 3RA1225-1KD23-1BA4 | |
| FBER334-1MM10B4 | 3RA1225-4AD25-1BB4 OR 3RA1225-1KD23-1BB4 | |
| FBER334-1MM10C2 | 3RA1225-4AD25-1AC2 OR 3RA1225-1KD23-1AC2 | |
| FBER334-1MM10G4 | 3RA1225-4AD25-1BG4 OR 3RA1225-1KD23-1BG4 | |
| FBER334-1MM10K6 | 3RA1225-4AD25-1AK6 OR 3RA1225-1KD23-1AK6 | |
| FBER334-1MM10M1 | 3RA1225-4AD25-1AM2 OR 3RA1225-1KD23-1AM2 | |
| FBER334-1MM10P6 | 3RA1225-4AD25-1AP6 OR 3RA1225-1KD23-1AP6 | |
| FBER334-1MM10Q0 | 3RA1225-4AD25-1AV0 OR 3RA1225-1KD23-1AV0 | |
| FBER334-1MM10Q4 | 3RA1225-4AD25-1BP4 OR 3RA1225-1KD23-1BP4 | |
| FBER334-1MM10U1 | 3RA1225-4AD25-1AU6 OR 3RA1225-1KD23-1AU6 | |
| FBER334-1MM10W4 | 3RA1225-4AD25-1BW4 OR 3RA1225-1KD23-1BW4 | |
| FBER634-1MG10A4 | 3RA1215-1AD15-1BA4 OR 3RA1215-0KD15-1BA4 | 3RA1225-1AD23-1BA4 OR 3RA1225-0KD23-1BA4 |
| FBER634-1MG10B4 | 3RA1215-1AD15-1BB4 OR 3RA1215-0KD15-1BB4 | 3RA1225-1AD23-1BB4 OR 3RA1225-0KD23-1BB4 |
| FBER634-1MG10C2 | 3RA1215-1AD15-1AC2 OR 3RA1215-0KD15-1AC2 | 3RA1225-1AD23-1AC2 OR 3RA1225-0KD23-1AC2 |
| FBER634-1MG10G4 | 3RA1215-1AD15-1BG4 OR 3RA1215-0KD15-1BG4 | 3RA1225-1AD23-1BG4 OR 3RA1225-0KD23-1BG4 |
| FBER634-1MG10K6 | 3RA1215-1AD15-1AK6 OR 3RA1215-0KD15-1AK6 | 3RA1225-1AD23-1AK6 OR 3RA1225-0KD23-1AK6 |
| FBER634-1MG10M1 | 3RA1215-1AD15-1AM2 OR 3RA1215-0KD15-1AM2 | 3RA1225-1AD23-1AM2 OR 3RA1225-0KD23-1AM2 |
| FBER634-1MG10P6 | 3RA1215-1AD15-1AP6 OR 3RA1215-0KD15-1AP6 | 3RA1225-1AD23-1AP6 OR 3RA1225-0KD23-1AP6 |
| FBER634-1MG10Q0 | 3RA1215-1AD15-1AV0 OR 3RA1215-0KD15-1AV0 | 3RA1225-1AD23-1AV0 OR 3RA1225-0KD23-1AV0 |
| FBER634-1MG10Q4 | 3RA1215-1AD15-1BP4 OR 3RA1215-0KD15-1BP4 | 3RA1225-1AD23-1BP4 OR 3RA1225-0KD23-1BP4 |
| FBER634-1MG10U1 | 3RA1215-1AD15-1AU6 OR 3RA1215-0KD15-1AU6 | 3RA1225-1AD23-1AU6 OR 3RA1225-0KD23-1AU6 |
| FBER634-1MG10W4 | 3RA1215-1AD15-1BW4 OR 3RA1215-0KD15-1BW4 | 3RA1225-1AD23-1BW4 OR 3RA1225-0KD23-1BW4 |
| FBER634-1MH10A4 | 3RA1215-1CD15-1BA4 OR 3RA1215-1BD15-1BA4 | 3RA1225-1CD23-1BA4 OR 3RA1225-1BD23-1BA4 |
| FBER634-1MH10B4 | 3RA1215-1CD15-1BB4 OR 3RA1215-1BD15-1BB4 | 3RA1225-1CD23-1BB4 OR 3RA1225-1BD23-1BB4 |
| FBER634-1MH10C2 | 3RA1215-1CD15-1AC2 OR 3RA1215-1BD15-1AC2 | 3RA1225-1CD23-1AC2 OR 3RA1225-1BD23-1AC2 |
| FBER634-1MH10G4 | 3RA1215-1CD15-1BG4 OR 3RA1215-1BD15-1BG4 | 3RA1225-1CD23-1BG4 OR 3RA1225-1BD23-1BG4 |
| FBER634-1MH10K6 | 3RA1215-1CD15-1AK6 OR 3RA1215-1BD15-1AK6 | 3RA1225-1CD23-1AK6 OR 3RA1225-1BD23-1AK6 |
| FBER634-1MH10M1 | 3RA1215-1CD15-1AM2 OR 3RA1215-1BD15-1AM2 | 3RA1225-1CD23-1AM2 OR 3RA1225-1BD23-1AM2 |
| FBER634-1MH10P6 | 3RA1215-1CD15-1AP6 OR 3RA1215-1BD15-1AP6 | 3RA1225-1CD23-1AP6 OR 3RA1225-1BD23-1AP6 |
| FBER634-1MH10Q0 | 3RA1215-1CD15-1AV0 OR 3RA1215-1BD15-1AV0 | 3RA1225-1CD23-1AV0 OR 3RA1225-1BD23-1AV0 |
| FBER634-1MH10Q4 | 3RA1215-1CD15-1BP4 OR 3RA1215-1BD15-1BP4 | 3RA1225-1CD23-1BP4 OR 3RA1225-1BD23-1BP4 |
| FBER634-1MH10U1 | 3RA1215-1CD15-1AU6 OR 3RA1215-1BD15-1AU6 | 3RA1225-1CD23-1AU6 OR 3RA1225-1BD23-1AU6 |
| FBER634-1MH10W4 | 3RA1215-1CD15-1BW4 OR 3RA1215-1BD15-1BW4 | 3RA1225-1CD23-1BW4 OR 3RA1225-1BD23-1BW4 |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| FBER634-1MJ10A4 | 3RA1215-1ED15-1BA4 OR 3RA1215-1DD15-1BA4 | 3RA1225-1ED23-1BA4 OR 3RA1225-1DD23-1BA4 |
| FBER634-1MJ10B4 | 3RA1215-1ED15-1BB4 OR 3RA1215-1DD15-1BB4 | 3RA1225-1ED23-1BB4 OR 3RA1225-1DD23-1BB4 |
| FBER634-1MJ10C2 | 3RA1215-1ED15-1AC2 OR 3RA1215-1DD15-1AC2 | 3RA1225-1ED23-1AC2 OR 3RA1225-1DD23-1AC2 |
| FBER634-1MJ10G4 | 3RA1215-1ED15-1BG4 OR 3RA1215-1DD15-1BG4 | 3RA1225-1ED23-1BG4 OR 3RA1225-1DD23-1BG4 |
| FBER634-1MJ10K6 | 3RA1215-1ED15-1AK6 OR 3RA1215-1DD15-1AK6 | 3RA1225-1ED23-1AK6 OR 3RA1225-1DD23-1AK6 |
| FBER634-1MJ10M1 | 3RA1215-1ED15-1AM2 OR 3RA1215-1DD15-1AM2 | 3RA1225-1ED23-1AM2 OR 3RA1225-1DD23-1AM2 |
| FBER634-1MJ10P6 | 3RA1215-1ED15-1AP6 OR 3RA1215-1DD15-1AP6 | 3RA1225-1ED23-1AP6 OR 3RA1225-1DD23-1AP6 |
| FBER634-1MJ10Q0 | 3RA1215-1ED15-1AV0 OR 3RA1215-1DD15-1AV0 | 3RA1225-1ED23-1AV0 OR 3RA1225-1DD23-1AV0 |
| FBER634-1MJ10Q4 | 3RA1215-1ED15-1BP4 OR 3RA1215-1DD15-1BP4 | 3RA1225-1ED23-1BP4 OR 3RA1225-1DD23-1BP4 |
| FBER634-1MJ10U1 | 3RA1215-1ED15-1AU6 OR 3RA1215-1DD15-1AU6 | 3RA1225-1ED23-1AU6 OR 3RA1225-1DD23-1AU6 |
| FBER634-1MJ10W4 | 3RA1215-1ED15-1BW4 OR 3RA1215-1DD15-1BW4 | 3RA1225-1ED23-1BW4 OR 3RA1225-1DD23-1BW4 |
| FBER634-1MK10A4 | 3RA1215-1GD15-1BA4 OR 3RA1215-1FD15-1BA4 | 3RA1225-1GD23-1BA4 OR 3RA1225-1FD23-1BA4 |
| FBER634-1MK10B4 | 3RA1215-1GD15-1BB4 OR 3RA1215-1FD15-1BB4 | 3RA1225-1GD23-1BB4 OR 3RA1225-1FD23-1BB4 |
| FBER634-1MK10C2 | 3RA1215-1GD15-1AC2 OR 3RA1215-1FD15-1AC2 | 3RA1225-1GD23-1AC2 OR 3RA1225-1FD23-1AC2 |
| FBER634-1MK10G4 | 3RA1215-1GD15-1BG4 OR 3RA1215-1FD15-1BG4 | 3RA1225-1GD23-1BG4 OR 3RA1225-1FD23-1BG4 |
| FBER634-1MK10K6 | 3RA1215-1GD15-1AK6 OR 3RA1215-1FD15-1AK6 | 3RA1225-1GD23-1AK6 OR 3RA1225-1FD23-1AK6 |
| FBER634-1MK10M1 | 3RA1215-1GD15-1AM2 OR 3RA1215-1FD15-1AM2 | 3RA1225-1GD23-1AM2 OR 3RA1225-1FD23-1AM2 |
| FBER634-1MK10P6 | 3RA1215-1GD15-1AP6 OR 3RA1215-1FD15-1AP6 | 3RA1225-1GD23-1AP6 OR 3RA1225-1FD23-1AP6 |
| FBER634-1MK10Q0 | 3RA1215-1GD15-1AV0 OR 3RA1215-1FD15-1AV0 | 3RA1225-1GD23-1AV0 OR 3RA1225-1FD23-1AV0 |
| FBER634-1MK10Q4 | 3RA1215-1GD15-1BP4 OR 3RA1215-1FD15-1BP4 | 3RA1225-1GD23-1BP4 OR 3RA1225-1FD23-1BP4 |
| FBER634-1MK10U1 | 3RA1215-1GD15-1AU6 OR 3RA1215-1FD15-1AU6 | 3RA1225-1GD23-1AU6 OR 3RA1225-1FD23-1AU6 |
| FBER634-1MK10W4 | 3RA1215-1GD15-1BW4 OR 3RA1215-1FD15-1BW4 | 3RA1225-1GD23-1BW4 OR 3RA1225-1FD23-1BW4 |
| FBER634-1ML10A4 | 3RA1225-1JD24-1BA4 OR 3RA1215-1HD16-1BA4 | |
| FBER634-1ML10B4 | 3RA1225-1JD24-1BB4 OR 3RA1215-1HD16-1BB4 | |
| FBER634-1ML10C2 | 3RA1225-1JD24-1AC2 OR 3RA1215-1HD16-1AC2 | |
| FBER634-1ML10G4 | 3RA1225-1JD24-1BG4 OR 3RA1215-1HD16-1BG4 | |
| FBER634-1ML10K6 | 3RA1225-1JD24-1AK6 OR 3RA1215-1HD16-1AK6 | |
| FBER634-1ML10M1 | 3RA1225-1JD24-1AM2 OR 3RA1215-1HD16-1AM2 | |
| FBER634-1ML10P6 | 3RA1225-1JD24-1AP6 OR 3RA1215-1HD16-1AP6 | |
| FBER634-1ML10Q0 | 3RA1225-1JD24-1AV0 OR 3RA1215-1HD16-1AV0 | |
| FBER634-1ML10Q4 | 3RA1225-1JD24-1BP4 OR 3RA1215-1HD16-1BP4 | |
| FBER634-1ML10U1 | 3RA1225-1JD24-1AU6 OR 3RA1215-1HD16-1AU6 | |
| FBER634-1ML10W4 | 3RA1225-1JD24-1BW4 OR 3RA1215-1HD16-1BW4 | |
| FBER634-1MM10A4 | 3RA1225-4AD25-1BA4 OR 3RA1225-1KD23-1BA4 | |
| FBER634-1MM10B4 | 3RA1225-4AD25-1BB4 OR 3RA1225-1KD23-1BB4 | |
| FBER634-1MM10C2 | 3RA1225-4AD25-1AC2 OR 3RA1225-1KD23-1AC2 | |
| FBER634-1MM10G4 | 3RA1225-4AD25-1BG4 OR 3RA1225-1KD23-1BG4 | |
| FBER634-1MM10K6 | 3RA1225-4AD25-1AK6 OR 3RA1225-1KD23-1AK6 | |
| FBER634-1MM10M1 | 3RA1225-4AD25-1AM2 OR 3RA1225-1KD23-1AM2 | |
| FBER634-1MM10P6 | 3RA1225-4AD25-1AP6 OR 3RA1225-1KD23-1AP6 | |
| FBER634-1MM10Q0 | 3RA1225-4AD25-1AV0 OR 3RA1225-1KD23-1AV0 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| FBER634-1MM10Q4 | 3RA1225-4AD25-1BP4 OR 3RA1225-1KD23-1BP4 | |
| FBER634-1MM10U1 | 3RA1225-4AD25-1AU6 OR 3RA1225-1KD23-1AU6 | |
| FBER634-1MM10W4 | 3RA1225-4AD25-1BW4 OR 3RA1225-1KD23-1BW4 | |
| FBER634-1MN10A4 | 3RA1225-4BD26-1BA4 | |
| FBER634-1MN10B4 | 3RA1225-4BD26-1BB4 | |
| FBER634-1MN10C2 | 3RA1225-4BD26-1AC2 | |
| FBER634-1MN10G4 | 3RA1225-4BD26-1BG4 | |
| FBER634-1MN10K6 | 3RA1225-4BD26-1AK6 | |
| FBER634-1MN10M1 | 3RA1225-4BD26-1AM2 | |
| FBER634-1MN10P6 | 3RA1225-4BD26-1AP6 | |
| FBER634-1MN10Q0 | 3RA1225-4BD26-1AV0 | |
| FBER634-1MN10Q4 | 3RA1225-4BD26-1BP4 | |
| FBER634-1MN10U1 | 3RA1225-4BD26-1AU6 | |
| FBER634-1MN10W4 | 3RA1225-4BD26-1BW4 | |
| FBER634-1MP10A4 | 3RA1235-4ED34-1BA4 | |
| FBER634-1MP10B4 | 3RA1235-4ED34-1BB4 | |
| FBER634-1MP10C2 | 3RA1235-4ED34-1AC2 | |
| FBER634-1MP10G4 | 3RA1235-4ED34-1BG4 | |
| FBER634-1MP10K6 | 3RA1235-4ED34-1AK6 | |
| FBER634-1MP10M1 | 3RA1235-4ED34-1AM2 | |
| FBER634-1MP10P6 | 3RA1235-4ED34-1AP6 | |
| FBER634-1MP10Q0 | 3RA1235-4ED34-1AV0 | |
| FBER634-1MP10Q4 | 3RA1235-4ED34-1BP4 | |
| FBER634-1MP10U1 | 3RA1235-4ED34-1AU6 | |
| FBER634-1MP10W4 | 3RA1235-4ED34-1BW4 | |
| FBES001 | NO DIRECT REPLACEMENT | |
| FBES002 | NO DIRECT REPLACEMENT | |
| FBES003 | NO DIRECT REPLACEMENT | |
| FBES004 | NO DIRECT REPLACEMENT | |
| FBES005 | NO DIRECT REPLACEMENT | |
| FBES006 | NO DIRECT REPLACEMENT | |
| FBES007 | NO DIRECT REPLACEMENT | |
| FBES008 | NO DIRECT REPLACEMENT | |
| FBES009 | NO DIRECT REPLACEMENT | |
| FBES010 | NO DIRECT REPLACEMENT | |
| FBES011 | NO DIRECT REPLACEMENT | |
| FBES012 | NO DIRECT REPLACEMENT | |
| FBES013 | NO DIRECT REPLACEMENT | |
| FBES015 | NO DIRECT REPLACEMENT | |
| FBES016 | NO DIRECT REPLACEMENT | |
| FBM1330-1MB10A4 | 3RA1115-0AD15-1BA4 | 3RA1125-0AD23-1BA4 |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| FBM1330-1MB10B4 | 3RA1115-0AD15-1BB4 | 3RA1125-0AD23-1BB4 |
| FBM1330-1MB10C2 | 3RA1115-0AD15-1AC2 | 3RA1125-0AD23-1AC2 |
| FBM1330-1MB10G4 | 3RA1115-0AD15-1BG4 | 3RA1125-0AD23-1BG4 |
| FBM1330-1MB10K6 | 3RA1115-0AD15-1AK6 | 3RA1125-0AD23-1AK6 |
| FBM1330-1MB10M1 | 3RA1115-0AD15-1AM2 | 3RA1125-0AD23-1AM2 |
| FBM1330-1MB10P6 | 3RA1115-0AD15-1AP6 | 3RA1125-0AD23-1AP6 |
| FBM1330-1MB10Q0 | 3RA1115-0AD15-1AV0 | 3RA1125-0AD23-1AV0 |
| FBM1330-1MB10Q4 | 3RA1115-0AD15-1BP4 | 3RA1125-0AD23-1BP4 |
| FBM1330-1MB10S0 | 3RA1115-0AD15-1AT6 | 3RA1125-0AD23-1AT6 |
| FBM1330-1MB10U1 | 3RA1115-0AD15-1AU6 | 3RA1125-0AD23-1AU6 |
| FBM1330-1MB10W4 | 3RA1115-0AD15-1BW4 | 3RA1125-0AD23-1BW4 |
| FBM1330-1MC10A4 | 3RA1115-0CD15-1BA4 OR 3RA1115-0BD15-1BA4 | 3RA1125-0CD23-1BA4 OR 3RA1125-0BD23-1BA4 |
| FBM1330-1MC10B4 | 3RA1115-0CD15-1BB4 OR 3RA1115-0BD15-1BB4 | 3RA1125-0CD23-1BB4 OR 3RA1125-0BD23-1BB4 |
| FBM1330-1MC10C2 | 3RA1115-0CD15-1AC2 OR 3RA1115-0BD15-1AC2 | 3RA1125-0CD23-1AC2 OR 3RA1125-0BD23-1AC2 |
| FBM1330-1MC10G4 | 3RA1115-0CD15-1BG4 OR 3RA1115-0BD15-1BG4 | 3RA1125-0CD23-1BG4 OR 3RA1125-0BD23-1BG4 |
| FBM1330-1MC10K6 | 3RA1115-0CD15-1AK6 OR 3RA1115-0BD15-1AK6 | 3RA1125-0CD23-1AK6 OR 3RA1125-0BD23-1AK6 |
| FBM1330-1MC10M1 | 3RA1115-0CD15-1AM2 OR 3RA1115-0BD15-1AM2 | 3RA1125-0CD23-1AM2 OR 3RA1125-0BD23-1AM2 |
| FBM1330-1MC10P6 | 3RA1115-0CD15-1AP6 OR 3RA1115-0BD15-1AP6 | 3RA1125-0CD23-1AP6 OR 3RA1125-0BD23-1AP6 |
| FBM1330-1MC10Q0 | 3RA1115-0CD15-1AV0 OR 3RA1115-0BD15-1AV0 | 3RA1125-0CD23-1AV0 OR 3RA1125-0BD23-1AV0 |
| FBM1330-1MC10Q4 | 3RA1115-0CD15-1BP4 OR 3RA1115-0BD15-1BP4 | 3RA1125-0CD23-1BP4 OR 3RA1125-0BD23-1BP4 |
| FBM1330-1MC10S0 | 3RA1115-0CD15-1AT6 OR 3RA1115-0BD15-1AT6 | 3RA1125-0CD23-1AT6 OR 3RA1125-0BD23-1AT6 |
| FBM1330-1MC10U1 | 3RA1115-0CD15-1AU6 OR 3RA1115-0BD15-1AU6 | 3RA1125-0CD23-1AU6 OR 3RA1125-0BD23-1AU6 |
| FBM1330-1MC10W4 | 3RA1115-0CD15-1BW4 OR 3RA1115-0BD15-1BW4 | 3RA1125-0CD23-1BW4 OR 3RA1125-0BD23-1BW4 |
| FBM1330-1MD10A4 | 3RA1115-0ED15-1BA4 OR 3RA1115-0DD15-1BA4 | 3RA1125-0ED23-1BA4 OR 3RA1125-0DD23-1BA4 |
| FBM1330-1MD10B4 | 3RA1115-0ED15-1BB4 OR 3RA1115-0DD15-1BB4 | 3RA1125-0ED23-1BB4 OR 3RA1125-0DD23-1BB4 |
| FBM1330-1MD10C2 | 3RA1115-0ED15-1AC2 OR 3RA1115-0DD15-1AC2 | 3RA1125-0ED23-1AC2 OR 3RA1125-0DD23-1AC2 |
| FBM1330-1MD10G4 | 3RA1115-0ED15-1BG4 OR 3RA1115-0DD15-1BG4 | 3RA1125-0ED23-1BG4 OR 3RA1125-0DD23-1BG4 |
| FBM1330-1MD10K6 | 3RA1115-0ED15-1AK6 OR 3RA1115-0DD15-1AK6 | 3RA1125-0ED23-1AK6 OR 3RA1125-0DD23-1AK6 |
| FBM1330-1MD10M1 | 3RA1115-0ED15-1AM2 OR 3RA1115-0DD15-1AM2 | 3RA1125-0ED23-1AM2 OR 3RA1125-0DD23-1AM2 |
| FBM1330-1MD10P6 | 3RA1115-0ED15-1AP6 OR 3RA1115-0DD15-1AP6 | 3RA1125-0ED23-1AP6 OR 3RA1125-0DD23-1AP6 |
| FBM1330-1MD10Q0 | 3RA1115-0ED15-1AV0 OR 3RA1115-0DD15-1AV0 | 3RA1125-0ED23-1AV0 OR 3RA1125-0DD23-1AV0 |
| FBM1330-1MD10Q4 | 3RA1115-0ED15-1BP4 OR 3RA1115-0DD15-1BP4 | 3RA1125-0ED23-1BP4 OR 3RA1125-0DD23-1BP4 |
| FBM1330-1MD10S0 | 3RA1115-0ED15-1AT6 OR 3RA1115-0DD15-1AT6 | 3RA1125-0ED23-1AT6 OR 3RA1125-0DD23-1AT6 |
| FBM1330-1MD10U1 | 3RA1115-0ED15-1AU6 OR 3RA1115-0DD15-1AU6 | 3RA1125-0ED23-1AU6 OR 3RA1125-0DD23-1AU6 |
| FBM1330-1MD10W4 | 3RA1115-0ED15-1BW4 OR 3RA1115-0DD15-1BW4 | 3RA1125-0ED23-1BW4 OR 3RA1125-0DD23-1BW4 |
| FBM1330-1ME10A4 | 3RA1115-0GD15-1BA4 OR 3RA1115-0FD15-1BA4 | 3RA1125-0GD23-1BA4 OR 3RA1125-0FD23-1BA4 |
| FBM1330-1ME10B4 | 3RA1115-0GD15-1BB4 OR 3RA1115-0FD15-1BB4 | 3RA1125-0GD23-1BB4 OR 3RA1125-0FD23-1BB4 |
| FBM1330-1ME10C2 | 3RA1115-0GD15-1AC2 OR 3RA1115-0FD15-1AC2 | 3RA1125-0GD23-1AC2 OR 3RA1125-0FD23-1AC2 |
| FBM1330-1ME10G4 | 3RA1115-0GD15-1BG4 OR 3RA1115-0FD15-1BG4 | 3RA1125-0GD23-1BG4 OR 3RA1125-0FD23-1BG4 |
| FBM1330-1ME10K6 | 3RA1115-0GD15-1AK6 OR 3RA1115-0FD15-1AK6 | 3RA1125-0GD23-1AK6 OR 3RA1125-0FD23-1AK6 |
| FBM1330-1ME10M1 | 3RA1115-0GD15-1AM2 OR 3RA1115-0FD15-1AM2 | 3RA1125-0GD23-1AM2 OR 3RA1125-0FD23-1AM2 |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| FBM1330-1ME10P6 | 3RA1115-0GD15-1AP6 OR 3RA1115-0FD15-1AP6 | 3RA1125-0GD23-1AP6 OR 3RA1125-0FD23-1AP6 |
| FBM1330-1ME10Q0 | 3RA1115-0GD15-1AV0 OR 3RA1115-0FD15-1AV0 | 3RA1125-0GD23-1AV0 OR 3RA1125-0FD23-1AV0 |
| FBM1330-1ME10Q4 | 3RA1115-0GD15-1BP4 OR 3RA1115-0FD15-1BP4 | 3RA1125-0GD23-1BP4 OR 3RA1125-0FD23-1BP4 |
| FBM1330-1ME10S0 | 3RA1115-0GD15-1AT6 OR 3RA1115-0FD15-1AT6 | 3RA1125-0GD23-1AT6 OR 3RA1125-0FD23-1AT6 |
| FBM1330-1ME10U1 | 3RA1115-0GD15-1AU6 OR 3RA1115-0FD15-1AU6 | 3RA1125-0GD23-1AU6 OR 3RA1125-0FD23-1AU6 |
| FBM1330-1ME10W4 | 3RA1115-0GD15-1BW4 OR 3RA1115-0FD15-1BW4 | 3RA1125-0GD23-1BW4 OR 3RA1125-0FD23-1BW4 |
| FBM1330-1MF10A4 | 3RA1115-0JD15-1BA4 OR 3RA1115-0HD15-1BA4 | 3RA1125-0JD23-1BA4 OR 3RA1125-0HD23-1BA4 |
| FBM1330-1MF10B4 | 3RA1115-0JD15-1BB4 OR 3RA1115-0HD15-1BB4 | 3RA1125-0JD23-1BB4 OR 3RA1125-0HD23-1BB4 |
| FBM1330-1MF10C2 | 3RA1115-0JD15-1AC2 OR 3RA1115-0HD15-1AC2 | 3RA1125-0JD23-1AC2 OR 3RA1125-0HD23-1AC2 |
| FBM1330-1MF10G4 | 3RA1115-0JD15-1BG4 OR 3RA1115-0HD15-1BG4 | 3RA1125-0JD23-1BG4 OR 3RA1125-0HD23-1BG4 |
| FBM1330-1MF10K6 | 3RA1115-0JD15-1AK6 OR 3RA1115-0HD15-1AK6 | 3RA1125-0JD23-1AK6 OR 3RA1125-0HD23-1AK6 |
| FBM1330-1MF10M1 | 3RA1115-0JD15-1AM2 OR 3RA1115-0HD15-1AM2 | 3RA1125-0JD23-1AM2 OR 3RA1125-0HD23-1AM2 |
| FBM1330-1MF10P6 | 3RA1115-0JD15-1AP6 OR 3RA1115-0HD15-1AP6 | 3RA1125-0JD23-1AP6 OR 3RA1125-0HD23-1AP6 |
| FBM1330-1MF10Q0 | 3RA1115-0JD15-1AV0 OR 3RA1115-0HD15-1AV0 | 3RA1125-0JD23-1AV0 OR 3RA1125-0HD23-1AV0 |
| FBM1330-1MF10Q4 | 3RA1115-0JD15-1BP4 OR 3RA1115-0HD15-1BP4 | 3RA1125-0JD23-1BP4 OR 3RA1125-0HD23-1BP4 |
| FBM1330-1MF10S0 | 3RA1115-0JD15-1AT6 OR 3RA1115-0HD15-1AT6 | 3RA1125-0JD23-1AT6 OR 3RA1125-0HD23-1AT6 |
| FBM1330-1MF10U1 | 3RA1115-0JD15-1AU6 OR 3RA1115-0HD15-1AU6 | 3RA1125-0JD23-1AU6 OR 3RA1125-0HD23-1AU6 |
| FBM1330-1MF10W4 | 3RA1115-0JD15-1BW4 OR 3RA1115-0HD15-1BW4 | 3RA1125-0JD23-1BW4 OR 3RA1125-0HD23-1BW4 |
| FBM1330-1MG10A4 | 3RA1115-1AD15-1BA4 OR 3RA1115-0KD15-1BA4 | 3RA1125-1AD23-1BA4 OR 3RA1125-0KD23-1BA4 |
| FBM1330-1MG10B4 | 3RA1115-1AD15-1BB4 OR 3RA1115-0KD15-1BB4 | 3RA1125-1AD23-1BB4 OR 3RA1125-0KD23-1BB4 |
| FBM1330-1MG10C2 | 3RA1115-1AD15-1AC2 OR 3RA1115-0KD15-1AC2 | 3RA1125-1AD23-1AC2 OR 3RA1125-0KD23-1AC2 |
| FBM1330-1MG10G4 | 3RA1115-1AD15-1BG4 OR 3RA1115-0KD15-1BG4 | 3RA1125-1AD23-1BG4 OR 3RA1125-0KD23-1BG4 |
| FBM1330-1MG10K6 | 3RA1115-1AD15-1AK6 OR 3RA1115-0KD15-1AK6 | 3RA1125-1AD23-1AK6 OR 3RA1125-0KD23-1AK6 |
| FBM1330-1MG10M1 | 3RA1115-1AD15-1AM2 OR 3RA1115-0KD15-1AM2 | 3RA1125-1AD23-1AM2 OR 3RA1125-0KD23-1AM2 |
| FBM1330-1MG10P6 | 3RA1115-1AD15-1AP6 OR 3RA1115-0KD15-1AP6 | 3RA1125-1AD23-1AP6 OR 3RA1125-0KD23-1AP6 |
| FBM1330-1MG10Q0 | 3RA1115-1AD15-1AV0 OR 3RA1115-0KD15-1AV0 | 3RA1125-1AD23-1AV0 OR 3RA1125-0KD23-1AV0 |
| FBM1330-1MG10Q4 | 3RA1115-1AD15-1BP4 OR 3RA1115-0KD15-1BP4 | 3RA1125-1AD23-1BP4 OR 3RA1125-0KD23-1BP4 |
| FBM1330-1MG10S0 | 3RA1115-1AD15-1AT6 OR 3RA1115-0KD15-1AT6 | 3RA1125-1AD23-1AT6 OR 3RA1125-0KD23-1AT6 |
| FBM1330-1MG10U1 | 3RA1115-1AD15-1AU6 OR 3RA1115-0KD15-1AU6 | 3RA1125-1AD23-1AU6 OR 3RA1125-0KD23-1AU6 |
| FBM1330-1MG10W4 | 3RA1115-1AD15-1BW4 OR 3RA1115-0KD15-1BW4 | 3RA1125-1AD23-1BW4 OR 3RA1125-0KD23-1BW4 |
| FBM1330-1MH10A4 | 3RA1115-1CD15-1BA4 OR 3RA1115-1BD15-1BA4 | 3RA1125-1CD23-1BA4 OR 3RA1125-1BD23-1BA4 |
| FBM1330-1MH10B4 | 3RA1115-1CD15-1BB4 OR 3RA1115-1BD15-1BB4 | 3RA1125-1CD23-1BB4 OR 3RA1125-1BD23-1BB4 |
| FBM1330-1MH10C2 | 3RA1115-1CD15-1AC2 OR 3RA1115-1BD15-1AC2 | 3RA1125-1CD23-1AC2 OR 3RA1125-1BD23-1AC2 |
| FBM1330-1MH10G4 | 3RA1115-1CD15-1BG4 OR 3RA1115-1BD15-1BG4 | 3RA1125-1CD23-1BG4 OR 3RA1125-1BD23-1BG4 |
| FBM1330-1MH10K6 | 3RA1115-1CD15-1AK6 OR 3RA1115-1BD15-1AK6 | 3RA1125-1CD23-1AK6 OR 3RA1125-1BD23-1AK6 |
| FBM1330-1MH10M1 | 3RA1115-1CD15-1AM2 OR 3RA1115-1BD15-1AM2 | 3RA1125-1CD23-1AM2 OR 3RA1125-1BD23-1AM2 |
| FBM1330-1MH10P6 | 3RA1115-1CD15-1AP6 OR 3RA1115-1BD15-1AP6 | 3RA1125-1CD23-1AP6 OR 3RA1125-1BD23-1AP6 |
| FBM1330-1MH10Q0 | 3RA1115-1CD15-1AV0 OR 3RA1115-1BD15-1AV0 | 3RA1125-1CD23-1AV0 OR 3RA1125-1BD23-1AV0 |
| FBM1330-1MH10Q4 | 3RA1115-1CD15-1BP4 OR 3RA1115-1BD15-1BP4 | 3RA1125-1CD23-1BP4 OR 3RA1125-1BD23-1BP4 |
| FBM1330-1MH10S0 | 3RA1115-1CD15-1AT6 OR 3RA1115-1BD15-1AT6 | 3RA1125-1CD23-1AT6 OR 3RA1125-1BD23-1AT6 |
| FBM1330-1MH10U1 | 3RA1115-1CD15-1AU6 OR 3RA1115-1BD15-1AU6 | 3RA1125-1CD23-1AU6 OR 3RA1125-1BD23-1AU6 |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| FBM1330-1MH10W4 | 3RA1115-1CD15-1BW4 OR 3RA1115-1BD15-1BW4 | 3RA1125-1CD23-1BW4 OR 3RA1125-1BD23-1BW4 |
| FBM1330-1MJ10A4 | 3RA1115-1ED15-1BA4 OR 3RA1115-1DD15-1BA4 | 3RA1125-1ED23-1BA4 OR 3RA1125-1DD23-1BA4 |
| FBM1330-1MJ10B4 | 3RA1115-1ED15-1BB4 OR 3RA1115-1DD15-1BB4 | 3RA1125-1ED23-1BB4 OR 3RA1125-1DD23-1BB4 |
| FBM1330-1MJ10C2 | 3RA1115-1ED15-1AC2 OR 3RA1115-1DD15-1AC2 | 3RA1125-1ED23-1AC2 OR 3RA1125-1DD23-1AC2 |
| FBM1330-1MJ10G4 | 3RA1115-1ED15-1BG4 OR 3RA1115-1DD15-1BG4 | 3RA1125-1ED23-1BG4 OR 3RA1125-1DD23-1BG4 |
| FBM1330-1MJ10K6 | 3RA1115-1ED15-1AK6 OR 3RA1115-1DD15-1AK6 | 3RA1125-1ED23-1AK6 OR 3RA1125-1DD23-1AK6 |
| FBM1330-1MJ10M1 | 3RA1115-1ED15-1AM2 OR 3RA1115-1DD15-1AM2 | 3RA1125-1ED23-1AM2 OR 3RA1125-1DD23-1AM2 |
| FBM1330-1MJ10P6 | 3RA1115-1ED15-1AP6 OR 3RA1115-1DD15-1AP6 | 3RA1125-1ED23-1AP6 OR 3RA1125-1DD23-1AP6 |
| FBM1330-1MJ10Q0 | 3RA1115-1ED15-1AV0 OR 3RA1115-1DD15-1AV0 | 3RA1125-1ED23-1AV0 OR 3RA1125-1DD23-1AV0 |
| FBM1330-1MJ10Q4 | 3RA1115-1ED15-1BP4 OR 3RA1115-1DD15-1BP4 | 3RA1125-1ED23-1BP4 OR 3RA1125-1DD23-1BP4 |
| FBM1330-1MJ10S0 | 3RA1115-1ED15-1AT6 OR 3RA1115-1DD15-1AT6 | 3RA1125-1ED23-1AT6 OR 3RA1125-1DD23-1AT6 |
| FBM1330-1MJ10U1 | 3RA1115-1ED15-1AU6 OR 3RA1115-1DD15-1AU6 | 3RA1125-1ED23-1AU6 OR 3RA1125-1DD23-1AU6 |
| FBM1330-1MJ10W4 | 3RA1115-1ED15-1BW4 OR 3RA1115-1DD15-1BW4 | 3RA1125-1ED23-1BW4 OR 3RA1125-1DD23-1BW4 |
| FBM1330-1MK10A4 | 3RA1115-1GD15-1BA4 OR 3RA1115-1FD15-1BA4 | 3RA1125-1GD23-1BA4 OR 3RA1125-1FD23-1BA4 |
| FBM1330-1MK10B4 | 3RA1115-1GD15-1BB4 OR 3RA1115-1FD15-1BB4 | 3RA1125-1GD23-1BB4 OR 3RA1125-1FD23-1BB4 |
| FBM1330-1MK10C2 | 3RA1115-1GD15-1AC2 OR 3RA1115-1FD15-1AC2 | 3RA1125-1GD23-1AC2 OR 3RA1125-1FD23-1AC2 |
| FBM1330-1MK10G4 | 3RA1115-1GD15-1BG4 OR 3RA1115-1FD15-1BG4 | 3RA1125-1GD23-1BG4 OR 3RA1125-1FD23-1BG4 |
| FBM1330-1MK10K6 | 3RA1115-1GD15-1AK6 OR 3RA1115-1FD15-1AK6 | 3RA1125-1GD23-1AK6 OR 3RA1125-1FD23-1AK6 |
| FBM1330-1MK10M1 | 3RA1115-1GD15-1AM2 OR 3RA1115-1FD15-1AM2 | 3RA1125-1GD23-1AM2 OR 3RA1125-1FD23-1AM2 |
| FBM1330-1MK10P6 | 3RA1115-1GD15-1AP6 OR 3RA1115-1FD15-1AP6 | 3RA1125-1GD23-1AP6 OR 3RA1125-1FD23-1AP6 |
| FBM1330-1MK10Q0 | 3RA1115-1GD15-1AV0 OR 3RA1115-1FD15-1AV0 | 3RA1125-1GD23-1AV0 OR 3RA1125-1FD23-1AV0 |
| FBM1330-1MK10Q4 | 3RA1115-1GD15-1BP4 OR 3RA1115-1FD15-1BP4 | 3RA1125-1GD23-1BP4 OR 3RA1125-1FD23-1BP4 |
| FBM1330-1MK10S0 | 3RA1115-1GD15-1AT6 OR 3RA1115-1FD15-1AT6 | 3RA1125-1GD23-1AT6 OR 3RA1125-1FD23-1AT6 |
| FBM1330-1MK10U1 | 3RA1115-1GD15-1AU6 OR 3RA1115-1FD15-1AU6 | 3RA1125-1GD23-1AU6 OR 3RA1125-1FD23-1AU6 |
| FBM1330-1MK10W4 | 3RA1115-1GD15-1BW4 OR 3RA1115-1FD15-1BW4 | 3RA1125-1GD23-1BW4 OR 3RA1125-1FD23-1BW4 |
| FBM1330-1ML10A4 | 3RA1125-1JD24-1BA4 OR 3RA1115-1HD16-1BA4 | |
| FBM1330-1ML10B4 | 3RA1125-1JD24-1BB4 OR 3RA1115-1HD16-1BB4 | |
| FBM1330-1ML10C2 | 3RA1125-1JD24-1AC2 OR 3RA1115-1HD16-1AC2 | |
| FBM1330-1ML10G4 | 3RA1125-1JD24-1BG4 OR 3RA1115-1HD16-1BG4 | |
| FBM1330-1ML10K6 | 3RA1125-1JD24-1AK6 OR 3RA1115-1HD16-1AK6 | |
| FBM1330-1ML10M1 | 3RA1125-1JD24-1AM2 OR 3RA1115-1HD16-1AM2 | |
| FBM1330-1ML10P6 | 3RA1125-1JD24-1AP6 OR 3RA1115-1HD16-1AP6 | |
| FBM1330-1ML10Q0 | 3RA1125-1JD24-1AV0 OR 3RA1115-1HD16-1AV0 | |
| FBM1330-1ML10Q4 | 3RA1125-1JD24-1BP4 OR 3RA1115-1HD16-1BP4 | |
| FBM1330-1ML10S0 | 3RA1125-1JD24-1AT6 OR 3RA1115-1HD16-1AT6 | |
| FBM1330-1ML10U1 | 3RA1125-1JD24-1AU6 OR 3RA1115-1HD16-1AU6 | |
| FBM1330-1ML10W4 | 3RA1125-1JD24-1BW4 OR 3RA1115-1HD16-1BW4 | |
| FBM1330-1NH10K6 | 3RA1115-1DD15-1AK6 OR 3RA1115-1CD15-1AK6 | 3RA1125-1DD23-1AK6 OR 3RA1125-1CD23-1AK6 |
| FBM1330-1NJ10K6 | 3RA1115-1FD15-1AK6 OR 3RA1115-1ED15-1AK6 | 3RA1125-1FD23-1AK6 OR 3RA1125-1ED23-1AK6 |
| FBM1330-1NK10K6 | 3RA1115-1HD16-1AK6 OR 3RA1115-1GD15-1AK6 | 3RA1125-1HD23-1AK6 OR 3RA1125-1GD23-1AK6 |
| FBM1332-1MG10A4 | 3RA1115-1AD15-1BA4 OR 3RA1115-0KD15-1BA4 | 3RA1125-1AD23-1BA4 OR 3RA1125-0KD23-1BA4 |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| FBM1332-1MG10B4 | 3RA1115-1AD15-1BB4 OR 3RA1115-0KD15-1BB4 | 3RA1125-1AD23-1BB4 OR 3RA1125-0KD23-1BB4 |
| FBM1332-1MG10C2 | 3RA1115-1AD15-1AC2 OR 3RA1115-0KD15-1AC2 | 3RA1125-1AD23-1AC2 OR 3RA1125-0KD23-1AC2 |
| FBM1332-1MG10G4 | 3RA1115-1AD15-1BG4 OR 3RA1115-0KD15-1BG4 | 3RA1125-1AD23-1BG4 OR 3RA1125-0KD23-1BG4 |
| FBM1332-1MG10K6 | 3RA1115-1AD15-1AK6 OR 3RA1115-0KD15-1AK6 | 3RA1125-1AD23-1AK6 OR 3RA1125-0KD23-1AK6 |
| FBM1332-1MG10M1 | 3RA1115-1AD15-1AM2 OR 3RA1115-0KD15-1AM2 | 3RA1125-1AD23-1AM2 OR 3RA1125-0KD23-1AM2 |
| FBM1332-1MG10P6 | 3RA1115-1AD15-1AP6 OR 3RA1115-0KD15-1AP6 | 3RA1125-1AD23-1AP6 OR 3RA1125-0KD23-1AP6 |
| FBM1332-1MG10Q0 | 3RA1115-1AD15-1AV0 OR 3RA1115-0KD15-1AV0 | 3RA1125-1AD23-1AV0 OR 3RA1125-0KD23-1AV0 |
| FBM1332-1MG10Q4 | 3RA1115-1AD15-1BP4 OR 3RA1115-0KD15-1BP4 | 3RA1125-1AD23-1BP4 OR 3RA1125-0KD23-1BP4 |
| FBM1332-1MG10S0 | 3RA1115-1AD15-1AT6 OR 3RA1115-0KD15-1AT6 | 3RA1125-1AD23-1AT6 OR 3RA1125-0KD23-1AT6 |
| FBM1332-1MG10U1 | 3RA1115-1AD15-1AU6 OR 3RA1115-0KD15-1AU6 | 3RA1125-1AD23-1AU6 OR 3RA1125-0KD23-1AU6 |
| FBM1332-1MG10W4 | 3RA1115-1AD15-1BW4 OR 3RA1115-0KD15-1BW4 | 3RA1125-1AD23-1BW4 OR 3RA1125-0KD23-1BW4 |
| FBM1332-1MH10A4 | 3RA1115-1CD15-1BA4 OR 3RA1115-1BD15-1BA4 | 3RA1125-1CD23-1BA4 OR 3RA1125-1BD23-1BA4 |
| FBM1332-1MH10B4 | 3RA1115-1CD15-1BB4 OR 3RA1115-1BD15-1BB4 | 3RA1125-1CD23-1BB4 OR 3RA1125-1BD23-1BB4 |
| FBM1332-1MH10C2 | 3RA1115-1CD15-1AC2 OR 3RA1115-1BD15-1AC2 | 3RA1125-1CD23-1AC2 OR 3RA1125-1BD23-1AC2 |
| FBM1332-1MH10G4 | 3RA1115-1CD15-1BG4 OR 3RA1115-1BD15-1BG4 | 3RA1125-1CD23-1BG4 OR 3RA1125-1BD23-1BG4 |
| FBM1332-1MH10K6 | 3RA1115-1CD15-1AK6 OR 3RA1115-1BD15-1AK6 | 3RA1125-1CD23-1AK6 OR 3RA1125-1BD23-1AK6 |
| FBM1332-1MH10M1 | 3RA1115-1CD15-1AM2 OR 3RA1115-1BD15-1AM2 | 3RA1125-1CD23-1AM2 OR 3RA1125-1BD23-1AM2 |
| FBM1332-1MH10P6 | 3RA1115-1CD15-1AP6 OR 3RA1115-1BD15-1AP6 | 3RA1125-1CD23-1AP6 OR 3RA1125-1BD23-1AP6 |
| FBM1332-1MH10Q0 | 3RA1115-1CD15-1AV0 OR 3RA1115-1BD15-1AV0 | 3RA1125-1CD23-1AV0 OR 3RA1125-1BD23-1AV0 |
| FBM1332-1MH10Q4 | 3RA1115-1CD15-1BP4 OR 3RA1115-1BD15-1BP4 | 3RA1125-1CD23-1BP4 OR 3RA1125-1BD23-1BP4 |
| FBM1332-1MH10S0 | 3RA1115-1CD15-1AT6 OR 3RA1115-1BD15-1AT6 | 3RA1125-1CD23-1AT6 OR 3RA1125-1BD23-1AT6 |
| FBM1332-1MH10U1 | 3RA1115-1CD15-1AU6 OR 3RA1115-1BD15-1AU6 | 3RA1125-1CD23-1AU6 OR 3RA1125-1BD23-1AU6 |
| FBM1332-1MH10W4 | 3RA1115-1CD15-1BW4 OR 3RA1115-1BD15-1BW4 | 3RA1125-1CD23-1BW4 OR 3RA1125-1BD23-1BW4 |
| FBM1332-1MJ10A4 | 3RA1115-1ED15-1BA4 OR 3RA1115-1DD15-1BA4 | 3RA1125-1ED23-1BA4 OR 3RA1125-1DD23-1BA4 |
| FBM1332-1MJ10B4 | 3RA1115-1ED15-1BB4 OR 3RA1115-1DD15-1BB4 | 3RA1125-1ED23-1BB4 OR 3RA1125-1DD23-1BB4 |
| FBM1332-1MJ10C2 | 3RA1115-1ED15-1AC2 OR 3RA1115-1DD15-1AC2 | 3RA1125-1ED23-1AC2 OR 3RA1125-1DD23-1AC2 |
| FBM1332-1MJ10G4 | 3RA1115-1ED15-1BG4 OR 3RA1115-1DD15-1BG4 | 3RA1125-1ED23-1BG4 OR 3RA1125-1DD23-1BG4 |
| FBM1332-1MJ10K6 | 3RA1115-1ED15-1AK6 OR 3RA1115-1DD15-1AK6 | 3RA1125-1ED23-1AK6 OR 3RA1125-1DD23-1AK6 |
| FBM1332-1MJ10M1 | 3RA1115-1ED15-1AM2 OR 3RA1115-1DD15-1AM2 | 3RA1125-1ED23-1AM2 OR 3RA1125-1DD23-1AM2 |
| FBM1332-1MJ10P6 | 3RA1115-1ED15-1AP6 OR 3RA1115-1DD15-1AP6 | 3RA1125-1ED23-1AP6 OR 3RA1125-1DD23-1AP6 |
| FBM1332-1MJ10Q0 | 3RA1115-1ED15-1AV0 OR 3RA1115-1DD15-1AV0 | 3RA1125-1ED23-1AV0 OR 3RA1125-1DD23-1AV0 |
| FBM1332-1MJ10Q4 | 3RA1115-1ED15-1BP4 OR 3RA1115-1DD15-1BP4 | 3RA1125-1ED23-1BP4 OR 3RA1125-1DD23-1BP4 |
| FBM1332-1MJ10S0 | 3RA1115-1ED15-1AT6 OR 3RA1115-1DD15-1AT6 | 3RA1125-1ED23-1AT6 OR 3RA1125-1DD23-1AT6 |
| FBM1332-1MJ10U1 | 3RA1115-1ED15-1AU6 OR 3RA1115-1DD15-1AU6 | 3RA1125-1ED23-1AU6 OR 3RA1125-1DD23-1AU6 |
| FBM1332-1MJ10W4 | 3RA1115-1ED15-1BW4 OR 3RA1115-1DD15-1BW4 | 3RA1125-1ED23-1BW4 OR 3RA1125-1DD23-1BW4 |
| FBM1332-1MK10A4 | 3RA1115-1GD15-1BA4 OR 3RA1115-1FD15-1BA4 | 3RA1125-1GD23-1BA4 OR 3RA1125-1FD23-1BA4 |
| FBM1332-1MK10B4 | 3RA1115-1GD15-1BB4 OR 3RA1115-1FD15-1BB4 | 3RA1125-1GD23-1BB4 OR 3RA1125-1FD23-1BB4 |
| FBM1332-1MK10C2 | 3RA1115-1GD15-1AC2 OR 3RA1115-1FD15-1AC2 | 3RA1125-1GD23-1AC2 OR 3RA1125-1FD23-1AC2 |
| FBM1332-1MK10G4 | 3RA1115-1GD15-1BG4 OR 3RA1115-1FD15-1BG4 | 3RA1125-1GD23-1BG4 OR 3RA1125-1FD23-1BG4 |
| FBM1332-1MK10K6 | 3RA1115-1GD15-1AK6 OR 3RA1115-1FD15-1AK6 | 3RA1125-1GD23-1AK6 OR 3RA1125-1FD23-1AK6 |
| FBM1332-1MK10M1 | 3RA1115-1GD15-1AM2 OR 3RA1115-1FD15-1AM2 | 3RA1125-1GD23-1AM2 OR 3RA1125-1FD23-1AM2 |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| FBM1332-1MK10P6 | 3RA1115-1GD15-1AP6 OR 3RA1115-1FD15-1AP6 | 3RA1125-1GD23-1AP6 OR 3RA1125-1FD23-1AP6 |
| FBM1332-1MK10Q0 | 3RA1115-1GD15-1AV0 OR 3RA1115-1FD15-1AV0 | 3RA1125-1GD23-1AV0 OR 3RA1125-1FD23-1AV0 |
| FBM1332-1MK10Q4 | 3RA1115-1GD15-1BP4 OR 3RA1115-1FD15-1BP4 | 3RA1125-1GD23-1BP4 OR 3RA1125-1FD23-1BP4 |
| FBM1332-1MK10S0 | 3RA1115-1GD15-1AT6 OR 3RA1115-1FD15-1AT6 | 3RA1125-1GD23-1AT6 OR 3RA1125-1FD23-1AT6 |
| FBM1332-1MK10U1 | 3RA1115-1GD15-1AU6 OR 3RA1115-1FD15-1AU6 | 3RA1125-1GD23-1AU6 OR 3RA1125-1FD23-1AU6 |
| FBM1332-1MK10W4 | 3RA1115-1GD15-1BW4 OR 3RA1115-1FD15-1BW4 | 3RA1125-1GD23-1BW4 OR 3RA1125-1FD23-1BW4 |
| FBM1332-1ML10K6 | 3RA1125-1JD24-1AK6 OR 3RA1115-1HD16-1AK6 | |
| FBM1332-1ML10P6 | 3RA1125-1JD24-1AP6 OR 3RA1115-1HD16-1AP6 | |
| FBM1332-1MM10A4 | 3RA1125-4AD25-1BA4 OR 3RA1125-1KD23-1BA4 | |
| FBM1332-1MM10B4 | 3RA1125-4AD25-1BB4 OR 3RA1125-1KD23-1BB4 | |
| FBM1332-1MM10C2 | 3RA1125-4AD25-1AC2 OR 3RA1125-1KD23-1AC2 | |
| FBM1332-1MM10G4 | 3RA1125-4AD25-1BG4 OR 3RA1125-1KD23-1BG4 | |
| FBM1332-1MM10K6 | 3RA1125-4AD25-1AK6 OR 3RA1125-1KD23-1AK6 | |
| FBM1332-1MM10M1 | 3RA1125-4AD25-1AM2 OR 3RA1125-1KD23-1AM2 | |
| FBM1332-1MM10P6 | 3RA1125-4AD25-1AP6 OR 3RA1125-1KD23-1AP6 | |
| FBM1332-1MM10Q0 | 3RA1125-4AD25-1AV0 OR 3RA1125-1KD23-1AV0 | |
| FBM1332-1MM10Q4 | 3RA1125-4AD25-1BP4 OR 3RA1125-1KD23-1BP4 | |
| FBM1332-1MM10S0 | 3RA1125-4AD25-1AT6 OR 3RA1125-1KD23-1AT6 | |
| FBM1332-1MM10U1 | 3RA1125-4AD25-1AU6 OR 3RA1125-1KD23-1AU6 | |
| FBM1332-1MM10W4 | 3RA1125-4AD25-1BW4 OR 3RA1125-1KD23-1BW4 | |
| FBM1332-1NL10K6 | 3RA1125-1KD25-1AK6 OR 3RA1125-1JD24-1AK6 | |
| FBM1333-1MN10A4 | 3RA1125-4BD26-1BA4 | |
| FBM1333-1MN10B4 | 3RA1125-4BD26-1BB4 | |
| FBM1333-1MN10C2 | 3RA1125-4BD26-1AC2 | |
| FBM1333-1MN10G4 | 3RA1125-4BD26-1BG4 | |
| FBM1333-1MN10K6 | 3RA1125-4BD26-1AK6 | |
| FBM1333-1MN10M1 | 3RA1125-4BD26-1AM2 | |
| FBM1333-1MN10P6 | 3RA1125-4BD26-1AP6 | |
| FBM1333-1MN10Q0 | 3RA1125-4BD26-1AV0 | |
| FBM1333-1MN10Q4 | 3RA1125-4BD26-1BP4 | |
| FBM1333-1MN10S0 | 3RA1125-4BD26-1AT6 | |
| FBM1333-1MN10U1 | 3RA1125-4BD26-1AU6 | |
| FBM1333-1MN10W4 | 3RA1125-4BD26-1BW4 | |
| FBM1334-1MM10K6 | 3RA1125-4AD25-1AK6 OR 3RA1125-1KD23-1AK6 | |
| FBM1334-1MM10P6 | 3RA1125-4AD25-1AP6 OR 3RA1125-1KD23-1AP6 | |
| FBM1334-1MN10A4 | 3RA1125-4BD26-1BA4 | |
| FBM1334-1MN10B4 | 3RA1125-4BD26-1BB4 | |
| FBM1334-1MN10C2 | 3RA1125-4BD26-1AC2 | |
| FBM1334-1MN10G4 | 3RA1125-4BD26-1BG4 | |
| FBM1334-1MN10K6 | 3RA1125-4BD26-1AK6 | |
| FBM1334-1MN10M1 | 3RA1125-4BD26-1AM2 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| FBM1334-1MN10P6 | 3RA1125-4BD26-1AP6 | |
| FBM1334-1MN10Q0 | 3RA1125-4BD26-1AV0 | |
| FBM1334-1MN10Q4 | 3RA1125-4BD26-1BP4 | |
| FBM1334-1MN10S0 | 3RA1125-4BD26-1AT6 | |
| FBM1334-1MN10U1 | 3RA1125-4BD26-1AU6 | |
| FBM1334-1MN10W4 | 3RA1125-4BD26-1BW4 | |
| FBM1334-1MP10A4 | 3RA1135-4DD33-1BA4 OR 3RA1125-4CD26-1BA4 | |
| FBM1334-1MP10B4 | 3RA1135-4DD33-1BB4 OR 3RA1125-4CD26-1BB4 | |
| FBM1334-1MP10C2 | 3RA1135-4DD33-1AC2 OR 3RA1125-4CD26-1AC2 | |
| FBM1334-1MP10G4 | 3RA1135-4DD33-1BG4 OR 3RA1125-4CD26-1BG4 | |
| FBM1334-1MP10K6 | 3RA1135-4DD33-1AK6 OR 3RA1125-4CD26-1AK6 | |
| FBM1334-1MP10M1 | 3RA1135-4DD33-1AM2 OR 3RA1125-4CD26-1AM2 | |
| FBM1334-1MP10P6 | 3RA1135-4DD33-1AP6 OR 3RA1125-4CD26-1AP6 | |
| FBM1334-1MP10Q0 | 3RA1135-4DD33-1AV0 OR 3RA1125-4CD26-1AV0 | |
| FBM1334-1MP10Q4 | 3RA1135-4DD33-1BP4 OR 3RA1125-4CD26-1BP4 | |
| FBM1334-1MP10S0 | 3RA1135-4DD33-1AT6 OR 3RA1125-4CD26-1AT6 | |
| FBM1334-1MP10U1 | 3RA1135-4DD33-1AU6 OR 3RA1125-4CD26-1AU6 | |
| FBM1334-1MP10W4 | 3RA1135-4DD33-1BW4 OR 3RA1125-4CD26-1BW4 | |
| FBM1634-1MP10A4 | 3RA1135-4ED34-1BA4 | |
| FBM1634-1MP10B4 | 3RA1135-4ED34-1BB4 | |
| FBM1634-1MP10C2 | 3RA1135-4ED34-1AC2 | |
| FBM1634-1MP10G4 | 3RA1135-4ED34-1BG4 | |
| FBM1634-1MP10K6 | 3RA1135-4ED34-1AK6 | |
| FBM1634-1MP10M1 | 3RA1135-4ED34-1AM2 | |
| FBM1634-1MP10P6 | 3RA1135-4ED34-1AP6 | |
| FBM1634-1MP10Q0 | 3RA1135-4ED34-1AV0 | |
| FBM1634-1MP10Q4 | 3RA1135-4ED34-1BP4 | |
| FBM1634-1MP10S0 | 3RA1135-4ED34-1AT6 | |
| FBM1634-1MP10U1 | 3RA1135-4ED34-1AU6 | |
| FBM1634-1MP10W4 | 3RA1135-4ED34-1BW4 | |
| FBM1635-1MQ10A4 | 3RA1135-4FD35-1BA4 | |
| FBM1635-1MQ10B4 | 3RA1135-4FD35-1BB4 | |
| FBM1635-1MQ10C2 | 3RA1135-4FD35-1AC2 | |
| FBM1635-1MQ10G4 | 3RA1135-4FD35-1BG4 | |
| FBM1635-1MQ10K6 | 3RA1135-4FD35-1AK6 | |
| FBM1635-1MQ10M1 | 3RA1135-4FD35-1AM2 | |
| FBM1635-1MQ10P6 | 3RA1135-4FD35-1AP6 | |
| FBM1635-1MQ10Q0 | 3RA1135-4FD35-1AV0 | |
| FBM1635-1MQ10Q4 | 3RA1135-4FD35-1BP4 | |
| FBM1635-1MQ10S0 | 3RA1135-4FD35-1AT6 | |
| FBM1635-1MQ10U1 | 3RA1135-4FD35-1AU6 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| FBM1635-1MQ10W4 | 3RA1135-4FD35-1BW4 | |
| FBM1646-1MR00 | NO DIRECT REPLACEMENT | |
| FBM1646-1MR00B4 | 3RA1135-4GD36-1BB4 OR 3RA1135-4HD36-1BB4 | |
| FBM1646-1MR00C1 | 3RA1135-4GD36-1AC2 OR 3RA1135-4HD36-1AC2 | |
| FBM1646-1MR00C2 | 3RA1135-4GD36-1AC2 OR 3RA1135-4HD36-1AC2 | |
| FBM1646-1MR00F4 | 3RA1135-4GD36-1BF4 OR 3RA1135-4HD36-1BF4 | |
| FBM1646-1MR00K6 | 3RA1135-4GD36-1AK6 OR 3RA1135-4HD36-1AK6 | |
| FBM1646-1MR00M1 | 3RA1135-4GD36-1AM2 OR 3RA1135-4HD36-1AM2 | |
| FBM1646-1MR00P4 | 3RA1135-4GD36-1AM2 OR 3RA1135-4HD36-1AM2 | |
| FBM1646-1MR00P6 | 3RA1135-4GD36-1AP6 OR 3RA1135-4HD36-1AP6 | |
| FBM1646-1MR00Q0 | 3RA1135-4GD36-1AV0 OR 3RA1135-4HD36-1AV0 | |
| FBM1646-1MR00S0 | 3RA1135-4GD36-1AT6 OR 3RA1135-4HD36-1AT6 | |
| FBM1646-1MR00U1 | 3RA1135-4GD36-1AU6 OR 3RA1135-4HD36-1AU6 | |
| FBM1646-1MR10B4 | 3RA1135-4GD36-1BB4 OR 3RA1135-4HD36-1BB4 | |
| FBM1646-1MR10C1 | 3RA1135-4GD36-1AC2 OR 3RA1135-4HD36-1AC2 | |
| FBM1646-1MR10C2 | 3RA1135-4GD36-1AC2 OR 3RA1135-4HD36-1AC2 | |
| FBM1646-1MR10F4 | 3RA1135-4GD36-1BF4 OR 3RA1135-4HD36-1BF4 | |
| FBM1646-1MR10K6 | 3RA1135-4GD36-1AK6 OR 3RA1135-4HD36-1AK6 | |
| FBM1646-1MR10M1 | 3RA1135-4GD36-1AM2 OR 3RA1135-4HD36-1AM2 | |
| FBM1646-1MR10P4 | 3RA1135-4GD36-1AM2 OR 3RA1135-4HD36-1AM2 | |
| FBM1646-1MR10P6 | 3RA1135-4GD36-1AP6 OR 3RA1135-4HD36-1AP6 | |
| FBM1646-1MR10Q0 | 3RA1135-4GD36-1AV0 OR 3RA1135-4HD36-1AV0 | |
| FBM1646-1MR10S0 | 3RA1135-4GD36-1AT6 OR 3RA1135-4HD36-1AT6 | |
| FBM1646-1MR10U1 | 3RA1135-4GD36-1AU6 OR 3RA1135-4HD36-1AU6 | |
| FBM1647-1LS00B4 | 3RA1145-4JD44-1BB4 OR 3RA1145-4KD45-1BB4 | |
| FBM1647-1LS00C1 | 3RA1145-4JD44-1AC2 OR 3RA1145-4KD45-1AC2 | |
| FBM1647-1LS00C2 | 3RA1145-4JD44-1AC2 OR 3RA1145-4KD45-1AC2 | |
| FBM1647-1LS00F4 | 3RA1145-4JD44-1BF4 OR 3RA1145-4KD45-1BF4 | |
| FBM1647-1LS00K6 | 3RA1145-4JD44-1AK6 OR 3RA1145-4KD45-1AK6 | |
| FBM1647-1LS00M1 | 3RA1145-4JD44-1AM2 OR 3RA1145-4KD45-1AM2 | |
| FBM1647-1LS00P4 | 3RA1145-4JD44-1AM2 OR 3RA1145-4KD45-1AM2 | |
| FBM1647-1LS00P6 | 3RA1145-4JD44-1AP6 OR 3RA1145-4KD45-1AP6 | |
| FBM1647-1LS00Q0 | 3RA1145-4JD44-1AV0 OR 3RA1145-4KD45-1AV0 | |
| FBM1647-1LS00S0 | 3RA1145-4JD44-1AT6 OR 3RA1145-4KD45-1AT6 | |
| FBM1647-1LS00U1 | 3RA1145-4JD44-1AU6 OR 3RA1145-4KD45-1AU6 | |
| FBM1647-1LS10B4 | 3RA1145-4JD44-1BB4 OR 3RA1145-4KD45-1BB4 | |
| FBM1647-1LS10C1 | 3RA1145-4JD44-1AC2 OR 3RA1145-4KD45-1AC2 | |
| FBM1647-1LS10C2 | 3RA1145-4JD44-1AC2 OR 3RA1145-4KD45-1AC2 | |
| FBM1647-1LS10F4 | 3RA1145-4JD44-1BF4 OR 3RA1145-4KD45-1BF4 | |
| FBM1647-1LS10K6 | 3RA1145-4JD44-1AK6 OR 3RA1145-4KD45-1AK6 | |
| FBM1647-1LS10M1 | 3RA1145-4JD44-1AM2 OR 3RA1145-4KD45-1AM2 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| FBM1647-1LS10P4 | 3RA1145-4JD44-1AM2 OR 3RA1145-4KD45-1AM2 | |
| FBM1647-1LS10P6 | 3RA1145-4JD44-1AP6 OR 3RA1145-4KD45-1AP6 | |
| FBM1647-1LS10Q0 | 3RA1145-4JD44-1AV0 OR 3RA1145-4KD45-1AV0 | |
| FBM1647-1LS10S0 | 3RA1145-4JD44-1AT6 OR 3RA1145-4KD45-1AT6 | |
| FBM1647-1LS10U1 | 3RA1145-4JD44-1AU6 OR 3RA1145-4KD45-1AU6 | |
| FBMR330-1MB10A4 | 3RA1215-0AD15-1BA4 | 3RA1225-0AD23-1BA4 |
| FBMR330-1MB10B4 | 3RA1215-0AD15-1BB4 | 3RA1225-0AD23-1BB4 |
| FBMR330-1MB10C2 | 3RA1215-0AD15-1AC2 | 3RA1225-0AD23-1AC2 |
| FBMR330-1MB10G4 | 3RA1215-0AD15-1BG4 | 3RA1225-0AD23-1BG4 |
| FBMR330-1MB10K6 | 3RA1215-0AD15-1AK6 | 3RA1225-0AD23-1AK6 |
| FBMR330-1MB10M1 | 3RA1215-0AD15-1AM2 | 3RA1225-0AD23-1AM2 |
| FBMR330-1MB10P6 | 3RA1215-0AD15-1AP6 | 3RA1225-0AD23-1AP6 |
| FBMR330-1MB10Q0 | 3RA1215-0AD15-1AV0 | 3RA1225-0AD23-1AV0 |
| FBMR330-1MB10Q4 | 3RA1215-0AD15-1BP4 | 3RA1225-0AD23-1BP4 |
| FBMR330-1MB10S0 | 3RA1215-0AD15-1AT6 | 3RA1225-0AD23-1AT6 |
| FBMR330-1MB10U1 | 3RA1215-0AD15-1AU6 | 3RA1225-0AD23-1AU6 |
| FBMR330-1MB10W4 | 3RA1215-0AD15-1BW4 | 3RA1225-0AD23-1BW4 |
| FBMR330-1MC10A4 | 3RA1215-0CD15-1BA4 OR 3RA1215-0BD15-1BA4 | 3RA1225-0CD23-1BA4 OR 3RA1225-0BD23-1BA4 |
| FBMR330-1MC10B4 | 3RA1215-0CD15-1BB4 OR 3RA1215-0BD15-1BB4 | 3RA1225-0CD23-1BB4 OR 3RA1225-0BD23-1BB4 |
| FBMR330-1MC10C2 | 3RA1215-0CD15-1AC2 OR 3RA1215-0BD15-1AC2 | 3RA1225-0CD23-1AC2 OR 3RA1225-0BD23-1AC2 |
| FBMR330-1MC10G4 | 3RA1215-0CD15-1BG4 OR 3RA1215-0BD15-1BG4 | 3RA1225-0CD23-1BG4 OR 3RA1225-0BD23-1BG4 |
| FBMR330-1MC10K6 | 3RA1215-0CD15-1AK6 OR 3RA1215-0BD15-1AK6 | 3RA1225-0CD23-1AK6 OR 3RA1225-0BD23-1AK6 |
| FBMR330-1MC10M1 | 3RA1215-0CD15-1AM2 OR 3RA1215-0BD15-1AM2 | 3RA1225-0CD23-1AM2 OR 3RA1225-0BD23-1AM2 |
| FBMR330-1MC10P6 | 3RA1215-0CD15-1AP6 OR 3RA1215-0BD15-1AP6 | 3RA1225-0CD23-1AP6 OR 3RA1225-0BD23-1AP6 |
| FBMR330-1MC10Q0 | 3RA1215-0CD15-1AV0 OR 3RA1215-0BD15-1AV0 | 3RA1225-0CD23-1AV0 OR 3RA1225-0BD23-1AV0 |
| FBMR330-1MC10Q4 | 3RA1215-0CD15-1BP4 OR 3RA1215-0BD15-1BP4 | 3RA1225-0CD23-1BP4 OR 3RA1225-0BD23-1BP4 |
| FBMR330-1MC10S0 | 3RA1215-0CD15-1AT6 OR 3RA1215-0BD15-1AT6 | 3RA1225-0CD23-1AT6 OR 3RA1225-0BD23-1AT6 |
| FBMR330-1MC10U1 | 3RA1215-0CD15-1AU6 OR 3RA1215-0BD15-1AU6 | 3RA1225-0CD23-1AU6 OR 3RA1225-0BD23-1AU6 |
| FBMR330-1MC10W4 | 3RA1215-0CD15-1BW4 OR 3RA1215-0BD15-1BW4 | 3RA1225-0CD23-1BW4 OR 3RA1225-0BD23-1BW4 |
| FBMR330-1MD10A4 | 3RA1215-0ED15-1BA4 OR 3RA1215-0DD15-1BA4 | 3RA1225-0ED23-1BA4 OR 3RA1225-0DD23-1BA4 |
| FBMR330-1MD10B4 | 3RA1215-0ED15-1BB4 OR 3RA1215-0DD15-1BB4 | 3RA1225-0ED23-1BB4 OR 3RA1225-0DD23-1BB4 |
| FBMR330-1MD10C2 | 3RA1215-0ED15-1AC2 OR 3RA1215-0DD15-1AC2 | 3RA1225-0ED23-1AC2 OR 3RA1225-0DD23-1AC2 |
| FBMR330-1MD10G4 | 3RA1215-0ED15-1BG4 OR 3RA1215-0DD15-1BG4 | 3RA1225-0ED23-1BG4 OR 3RA1225-0DD23-1BG4 |
| FBMR330-1MD10K6 | 3RA1215-0ED15-1AK6 OR 3RA1215-0DD15-1AK6 | 3RA1225-0ED23-1AK6 OR 3RA1225-0DD23-1AK6 |
| FBMR330-1MD10M1 | 3RA1215-0ED15-1AM2 OR 3RA1215-0DD15-1AM2 | 3RA1225-0ED23-1AM2 OR 3RA1225-0DD23-1AM2 |
| FBMR330-1MD10P6 | 3RA1215-0ED15-1AP6 OR 3RA1215-0DD15-1AP6 | 3RA1225-0ED23-1AP6 OR 3RA1225-0DD23-1AP6 |
| FBMR330-1MD10Q0 | 3RA1215-0ED15-1AV0 OR 3RA1215-0DD15-1AV0 | 3RA1225-0ED23-1AV0 OR 3RA1225-0DD23-1AV0 |
| FBMR330-1MD10Q4 | 3RA1215-0ED15-1BP4 OR 3RA1215-0DD15-1BP4 | 3RA1225-0ED23-1BP4 OR 3RA1225-0DD23-1BP4 |
| FBMR330-1MD10S0 | 3RA1215-0ED15-1AT6 OR 3RA1215-0DD15-1AT6 | 3RA1225-0ED23-1AT6 OR 3RA1225-0DD23-1AT6 |
| FBMR330-1MD10U1 | 3RA1215-0ED15-1AU6 OR 3RA1215-0DD15-1AU6 | 3RA1225-0ED23-1AU6 OR 3RA1225-0DD23-1AU6 |
| FBMR330-1MD10W4 | 3RA1215-0ED15-1BW4 OR 3RA1215-0DD15-1BW4 | 3RA1225-0ED23-1BW4 OR 3RA1225-0DD23-1BW4 |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| FBMR330-1ME10A4 | 3RA1215-0GD15-1BA4 OR 3RA1215-0FD15-1BA4 | 3RA1225-0GD23-1BA4 OR 3RA1225-0FD23-1BA4 |
| FBMR330-1ME10B4 | 3RA1215-0GD15-1BB4 OR 3RA1215-0FD15-1BB4 | 3RA1225-0GD23-1BB4 OR 3RA1225-0FD23-1BB4 |
| FBMR330-1ME10C2 | 3RA1215-0GD15-1AC2 OR 3RA1215-0FD15-1AC2 | 3RA1225-0GD23-1AC2 OR 3RA1225-0FD23-1AC2 |
| FBMR330-1ME10G4 | 3RA1215-0GD15-1BG4 OR 3RA1215-0FD15-1BG4 | 3RA1225-0GD23-1BG4 OR 3RA1225-0FD23-1BG4 |
| FBMR330-1ME10K6 | 3RA1215-0GD15-1AK6 OR 3RA1215-0FD15-1AK6 | 3RA1225-0GD23-1AK6 OR 3RA1225-0FD23-1AK6 |
| FBMR330-1ME10M1 | 3RA1215-0GD15-1AM2 OR 3RA1215-0FD15-1AM2 | 3RA1225-0GD23-1AM2 OR 3RA1225-0FD23-1AM2 |
| FBMR330-1ME10P6 | 3RA1215-0GD15-1AP6 OR 3RA1215-0FD15-1AP6 | 3RA1225-0GD23-1AP6 OR 3RA1225-0FD23-1AP6 |
| FBMR330-1ME10Q0 | 3RA1215-0GD15-1AV0 OR 3RA1215-0FD15-1AV0 | 3RA1225-0GD23-1AV0 OR 3RA1225-0FD23-1AV0 |
| FBMR330-1ME10Q4 | 3RA1215-0GD15-1BP4 OR 3RA1215-0FD15-1BP4 | 3RA1225-0GD23-1BP4 OR 3RA1225-0FD23-1BP4 |
| FBMR330-1ME10S0 | 3RA1215-0GD15-1AT6 OR 3RA1215-0FD15-1AT6 | 3RA1225-0GD23-1AT6 OR 3RA1225-0FD23-1AT6 |
| FBMR330-1ME10U1 | 3RA1215-0GD15-1AU6 OR 3RA1215-0FD15-1AU6 | 3RA1225-0GD23-1AU6 OR 3RA1225-0FD23-1AU6 |
| FBMR330-1ME10W4 | 3RA1215-0GD15-1BW4 OR 3RA1215-0FD15-1BW4 | 3RA1225-0GD23-1BW4 OR 3RA1225-0FD23-1BW4 |
| FBMR330-1MF10A4 | 3RA1215-0JD15-1BA4 OR 3RA1215-0HD15-1BA4 | 3RA1225-0JD23-1BA4 OR 3RA1225-0HD23-1BA4 |
| FBMR330-1MF10B4 | 3RA1215-0JD15-1BB4 OR 3RA1215-0HD15-1BB4 | 3RA1225-0JD23-1BB4 OR 3RA1225-0HD23-1BB4 |
| FBMR330-1MF10C2 | 3RA1215-0JD15-1AC2 OR 3RA1215-0HD15-1AC2 | 3RA1225-0JD23-1AC2 OR 3RA1225-0HD23-1AC2 |
| FBMR330-1MF10G4 | 3RA1215-0JD15-1BG4 OR 3RA1215-0HD15-1BG4 | 3RA1225-0JD23-1BG4 OR 3RA1225-0HD23-1BG4 |
| FBMR330-1MF10K6 | 3RA1215-0JD15-1AK6 OR 3RA1215-0HD15-1AK6 | 3RA1225-0JD23-1AK6 OR 3RA1225-0HD23-1AK6 |
| FBMR330-1MF10M1 | 3RA1215-0JD15-1AM2 OR 3RA1215-0HD15-1AM2 | 3RA1225-0JD23-1AM2 OR 3RA1225-0HD23-1AM2 |
| FBMR330-1MF10P6 | 3RA1215-0JD15-1AP6 OR 3RA1215-0HD15-1AP6 | 3RA1225-0JD23-1AP6 OR 3RA1225-0HD23-1AP6 |
| FBMR330-1MF10Q0 | 3RA1215-0JD15-1AV0 OR 3RA1215-0HD15-1AV0 | 3RA1225-0JD23-1AV0 OR 3RA1225-0HD23-1AV0 |
| FBMR330-1MF10Q4 | 3RA1215-0JD15-1BP4 OR 3RA1215-0HD15-1BP4 | 3RA1225-0JD23-1BP4 OR 3RA1225-0HD23-1BP4 |
| FBMR330-1MF10S0 | 3RA1215-0JD15-1AT6 OR 3RA1215-0HD15-1AT6 | 3RA1225-0JD23-1AT6 OR 3RA1225-0HD23-1AT6 |
| FBMR330-1MF10U1 | 3RA1215-0JD15-1AU6 OR 3RA1215-0HD15-1AU6 | 3RA1225-0JD23-1AU6 OR 3RA1225-0HD23-1AU6 |
| FBMR330-1MF10W4 | 3RA1215-0JD15-1BW4 OR 3RA1215-0HD15-1BW4 | 3RA1225-0JD23-1BW4 OR 3RA1225-0HD23-1BW4 |
| FBMR330-1MG10A4 | 3RA1215-1AD15-1BA4 OR 3RA1215-0KD15-1BA4 | 3RA1225-1AD23-1BA4 OR 3RA1225-0KD23-1BA4 |
| FBMR330-1MG10B4 | 3RA1215-1AD15-1BB4 OR 3RA1215-0KD15-1BB4 | 3RA1225-1AD23-1BB4 OR 3RA1225-0KD23-1BB4 |
| FBMR330-1MG10C2 | 3RA1215-1AD15-1AC2 OR 3RA1215-0KD15-1AC2 | 3RA1225-1AD23-1AC2 OR 3RA1225-0KD23-1AC2 |
| FBMR330-1MG10G4 | 3RA1215-1AD15-1BG4 OR 3RA1215-0KD15-1BG4 | 3RA1225-1AD23-1BG4 OR 3RA1225-0KD23-1BG4 |
| FBMR330-1MG10K6 | 3RA1215-1AD15-1AK6 OR 3RA1215-0KD15-1AK6 | 3RA1225-1AD23-1AK6 OR 3RA1225-0KD23-1AK6 |
| FBMR330-1MG10M1 | 3RA1215-1AD15-1AM2 OR 3RA1215-0KD15-1AM2 | 3RA1225-1AD23-1AM2 OR 3RA1225-0KD23-1AM2 |
| FBMR330-1MG10P6 | 3RA1215-1AD15-1AP6 OR 3RA1215-0KD15-1AP6 | 3RA1225-1AD23-1AP6 OR 3RA1225-0KD23-1AP6 |
| FBMR330-1MG10Q0 | 3RA1215-1AD15-1AV0 OR 3RA1215-0KD15-1AV0 | 3RA1225-1AD23-1AV0 OR 3RA1225-0KD23-1AV0 |
| FBMR330-1MG10Q4 | 3RA1215-1AD15-1BP4 OR 3RA1215-0KD15-1BP4 | 3RA1225-1AD23-1BP4 OR 3RA1225-0KD23-1BP4 |
| FBMR330-1MG10S0 | 3RA1215-1AD15-1AT6 OR 3RA1215-0KD15-1AT6 | 3RA1225-1AD23-1AT6 OR 3RA1225-0KD23-1AT6 |
| FBMR330-1MG10U1 | 3RA1215-1AD15-1AU6 OR 3RA1215-0KD15-1AU6 | 3RA1225-1AD23-1AU6 OR 3RA1225-0KD23-1AU6 |
| FBMR330-1MG10W4 | 3RA1215-1AD15-1BW4 OR 3RA1215-0KD15-1BW4 | 3RA1225-1AD23-1BW4 OR 3RA1225-0KD23-1BW4 |
| FBMR330-1MH10A4 | 3RA1215-1CD15-1BA4 OR 3RA1215-1BD15-1BA4 | 3RA1225-1CD23-1BA4 OR 3RA1225-1BD23-1BA4 |
| FBMR330-1MH10B4 | 3RA1215-1CD15-1BB4 OR 3RA1215-1BD15-1BB4 | 3RA1225-1CD23-1BB4 OR 3RA1225-1BD23-1BB4 |
| FBMR330-1MH10C2 | 3RA1215-1CD15-1AC2 OR 3RA1215-1BD15-1AC2 | 3RA1225-1CD23-1AC2 OR 3RA1225-1BD23-1AC2 |
| FBMR330-1MH10G4 | 3RA1215-1CD15-1BG4 OR 3RA1215-1BD15-1BG4 | 3RA1225-1CD23-1BG4 OR 3RA1225-1BD23-1BG4 |
| FBMR330-1MH10K6 | 3RA1215-1CD15-1AK6 OR 3RA1215-1BD15-1AK6 | 3RA1225-1CD23-1AK6 OR 3RA1225-1BD23-1AK6 |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| FBMR330-1MH10M1 | 3RA1215-1CD15-1AM2 OR 3RA1215-1BD15-1AM2 | 3RA1225-1CD23-1AM2 OR 3RA1225-1BD23-1AM2 |
| FBMR330-1MH10P6 | 3RA1215-1CD15-1AP6 OR 3RA1215-1BD15-1AP6 | 3RA1225-1CD23-1AP6 OR 3RA1225-1BD23-1AP6 |
| FBMR330-1MH10Q0 | 3RA1215-1CD15-1AV0 OR 3RA1215-1BD15-1AV0 | 3RA1225-1CD23-1AV0 OR 3RA1225-1BD23-1AV0 |
| FBMR330-1MH10Q4 | 3RA1215-1CD15-1BP4 OR 3RA1215-1BD15-1BP4 | 3RA1225-1CD23-1BP4 OR 3RA1225-1BD23-1BP4 |
| FBMR330-1MH10S0 | 3RA1215-1CD15-1AT6 OR 3RA1215-1BD15-1AT6 | 3RA1225-1CD23-1AT6 OR 3RA1225-1BD23-1AT6 |
| FBMR330-1MH10U1 | 3RA1215-1CD15-1AU6 OR 3RA1215-1BD15-1AU6 | 3RA1225-1CD23-1AU6 OR 3RA1225-1BD23-1AU6 |
| FBMR330-1MH10W4 | 3RA1215-1CD15-1BW4 OR 3RA1215-1BD15-1BW4 | 3RA1225-1CD23-1BW4 OR 3RA1225-1BD23-1BW4 |
| FBMR330-1MJ10A4 | 3RA1215-1ED15-1BA4 OR 3RA1215-1DD15-1BA4 | 3RA1225-1ED23-1BA4 OR 3RA1225-1DD23-1BA4 |
| FBMR330-1MJ10B4 | 3RA1215-1ED15-1BB4 OR 3RA1215-1DD15-1BB4 | 3RA1225-1ED23-1BB4 OR 3RA1225-1DD23-1BB4 |
| FBMR330-1MJ10C2 | 3RA1215-1ED15-1AC2 OR 3RA1215-1DD15-1AC2 | 3RA1225-1ED23-1AC2 OR 3RA1225-1DD23-1AC2 |
| FBMR330-1MJ10G4 | 3RA1215-1ED15-1BG4 OR 3RA1215-1DD15-1BG4 | 3RA1225-1ED23-1BG4 OR 3RA1225-1DD23-1BG4 |
| FBMR330-1MJ10K6 | 3RA1215-1ED15-1AK6 OR 3RA1215-1DD15-1AK6 | 3RA1225-1ED23-1AK6 OR 3RA1225-1DD23-1AK6 |
| FBMR330-1MJ10M1 | 3RA1215-1ED15-1AM2 OR 3RA1215-1DD15-1AM2 | 3RA1225-1ED23-1AM2 OR 3RA1225-1DD23-1AM2 |
| FBMR330-1MJ10P6 | 3RA1215-1ED15-1AP6 OR 3RA1215-1DD15-1AP6 | 3RA1225-1ED23-1AP6 OR 3RA1225-1DD23-1AP6 |
| FBMR330-1MJ10Q0 | 3RA1215-1ED15-1AV0 OR 3RA1215-1DD15-1AV0 | 3RA1225-1ED23-1AV0 OR 3RA1225-1DD23-1AV0 |
| FBMR330-1MJ10Q4 | 3RA1215-1ED15-1BP4 OR 3RA1215-1DD15-1BP4 | 3RA1225-1ED23-1BP4 OR 3RA1225-1DD23-1BP4 |
| FBMR330-1MJ10S0 | 3RA1215-1ED15-1AT6 OR 3RA1215-1DD15-1AT6 | 3RA1225-1ED23-1AT6 OR 3RA1225-1DD23-1AT6 |
| FBMR330-1MJ10U1 | 3RA1215-1ED15-1AU6 OR 3RA1215-1DD15-1AU6 | 3RA1225-1ED23-1AU6 OR 3RA1225-1DD23-1AU6 |
| FBMR330-1MJ10W4 | 3RA1215-1ED15-1BW4 OR 3RA1215-1DD15-1BW4 | 3RA1225-1ED23-1BW4 OR 3RA1225-1DD23-1BW4 |
| FBMR330-1MK10A4 | 3RA1215-1GD15-1BA4 OR 3RA1215-1FD15-1BA4 | 3RA1225-1GD23-1BA4 OR 3RA1225-1FD23-1BA4 |
| FBMR330-1MK10B4 | 3RA1215-1GD15-1BB4 OR 3RA1215-1FD15-1BB4 | 3RA1225-1GD23-1BB4 OR 3RA1225-1FD23-1BB4 |
| FBMR330-1MK10C2 | 3RA1215-1GD15-1AC2 OR 3RA1215-1FD15-1AC2 | 3RA1225-1GD23-1AC2 OR 3RA1225-1FD23-1AC2 |
| FBMR330-1MK10G4 | 3RA1215-1GD15-1BG4 OR 3RA1215-1FD15-1BG4 | 3RA1225-1GD23-1BG4 OR 3RA1225-1FD23-1BG4 |
| FBMR330-1MK10K6 | 3RA1215-1GD15-1AK6 OR 3RA1215-1FD15-1AK6 | 3RA1225-1GD23-1AK6 OR 3RA1225-1FD23-1AK6 |
| FBMR330-1MK10M1 | 3RA1215-1GD15-1AM2 OR 3RA1215-1FD15-1AM2 | 3RA1225-1GD23-1AM2 OR 3RA1225-1FD23-1AM2 |
| FBMR330-1MK10P6 | 3RA1215-1GD15-1AP6 OR 3RA1215-1FD15-1AP6 | 3RA1225-1GD23-1AP6 OR 3RA1225-1FD23-1AP6 |
| FBMR330-1MK10Q0 | 3RA1215-1GD15-1AV0 OR 3RA1215-1FD15-1AV0 | 3RA1225-1GD23-1AV0 OR 3RA1225-1FD23-1AV0 |
| FBMR330-1MK10Q4 | 3RA1215-1GD15-1BP4 OR 3RA1215-1FD15-1BP4 | 3RA1225-1GD23-1BP4 OR 3RA1225-1FD23-1BP4 |
| FBMR330-1MK10S0 | 3RA1215-1GD15-1AT6 OR 3RA1215-1FD15-1AT6 | 3RA1225-1GD23-1AT6 OR 3RA1225-1FD23-1AT6 |
| FBMR330-1MK10U1 | 3RA1215-1GD15-1AU6 OR 3RA1215-1FD15-1AU6 | 3RA1225-1GD23-1AU6 OR 3RA1225-1FD23-1AU6 |
| FBMR330-1MK10W4 | 3RA1215-1GD15-1BW4 OR 3RA1215-1FD15-1BW4 | 3RA1225-1GD23-1BW4 OR 3RA1225-1FD23-1BW4 |
| FBMR330-1ML10A4 | 3RA1225-1JD24-1BA4 OR 3RA1215-1HD16-1BA4 | |
| FBMR330-1ML10B4 | 3RA1225-1JD24-1BB4 OR 3RA1215-1HD16-1BB4 | |
| FBMR330-1ML10C2 | 3RA1225-1JD24-1AC2 OR 3RA1215-1HD16-1AC2 | |
| FBMR330-1ML10G4 | 3RA1225-1JD24-1BG4 OR 3RA1215-1HD16-1BG4 | |
| FBMR330-1ML10K6 | 3RA1225-1JD24-1AK6 OR 3RA1215-1HD16-1AK6 | |
| FBMR330-1ML10M1 | 3RA1225-1JD24-1AM2 OR 3RA1215-1HD16-1AM2 | |
| FBMR330-1ML10P6 | 3RA1225-1JD24-1AP6 OR 3RA1215-1HD16-1AP6 | |
| FBMR330-1ML10Q0 | 3RA1225-1JD24-1AV0 OR 3RA1215-1HD16-1AV0 | |
| FBMR330-1ML10Q4 | 3RA1225-1JD24-1BP4 OR 3RA1215-1HD16-1BP4 | |
| FBMR330-1ML10S0 | 3RA1225-1JD24-1AT6 OR 3RA1215-1HD16-1AT6 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| FBMR330-1ML10U1 | 3RA1225-1JD24-1AU6 OR 3RA1215-1HD16-1AU6 | |
| FBMR330-1ML10W4 | 3RA1225-1JD24-1BW4 OR 3RA1215-1HD16-1BW4 | |
| FBMR332-1MG10A4 | 3RA1215-1AD15-1BA4 OR 3RA1215-0KD15-1BA4 | 3RA1225-1AD23-1BA4 OR 3RA1225-0KD23-1BA4 |
| FBMR332-1MG10B4 | 3RA1215-1AD15-1BB4 OR 3RA1215-0KD15-1BB4 | 3RA1225-1AD23-1BB4 OR 3RA1225-0KD23-1BB4 |
| FBMR332-1MG10C2 | 3RA1215-1AD15-1AC2 OR 3RA1215-0KD15-1AC2 | 3RA1225-1AD23-1AC2 OR 3RA1225-0KD23-1AC2 |
| FBMR332-1MG10G4 | 3RA1215-1AD15-1BG4 OR 3RA1215-0KD15-1BG4 | 3RA1225-1AD23-1BG4 OR 3RA1225-0KD23-1BG4 |
| FBMR332-1MG10K6 | 3RA1215-1AD15-1AK6 OR 3RA1215-0KD15-1AK6 | 3RA1225-1AD23-1AK6 OR 3RA1225-0KD23-1AK6 |
| FBMR332-1MG10M1 | 3RA1215-1AD15-1AM2 OR 3RA1215-0KD15-1AM2 | 3RA1225-1AD23-1AM2 OR 3RA1225-0KD23-1AM2 |
| FBMR332-1MG10P6 | 3RA1215-1AD15-1AP6 OR 3RA1215-0KD15-1AP6 | 3RA1225-1AD23-1AP6 OR 3RA1225-0KD23-1AP6 |
| FBMR332-1MG10Q0 | 3RA1215-1AD15-1AV0 OR 3RA1215-0KD15-1AV0 | 3RA1225-1AD23-1AV0 OR 3RA1225-0KD23-1AV0 |
| FBMR332-1MG10Q4 | 3RA1215-1AD15-1BP4 OR 3RA1215-0KD15-1BP4 | 3RA1225-1AD23-1BP4 OR 3RA1225-0KD23-1BP4 |
| FBMR332-1MG10S0 | 3RA1215-1AD15-1AT6 OR 3RA1215-0KD15-1AT6 | 3RA1225-1AD23-1AT6 OR 3RA1225-0KD23-1AT6 |
| FBMR332-1MG10U1 | 3RA1215-1AD15-1AU6 OR 3RA1215-0KD15-1AU6 | 3RA1225-1AD23-1AU6 OR 3RA1225-0KD23-1AU6 |
| FBMR332-1MG10W4 | 3RA1215-1AD15-1BW4 OR 3RA1215-0KD15-1BW4 | 3RA1225-1AD23-1BW4 OR 3RA1225-0KD23-1BW4 |
| FBMR332-1MH10A4 | 3RA1215-1CD15-1BA4 OR 3RA1215-1BD15-1BA4 | 3RA1225-1CD23-1BA4 OR 3RA1225-1BD23-1BA4 |
| FBMR332-1MH10B4 | 3RA1215-1CD15-1BB4 OR 3RA1215-1BD15-1BB4 | 3RA1225-1CD23-1BB4 OR 3RA1225-1BD23-1BB4 |
| FBMR332-1MH10C2 | 3RA1215-1CD15-1AC2 OR 3RA1215-1BD15-1AC2 | 3RA1225-1CD23-1AC2 OR 3RA1225-1BD23-1AC2 |
| FBMR332-1MH10G4 | 3RA1215-1CD15-1BG4 OR 3RA1215-1BD15-1BG4 | 3RA1225-1CD23-1BG4 OR 3RA1225-1BD23-1BG4 |
| FBMR332-1MH10K6 | 3RA1215-1CD15-1AK6 OR 3RA1215-1BD15-1AK6 | 3RA1225-1CD23-1AK6 OR 3RA1225-1BD23-1AK6 |
| FBMR332-1MH10M1 | 3RA1215-1CD15-1AM2 OR 3RA1215-1BD15-1AM2 | 3RA1225-1CD23-1AM2 OR 3RA1225-1BD23-1AM2 |
| FBMR332-1MH10P6 | 3RA1215-1CD15-1AP6 OR 3RA1215-1BD15-1AP6 | 3RA1225-1CD23-1AP6 OR 3RA1225-1BD23-1AP6 |
| FBMR332-1MH10Q0 | 3RA1215-1CD15-1AV0 OR 3RA1215-1BD15-1AV0 | 3RA1225-1CD23-1AV0 OR 3RA1225-1BD23-1AV0 |
| FBMR332-1MH10Q4 | 3RA1215-1CD15-1BP4 OR 3RA1215-1BD15-1BP4 | 3RA1225-1CD23-1BP4 OR 3RA1225-1BD23-1BP4 |
| FBMR332-1MH10S0 | 3RA1215-1CD15-1AT6 OR 3RA1215-1BD15-1AT6 | 3RA1225-1CD23-1AT6 OR 3RA1225-1BD23-1AT6 |
| FBMR332-1MH10U1 | 3RA1215-1CD15-1AU6 OR 3RA1215-1BD15-1AU6 | 3RA1225-1CD23-1AU6 OR 3RA1225-1BD23-1AU6 |
| FBMR332-1MH10W4 | 3RA1215-1CD15-1BW4 OR 3RA1215-1BD15-1BW4 | 3RA1225-1CD23-1BW4 OR 3RA1225-1BD23-1BW4 |
| FBMR332-1MJ10A4 | 3RA1215-1ED15-1BA4 OR 3RA1215-1DD15-1BA4 | 3RA1225-1ED23-1BA4 OR 3RA1225-1DD23-1BA4 |
| FBMR332-1MJ10B4 | 3RA1215-1ED15-1BB4 OR 3RA1215-1DD15-1BB4 | 3RA1225-1ED23-1BB4 OR 3RA1225-1DD23-1BB4 |
| FBMR332-1MJ10C2 | 3RA1215-1ED15-1AC2 OR 3RA1215-1DD15-1AC2 | 3RA1225-1ED23-1AC2 OR 3RA1225-1DD23-1AC2 |
| FBMR332-1MJ10G4 | 3RA1215-1ED15-1BG4 OR 3RA1215-1DD15-1BG4 | 3RA1225-1ED23-1BG4 OR 3RA1225-1DD23-1BG4 |
| FBMR332-1MJ10K6 | 3RA1215-1ED15-1AK6 OR 3RA1215-1DD15-1AK6 | 3RA1225-1ED23-1AK6 OR 3RA1225-1DD23-1AK6 |
| FBMR332-1MJ10M1 | 3RA1215-1ED15-1AM2 OR 3RA1215-1DD15-1AM2 | 3RA1225-1ED23-1AM2 OR 3RA1225-1DD23-1AM2 |
| FBMR332-1MJ10P6 | 3RA1215-1ED15-1AP6 OR 3RA1215-1DD15-1AP6 | 3RA1225-1ED23-1AP6 OR 3RA1225-1DD23-1AP6 |
| FBMR332-1MJ10Q0 | 3RA1215-1ED15-1AV0 OR 3RA1215-1DD15-1AV0 | 3RA1225-1ED23-1AV0 OR 3RA1225-1DD23-1AV0 |
| FBMR332-1MJ10Q4 | 3RA1215-1ED15-1BP4 OR 3RA1215-1DD15-1BP4 | 3RA1225-1ED23-1BP4 OR 3RA1225-1DD23-1BP4 |
| FBMR332-1MJ10S0 | 3RA1215-1ED15-1AT6 OR 3RA1215-1DD15-1AT6 | 3RA1225-1ED23-1AT6 OR 3RA1225-1DD23-1AT6 |
| FBMR332-1MJ10U1 | 3RA1215-1ED15-1AU6 OR 3RA1215-1DD15-1AU6 | 3RA1225-1ED23-1AU6 OR 3RA1225-1DD23-1AU6 |
| FBMR332-1MJ10W4 | 3RA1215-1ED15-1BW4 OR 3RA1215-1DD15-1BW4 | 3RA1225-1ED23-1BW4 OR 3RA1225-1DD23-1BW4 |
| FBMR332-1MK10A4 | 3RA1215-1GD15-1BA4 OR 3RA1215-1FD15-1BA4 | 3RA1225-1GD23-1BA4 OR 3RA1225-1FD23-1BA4 |
| FBMR332-1MK10B4 | 3RA1215-1GD15-1BB4 OR 3RA1215-1FD15-1BB4 | 3RA1225-1GD23-1BB4 OR 3RA1225-1FD23-1BB4 |
| FBMR332-1MK10C2 | 3RA1215-1GD15-1AC2 OR 3RA1215-1FD15-1AC2 | 3RA1225-1GD23-1AC2 OR 3RA1225-1FD23-1AC2 |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| FBMR332-1MK10G4 | 3RA1215-1GD15-1BG4 OR 3RA1215-1FD15-1BG4 | 3RA1225-1GD23-1BG4 OR 3RA1225-1FD23-1BG4 |
| FBMR332-1MK10K6 | 3RA1215-1GD15-1AK6 OR 3RA1215-1FD15-1AK6 | 3RA1225-1GD23-1AK6 OR 3RA1225-1FD23-1AK6 |
| FBMR332-1MK10M1 | 3RA1215-1GD15-1AM2 OR 3RA1215-1FD15-1AM2 | 3RA1225-1GD23-1AM2 OR 3RA1225-1FD23-1AM2 |
| FBMR332-1MK10P6 | 3RA1215-1GD15-1AP6 OR 3RA1215-1FD15-1AP6 | 3RA1225-1GD23-1AP6 OR 3RA1225-1FD23-1AP6 |
| FBMR332-1MK10Q0 | 3RA1215-1GD15-1AV0 OR 3RA1215-1FD15-1AV0 | 3RA1225-1GD23-1AV0 OR 3RA1225-1FD23-1AV0 |
| FBMR332-1MK10Q4 | 3RA1215-1GD15-1BP4 OR 3RA1215-1FD15-1BP4 | 3RA1225-1GD23-1BP4 OR 3RA1225-1FD23-1BP4 |
| FBMR332-1MK10S0 | 3RA1215-1GD15-1AT6 OR 3RA1215-1FD15-1AT6 | 3RA1225-1GD23-1AT6 OR 3RA1225-1FD23-1AT6 |
| FBMR332-1MK10U1 | 3RA1215-1GD15-1AU6 OR 3RA1215-1FD15-1AU6 | 3RA1225-1GD23-1AU6 OR 3RA1225-1FD23-1AU6 |
| FBMR332-1MK10W4 | 3RA1215-1GD15-1BW4 OR 3RA1215-1FD15-1BW4 | 3RA1225-1GD23-1BW4 OR 3RA1225-1FD23-1BW4 |
| FBMR332-1MM10A4 | 3RA1225-4AD25-1BA4 OR 3RA1225-1KD23-1BA4 | |
| FBMR332-1MM10B4 | 3RA1225-4AD25-1BB4 OR 3RA1225-1KD23-1BB4 | |
| FBMR332-1MM10C2 | 3RA1225-4AD25-1AC2 OR 3RA1225-1KD23-1AC2 | |
| FBMR332-1MM10G4 | 3RA1225-4AD25-1BG4 OR 3RA1225-1KD23-1BG4 | |
| FBMR332-1MM10K6 | 3RA1225-4AD25-1AK6 OR 3RA1225-1KD23-1AK6 | |
| FBMR332-1MM10M1 | 3RA1225-4AD25-1AM2 OR 3RA1225-1KD23-1AM2 | |
| FBMR332-1MM10P6 | 3RA1225-4AD25-1AP6 OR 3RA1225-1KD23-1AP6 | |
| FBMR332-1MM10Q0 | 3RA1225-4AD25-1AV0 OR 3RA1225-1KD23-1AV0 | |
| FBMR332-1MM10Q4 | 3RA1225-4AD25-1BP4 OR 3RA1225-1KD23-1BP4 | |
| FBMR332-1MM10S0 | 3RA1225-4AD25-1AT6 OR 3RA1225-1KD23-1AT6 | |
| FBMR332-1MM10U1 | 3RA1225-4AD25-1AU6 OR 3RA1225-1KD23-1AU6 | |
| FBMR332-1MM10W4 | 3RA1225-4AD25-1BW4 OR 3RA1225-1KD23-1BW4 | |
| FBMR333-1MN10A4 | 3RA1225-4BD26-1BA4 | |
| FBMR333-1MN10B4 | 3RA1225-4BD26-1BB4 | |
| FBMR333-1MN10C2 | 3RA1225-4BD26-1AC2 | |
| FBMR333-1MN10G4 | 3RA1225-4BD26-1BG4 | |
| FBMR333-1MN10K6 | 3RA1225-4BD26-1AK6 | |
| FBMR333-1MN10M1 | 3RA1225-4BD26-1AM2 | |
| FBMR333-1MN10P6 | 3RA1225-4BD26-1AP6 | |
| FBMR333-1MN10Q0 | 3RA1225-4BD26-1AV0 | |
| FBMR333-1MN10Q4 | 3RA1225-4BD26-1BP4 | |
| FBMR333-1MN10S0 | 3RA1225-4BD26-1AT6 | |
| FBMR333-1MN10U1 | 3RA1225-4BD26-1AU6 | |
| FBMR333-1MN10W4 | 3RA1225-4BD26-1BW4 | |
| FBMR334-1MN10A4 | 3RA1225-4BD26-1BA4 | |
| FBMR334-1MN10B4 | 3RA1225-4BD26-1BB4 | |
| FBMR334-1MN10C2 | 3RA1225-4BD26-1AC2 | |
| FBMR334-1MN10G4 | 3RA1225-4BD26-1BG4 | |
| FBMR334-1MN10K6 | 3RA1225-4BD26-1AK6 | |
| FBMR334-1MN10M1 | 3RA1225-4BD26-1AM2 | |
| FBMR334-1MN10P6 | 3RA1225-4BD26-1AP6 | |
| FBMR334-1MN10Q0 | 3RA1225-4BD26-1AV0 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| FBMR334-1MN10Q4 | 3RA1225-4BD26-1BP4 | |
| FBMR334-1MN10S0 | 3RA1225-4BD26-1AT6 | |
| FBMR334-1MN10U1 | 3RA1225-4BD26-1AU6 | |
| FBMR334-1MN10W4 | 3RA1225-4BD26-1BW4 | |
| FBMR334-1MP10A4 | 3RA1235-4DD33-1BA4 OR 3RA1225-4CD26-1BA4 | |
| FBMR334-1MP10B4 | 3RA1235-4DD33-1BB4 OR 3RA1225-4CD26-1BB4 | |
| FBMR334-1MP10C2 | 3RA1235-4DD33-1AC2 OR 3RA1225-4CD26-1AC2 | |
| FBMR334-1MP10G4 | 3RA1235-4DD33-1BG4 OR 3RA1225-4CD26-1BG4 | |
| FBMR334-1MP10K6 | 3RA1235-4DD33-1AK6 OR 3RA1225-4CD26-1AK6 | |
| FBMR334-1MP10M1 | 3RA1235-4DD33-1AM2 OR 3RA1225-4CD26-1AM2 | |
| FBMR334-1MP10P6 | 3RA1235-4DD33-1AP6 OR 3RA1225-4CD26-1AP6 | |
| FBMR334-1MP10Q0 | 3RA1235-4DD33-1AV0 OR 3RA1225-4CD26-1AV0 | |
| FBMR334-1MP10Q4 | 3RA1235-4DD33-1BP4 OR 3RA1225-4CD26-1BP4 | |
| FBMR334-1MP10S0 | 3RA1235-4DD33-1AT6 OR 3RA1225-4CD26-1AT6 | |
| FBMR334-1MP10U1 | 3RA1235-4DD33-1AU6 OR 3RA1225-4CD26-1AU6 | |
| FBMR334-1MP10W4 | 3RA1235-4DD33-1BW4 OR 3RA1225-4CD26-1BW4 | |
| FBMR634-1MP10A4 | 3RA1235-4ED34-1BA4 | |
| FBMR634-1MP10B4 | 3RA1235-4ED34-1BB4 | |
| FBMR634-1MP10C2 | 3RA1235-4ED34-1AC2 | |
| FBMR634-1MP10G4 | 3RA1235-4ED34-1BG4 | |
| FBMR634-1MP10K6 | 3RA1235-4ED34-1AK6 | |
| FBMR634-1MP10M1 | 3RA1235-4ED34-1AM2 | |
| FBMR634-1MP10P6 | 3RA1235-4ED34-1AP6 | |
| FBMR634-1MP10Q0 | 3RA1235-4ED34-1AV0 | |
| FBMR634-1MP10Q4 | 3RA1235-4ED34-1BP4 | |
| FBMR634-1MP10S0 | 3RA1235-4ED34-1AT6 | |
| FBMR634-1MP10U1 | 3RA1235-4ED34-1AU6 | |
| FBMR634-1MP10W4 | 3RA1235-4ED34-1BW4 | |
| FBMR635-1MQ10A4 | 3RA1235-4FD35-1BA4 | |
| FBMR635-1MQ10B4 | 3RA1235-4FD35-1BB4 | |
| FBMR635-1MQ10C2 | 3RA1235-4FD35-1AC2 | |
| FBMR635-1MQ10G4 | 3RA1235-4FD35-1BG4 | |
| FBMR635-1MQ10K6 | 3RA1235-4FD35-1AK6 | |
| FBMR635-1MQ10M1 | 3RA1235-4FD35-1AM2 | |
| FBMR635-1MQ10P6 | 3RA1235-4FD35-1AP6 | |
| FBMR635-1MQ10Q0 | 3RA1235-4FD35-1AV0 | |
| FBMR635-1MQ10Q4 | 3RA1235-4FD35-1BP4 | |
| FBMR635-1MQ10S0 | 3RA1235-4FD35-1AT6 | |
| FBMR635-1MQ10U1 | 3RA1235-4FD35-1AU6 | |
| FBMR635-1MQ10W4 | 3RA1235-4FD35-1BW4 | |
| FBMR646-1MR10C2 | 3RA1235-4GD36-1AC2 OR 3RA1235-4HD36-1AC2 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| FBMR646-1MR10K6 | 3RA1235-4GD36-1AK6 OR 3RA1235-4HD36-1AK6 | |
| FBMR646-1MR10M1 | 3RA1235-4GD36-1AM2 OR 3RA1235-4HD36-1AM2 | |
| FBMR646-1MR10P6 | 3RA1235-4GD36-1AP6 OR 3RA1235-4HD36-1AP6 | |
| FBMR646-1MR10Q0 | 3RA1235-4GD36-1AV0 OR 3RA1235-4HD36-1AV0 | |
| FBMR646-1MR10S0 | 3RA1235-4GD36-1AT6 OR 3RA1235-4HD36-1AT6 | |
| FBMR646-1MR10U1 | 3RA1235-4GD36-1AU6 OR 3RA1235-4HD36-1AU6 | |
| FBMR647-1LS10C2 | 3RA1245-4JD44-1AC2 OR 3RA1245-4KD45-1AC2 | |
| FBMR647-1LS10K6 | 3RA1245-4JD44-1AK6 OR 3RA1245-4KD45-1AK6 | |
| FBMR647-1LS10M1 | 3RA1245-4JD44-1AM2 OR 3RA1245-4KD45-1AM2 | |
| FBMR647-1LS10P6 | 3RA1245-4JD44-1AP6 OR 3RA1245-4KD45-1AP6 | |
| FBMR647-1LS10Q0 | 3RA1245-4JD44-1AV0 OR 3RA1245-4KD45-1AV0 | |
| FBMR647-1LS10S0 | 3RA1245-4JD44-1AT6 OR 3RA1245-4KD45-1AT6 | |
| FBMR647-1LS10U1 | 3RA1245-4JD44-1AU6 OR 3RA1245-4KD45-1AU6 | |
| FWE1334-1MG10A4 | 3RA1115-1AD15-1BA4 OR 3RA1115-0KD15-1BA4 | 3RA1125-1AD23-1BA4 OR 3RA1125-0KD23-1BA4 |
| FWE1334-1MG10B4 | 3RA1115-1AD15-1BB4 OR 3RA1115-0KD15-1BB4 | 3RA1125-1AD23-1BB4 OR 3RA1125-0KD23-1BB4 |
| FWE1334-1MG10C2 | 3RA1115-1AD15-1AC2 OR 3RA1115-0KD15-1AC2 | 3RA1125-1AD23-1AC2 OR 3RA1125-0KD23-1AC2 |
| FWE1334-1MG10G4 | 3RA1115-1AD15-1BG4 OR 3RA1115-0KD15-1BG4 | 3RA1125-1AD23-1BG4 OR 3RA1125-0KD23-1BG4 |
| FWE1334-1MG10K6 | 3RA1115-1AD15-1AK6 OR 3RA1115-0KD15-1AK6 | 3RA1125-1AD23-1AK6 OR 3RA1125-0KD23-1AK6 |
| FWE1334-1MG10M1 | 3RA1115-1AD15-1AM2 OR 3RA1115-0KD15-1AM2 | 3RA1125-1AD23-1AM2 OR 3RA1125-0KD23-1AM2 |
| FWE1334-1MG10P6 | 3RA1115-1AD15-1AP6 OR 3RA1115-0KD15-1AP6 | 3RA1125-1AD23-1AP6 OR 3RA1125-0KD23-1AP6 |
| FWE1334-1MG10Q0 | 3RA1115-1AD15-1AV0 OR 3RA1115-0KD15-1AV0 | 3RA1125-1AD23-1AV0 OR 3RA1125-0KD23-1AV0 |
| FWE1334-1MG10Q4 | 3RA1115-1AD15-1BP4 OR 3RA1115-0KD15-1BP4 | 3RA1125-1AD23-1BP4 OR 3RA1125-0KD23-1BP4 |
| FWE1334-1MG10U1 | 3RA1115-1AD15-1AU6 OR 3RA1115-0KD15-1AU6 | 3RA1125-1AD23-1AU6 OR 3RA1125-0KD23-1AU6 |
| FWE1334-1MG10W4 | 3RA1115-1AD15-1BW4 OR 3RA1115-0KD15-1BW4 | 3RA1125-1AD23-1BW4 OR 3RA1125-0KD23-1BW4 |
| FWE1334-1MH10A4 | 3RA1115-1CD15-1BA4 OR 3RA1115-1BD15-1BA4 | 3RA1125-1CD23-1BA4 OR 3RA1125-1BD23-1BA4 |
| FWE1334-1MH10B4 | 3RA1115-1CD15-1BB4 OR 3RA1115-1BD15-1BB4 | 3RA1125-1CD23-1BB4 OR 3RA1125-1BD23-1BB4 |
| FWE1334-1MH10C2 | 3RA1115-1CD15-1AC2 OR 3RA1115-1BD15-1AC2 | 3RA1125-1CD23-1AC2 OR 3RA1125-1BD23-1AC2 |
| FWE1334-1MH10G4 | 3RA1115-1CD15-1BG4 OR 3RA1115-1BD15-1BG4 | 3RA1125-1CD23-1BG4 OR 3RA1125-1BD23-1BG4 |
| FWE1334-1MH10K6 | 3RA1115-1CD15-1AK6 OR 3RA1115-1BD15-1AK6 | 3RA1125-1CD23-1AK6 OR 3RA1125-1BD23-1AK6 |
| FWE1334-1MH10M1 | 3RA1115-1CD15-1AM2 OR 3RA1115-1BD15-1AM2 | 3RA1125-1CD23-1AM2 OR 3RA1125-1BD23-1AM2 |
| FWE1334-1MH10P6 | 3RA1115-1CD15-1AP6 OR 3RA1115-1BD15-1AP6 | 3RA1125-1CD23-1AP6 OR 3RA1125-1BD23-1AP6 |
| FWE1334-1MH10Q0 | 3RA1115-1CD15-1AV0 OR 3RA1115-1BD15-1AV0 | 3RA1125-1CD23-1AV0 OR 3RA1125-1BD23-1AV0 |
| FWE1334-1MH10Q4 | 3RA1115-1CD15-1BP4 OR 3RA1115-1BD15-1BP4 | 3RA1125-1CD23-1BP4 OR 3RA1125-1BD23-1BP4 |
| FWE1334-1MH10U1 | 3RA1115-1CD15-1AU6 OR 3RA1115-1BD15-1AU6 | 3RA1125-1CD23-1AU6 OR 3RA1125-1BD23-1AU6 |
| FWE1334-1MH10W4 | 3RA1115-1CD15-1BW4 OR 3RA1115-1BD15-1BW4 | 3RA1125-1CD23-1BW4 OR 3RA1125-1BD23-1BW4 |
| FWE1334-1MJ10A4 | 3RA1115-1ED15-1BA4 OR 3RA1115-1DD15-1BA4 | 3RA1125-1ED23-1BA4 OR 3RA1125-1DD23-1BA4 |
| FWE1334-1MJ10B4 | 3RA1115-1ED15-1BB4 OR 3RA1115-1DD15-1BB4 | 3RA1125-1ED23-1BB4 OR 3RA1125-1DD23-1BB4 |
| FWE1334-1MJ10C2 | 3RA1115-1ED15-1AC2 OR 3RA1115-1DD15-1AC2 | 3RA1125-1ED23-1AC2 OR 3RA1125-1DD23-1AC2 |
| FWE1334-1MJ10G4 | 3RA1115-1ED15-1BG4 OR 3RA1115-1DD15-1BG4 | 3RA1125-1ED23-1BG4 OR 3RA1125-1DD23-1BG4 |
| FWE1334-1MJ10K6 | 3RA1115-1ED15-1AK6 OR 3RA1115-1DD15-1AK6 | 3RA1125-1ED23-1AK6 OR 3RA1125-1DD23-1AK6 |
| FWE1334-1MJ10M1 | 3RA1115-1ED15-1AM2 OR 3RA1115-1DD15-1AM2 | 3RA1125-1ED23-1AM2 OR 3RA1125-1DD23-1AM2 |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| FWE1334-1MJ10P6 | 3RA1115-1ED15-1AP6 OR 3RA1115-1DD15-1AP6 | 3RA1125-1ED23-1AP6 OR 3RA1125-1DD23-1AP6 |
| FWE1334-1MJ10Q0 | 3RA1115-1ED15-1AV0 OR 3RA1115-1DD15-1AV0 | 3RA1125-1ED23-1AV0 OR 3RA1125-1DD23-1AV0 |
| FWE1334-1MJ10Q4 | 3RA1115-1ED15-1BP4 OR 3RA1115-1DD15-1BP4 | 3RA1125-1ED23-1BP4 OR 3RA1125-1DD23-1BP4 |
| FWE1334-1MJ10U1 | 3RA1115-1ED15-1AU6 OR 3RA1115-1DD15-1AU6 | 3RA1125-1ED23-1AU6 OR 3RA1125-1DD23-1AU6 |
| FWE1334-1MJ10W4 | 3RA1115-1ED15-1BW4 OR 3RA1115-1DD15-1BW4 | 3RA1125-1ED23-1BW4 OR 3RA1125-1DD23-1BW4 |
| FWE1334-1MK10A4 | 3RA1115-1GD15-1BA4 OR 3RA1115-1FD15-1BA4 | 3RA1125-1GD23-1BA4 OR 3RA1125-1FD23-1BA4 |
| FWE1334-1MK10B4 | 3RA1115-1GD15-1BB4 OR 3RA1115-1FD15-1BB4 | 3RA1125-1GD23-1BB4 OR 3RA1125-1FD23-1BB4 |
| FWE1334-1MK10C2 | 3RA1115-1GD15-1AC2 OR 3RA1115-1FD15-1AC2 | 3RA1125-1GD23-1AC2 OR 3RA1125-1FD23-1AC2 |
| FWE1334-1MK10G4 | 3RA1115-1GD15-1BG4 OR 3RA1115-1FD15-1BG4 | 3RA1125-1GD23-1BG4 OR 3RA1125-1FD23-1BG4 |
| FWE1334-1MK10K6 | 3RA1115-1GD15-1AK6 OR 3RA1115-1FD15-1AK6 | 3RA1125-1GD23-1AK6 OR 3RA1125-1FD23-1AK6 |
| FWE1334-1MK10M1 | 3RA1115-1GD15-1AM2 OR 3RA1115-1FD15-1AM2 | 3RA1125-1GD23-1AM2 OR 3RA1125-1FD23-1AM2 |
| FWE1334-1MK10P6 | 3RA1115-1GD15-1AP6 OR 3RA1115-1FD15-1AP6 | 3RA1125-1GD23-1AP6 OR 3RA1125-1FD23-1AP6 |
| FWE1334-1MK10Q0 | 3RA1115-1GD15-1AV0 OR 3RA1115-1FD15-1AV0 | 3RA1125-1GD23-1AV0 OR 3RA1125-1FD23-1AV0 |
| FWE1334-1MK10Q4 | 3RA1115-1GD15-1BP4 OR 3RA1115-1FD15-1BP4 | 3RA1125-1GD23-1BP4 OR 3RA1125-1FD23-1BP4 |
| FWE1334-1MK10U1 | 3RA1115-1GD15-1AU6 OR 3RA1115-1FD15-1AU6 | 3RA1125-1GD23-1AU6 OR 3RA1125-1FD23-1AU6 |
| FWE1334-1MK10W4 | 3RA1115-1GD15-1BW4 OR 3RA1115-1FD15-1BW4 | 3RA1125-1GD23-1BW4 OR 3RA1125-1FD23-1BW4 |
| FWE1334-1ML10A4 | 3RA1125-1JD24-1BA4 OR 3RA1115-1HD16-1BA4 | |
| FWE1334-1ML10B4 | 3RA1125-1JD24-1BB4 OR 3RA1115-1HD16-1BB4 | |
| FWE1334-1ML10C2 | 3RA1125-1JD24-1AC2 OR 3RA1115-1HD16-1AC2 | |
| FWE1334-1ML10G4 | 3RA1125-1JD24-1BG4 OR 3RA1115-1HD16-1BG4 | |
| FWE1334-1ML10K6 | 3RA1125-1JD24-1AK6 OR 3RA1115-1HD16-1AK6 | |
| FWE1334-1ML10M1 | 3RA1125-1JD24-1AM2 OR 3RA1115-1HD16-1AM2 | |
| FWE1334-1ML10P6 | 3RA1125-1JD24-1AP6 OR 3RA1115-1HD16-1AP6 | |
| FWE1334-1ML10Q0 | 3RA1125-1JD24-1AV0 OR 3RA1115-1HD16-1AV0 | |
| FWE1334-1ML10Q4 | 3RA1125-1JD24-1BP4 OR 3RA1115-1HD16-1BP4 | |
| FWE1334-1ML10U1 | 3RA1125-1JD24-1AU6 OR 3RA1115-1HD16-1AU6 | |
| FWE1334-1ML10W4 | 3RA1125-1JD24-1BW4 OR 3RA1115-1HD16-1BW4 | |
| FWE1334-1MM10A4 | 3RA1125-4AD25-1BA4 OR 3RA1125-1KD23-1BA4 | |
| FWE1334-1MM10B4 | 3RA1125-4AD25-1BB4 OR 3RA1125-1KD23-1BB4 | |
| FWE1334-1MM10C2 | 3RA1125-4AD25-1AC2 OR 3RA1125-1KD23-1AC2 | |
| FWE1334-1MM10G4 | 3RA1125-4AD25-1BG4 OR 3RA1125-1KD23-1BG4 | |
| FWE1334-1MM10K6 | 3RA1125-4AD25-1AK6 OR 3RA1125-1KD23-1AK6 | |
| FWE1334-1MM10M1 | 3RA1125-4AD25-1AM2 OR 3RA1125-1KD23-1AM2 | |
| FWE1334-1MM10P6 | 3RA1125-4AD25-1AP6 OR 3RA1125-1KD23-1AP6 | |
| FWE1334-1MM10Q0 | 3RA1125-4AD25-1AV0 OR 3RA1125-1KD23-1AV0 | |
| FWE1334-1MM10Q4 | 3RA1125-4AD25-1BP4 OR 3RA1125-1KD23-1BP4 | |
| FWE1334-1MM10U1 | 3RA1125-4AD25-1AU6 OR 3RA1125-1KD23-1AU6 | |
| FWE1334-1MM10W4 | 3RA1125-4AD25-1BW4 OR 3RA1125-1KD23-1BW4 | |
| FWE9138-2AB10 | NO DIRECT REPLACEMENT | |
| FWER330-1MB10A4 | 3RA1215-0AD15-1BA4 | 3RA1225-0AD23-1BA4 |
| FWER330-1MB10B4 | 3RA1215-0AD15-1BB4 | 3RA1225-0AD23-1BB4 |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| FWER330-1MB10C2 | 3RA1215-0AD15-1AC2 | 3RA1225-0AD23-1AC2 |
| FWER330-1MB10G4 | 3RA1215-0AD15-1BG4 | 3RA1225-0AD23-1BG4 |
| FWER330-1MB10K6 | 3RA1215-0AD15-1AK6 | 3RA1225-0AD23-1AK6 |
| FWER330-1MB10M1 | 3RA1215-0AD15-1AM2 | 3RA1225-0AD23-1AM2 |
| FWER330-1MB10P6 | 3RA1215-0AD15-1AP6 | 3RA1225-0AD23-1AP6 |
| FWER330-1MB10Q0 | 3RA1215-0AD15-1AV0 | 3RA1225-0AD23-1AV0 |
| FWER330-1MB10Q4 | 3RA1215-0AD15-1BP4 | 3RA1225-0AD23-1BP4 |
| FWER330-1MB10U1 | 3RA1215-0AD15-1AU6 | 3RA1225-0AD23-1AU6 |
| FWER330-1MB10W4 | 3RA1215-0AD15-1BW4 | 3RA1225-0AD23-1BW4 |
| FWER330-1MC10A4 | 3RA1215-0CD15-1BA4 OR 3RA1215-0BD15-1BA4 | 3RA1225-0CD23-1BA4 OR 3RA1225-0BD23-1BA4 |
| FWER330-1MC10B4 | 3RA1215-0CD15-1BB4 OR 3RA1215-0BD15-1BB4 | 3RA1225-0CD23-1BB4 OR 3RA1225-0BD23-1BB4 |
| FWER330-1MC10C2 | 3RA1215-0CD15-1AC2 OR 3RA1215-0BD15-1AC2 | 3RA1225-0CD23-1AC2 OR 3RA1225-0BD23-1AC2 |
| FWER330-1MC10G4 | 3RA1215-0CD15-1BG4 OR 3RA1215-0BD15-1BG4 | 3RA1225-0CD23-1BG4 OR 3RA1225-0BD23-1BG4 |
| FWER330-1MC10K6 | 3RA1215-0CD15-1AK6 OR 3RA1215-0BD15-1AK6 | 3RA1225-0CD23-1AK6 OR 3RA1225-0BD23-1AK6 |
| FWER330-1MC10M1 | 3RA1215-0CD15-1AM2 OR 3RA1215-0BD15-1AM2 | 3RA1225-0CD23-1AM2 OR 3RA1225-0BD23-1AM2 |
| FWER330-1MC10P6 | 3RA1215-0CD15-1AP6 OR 3RA1215-0BD15-1AP6 | 3RA1225-0CD23-1AP6 OR 3RA1225-0BD23-1AP6 |
| FWER330-1MC10Q0 | 3RA1215-0CD15-1AV0 OR 3RA1215-0BD15-1AV0 | 3RA1225-0CD23-1AV0 OR 3RA1225-0BD23-1AV0 |
| FWER330-1MC10Q4 | 3RA1215-0CD15-1BP4 OR 3RA1215-0BD15-1BP4 | 3RA1225-0CD23-1BP4 OR 3RA1225-0BD23-1BP4 |
| FWER330-1MC10U1 | 3RA1215-0CD15-1AU6 OR 3RA1215-0BD15-1AU6 | 3RA1225-0CD23-1AU6 OR 3RA1225-0BD23-1AU6 |
| FWER330-1MC10W4 | 3RA1215-0CD15-1BW4 OR 3RA1215-0BD15-1BW4 | 3RA1225-0CD23-1BW4 OR 3RA1225-0BD23-1BW4 |
| FWER330-1MD10A4 | 3RA1215-0ED15-1BA4 OR 3RA1215-0DD15-1BA4 | 3RA1225-0ED23-1BA4 OR 3RA1225-0DD23-1BA4 |
| FWER330-1MD10B4 | 3RA1215-0ED15-1BB4 OR 3RA1215-0DD15-1BB4 | 3RA1225-0ED23-1BB4 OR 3RA1225-0DD23-1BB4 |
| FWER330-1MD10C2 | 3RA1215-0ED15-1AC2 OR 3RA1215-0DD15-1AC2 | 3RA1225-0ED23-1AC2 OR 3RA1225-0DD23-1AC2 |
| FWER330-1MD10G4 | 3RA1215-0ED15-1BG4 OR 3RA1215-0DD15-1BG4 | 3RA1225-0ED23-1BG4 OR 3RA1225-0DD23-1BG4 |
| FWER330-1MD10K6 | 3RA1215-0ED15-1AK6 OR 3RA1215-0DD15-1AK6 | 3RA1225-0ED23-1AK6 OR 3RA1225-0DD23-1AK6 |
| FWER330-1MD10M1 | 3RA1215-0ED15-1AM2 OR 3RA1215-0DD15-1AM2 | 3RA1225-0ED23-1AM2 OR 3RA1225-0DD23-1AM2 |
| FWER330-1MD10P6 | 3RA1215-0ED15-1AP6 OR 3RA1215-0DD15-1AP6 | 3RA1225-0ED23-1AP6 OR 3RA1225-0DD23-1AP6 |
| FWER330-1MD10Q0 | 3RA1215-0ED15-1AV0 OR 3RA1215-0DD15-1AV0 | 3RA1225-0ED23-1AV0 OR 3RA1225-0DD23-1AV0 |
| FWER330-1MD10Q4 | 3RA1215-0ED15-1BP4 OR 3RA1215-0DD15-1BP4 | 3RA1225-0ED23-1BP4 OR 3RA1225-0DD23-1BP4 |
| FWER330-1MD10U1 | 3RA1215-0ED15-1AU6 OR 3RA1215-0DD15-1AU6 | 3RA1225-0ED23-1AU6 OR 3RA1225-0DD23-1AU6 |
| FWER330-1MD10W4 | 3RA1215-0ED15-1BW4 OR 3RA1215-0DD15-1BW4 | 3RA1225-0ED23-1BW4 OR 3RA1225-0DD23-1BW4 |
| FWER330-1ME10A4 | 3RA1215-0GD15-1BA4 OR 3RA1215-0FD15-1BA4 | 3RA1225-0GD23-1BA4 OR 3RA1225-0FD23-1BA4 |
| FWER330-1ME10B4 | 3RA1215-0GD15-1BB4 OR 3RA1215-0FD15-1BB4 | 3RA1225-0GD23-1BB4 OR 3RA1225-0FD23-1BB4 |
| FWER330-1ME10C2 | 3RA1215-0GD15-1AC2 OR 3RA1215-0FD15-1AC2 | 3RA1225-0GD23-1AC2 OR 3RA1225-0FD23-1AC2 |
| FWER330-1ME10G4 | 3RA1215-0GD15-1BG4 OR 3RA1215-0FD15-1BG4 | 3RA1225-0GD23-1BG4 OR 3RA1225-0FD23-1BG4 |
| FWER330-1ME10K6 | 3RA1215-0GD15-1AK6 OR 3RA1215-0FD15-1AK6 | 3RA1225-0GD23-1AK6 OR 3RA1225-0FD23-1AK6 |
| FWER330-1ME10M1 | 3RA1215-0GD15-1AM2 OR 3RA1215-0FD15-1AM2 | 3RA1225-0GD23-1AM2 OR 3RA1225-0FD23-1AM2 |
| FWER330-1ME10P6 | 3RA1215-0GD15-1AP6 OR 3RA1215-0FD15-1AP6 | 3RA1225-0GD23-1AP6 OR 3RA1225-0FD23-1AP6 |
| FWER330-1ME10Q0 | 3RA1215-0GD15-1AV0 OR 3RA1215-0FD15-1AV0 | 3RA1225-0GD23-1AV0 OR 3RA1225-0FD23-1AV0 |
| FWER330-1ME10Q4 | 3RA1215-0GD15-1BP4 OR 3RA1215-0FD15-1BP4 | 3RA1225-0GD23-1BP4 OR 3RA1225-0FD23-1BP4 |
| FWER330-1ME10U1 | 3RA1215-0GD15-1AU6 OR 3RA1215-0FD15-1AU6 | 3RA1225-0GD23-1AU6 OR 3RA1225-0FD23-1AU6 |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| FWER330-1ME10W4 | 3RA1215-0GD15-1BW4 OR 3RA1215-0FD15-1BW4 | 3RA1225-0GD23-1BW4 OR 3RA1225-0FD23-1BW4 |
| FWER330-1MF10A4 | 3RA1215-0JD15-1BA4 OR 3RA1215-0HD15-1BA4 | 3RA1225-0JD23-1BA4 OR 3RA1225-0HD23-1BA4 |
| FWER330-1MF10B4 | 3RA1215-0JD15-1BB4 OR 3RA1215-0HD15-1BB4 | 3RA1225-0JD23-1BB4 OR 3RA1225-0HD23-1BB4 |
| FWER330-1MF10C2 | 3RA1215-0JD15-1AC2 OR 3RA1215-0HD15-1AC2 | 3RA1225-0JD23-1AC2 OR 3RA1225-0HD23-1AC2 |
| FWER330-1MF10G4 | 3RA1215-0JD15-1BG4 OR 3RA1215-0HD15-1BG4 | 3RA1225-0JD23-1BG4 OR 3RA1225-0HD23-1BG4 |
| FWER330-1MF10K6 | 3RA1215-0JD15-1AK6 OR 3RA1215-0HD15-1AK6 | 3RA1225-0JD23-1AK6 OR 3RA1225-0HD23-1AK6 |
| FWER330-1MF10M1 | 3RA1215-0JD15-1AM2 OR 3RA1215-0HD15-1AM2 | 3RA1225-0JD23-1AM2 OR 3RA1225-0HD23-1AM2 |
| FWER330-1MF10P6 | 3RA1215-0JD15-1AP6 OR 3RA1215-0HD15-1AP6 | 3RA1225-0JD23-1AP6 OR 3RA1225-0HD23-1AP6 |
| FWER330-1MF10Q0 | 3RA1215-0JD15-1AV0 OR 3RA1215-0HD15-1AV0 | 3RA1225-0JD23-1AV0 OR 3RA1225-0HD23-1AV0 |
| FWER330-1MF10Q4 | 3RA1215-0JD15-1BP4 OR 3RA1215-0HD15-1BP4 | 3RA1225-0JD23-1BP4 OR 3RA1225-0HD23-1BP4 |
| FWER330-1MF10U1 | 3RA1215-0JD15-1AU6 OR 3RA1215-0HD15-1AU6 | 3RA1225-0JD23-1AU6 OR 3RA1225-0HD23-1AU6 |
| FWER330-1MF10W4 | 3RA1215-0JD15-1BW4 OR 3RA1215-0HD15-1BW4 | 3RA1225-0JD23-1BW4 OR 3RA1225-0HD23-1BW4 |
| FWER334-1MG10A4 | 3RA1215-1AD15-1BA4 OR 3RA1215-0KD15-1BA4 | 3RA1225-1AD23-1BA4 OR 3RA1225-0KD23-1BA4 |
| FWER334-1MG10B4 | 3RA1215-1AD15-1BB4 OR 3RA1215-0KD15-1BB4 | 3RA1225-1AD23-1BB4 OR 3RA1225-0KD23-1BB4 |
| FWER334-1MG10C2 | 3RA1215-1AD15-1AC2 OR 3RA1215-0KD15-1AC2 | 3RA1225-1AD23-1AC2 OR 3RA1225-0KD23-1AC2 |
| FWER334-1MG10G4 | 3RA1215-1AD15-1BG4 OR 3RA1215-0KD15-1BG4 | 3RA1225-1AD23-1BG4 OR 3RA1225-0KD23-1BG4 |
| FWER334-1MG10K6 | 3RA1215-1AD15-1AK6 OR 3RA1215-0KD15-1AK6 | 3RA1225-1AD23-1AK6 OR 3RA1225-0KD23-1AK6 |
| FWER334-1MG10M1 | 3RA1215-1AD15-1AM2 OR 3RA1215-0KD15-1AM2 | 3RA1225-1AD23-1AM2 OR 3RA1225-0KD23-1AM2 |
| FWER334-1MG10P6 | 3RA1215-1AD15-1AP6 OR 3RA1215-0KD15-1AP6 | 3RA1225-1AD23-1AP6 OR 3RA1225-0KD23-1AP6 |
| FWER334-1MG10Q0 | 3RA1215-1AD15-1AV0 OR 3RA1215-0KD15-1AV0 | 3RA1225-1AD23-1AV0 OR 3RA1225-0KD23-1AV0 |
| FWER334-1MG10Q4 | 3RA1215-1AD15-1BP4 OR 3RA1215-0KD15-1BP4 | 3RA1225-1AD23-1BP4 OR 3RA1225-0KD23-1BP4 |
| FWER334-1MG10U1 | 3RA1215-1AD15-1AU6 OR 3RA1215-0KD15-1AU6 | 3RA1225-1AD23-1AU6 OR 3RA1225-0KD23-1AU6 |
| FWER334-1MG10W4 | 3RA1215-1AD15-1BW4 OR 3RA1215-0KD15-1BW4 | 3RA1225-1AD23-1BW4 OR 3RA1225-0KD23-1BW4 |
| FWER334-1MH10A4 | 3RA1215-1CD15-1BA4 OR 3RA1215-1BD15-1BA4 | 3RA1225-1CD23-1BA4 OR 3RA1225-1BD23-1BA4 |
| FWER334-1MH10B4 | 3RA1215-1CD15-1BB4 OR 3RA1215-1BD15-1BB4 | 3RA1225-1CD23-1BB4 OR 3RA1225-1BD23-1BB4 |
| FWER334-1MH10C2 | 3RA1215-1CD15-1AC2 OR 3RA1215-1BD15-1AC2 | 3RA1225-1CD23-1AC2 OR 3RA1225-1BD23-1AC2 |
| FWER334-1MH10G4 | 3RA1215-1CD15-1BG4 OR 3RA1215-1BD15-1BG4 | 3RA1225-1CD23-1BG4 OR 3RA1225-1BD23-1BG4 |
| FWER334-1MH10K6 | 3RA1215-1CD15-1AK6 OR 3RA1215-1BD15-1AK6 | 3RA1225-1CD23-1AK6 OR 3RA1225-1BD23-1AK6 |
| FWER334-1MH10M1 | 3RA1215-1CD15-1AM2 OR 3RA1215-1BD15-1AM2 | 3RA1225-1CD23-1AM2 OR 3RA1225-1BD23-1AM2 |
| FWER334-1MH10P6 | 3RA1215-1CD15-1AP6 OR 3RA1215-1BD15-1AP6 | 3RA1225-1CD23-1AP6 OR 3RA1225-1BD23-1AP6 |
| FWER334-1MH10Q0 | 3RA1215-1CD15-1AV0 OR 3RA1215-1BD15-1AV0 | 3RA1225-1CD23-1AV0 OR 3RA1225-1BD23-1AV0 |
| FWER334-1MH10Q4 | 3RA1215-1CD15-1BP4 OR 3RA1215-1BD15-1BP4 | 3RA1225-1CD23-1BP4 OR 3RA1225-1BD23-1BP4 |
| FWER334-1MH10U1 | 3RA1215-1CD15-1AU6 OR 3RA1215-1BD15-1AU6 | 3RA1225-1CD23-1AU6 OR 3RA1225-1BD23-1AU6 |
| FWER334-1MH10W4 | 3RA1215-1CD15-1BW4 OR 3RA1215-1BD15-1BW4 | 3RA1225-1CD23-1BW4 OR 3RA1225-1BD23-1BW4 |
| FWER334-1MJ10A4 | 3RA1215-1ED15-1BA4 OR 3RA1215-1DD15-1BA4 | 3RA1225-1ED23-1BA4 OR 3RA1225-1DD23-1BA4 |
| FWER334-1MJ10B4 | 3RA1215-1ED15-1BB4 OR 3RA1215-1DD15-1BB4 | 3RA1225-1ED23-1BB4 OR 3RA1225-1DD23-1BB4 |
| FWER334-1MJ10C2 | 3RA1215-1ED15-1AC2 OR 3RA1215-1DD15-1AC2 | 3RA1225-1ED23-1AC2 OR 3RA1225-1DD23-1AC2 |
| FWER334-1MJ10G4 | 3RA1215-1ED15-1BG4 OR 3RA1215-1DD15-1BG4 | 3RA1225-1ED23-1BG4 OR 3RA1225-1DD23-1BG4 |
| FWER334-1MJ10K6 | 3RA1215-1ED15-1AK6 OR 3RA1215-1DD15-1AK6 | 3RA1225-1ED23-1AK6 OR 3RA1225-1DD23-1AK6 |
| FWER334-1MJ10M1 | 3RA1215-1ED15-1AM2 OR 3RA1215-1DD15-1AM2 | 3RA1225-1ED23-1AM2 OR 3RA1225-1DD23-1AM2 |
| FWER334-1MJ10P6 | 3RA1215-1ED15-1AP6 OR 3RA1215-1DD15-1AP6 | 3RA1225-1ED23-1AP6 OR 3RA1225-1DD23-1AP6 |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| FWER334-1MJ10Q0 | 3RA1215-1ED15-1AV0 OR 3RA1215-1DD15-1AV0 | 3RA1225-1ED23-1AV0 OR 3RA1225-1DD23-1AV0 |
| FWER334-1MJ10Q4 | 3RA1215-1ED15-1BP4 OR 3RA1215-1DD15-1BP4 | 3RA1225-1ED23-1BP4 OR 3RA1225-1DD23-1BP4 |
| FWER334-1MJ10U1 | 3RA1215-1ED15-1AU6 OR 3RA1215-1DD15-1AU6 | 3RA1225-1ED23-1AU6 OR 3RA1225-1DD23-1AU6 |
| FWER334-1MJ10W4 | 3RA1215-1ED15-1BW4 OR 3RA1215-1DD15-1BW4 | 3RA1225-1ED23-1BW4 OR 3RA1225-1DD23-1BW4 |
| FWER334-1MK10A4 | 3RA1215-1GD15-1BA4 OR 3RA1215-1FD15-1BA4 | 3RA1225-1GD23-1BA4 OR 3RA1225-1FD23-1BA4 |
| FWER334-1MK10B4 | 3RA1215-1GD15-1BB4 OR 3RA1215-1FD15-1BB4 | 3RA1225-1GD23-1BB4 OR 3RA1225-1FD23-1BB4 |
| FWER334-1MK10C2 | 3RA1215-1GD15-1AC2 OR 3RA1215-1FD15-1AC2 | 3RA1225-1GD23-1AC2 OR 3RA1225-1FD23-1AC2 |
| FWER334-1MK10G4 | 3RA1215-1GD15-1BG4 OR 3RA1215-1FD15-1BG4 | 3RA1225-1GD23-1BG4 OR 3RA1225-1FD23-1BG4 |
| FWER334-1MK10K6 | 3RA1215-1GD15-1AK6 OR 3RA1215-1FD15-1AK6 | 3RA1225-1GD23-1AK6 OR 3RA1225-1FD23-1AK6 |
| FWER334-1MK10M1 | 3RA1215-1GD15-1AM2 OR 3RA1215-1FD15-1AM2 | 3RA1225-1GD23-1AM2 OR 3RA1225-1FD23-1AM2 |
| FWER334-1MK10P6 | 3RA1215-1GD15-1AP6 OR 3RA1215-1FD15-1AP6 | 3RA1225-1GD23-1AP6 OR 3RA1225-1FD23-1AP6 |
| FWER334-1MK10Q0 | 3RA1215-1GD15-1AV0 OR 3RA1215-1FD15-1AV0 | 3RA1225-1GD23-1AV0 OR 3RA1225-1FD23-1AV0 |
| FWER334-1MK10Q4 | 3RA1215-1GD15-1BP4 OR 3RA1215-1FD15-1BP4 | 3RA1225-1GD23-1BP4 OR 3RA1225-1FD23-1BP4 |
| FWER334-1MK10U1 | 3RA1215-1GD15-1AU6 OR 3RA1215-1FD15-1AU6 | 3RA1225-1GD23-1AU6 OR 3RA1225-1FD23-1AU6 |
| FWER334-1MK10W4 | 3RA1215-1GD15-1BW4 OR 3RA1215-1FD15-1BW4 | 3RA1225-1GD23-1BW4 OR 3RA1225-1FD23-1BW4 |
| FWER334-1ML10A4 | 3RA1225-1JD24-1BA4 OR 3RA1215-1HD16-1BA4 | |
| FWER334-1ML10B4 | 3RA1225-1JD24-1BB4 OR 3RA1215-1HD16-1BB4 | |
| FWER334-1ML10C2 | 3RA1225-1JD24-1AC2 OR 3RA1215-1HD16-1AC2 | |
| FWER334-1ML10G4 | 3RA1225-1JD24-1BG4 OR 3RA1215-1HD16-1BG4 | |
| FWER334-1ML10K6 | 3RA1225-1JD24-1AK6 OR 3RA1215-1HD16-1AK6 | |
| FWER334-1ML10M1 | 3RA1225-1JD24-1AM2 OR 3RA1215-1HD16-1AM2 | |
| FWER334-1ML10P6 | 3RA1225-1JD24-1AP6 OR 3RA1215-1HD16-1AP6 | |
| FWER334-1ML10Q0 | 3RA1225-1JD24-1AV0 OR 3RA1215-1HD16-1AV0 | |
| FWER334-1ML10Q4 | 3RA1225-1JD24-1BP4 OR 3RA1215-1HD16-1BP4 | |
| FWER334-1ML10U1 | 3RA1225-1JD24-1AU6 OR 3RA1215-1HD16-1AU6 | |
| FWER334-1ML10W4 | 3RA1225-1JD24-1BW4 OR 3RA1215-1HD16-1BW4 | |
| FWER334-1MM10A4 | 3RA1225-4AD25-1BA4 OR 3RA1225-1KD23-1BA4 | |
| FWER334-1MM10B4 | 3RA1225-4AD25-1BB4 OR 3RA1225-1KD23-1BB4 | |
| FWER334-1MM10C2 | 3RA1225-4AD25-1AC2 OR 3RA1225-1KD23-1AC2 | |
| FWER334-1MM10G4 | 3RA1225-4AD25-1BG4 OR 3RA1225-1KD23-1BG4 | |
| FWER334-1MM10K6 | 3RA1225-4AD25-1AK6 OR 3RA1225-1KD23-1AK6 | |
| FWER334-1MM10M1 | 3RA1225-4AD25-1AM2 OR 3RA1225-1KD23-1AM2 | |
| FWER334-1MM10P6 | 3RA1225-4AD25-1AP6 OR 3RA1225-1KD23-1AP6 | |
| FWER334-1MM10Q0 | 3RA1225-4AD25-1AV0 OR 3RA1225-1KD23-1AV0 | |
| FWER334-1MM10Q4 | 3RA1225-4AD25-1BP4 OR 3RA1225-1KD23-1BP4 | |
| FWER334-1MM10U1 | 3RA1225-4AD25-1AU6 OR 3RA1225-1KD23-1AU6 | |
| FWER334-1MM10W4 | 3RA1225-4AD25-1BW4 OR 3RA1225-1KD23-1BW4 | |
| SCE1330-1MB10A4 | 3RA1115-0AD15-1BA4 | 3RA1125-0AD23-1BA4 |
| SCE1330-1MB10B4 | 3RA1115-0AD15-1BB4 | 3RA1125-0AD23-1BB4 |
| SCE1330-1MB10C2 | 3RA1115-0AD15-1AC2 | 3RA1125-0AD23-1AC2 |
| SCE1330-1MB10G4 | 3RA1115-0AD15-1BG4 | 3RA1125-0AD23-1BG4 |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| SCE1330-1MB10K6 | 3RA1115-0AD15-1AK6 | 3RA1125-0AD23-1AK6 |
| SCE1330-1MB10M1 | 3RA1115-0AD15-1AM2 | 3RA1125-0AD23-1AM2 |
| SCE1330-1MB10P6 | 3RA1115-0AD15-1AP6 | 3RA1125-0AD23-1AP6 |
| SCE1330-1MB10Q0 | 3RA1115-0AD15-1AV0 | 3RA1125-0AD23-1AV0 |
| SCE1330-1MB10Q4 | 3RA1115-0AD15-1BP4 | 3RA1125-0AD23-1BP4 |
| SCE1330-1MB10U1 | 3RA1115-0AD15-1AU6 | 3RA1125-0AD23-1AU6 |
| SCE1330-1MB10W4 | 3RA1115-0AD15-1BW4 | 3RA1125-0AD23-1BW4 |
| SCE1330-1MC10A4 | 3RA1115-0CD15-1BA4 OR 3RA1115-0BD15-1BA4 | 3RA1125-0CD23-1BA4 OR 3RA1125-0BD23-1BA4 |
| SCE1330-1MC10B4 | 3RA1115-0CD15-1BB4 OR 3RA1115-0BD15-1BB4 | 3RA1125-0CD23-1BB4 OR 3RA1125-0BD23-1BB4 |
| SCE1330-1MC10C2 | 3RA1115-0CD15-1AC2 OR 3RA1115-0BD15-1AC2 | 3RA1125-0CD23-1AC2 OR 3RA1125-0BD23-1AC2 |
| SCE1330-1MC10G4 | 3RA1115-0CD15-1BG4 OR 3RA1115-0BD15-1BG4 | 3RA1125-0CD23-1BG4 OR 3RA1125-0BD23-1BG4 |
| SCE1330-1MC10K6 | 3RA1115-0CD15-1AK6 OR 3RA1115-0BD15-1AK6 | 3RA1125-0CD23-1AK6 OR 3RA1125-0BD23-1AK6 |
| SCE1330-1MC10M1 | 3RA1115-0CD15-1AM2 OR 3RA1115-0BD15-1AM2 | 3RA1125-0CD23-1AM2 OR 3RA1125-0BD23-1AM2 |
| SCE1330-1MC10P6 | 3RA1115-0CD15-1AP6 OR 3RA1115-0BD15-1AP6 | 3RA1125-0CD23-1AP6 OR 3RA1125-0BD23-1AP6 |
| SCE1330-1MC10Q0 | 3RA1115-0CD15-1AV0 OR 3RA1115-0BD15-1AV0 | 3RA1125-0CD23-1AV0 OR 3RA1125-0BD23-1AV0 |
| SCE1330-1MC10Q4 | 3RA1115-0CD15-1BP4 OR 3RA1115-0BD15-1BP4 | 3RA1125-0CD23-1BP4 OR 3RA1125-0BD23-1BP4 |
| SCE1330-1MC10U1 | 3RA1115-0CD15-1AU6 OR 3RA1115-0BD15-1AU6 | 3RA1125-0CD23-1AU6 OR 3RA1125-0BD23-1AU6 |
| SCE1330-1MC10W4 | 3RA1115-0CD15-1BW4 OR 3RA1115-0BD15-1BW4 | 3RA1125-0CD23-1BW4 OR 3RA1125-0BD23-1BW4 |
| SCE1330-1MD10A4 | 3RA1115-0ED15-1BA4 OR 3RA1115-0DD15-1BA4 | 3RA1125-0ED23-1BA4 OR 3RA1125-0DD23-1BA4 |
| SCE1330-1MD10B4 | 3RA1115-0ED15-1BB4 OR 3RA1115-0DD15-1BB4 | 3RA1125-0ED23-1BB4 OR 3RA1125-0DD23-1BB4 |
| SCE1330-1MD10C2 | 3RA1115-0ED15-1AC2 OR 3RA1115-0DD15-1AC2 | 3RA1125-0ED23-1AC2 OR 3RA1125-0DD23-1AC2 |
| SCE1330-1MD10G4 | 3RA1115-0ED15-1BG4 OR 3RA1115-0DD15-1BG4 | 3RA1125-0ED23-1BG4 OR 3RA1125-0DD23-1BG4 |
| SCE1330-1MD10K6 | 3RA1115-0ED15-1AK6 OR 3RA1115-0DD15-1AK6 | 3RA1125-0ED23-1AK6 OR 3RA1125-0DD23-1AK6 |
| SCE1330-1MD10M1 | 3RA1115-0ED15-1AM2 OR 3RA1115-0DD15-1AM2 | 3RA1125-0ED23-1AM2 OR 3RA1125-0DD23-1AM2 |
| SCE1330-1MD10P6 | 3RA1115-0ED15-1AP6 OR 3RA1115-0DD15-1AP6 | 3RA1125-0ED23-1AP6 OR 3RA1125-0DD23-1AP6 |
| SCE1330-1MD10Q0 | 3RA1115-0ED15-1AV0 OR 3RA1115-0DD15-1AV0 | 3RA1125-0ED23-1AV0 OR 3RA1125-0DD23-1AV0 |
| SCE1330-1MD10Q4 | 3RA1115-0ED15-1BP4 OR 3RA1115-0DD15-1BP4 | 3RA1125-0ED23-1BP4 OR 3RA1125-0DD23-1BP4 |
| SCE1330-1MD10U1 | 3RA1115-0ED15-1AU6 OR 3RA1115-0DD15-1AU6 | 3RA1125-0ED23-1AU6 OR 3RA1125-0DD23-1AU6 |
| SCE1330-1MD10W4 | 3RA1115-0ED15-1BW4 OR 3RA1115-0DD15-1BW4 | 3RA1125-0ED23-1BW4 OR 3RA1125-0DD23-1BW4 |
| SCE1330-1ME10A4 | 3RA1115-0GD15-1BA4 OR 3RA1115-0FD15-1BA4 | 3RA1125-0GD23-1BA4 OR 3RA1125-0FD23-1BA4 |
| SCE1330-1ME10B4 | 3RA1115-0GD15-1BB4 OR 3RA1115-0FD15-1BB4 | 3RA1125-0GD23-1BB4 OR 3RA1125-0FD23-1BB4 |
| SCE1330-1ME10C2 | 3RA1115-0GD15-1AC2 OR 3RA1115-0FD15-1AC2 | 3RA1125-0GD23-1AC2 OR 3RA1125-0FD23-1AC2 |
| SCE1330-1ME10G4 | 3RA1115-0GD15-1BG4 OR 3RA1115-0FD15-1BG4 | 3RA1125-0GD23-1BG4 OR 3RA1125-0FD23-1BG4 |
| SCE1330-1ME10K6 | 3RA1115-0GD15-1AK6 OR 3RA1115-0FD15-1AK6 | 3RA1125-0GD23-1AK6 OR 3RA1125-0FD23-1AK6 |
| SCE1330-1ME10M1 | 3RA1115-0GD15-1AM2 OR 3RA1115-0FD15-1AM2 | 3RA1125-0GD23-1AM2 OR 3RA1125-0FD23-1AM2 |
| SCE1330-1ME10P6 | 3RA1115-0GD15-1AP6 OR 3RA1115-0FD15-1AP6 | 3RA1125-0GD23-1AP6 OR 3RA1125-0FD23-1AP6 |
| SCE1330-1ME10Q0 | 3RA1115-0GD15-1AV0 OR 3RA1115-0FD15-1AV0 | 3RA1125-0GD23-1AV0 OR 3RA1125-0FD23-1AV0 |
| SCE1330-1ME10Q4 | 3RA1115-0GD15-1BP4 OR 3RA1115-0FD15-1BP4 | 3RA1125-0GD23-1BP4 OR 3RA1125-0FD23-1BP4 |
| SCE1330-1ME10U1 | 3RA1115-0GD15-1AU6 OR 3RA1115-0FD15-1AU6 | 3RA1125-0GD23-1AU6 OR 3RA1125-0FD23-1AU6 |
| SCE1330-1ME10W4 | 3RA1115-0GD15-1BW4 OR 3RA1115-0FD15-1BW4 | 3RA1125-0GD23-1BW4 OR 3RA1125-0FD23-1BW4 |
| SCE1330-1MF10A4 | 3RA1115-0JD15-1BA4 OR 3RA1115-0HD15-1BA4 | 3RA1125-0JD23-1BA4 OR 3RA1125-0HD23-1BA4 |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| SCE1330-1MF10B4 | 3RA1115-0JD15-1BB4 OR 3RA1115-0HD15-1BB4 | 3RA1125-0JD23-1BB4 OR 3RA1125-0HD23-1BB4 |
| SCE1330-1MF10C2 | 3RA1115-0JD15-1AC2 OR 3RA1115-0HD15-1AC2 | 3RA1125-0JD23-1AC2 OR 3RA1125-0HD23-1AC2 |
| SCE1330-1MF10G4 | 3RA1115-0JD15-1BG4 OR 3RA1115-0HD15-1BG4 | 3RA1125-0JD23-1BG4 OR 3RA1125-0HD23-1BG4 |
| SCE1330-1MF10K6 | 3RA1115-0JD15-1AK6 OR 3RA1115-0HD15-1AK6 | 3RA1125-0JD23-1AK6 OR 3RA1125-0HD23-1AK6 |
| SCE1330-1MF10M1 | 3RA1115-0JD15-1AM2 OR 3RA1115-0HD15-1AM2 | 3RA1125-0JD23-1AM2 OR 3RA1125-0HD23-1AM2 |
| SCE1330-1MF10P6 | 3RA1115-0JD15-1AP6 OR 3RA1115-0HD15-1AP6 | 3RA1125-0JD23-1AP6 OR 3RA1125-0HD23-1AP6 |
| SCE1330-1MF10Q0 | 3RA1115-0JD15-1AV0 OR 3RA1115-0HD15-1AV0 | 3RA1125-0JD23-1AV0 OR 3RA1125-0HD23-1AV0 |
| SCE1330-1MF10Q4 | 3RA1115-0JD15-1BP4 OR 3RA1115-0HD15-1BP4 | 3RA1125-0JD23-1BP4 OR 3RA1125-0HD23-1BP4 |
| SCE1330-1MF10U1 | 3RA1115-0JD15-1AU6 OR 3RA1115-0HD15-1AU6 | 3RA1125-0JD23-1AU6 OR 3RA1125-0HD23-1AU6 |
| SCE1330-1MF10W4 | 3RA1115-0JD15-1BW4 OR 3RA1115-0HD15-1BW4 | 3RA1125-0JD23-1BW4 OR 3RA1125-0HD23-1BW4 |
| SCE1334-1MG10A4 | 3RA1115-1AD15-1BA4 OR 3RA1115-0KD15-1BA4 | 3RA1125-1AD23-1BA4 OR 3RA1125-0KD23-1BA4 |
| SCE1334-1MG10B4 | 3RA1115-1AD15-1BB4 OR 3RA1115-0KD15-1BB4 | 3RA1125-1AD23-1BB4 OR 3RA1125-0KD23-1BB4 |
| SCE1334-1MG10C2 | 3RA1115-1AD15-1AC2 OR 3RA1115-0KD15-1AC2 | 3RA1125-1AD23-1AC2 OR 3RA1125-0KD23-1AC2 |
| SCE1334-1MG10G4 | 3RA1115-1AD15-1BG4 OR 3RA1115-0KD15-1BG4 | 3RA1125-1AD23-1BG4 OR 3RA1125-0KD23-1BG4 |
| SCE1334-1MG10K6 | 3RA1115-1AD15-1AK6 OR 3RA1115-0KD15-1AK6 | 3RA1125-1AD23-1AK6 OR 3RA1125-0KD23-1AK6 |
| SCE1334-1MG10M1 | 3RA1115-1AD15-1AM2 OR 3RA1115-0KD15-1AM2 | 3RA1125-1AD23-1AM2 OR 3RA1125-0KD23-1AM2 |
| SCE1334-1MG10P6 | 3RA1115-1AD15-1AP6 OR 3RA1115-0KD15-1AP6 | 3RA1125-1AD23-1AP6 OR 3RA1125-0KD23-1AP6 |
| SCE1334-1MG10Q0 | 3RA1115-1AD15-1AV0 OR 3RA1115-0KD15-1AV0 | 3RA1125-1AD23-1AV0 OR 3RA1125-0KD23-1AV0 |
| SCE1334-1MG10Q4 | 3RA1115-1AD15-1BP4 OR 3RA1115-0KD15-1BP4 | 3RA1125-1AD23-1BP4 OR 3RA1125-0KD23-1BP4 |
| SCE1334-1MG10U1 | 3RA1115-1AD15-1AU6 OR 3RA1115-0KD15-1AU6 | 3RA1125-1AD23-1AU6 OR 3RA1125-0KD23-1AU6 |
| SCE1334-1MG10W4 | 3RA1115-1AD15-1BW4 OR 3RA1115-0KD15-1BW4 | 3RA1125-1AD23-1BW4 OR 3RA1125-0KD23-1BW4 |
| SCE1334-1MH10A4 | 3RA1115-1CD15-1BA4 OR 3RA1115-1BD15-1BA4 | 3RA1125-1CD23-1BA4 OR 3RA1125-1BD23-1BA4 |
| SCE1334-1MH10B4 | 3RA1115-1CD15-1BB4 OR 3RA1115-1BD15-1BB4 | 3RA1125-1CD23-1BB4 OR 3RA1125-1BD23-1BB4 |
| SCE1334-1MH10C2 | 3RA1115-1CD15-1AC2 OR 3RA1115-1BD15-1AC2 | 3RA1125-1CD23-1AC2 OR 3RA1125-1BD23-1AC2 |
| SCE1334-1MH10G4 | 3RA1115-1CD15-1BG4 OR 3RA1115-1BD15-1BG4 | 3RA1125-1CD23-1BG4 OR 3RA1125-1BD23-1BG4 |
| SCE1334-1MH10K6 | 3RA1115-1CD15-1AK6 OR 3RA1115-1BD15-1AK6 | 3RA1125-1CD23-1AK6 OR 3RA1125-1BD23-1AK6 |
| SCE1334-1MH10M1 | 3RA1115-1CD15-1AM2 OR 3RA1115-1BD15-1AM2 | 3RA1125-1CD23-1AM2 OR 3RA1125-1BD23-1AM2 |
| SCE1334-1MH10P6 | 3RA1115-1CD15-1AP6 OR 3RA1115-1BD15-1AP6 | 3RA1125-1CD23-1AP6 OR 3RA1125-1BD23-1AP6 |
| SCE1334-1MH10Q0 | 3RA1115-1CD15-1AV0 OR 3RA1115-1BD15-1AV0 | 3RA1125-1CD23-1AV0 OR 3RA1125-1BD23-1AV0 |
| SCE1334-1MH10Q4 | 3RA1115-1CD15-1BP4 OR 3RA1115-1BD15-1BP4 | 3RA1125-1CD23-1BP4 OR 3RA1125-1BD23-1BP4 |
| SCE1334-1MH10U1 | 3RA1115-1CD15-1AU6 OR 3RA1115-1BD15-1AU6 | 3RA1125-1CD23-1AU6 OR 3RA1125-1BD23-1AU6 |
| SCE1334-1MH10W4 | 3RA1115-1CD15-1BW4 OR 3RA1115-1BD15-1BW4 | 3RA1125-1CD23-1BW4 OR 3RA1125-1BD23-1BW4 |
| SCE1334-1MJ10A4 | 3RA1115-1ED15-1BA4 OR 3RA1115-1DD15-1BA4 | 3RA1125-1ED23-1BA4 OR 3RA1125-1DD23-1BA4 |
| SCE1334-1MJ10B4 | 3RA1115-1ED15-1BB4 OR 3RA1115-1DD15-1BB4 | 3RA1125-1ED23-1BB4 OR 3RA1125-1DD23-1BB4 |
| SCE1334-1MJ10C2 | 3RA1115-1ED15-1AC2 OR 3RA1115-1DD15-1AC2 | 3RA1125-1ED23-1AC2 OR 3RA1125-1DD23-1AC2 |
| SCE1334-1MJ10G4 | 3RA1115-1ED15-1BG4 OR 3RA1115-1DD15-1BG4 | 3RA1125-1ED23-1BG4 OR 3RA1125-1DD23-1BG4 |
| SCE1334-1MJ10K6 | 3RA1115-1ED15-1AK6 OR 3RA1115-1DD15-1AK6 | 3RA1125-1ED23-1AK6 OR 3RA1125-1DD23-1AK6 |
| SCE1334-1MJ10M1 | 3RA1115-1ED15-1AM2 OR 3RA1115-1DD15-1AM2 | 3RA1125-1ED23-1AM2 OR 3RA1125-1DD23-1AM2 |
| SCE1334-1MJ10P6 | 3RA1115-1ED15-1AP6 OR 3RA1115-1DD15-1AP6 | 3RA1125-1ED23-1AP6 OR 3RA1125-1DD23-1AP6 |
| SCE1334-1MJ10Q0 | 3RA1115-1ED15-1AV0 OR 3RA1115-1DD15-1AV0 | 3RA1125-1ED23-1AV0 OR 3RA1125-1DD23-1AV0 |
| SCE1334-1MJ10Q4 | 3RA1115-1ED15-1BP4 OR 3RA1115-1DD15-1BP4 | 3RA1125-1ED23-1BP4 OR 3RA1125-1DD23-1BP4 |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| SCE1334-1MJ10U1 | 3RA1115-1ED15-1AU6 OR 3RA1115-1DD15-1AU6 | 3RA1125-1ED23-1AU6 OR 3RA1125-1DD23-1AU6 |
| SCE1334-1MJ10W4 | 3RA1115-1ED15-1BW4 OR 3RA1115-1DD15-1BW4 | 3RA1125-1ED23-1BW4 OR 3RA1125-1DD23-1BW4 |
| SCE1334-1MK10A4 | 3RA1115-1GD15-1BA4 OR 3RA1115-1FD15-1BA4 | 3RA1125-1GD23-1BA4 OR 3RA1125-1FD23-1BA4 |
| SCE1334-1MK10B4 | 3RA1115-1GD15-1BB4 OR 3RA1115-1FD15-1BB4 | 3RA1125-1GD23-1BB4 OR 3RA1125-1FD23-1BB4 |
| SCE1334-1MK10C2 | 3RA1115-1GD15-1AC2 OR 3RA1115-1FD15-1AC2 | 3RA1125-1GD23-1AC2 OR 3RA1125-1FD23-1AC2 |
| SCE1334-1MK10G4 | 3RA1115-1GD15-1BG4 OR 3RA1115-1FD15-1BG4 | 3RA1125-1GD23-1BG4 OR 3RA1125-1FD23-1BG4 |
| SCE1334-1MK10K6 | 3RA1115-1GD15-1AK6 OR 3RA1115-1FD15-1AK6 | 3RA1125-1GD23-1AK6 OR 3RA1125-1FD23-1AK6 |
| SCE1334-1MK10M1 | 3RA1115-1GD15-1AM2 OR 3RA1115-1FD15-1AM2 | 3RA1125-1GD23-1AM2 OR 3RA1125-1FD23-1AM2 |
| SCE1334-1MK10P6 | 3RA1115-1GD15-1AP6 OR 3RA1115-1FD15-1AP6 | 3RA1125-1GD23-1AP6 OR 3RA1125-1FD23-1AP6 |
| SCE1334-1MK10Q0 | 3RA1115-1GD15-1AV0 OR 3RA1115-1FD15-1AV0 | 3RA1125-1GD23-1AV0 OR 3RA1125-1FD23-1AV0 |
| SCE1334-1MK10Q4 | 3RA1115-1GD15-1BP4 OR 3RA1115-1FD15-1BP4 | 3RA1125-1GD23-1BP4 OR 3RA1125-1FD23-1BP4 |
| SCE1334-1MK10U1 | 3RA1115-1GD15-1AU6 OR 3RA1115-1FD15-1AU6 | 3RA1125-1GD23-1AU6 OR 3RA1125-1FD23-1AU6 |
| SCE1334-1MK10W4 | 3RA1115-1GD15-1BW4 OR 3RA1115-1FD15-1BW4 | 3RA1125-1GD23-1BW4 OR 3RA1125-1FD23-1BW4 |
| SCE1334-1ML10A4 | 3RA1125-1JD24-1BA4 OR 3RA1115-1HD16-1BA4 | |
| SCE1334-1ML10B4 | 3RA1125-1JD24-1BB4 OR 3RA1115-1HD16-1BB4 | |
| SCE1334-1ML10C2 | 3RA1125-1JD24-1AC2 OR 3RA1115-1HD16-1AC2 | |
| SCE1334-1ML10G4 | 3RA1125-1JD24-1BG4 OR 3RA1115-1HD16-1BG4 | |
| SCE1334-1ML10K6 | 3RA1125-1JD24-1AK6 OR 3RA1115-1HD16-1AK6 | |
| SCE1334-1ML10M1 | 3RA1125-1JD24-1AM2 OR 3RA1115-1HD16-1AM2 | |
| SCE1334-1ML10P6 | 3RA1125-1JD24-1AP6 OR 3RA1115-1HD16-1AP6 | |
| SCE1334-1ML10Q0 | 3RA1125-1JD24-1AV0 OR 3RA1115-1HD16-1AV0 | |
| SCE1334-1ML10Q4 | 3RA1125-1JD24-1BP4 OR 3RA1115-1HD16-1BP4 | |
| SCE1334-1ML10U1 | 3RA1125-1JD24-1AU6 OR 3RA1115-1HD16-1AU6 | |
| SCE1334-1ML10W4 | 3RA1125-1JD24-1BW4 OR 3RA1115-1HD16-1BW4 | |
| SCE1334-1MM10A4 | 3RA1125-4AD25-1BA4 OR 3RA1125-1KD23-1BA4 | |
| SCE1334-1MM10B4 | 3RA1125-4AD25-1BB4 OR 3RA1125-1KD23-1BB4 | |
| SCE1334-1MM10C2 | 3RA1125-4AD25-1AC2 OR 3RA1125-1KD23-1AC2 | |
| SCE1334-1MM10G4 | 3RA1125-4AD25-1BG4 OR 3RA1125-1KD23-1BG4 | |
| SCE1334-1MM10K6 | 3RA1125-4AD25-1AK6 OR 3RA1125-1KD23-1AK6 | |
| SCE1334-1MM10M1 | 3RA1125-4AD25-1AM2 OR 3RA1125-1KD23-1AM2 | |
| SCE1334-1MM10P6 | 3RA1125-4AD25-1AP6 OR 3RA1125-1KD23-1AP6 | |
| SCE1334-1MM10Q0 | 3RA1125-4AD25-1AV0 OR 3RA1125-1KD23-1AV0 | |
| SCE1334-1MM10Q4 | 3RA1125-4AD25-1BP4 OR 3RA1125-1KD23-1BP4 | |
| SCE1334-1MM10U1 | 3RA1125-4AD25-1AU6 OR 3RA1125-1KD23-1AU6 | |
| SCE1334-1MM10W4 | 3RA1125-4AD25-1BW4 OR 3RA1125-1KD23-1BW4 | |
| SCE1634-1MG10A4 | 3RA1115-1AD15-1BA4 OR 3RA1115-0KD15-1BA4 | 3RA1125-1AD23-1BA4 OR 3RA1125-0KD23-1BA4 |
| SCE1634-1MG10B4 | 3RA1115-1AD15-1BB4 OR 3RA1115-0KD15-1BB4 | 3RA1125-1AD23-1BB4 OR 3RA1125-0KD23-1BB4 |
| SCE1634-1MG10C2 | 3RA1115-1AD15-1AC2 OR 3RA1115-0KD15-1AC2 | 3RA1125-1AD23-1AC2 OR 3RA1125-0KD23-1AC2 |
| SCE1634-1MG10G4 | 3RA1115-1AD15-1BG4 OR 3RA1115-0KD15-1BG4 | 3RA1125-1AD23-1BG4 OR 3RA1125-0KD23-1BG4 |
| SCE1634-1MG10K6 | 3RA1115-1AD15-1AK6 OR 3RA1115-0KD15-1AK6 | 3RA1125-1AD23-1AK6 OR 3RA1125-0KD23-1AK6 |
| SCE1634-1MG10M1 | 3RA1115-1AD15-1AM2 OR 3RA1115-0KD15-1AM2 | 3RA1125-1AD23-1AM2 OR 3RA1125-0KD23-1AM2 |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| SCE1634-1MG10P6 | 3RA1115-1AD15-1AP6 OR 3RA1115-0KD15-1AP6 | 3RA1125-1AD23-1AP6 OR 3RA1125-0KD23-1AP6 |
| SCE1634-1MG10Q0 | 3RA1115-1AD15-1AV0 OR 3RA1115-0KD15-1AV0 | 3RA1125-1AD23-1AV0 OR 3RA1125-0KD23-1AV0 |
| SCE1634-1MG10Q4 | 3RA1115-1AD15-1BP4 OR 3RA1115-0KD15-1BP4 | 3RA1125-1AD23-1BP4 OR 3RA1125-0KD23-1BP4 |
| SCE1634-1MG10U1 | 3RA1115-1AD15-1AU6 OR 3RA1115-0KD15-1AU6 | 3RA1125-1AD23-1AU6 OR 3RA1125-0KD23-1AU6 |
| SCE1634-1MG10W4 | 3RA1115-1AD15-1BW4 OR 3RA1115-0KD15-1BW4 | 3RA1125-1AD23-1BW4 OR 3RA1125-0KD23-1BW4 |
| SCE1634-1MH10A4 | 3RA1115-1CD15-1BA4 OR 3RA1115-1BD15-1BA4 | 3RA1125-1CD23-1BA4 OR 3RA1125-1BD23-1BA4 |
| SCE1634-1MH10B4 | 3RA1115-1CD15-1BB4 OR 3RA1115-1BD15-1BB4 | 3RA1125-1CD23-1BB4 OR 3RA1125-1BD23-1BB4 |
| SCE1634-1MH10C2 | 3RA1115-1CD15-1AC2 OR 3RA1115-1BD15-1AC2 | 3RA1125-1CD23-1AC2 OR 3RA1125-1BD23-1AC2 |
| SCE1634-1MH10G4 | 3RA1115-1CD15-1BG4 OR 3RA1115-1BD15-1BG4 | 3RA1125-1CD23-1BG4 OR 3RA1125-1BD23-1BG4 |
| SCE1634-1MH10K6 | 3RA1115-1CD15-1AK6 OR 3RA1115-1BD15-1AK6 | 3RA1125-1CD23-1AK6 OR 3RA1125-1BD23-1AK6 |
| SCE1634-1MH10M1 | 3RA1115-1CD15-1AM2 OR 3RA1115-1BD15-1AM2 | 3RA1125-1CD23-1AM2 OR 3RA1125-1BD23-1AM2 |
| SCE1634-1MH10P6 | 3RA1115-1CD15-1AP6 OR 3RA1115-1BD15-1AP6 | 3RA1125-1CD23-1AP6 OR 3RA1125-1BD23-1AP6 |
| SCE1634-1MH10Q0 | 3RA1115-1CD15-1AV0 OR 3RA1115-1BD15-1AV0 | 3RA1125-1CD23-1AV0 OR 3RA1125-1BD23-1AV0 |
| SCE1634-1MH10Q4 | 3RA1115-1CD15-1BP4 OR 3RA1115-1BD15-1BP4 | 3RA1125-1CD23-1BP4 OR 3RA1125-1BD23-1BP4 |
| SCE1634-1MH10U1 | 3RA1115-1CD15-1AU6 OR 3RA1115-1BD15-1AU6 | 3RA1125-1CD23-1AU6 OR 3RA1125-1BD23-1AU6 |
| SCE1634-1MH10W4 | 3RA1115-1CD15-1BW4 OR 3RA1115-1BD15-1BW4 | 3RA1125-1CD23-1BW4 OR 3RA1125-1BD23-1BW4 |
| SCE1634-1MJ10A4 | 3RA1115-1ED15-1BA4 OR 3RA1115-1DD15-1BA4 | 3RA1125-1ED23-1BA4 OR 3RA1125-1DD23-1BA4 |
| SCE1634-1MJ10B4 | 3RA1115-1ED15-1BB4 OR 3RA1115-1DD15-1BB4 | 3RA1125-1ED23-1BB4 OR 3RA1125-1DD23-1BB4 |
| SCE1634-1MJ10C2 | 3RA1115-1ED15-1AC2 OR 3RA1115-1DD15-1AC2 | 3RA1125-1ED23-1AC2 OR 3RA1125-1DD23-1AC2 |
| SCE1634-1MJ10G4 | 3RA1115-1ED15-1BG4 OR 3RA1115-1DD15-1BG4 | 3RA1125-1ED23-1BG4 OR 3RA1125-1DD23-1BG4 |
| SCE1634-1MJ10K6 | 3RA1115-1ED15-1AK6 OR 3RA1115-1DD15-1AK6 | 3RA1125-1ED23-1AK6 OR 3RA1125-1DD23-1AK6 |
| SCE1634-1MJ10M1 | 3RA1115-1ED15-1AM2 OR 3RA1115-1DD15-1AM2 | 3RA1125-1ED23-1AM2 OR 3RA1125-1DD23-1AM2 |
| SCE1634-1MJ10P6 | 3RA1115-1ED15-1AP6 OR 3RA1115-1DD15-1AP6 | 3RA1125-1ED23-1AP6 OR 3RA1125-1DD23-1AP6 |
| SCE1634-1MJ10Q0 | 3RA1115-1ED15-1AV0 OR 3RA1115-1DD15-1AV0 | 3RA1125-1ED23-1AV0 OR 3RA1125-1DD23-1AV0 |
| SCE1634-1MJ10Q4 | 3RA1115-1ED15-1BP4 OR 3RA1115-1DD15-1BP4 | 3RA1125-1ED23-1BP4 OR 3RA1125-1DD23-1BP4 |
| SCE1634-1MJ10U1 | 3RA1115-1ED15-1AU6 OR 3RA1115-1DD15-1AU6 | 3RA1125-1ED23-1AU6 OR 3RA1125-1DD23-1AU6 |
| SCE1634-1MJ10W4 | 3RA1115-1ED15-1BW4 OR 3RA1115-1DD15-1BW4 | 3RA1125-1ED23-1BW4 OR 3RA1125-1DD23-1BW4 |
| SCE1634-1MK10A4 | 3RA1115-1GD15-1BA4 OR 3RA1115-1FD15-1BA4 | 3RA1125-1GD23-1BA4 OR 3RA1125-1FD23-1BA4 |
| SCE1634-1MK10B4 | 3RA1115-1GD15-1BB4 OR 3RA1115-1FD15-1BB4 | 3RA1125-1GD23-1BB4 OR 3RA1125-1FD23-1BB4 |
| SCE1634-1MK10C2 | 3RA1115-1GD15-1AC2 OR 3RA1115-1FD15-1AC2 | 3RA1125-1GD23-1AC2 OR 3RA1125-1FD23-1AC2 |
| SCE1634-1MK10G4 | 3RA1115-1GD15-1BG4 OR 3RA1115-1FD15-1BG4 | 3RA1125-1GD23-1BG4 OR 3RA1125-1FD23-1BG4 |
| SCE1634-1MK10K6 | 3RA1115-1GD15-1AK6 OR 3RA1115-1FD15-1AK6 | 3RA1125-1GD23-1AK6 OR 3RA1125-1FD23-1AK6 |
| SCE1634-1MK10M1 | 3RA1115-1GD15-1AM2 OR 3RA1115-1FD15-1AM2 | 3RA1125-1GD23-1AM2 OR 3RA1125-1FD23-1AM2 |
| SCE1634-1MK10P6 | 3RA1115-1GD15-1AP6 OR 3RA1115-1FD15-1AP6 | 3RA1125-1GD23-1AP6 OR 3RA1125-1FD23-1AP6 |
| SCE1634-1MK10Q0 | 3RA1115-1GD15-1AV0 OR 3RA1115-1FD15-1AV0 | 3RA1125-1GD23-1AV0 OR 3RA1125-1FD23-1AV0 |
| SCE1634-1MK10Q4 | 3RA1115-1GD15-1BP4 OR 3RA1115-1FD15-1BP4 | 3RA1125-1GD23-1BP4 OR 3RA1125-1FD23-1BP4 |
| SCE1634-1MK10U1 | 3RA1115-1GD15-1AU6 OR 3RA1115-1FD15-1AU6 | 3RA1125-1GD23-1AU6 OR 3RA1125-1FD23-1AU6 |
| SCE1634-1MK10W4 | 3RA1115-1GD15-1BW4 OR 3RA1115-1FD15-1BW4 | 3RA1125-1GD23-1BW4 OR 3RA1125-1FD23-1BW4 |
| SCE1634-1ML10A4 | 3RA1125-1JD24-1BA4 OR 3RA1115-1HD16-1BA4 | |
| SCE1634-1ML10B4 | 3RA1125-1JD24-1BB4 OR 3RA1115-1HD16-1BB4 | |
| SCE1634-1ML10C2 | 3RA1125-1JD24-1AC2 OR 3RA1115-1HD16-1AC2 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| SCE1634-1ML10G4 | 3RA1125-1JD24-1BG4 OR 3RA1115-1HD16-1BG4 | |
| SCE1634-1ML10K6 | 3RA1125-1JD24-1AK6 OR 3RA1115-1HD16-1AK6 | |
| SCE1634-1ML10M1 | 3RA1125-1JD24-1AM2 OR 3RA1115-1HD16-1AM2 | |
| SCE1634-1ML10P6 | 3RA1125-1JD24-1AP6 OR 3RA1115-1HD16-1AP6 | |
| SCE1634-1ML10Q0 | 3RA1125-1JD24-1AV0 OR 3RA1115-1HD16-1AV0 | |
| SCE1634-1ML10Q4 | 3RA1125-1JD24-1BP4 OR 3RA1115-1HD16-1BP4 | |
| SCE1634-1ML10U1 | 3RA1125-1JD24-1AU6 OR 3RA1115-1HD16-1AU6 | |
| SCE1634-1ML10W4 | 3RA1125-1JD24-1BW4 OR 3RA1115-1HD16-1BW4 | |
| SCE1634-1MM10A4 | 3RA1125-4AD25-1BA4 OR 3RA1125-1KD23-1BA4 | |
| SCE1634-1MM10B4 | 3RA1125-4AD25-1BB4 OR 3RA1125-1KD23-1BB4 | |
| SCE1634-1MM10C2 | 3RA1125-4AD25-1AC2 OR 3RA1125-1KD23-1AC2 | |
| SCE1634-1MM10G4 | 3RA1125-4AD25-1BG4 OR 3RA1125-1KD23-1BG4 | |
| SCE1634-1MM10K6 | 3RA1125-4AD25-1AK6 OR 3RA1125-1KD23-1AK6 | |
| SCE1634-1MM10M1 | 3RA1125-4AD25-1AM2 OR 3RA1125-1KD23-1AM2 | |
| SCE1634-1MM10P6 | 3RA1125-4AD25-1AP6 OR 3RA1125-1KD23-1AP6 | |
| SCE1634-1MM10Q0 | 3RA1125-4AD25-1AV0 OR 3RA1125-1KD23-1AV0 | |
| SCE1634-1MM10Q4 | 3RA1125-4AD25-1BP4 OR 3RA1125-1KD23-1BP4 | |
| SCE1634-1MM10U1 | 3RA1125-4AD25-1AU6 OR 3RA1125-1KD23-1AU6 | |
| SCE1634-1MM10W4 | 3RA1125-4AD25-1BW4 OR 3RA1125-1KD23-1BW4 | |
| SCE1634-1MN10A4 | 3RA1125-4BD26-1BA4 | |
| SCE1634-1MN10B4 | 3RA1125-4BD26-1BB4 | |
| SCE1634-1MN10C2 | 3RA1125-4BD26-1AC2 | |
| SCE1634-1MN10G4 | 3RA1125-4BD26-1BG4 | |
| SCE1634-1MN10K6 | 3RA1125-4BD26-1AK6 | |
| SCE1634-1MN10M1 | 3RA1125-4BD26-1AM2 | |
| SCE1634-1MN10P6 | 3RA1125-4BD26-1AP6 | |
| SCE1634-1MN10Q0 | 3RA1125-4BD26-1AV0 | |
| SCE1634-1MN10Q4 | 3RA1125-4BD26-1BP4 | |
| SCE1634-1MN10U1 | 3RA1125-4BD26-1AU6 | |
| SCE1634-1MN10W4 | 3RA1125-4BD26-1BW4 | |
| SCE1634-1MP10A4 | 3RA1135-4ED34-1BA4 | |
| SCE1634-1MP10B4 | 3RA1135-4ED34-1BB4 | |
| SCE1634-1MP10C2 | 3RA1135-4ED34-1AC2 | |
| SCE1634-1MP10G4 | 3RA1135-4ED34-1BG4 | |
| SCE1634-1MP10K6 | 3RA1135-4ED34-1AK6 | |
| SCE1634-1MP10M1 | 3RA1135-4ED34-1AM2 | |
| SCE1634-1MP10P6 | 3RA1135-4ED34-1AP6 | |
| SCE1634-1MP10Q0 | 3RA1135-4ED34-1AV0 | |
| SCE1634-1MP10Q4 | 3RA1135-4ED34-1BP4 | |
| SCE1634-1MP10U1 | 3RA1135-4ED34-1AU6 | |
| SCE1634-1MP10W4 | 3RA1135-4ED34-1BW4 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| SCE9138-2AB10 | NO DIRECT REPLACEMENT | |
| SCER330-1MB10A4 | 3RA1215-0AD15-1BA4 | 3RA1225-0AD23-1BA4 |
| SCER330-1MB10B4 | 3RA1215-0AD15-1BB4 | 3RA1225-0AD23-1BB4 |
| SCER330-1MB10C2 | 3RA1215-0AD15-1AC2 | 3RA1225-0AD23-1AC2 |
| SCER330-1MB10G4 | 3RA1215-0AD15-1BG4 | 3RA1225-0AD23-1BG4 |
| SCER330-1MB10K6 | 3RA1215-0AD15-1AK6 | 3RA1225-0AD23-1AK6 |
| SCER330-1MB10M1 | 3RA1215-0AD15-1AM2 | 3RA1225-0AD23-1AM2 |
| SCER330-1MB10P6 | 3RA1215-0AD15-1AP6 | 3RA1225-0AD23-1AP6 |
| SCER330-1MB10Q0 | 3RA1215-0AD15-1AV0 | 3RA1225-0AD23-1AV0 |
| SCER330-1MB10Q4 | 3RA1215-0AD15-1BP4 | 3RA1225-0AD23-1BP4 |
| SCER330-1MB10U1 | 3RA1215-0AD15-1AU6 | 3RA1225-0AD23-1AU6 |
| SCER330-1MB10W4 | 3RA1215-0AD15-1BW4 | 3RA1225-0AD23-1BW4 |
| SCER330-1MC10A4 | 3RA1215-0CD15-1BA4 OR 3RA1215-0BD15-1BA4 | 3RA1225-0CD23-1BA4 OR 3RA1225-0BD23-1BA4 |
| SCER330-1MC10B4 | 3RA1215-0CD15-1BB4 OR 3RA1215-0BD15-1BB4 | 3RA1225-0CD23-1BB4 OR 3RA1225-0BD23-1BB4 |
| SCER330-1MC10C2 | 3RA1215-0CD15-1AC2 OR 3RA1215-0BD15-1AC2 | 3RA1225-0CD23-1AC2 OR 3RA1225-0BD23-1AC2 |
| SCER330-1MC10G4 | 3RA1215-0CD15-1BG4 OR 3RA1215-0BD15-1BG4 | 3RA1225-0CD23-1BG4 OR 3RA1225-0BD23-1BG4 |
| SCER330-1MC10K6 | 3RA1215-0CD15-1AK6 OR 3RA1215-0BD15-1AK6 | 3RA1225-0CD23-1AK6 OR 3RA1225-0BD23-1AK6 |
| SCER330-1MC10M1 | 3RA1215-0CD15-1AM2 OR 3RA1215-0BD15-1AM2 | 3RA1225-0CD23-1AM2 OR 3RA1225-0BD23-1AM2 |
| SCER330-1MC10P6 | 3RA1215-0CD15-1AP6 OR 3RA1215-0BD15-1AP6 | 3RA1225-0CD23-1AP6 OR 3RA1225-0BD23-1AP6 |
| SCER330-1MC10Q0 | 3RA1215-0CD15-1AV0 OR 3RA1215-0BD15-1AV0 | 3RA1225-0CD23-1AV0 OR 3RA1225-0BD23-1AV0 |
| SCER330-1MC10Q4 | 3RA1215-0CD15-1BP4 OR 3RA1215-0BD15-1BP4 | 3RA1225-0CD23-1BP4 OR 3RA1225-0BD23-1BP4 |
| SCER330-1MC10U1 | 3RA1215-0CD15-1AU6 OR 3RA1215-0BD15-1AU6 | 3RA1225-0CD23-1AU6 OR 3RA1225-0BD23-1AU6 |
| SCER330-1MC10W4 | 3RA1215-0CD15-1BW4 OR 3RA1215-0BD15-1BW4 | 3RA1225-0CD23-1BW4 OR 3RA1225-0BD23-1BW4 |
| SCER330-1MD10A4 | 3RA1215-0ED15-1BA4 OR 3RA1215-0DD15-1BA4 | 3RA1225-0ED23-1BA4 OR 3RA1225-0DD23-1BA4 |
| SCER330-1MD10B4 | 3RA1215-0ED15-1BB4 OR 3RA1215-0DD15-1BB4 | 3RA1225-0ED23-1BB4 OR 3RA1225-0DD23-1BB4 |
| SCER330-1MD10C2 | 3RA1215-0ED15-1AC2 OR 3RA1215-0DD15-1AC2 | 3RA1225-0ED23-1AC2 OR 3RA1225-0DD23-1AC2 |
| SCER330-1MD10G4 | 3RA1215-0ED15-1BG4 OR 3RA1215-0DD15-1BG4 | 3RA1225-0ED23-1BG4 OR 3RA1225-0DD23-1BG4 |
| SCER330-1MD10K6 | 3RA1215-0ED15-1AK6 OR 3RA1215-0DD15-1AK6 | 3RA1225-0ED23-1AK6 OR 3RA1225-0DD23-1AK6 |
| SCER330-1MD10M1 | 3RA1215-0ED15-1AM2 OR 3RA1215-0DD15-1AM2 | 3RA1225-0ED23-1AM2 OR 3RA1225-0DD23-1AM2 |
| SCER330-1MD10P6 | 3RA1215-0ED15-1AP6 OR 3RA1215-0DD15-1AP6 | 3RA1225-0ED23-1AP6 OR 3RA1225-0DD23-1AP6 |
| SCER330-1MD10Q0 | 3RA1215-0ED15-1AV0 OR 3RA1215-0DD15-1AV0 | 3RA1225-0ED23-1AV0 OR 3RA1225-0DD23-1AV0 |
| SCER330-1MD10Q4 | 3RA1215-0ED15-1BP4 OR 3RA1215-0DD15-1BP4 | 3RA1225-0ED23-1BP4 OR 3RA1225-0DD23-1BP4 |
| SCER330-1MD10U1 | 3RA1215-0ED15-1AU6 OR 3RA1215-0DD15-1AU6 | 3RA1225-0ED23-1AU6 OR 3RA1225-0DD23-1AU6 |
| SCER330-1MD10W4 | 3RA1215-0ED15-1BW4 OR 3RA1215-0DD15-1BW4 | 3RA1225-0ED23-1BW4 OR 3RA1225-0DD23-1BW4 |
| SCER330-1ME10A4 | 3RA1215-0GD15-1BA4 OR 3RA1215-0FD15-1BA4 | 3RA1225-0GD23-1BA4 OR 3RA1225-0FD23-1BA4 |
| SCER330-1ME10B4 | 3RA1215-0GD15-1BB4 OR 3RA1215-0FD15-1BB4 | 3RA1225-0GD23-1BB4 OR 3RA1225-0FD23-1BB4 |
| SCER330-1ME10C2 | 3RA1215-0GD15-1AC2 OR 3RA1215-0FD15-1AC2 | 3RA1225-0GD23-1AC2 OR 3RA1225-0FD23-1AC2 |
| SCER330-1ME10G4 | 3RA1215-0GD15-1BG4 OR 3RA1215-0FD15-1BG4 | 3RA1225-0GD23-1BG4 OR 3RA1225-0FD23-1BG4 |
| SCER330-1ME10K6 | 3RA1215-0GD15-1AK6 OR 3RA1215-0FD15-1AK6 | 3RA1225-0GD23-1AK6 OR 3RA1225-0FD23-1AK6 |
| SCER330-1ME10M1 | 3RA1215-0GD15-1AM2 OR 3RA1215-0FD15-1AM2 | 3RA1225-0GD23-1AM2 OR 3RA1225-0FD23-1AM2 |
| SCER330-1ME10P6 | 3RA1215-0GD15-1AP6 OR 3RA1215-0FD15-1AP6 | 3RA1225-0GD23-1AP6 OR 3RA1225-0FD23-1AP6 |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| SCER330-1ME10Q0 | 3RA1215-0GD15-1AV0 OR 3RA1215-0FD15-1AV0 | 3RA1225-0GD23-1AV0 OR 3RA1225-0FD23-1AV0 |
| SCER330-1ME10Q4 | 3RA1215-0GD15-1BP4 OR 3RA1215-0FD15-1BP4 | 3RA1225-0GD23-1BP4 OR 3RA1225-0FD23-1BP4 |
| SCER330-1ME10U1 | 3RA1215-0GD15-1AU6 OR 3RA1215-0FD15-1AU6 | 3RA1225-0GD23-1AU6 OR 3RA1225-0FD23-1AU6 |
| SCER330-1ME10W4 | 3RA1215-0GD15-1BW4 OR 3RA1215-0FD15-1BW4 | 3RA1225-0GD23-1BW4 OR 3RA1225-0FD23-1BW4 |
| SCER330-1MF10A4 | 3RA1215-0JD15-1BA4 OR 3RA1215-0HD15-1BA4 | 3RA1225-0JD23-1BA4 OR 3RA1225-0HD23-1BA4 |
| SCER330-1MF10B4 | 3RA1215-0JD15-1BB4 OR 3RA1215-0HD15-1BB4 | 3RA1225-0JD23-1BB4 OR 3RA1225-0HD23-1BB4 |
| SCER330-1MF10C2 | 3RA1215-0JD15-1AC2 OR 3RA1215-0HD15-1AC2 | 3RA1225-0JD23-1AC2 OR 3RA1225-0HD23-1AC2 |
| SCER330-1MF10G4 | 3RA1215-0JD15-1BG4 OR 3RA1215-0HD15-1BG4 | 3RA1225-0JD23-1BG4 OR 3RA1225-0HD23-1BG4 |
| SCER330-1MF10K6 | 3RA1215-0JD15-1AK6 OR 3RA1215-0HD15-1AK6 | 3RA1225-0JD23-1AK6 OR 3RA1225-0HD23-1AK6 |
| SCER330-1MF10M1 | 3RA1215-0JD15-1AM2 OR 3RA1215-0HD15-1AM2 | 3RA1225-0JD23-1AM2 OR 3RA1225-0HD23-1AM2 |
| SCER330-1MF10P6 | 3RA1215-0JD15-1AP6 OR 3RA1215-0HD15-1AP6 | 3RA1225-0JD23-1AP6 OR 3RA1225-0HD23-1AP6 |
| SCER330-1MF10Q0 | 3RA1215-0JD15-1AV0 OR 3RA1215-0HD15-1AV0 | 3RA1225-0JD23-1AV0 OR 3RA1225-0HD23-1AV0 |
| SCER330-1MF10Q4 | 3RA1215-0JD15-1BP4 OR 3RA1215-0HD15-1BP4 | 3RA1225-0JD23-1BP4 OR 3RA1225-0HD23-1BP4 |
| SCER330-1MF10U1 | 3RA1215-0JD15-1AU6 OR 3RA1215-0HD15-1AU6 | 3RA1225-0JD23-1AU6 OR 3RA1225-0HD23-1AU6 |
| SCER330-1MF10W4 | 3RA1215-0JD15-1BW4 OR 3RA1215-0HD15-1BW4 | 3RA1225-0JD23-1BW4 OR 3RA1225-0HD23-1BW4 |
| SCER334-1MG10A4 | 3RA1215-1AD15-1BA4 OR 3RA1215-0KD15-1BA4 | 3RA1225-1AD23-1BA4 OR 3RA1225-0KD23-1BA4 |
| SCER334-1MG10B4 | 3RA1215-1AD15-1BB4 OR 3RA1215-0KD15-1BB4 | 3RA1225-1AD23-1BB4 OR 3RA1225-0KD23-1BB4 |
| SCER334-1MG10C2 | 3RA1215-1AD15-1AC2 OR 3RA1215-0KD15-1AC2 | 3RA1225-1AD23-1AC2 OR 3RA1225-0KD23-1AC2 |
| SCER334-1MG10G4 | 3RA1215-1AD15-1BG4 OR 3RA1215-0KD15-1BG4 | 3RA1225-1AD23-1BG4 OR 3RA1225-0KD23-1BG4 |
| SCER334-1MG10K6 | 3RA1215-1AD15-1AK6 OR 3RA1215-0KD15-1AK6 | 3RA1225-1AD23-1AK6 OR 3RA1225-0KD23-1AK6 |
| SCER334-1MG10M1 | 3RA1215-1AD15-1AM2 OR 3RA1215-0KD15-1AM2 | 3RA1225-1AD23-1AM2 OR 3RA1225-0KD23-1AM2 |
| SCER334-1MG10P6 | 3RA1215-1AD15-1AP6 OR 3RA1215-0KD15-1AP6 | 3RA1225-1AD23-1AP6 OR 3RA1225-0KD23-1AP6 |
| SCER334-1MG10Q0 | 3RA1215-1AD15-1AV0 OR 3RA1215-0KD15-1AV0 | 3RA1225-1AD23-1AV0 OR 3RA1225-0KD23-1AV0 |
| SCER334-1MG10Q4 | 3RA1215-1AD15-1BP4 OR 3RA1215-0KD15-1BP4 | 3RA1225-1AD23-1BP4 OR 3RA1225-0KD23-1BP4 |
| SCER334-1MG10U1 | 3RA1215-1AD15-1AU6 OR 3RA1215-0KD15-1AU6 | 3RA1225-1AD23-1AU6 OR 3RA1225-0KD23-1AU6 |
| SCER334-1MG10W4 | 3RA1215-1AD15-1BW4 OR 3RA1215-0KD15-1BW4 | 3RA1225-1AD23-1BW4 OR 3RA1225-0KD23-1BW4 |
| SCER334-1MH10A4 | 3RA1215-1CD15-1BA4 OR 3RA1215-1BD15-1BA4 | 3RA1225-1CD23-1BA4 OR 3RA1225-1BD23-1BA4 |
| SCER334-1MH10B4 | 3RA1215-1CD15-1BB4 OR 3RA1215-1BD15-1BB4 | 3RA1225-1CD23-1BB4 OR 3RA1225-1BD23-1BB4 |
| SCER334-1MH10C2 | 3RA1215-1CD15-1AC2 OR 3RA1215-1BD15-1AC2 | 3RA1225-1CD23-1AC2 OR 3RA1225-1BD23-1AC2 |
| SCER334-1MH10G4 | 3RA1215-1CD15-1BG4 OR 3RA1215-1BD15-1BG4 | 3RA1225-1CD23-1BG4 OR 3RA1225-1BD23-1BG4 |
| SCER334-1MH10K6 | 3RA1215-1CD15-1AK6 OR 3RA1215-1BD15-1AK6 | 3RA1225-1CD23-1AK6 OR 3RA1225-1BD23-1AK6 |
| SCER334-1MH10M1 | 3RA1215-1CD15-1AM2 OR 3RA1215-1BD15-1AM2 | 3RA1225-1CD23-1AM2 OR 3RA1225-1BD23-1AM2 |
| SCER334-1MH10P6 | 3RA1215-1CD15-1AP6 OR 3RA1215-1BD15-1AP6 | 3RA1225-1CD23-1AP6 OR 3RA1225-1BD23-1AP6 |
| SCER334-1MH10Q0 | 3RA1215-1CD15-1AV0 OR 3RA1215-1BD15-1AV0 | 3RA1225-1CD23-1AV0 OR 3RA1225-1BD23-1AV0 |
| SCER334-1MH10Q4 | 3RA1215-1CD15-1BP4 OR 3RA1215-1BD15-1BP4 | 3RA1225-1CD23-1BP4 OR 3RA1225-1BD23-1BP4 |
| SCER334-1MH10U1 | 3RA1215-1CD15-1AU6 OR 3RA1215-1BD15-1AU6 | 3RA1225-1CD23-1AU6 OR 3RA1225-1BD23-1AU6 |
| SCER334-1MH10W4 | 3RA1215-1CD15-1BW4 OR 3RA1215-1BD15-1BW4 | 3RA1225-1CD23-1BW4 OR 3RA1225-1BD23-1BW4 |
| SCER334-1MJ10A4 | 3RA1215-1ED15-1BA4 OR 3RA1215-1DD15-1BA4 | 3RA1225-1ED23-1BA4 OR 3RA1225-1DD23-1BA4 |
| SCER334-1MJ10B4 | 3RA1215-1ED15-1BB4 OR 3RA1215-1DD15-1BB4 | 3RA1225-1ED23-1BB4 OR 3RA1225-1DD23-1BB4 |
| SCER334-1MJ10C2 | 3RA1215-1ED15-1AC2 OR 3RA1215-1DD15-1AC2 | 3RA1225-1ED23-1AC2 OR 3RA1225-1DD23-1AC2 |
| SCER334-1MJ10G4 | 3RA1215-1ED15-1BG4 OR 3RA1215-1DD15-1BG4 | 3RA1225-1ED23-1BG4 OR 3RA1225-1DD23-1BG4 |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| SCER334-1MJ10K6 | 3RA1215-1ED15-1AK6 OR 3RA1215-1DD15-1AK6 | 3RA1225-1ED23-1AK6 OR 3RA1225-1DD23-1AK6 |
| SCER334-1MJ10M1 | 3RA1215-1ED15-1AM2 OR 3RA1215-1DD15-1AM2 | 3RA1225-1ED23-1AM2 OR 3RA1225-1DD23-1AM2 |
| SCER334-1MJ10P6 | 3RA1215-1ED15-1AP6 OR 3RA1215-1DD15-1AP6 | 3RA1225-1ED23-1AP6 OR 3RA1225-1DD23-1AP6 |
| SCER334-1MJ10Q0 | 3RA1215-1ED15-1AV0 OR 3RA1215-1DD15-1AV0 | 3RA1225-1ED23-1AV0 OR 3RA1225-1DD23-1AV0 |
| SCER334-1MJ10Q4 | 3RA1215-1ED15-1BP4 OR 3RA1215-1DD15-1BP4 | 3RA1225-1ED23-1BP4 OR 3RA1225-1DD23-1BP4 |
| SCER334-1MJ10U1 | 3RA1215-1ED15-1AU6 OR 3RA1215-1DD15-1AU6 | 3RA1225-1ED23-1AU6 OR 3RA1225-1DD23-1AU6 |
| SCER334-1MJ10W4 | 3RA1215-1ED15-1BW4 OR 3RA1215-1DD15-1BW4 | 3RA1225-1ED23-1BW4 OR 3RA1225-1DD23-1BW4 |
| SCER334-1MK10A4 | 3RA1215-1GD15-1BA4 OR 3RA1215-1FD15-1BA4 | 3RA1225-1GD23-1BA4 OR 3RA1225-1FD23-1BA4 |
| SCER334-1MK10B4 | 3RA1215-1GD15-1BB4 OR 3RA1215-1FD15-1BB4 | 3RA1225-1GD23-1BB4 OR 3RA1225-1FD23-1BB4 |
| SCER334-1MK10C2 | 3RA1215-1GD15-1AC2 OR 3RA1215-1FD15-1AC2 | 3RA1225-1GD23-1AC2 OR 3RA1225-1FD23-1AC2 |
| SCER334-1MK10G4 | 3RA1215-1GD15-1BG4 OR 3RA1215-1FD15-1BG4 | 3RA1225-1GD23-1BG4 OR 3RA1225-1FD23-1BG4 |
| SCER334-1MK10K6 | 3RA1215-1GD15-1AK6 OR 3RA1215-1FD15-1AK6 | 3RA1225-1GD23-1AK6 OR 3RA1225-1FD23-1AK6 |
| SCER334-1MK10M1 | 3RA1215-1GD15-1AM2 OR 3RA1215-1FD15-1AM2 | 3RA1225-1GD23-1AM2 OR 3RA1225-1FD23-1AM2 |
| SCER334-1MK10P6 | 3RA1215-1GD15-1AP6 OR 3RA1215-1FD15-1AP6 | 3RA1225-1GD23-1AP6 OR 3RA1225-1FD23-1AP6 |
| SCER334-1MK10Q0 | 3RA1215-1GD15-1AV0 OR 3RA1215-1FD15-1AV0 | 3RA1225-1GD23-1AV0 OR 3RA1225-1FD23-1AV0 |
| SCER334-1MK10Q4 | 3RA1215-1GD15-1BP4 OR 3RA1215-1FD15-1BP4 | 3RA1225-1GD23-1BP4 OR 3RA1225-1FD23-1BP4 |
| SCER334-1MK10U1 | 3RA1215-1GD15-1AU6 OR 3RA1215-1FD15-1AU6 | 3RA1225-1GD23-1AU6 OR 3RA1225-1FD23-1AU6 |
| SCER334-1MK10W4 | 3RA1215-1GD15-1BW4 OR 3RA1215-1FD15-1BW4 | 3RA1225-1GD23-1BW4 OR 3RA1225-1FD23-1BW4 |
| SCER334-1ML10A4 | 3RA1225-1JD24-1BA4 OR 3RA1215-1HD16-1BA4 | |
| SCER334-1ML10B4 | 3RA1225-1JD24-1BB4 OR 3RA1215-1HD16-1BB4 | |
| SCER334-1ML10C2 | 3RA1225-1JD24-1AC2 OR 3RA1215-1HD16-1AC2 | |
| SCER334-1ML10G4 | 3RA1225-1JD24-1BG4 OR 3RA1215-1HD16-1BG4 | |
| SCER334-1ML10K6 | 3RA1225-1JD24-1AK6 OR 3RA1215-1HD16-1AK6 | |
| SCER334-1ML10M1 | 3RA1225-1JD24-1AM2 OR 3RA1215-1HD16-1AM2 | |
| SCER334-1ML10P6 | 3RA1225-1JD24-1AP6 OR 3RA1215-1HD16-1AP6 | |
| SCER334-1ML10Q0 | 3RA1225-1JD24-1AV0 OR 3RA1215-1HD16-1AV0 | |
| SCER334-1ML10Q4 | 3RA1225-1JD24-1BP4 OR 3RA1215-1HD16-1BP4 | |
| SCER334-1ML10U1 | 3RA1225-1JD24-1AU6 OR 3RA1215-1HD16-1AU6 | |
| SCER334-1ML10W4 | 3RA1225-1JD24-1BW4 OR 3RA1215-1HD16-1BW4 | |
| SCER334-1MM10A4 | 3RA1225-4AD25-1BA4 OR 3RA1225-1KD23-1BA4 | |
| SCER334-1MM10B4 | 3RA1225-4AD25-1BB4 OR 3RA1225-1KD23-1BB4 | |
| SCER334-1MM10C2 | 3RA1225-4AD25-1AC2 OR 3RA1225-1KD23-1AC2 | |
| SCER334-1MM10G4 | 3RA1225-4AD25-1BG4 OR 3RA1225-1KD23-1BG4 | |
| SCER334-1MM10K6 | 3RA1225-4AD25-1AK6 OR 3RA1225-1KD23-1AK6 | |
| SCER334-1MM10M1 | 3RA1225-4AD25-1AM2 OR 3RA1225-1KD23-1AM2 | |
| SCER334-1MM10P6 | 3RA1225-4AD25-1AP6 OR 3RA1225-1KD23-1AP6 | |
| SCER334-1MM10Q0 | 3RA1225-4AD25-1AV0 OR 3RA1225-1KD23-1AV0 | |
| SCER334-1MM10Q4 | 3RA1225-4AD25-1BP4 OR 3RA1225-1KD23-1BP4 | |
| SCER334-1MM10U1 | 3RA1225-4AD25-1AU6 OR 3RA1225-1KD23-1AU6 | |
| SCER334-1MM10W4 | 3RA1225-4AD25-1BW4 OR 3RA1225-1KD23-1BW4 | |
| SCER634-1MG10A4 | 3RA1215-1AD15-1BA4 OR 3RA1215-0KD15-1BA4 | 3RA1225-1AD23-1BA4 OR 3RA1225-0KD23-1BA4 |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| SCER634-1MG10B4 | 3RA1215-1AD15-1BB4 OR 3RA1215-0KD15-1BB4 | 3RA1225-1AD23-1BB4 OR 3RA1225-0KD23-1BB4 |
| SCER634-1MG10C2 | 3RA1215-1AD15-1AC2 OR 3RA1215-0KD15-1AC2 | 3RA1225-1AD23-1AC2 OR 3RA1225-0KD23-1AC2 |
| SCER634-1MG10G4 | 3RA1215-1AD15-1BG4 OR 3RA1215-0KD15-1BG4 | 3RA1225-1AD23-1BG4 OR 3RA1225-0KD23-1BG4 |
| SCER634-1MG10K6 | 3RA1215-1AD15-1AK6 OR 3RA1215-0KD15-1AK6 | 3RA1225-1AD23-1AK6 OR 3RA1225-0KD23-1AK6 |
| SCER634-1MG10M1 | 3RA1215-1AD15-1AM2 OR 3RA1215-0KD15-1AM2 | 3RA1225-1AD23-1AM2 OR 3RA1225-0KD23-1AM2 |
| SCER634-1MG10P6 | 3RA1215-1AD15-1AP6 OR 3RA1215-0KD15-1AP6 | 3RA1225-1AD23-1AP6 OR 3RA1225-0KD23-1AP6 |
| SCER634-1MG10Q0 | 3RA1215-1AD15-1AV0 OR 3RA1215-0KD15-1AV0 | 3RA1225-1AD23-1AV0 OR 3RA1225-0KD23-1AV0 |
| SCER634-1MG10Q4 | 3RA1215-1AD15-1BP4 OR 3RA1215-0KD15-1BP4 | 3RA1225-1AD23-1BP4 OR 3RA1225-0KD23-1BP4 |
| SCER634-1MG10U1 | 3RA1215-1AD15-1AU6 OR 3RA1215-0KD15-1AU6 | 3RA1225-1AD23-1AU6 OR 3RA1225-0KD23-1AU6 |
| SCER634-1MG10W4 | 3RA1215-1AD15-1BW4 OR 3RA1215-0KD15-1BW4 | 3RA1225-1AD23-1BW4 OR 3RA1225-0KD23-1BW4 |
| SCER634-1MH10A4 | 3RA1215-1CD15-1BA4 OR 3RA1215-1BD15-1BA4 | 3RA1225-1CD23-1BA4 OR 3RA1225-1BD23-1BA4 |
| SCER634-1MH10B4 | 3RA1215-1CD15-1BB4 OR 3RA1215-1BD15-1BB4 | 3RA1225-1CD23-1BB4 OR 3RA1225-1BD23-1BB4 |
| SCER634-1MH10C2 | 3RA1215-1CD15-1AC2 OR 3RA1215-1BD15-1AC2 | 3RA1225-1CD23-1AC2 OR 3RA1225-1BD23-1AC2 |
| SCER634-1MH10G4 | 3RA1215-1CD15-1BG4 OR 3RA1215-1BD15-1BG4 | 3RA1225-1CD23-1BG4 OR 3RA1225-1BD23-1BG4 |
| SCER634-1MH10K6 | 3RA1215-1CD15-1AK6 OR 3RA1215-1BD15-1AK6 | 3RA1225-1CD23-1AK6 OR 3RA1225-1BD23-1AK6 |
| SCER634-1MH10M1 | 3RA1215-1CD15-1AM2 OR 3RA1215-1BD15-1AM2 | 3RA1225-1CD23-1AM2 OR 3RA1225-1BD23-1AM2 |
| SCER634-1MH10P6 | 3RA1215-1CD15-1AP6 OR 3RA1215-1BD15-1AP6 | 3RA1225-1CD23-1AP6 OR 3RA1225-1BD23-1AP6 |
| SCER634-1MH10Q0 | 3RA1215-1CD15-1AV0 OR 3RA1215-1BD15-1AV0 | 3RA1225-1CD23-1AV0 OR 3RA1225-1BD23-1AV0 |
| SCER634-1MH10Q4 | 3RA1215-1CD15-1BP4 OR 3RA1215-1BD15-1BP4 | 3RA1225-1CD23-1BP4 OR 3RA1225-1BD23-1BP4 |
| SCER634-1MH10U1 | 3RA1215-1CD15-1AU6 OR 3RA1215-1BD15-1AU6 | 3RA1225-1CD23-1AU6 OR 3RA1225-1BD23-1AU6 |
| SCER634-1MH10W4 | 3RA1215-1CD15-1BW4 OR 3RA1215-1BD15-1BW4 | 3RA1225-1CD23-1BW4 OR 3RA1225-1BD23-1BW4 |
| SCER634-1MJ10A4 | 3RA1215-1ED15-1BA4 OR 3RA1215-1DD15-1BA4 | 3RA1225-1ED23-1BA4 OR 3RA1225-1DD23-1BA4 |
| SCER634-1MJ10B4 | 3RA1215-1ED15-1BB4 OR 3RA1215-1DD15-1BB4 | 3RA1225-1ED23-1BB4 OR 3RA1225-1DD23-1BB4 |
| SCER634-1MJ10C2 | 3RA1215-1ED15-1AC2 OR 3RA1215-1DD15-1AC2 | 3RA1225-1ED23-1AC2 OR 3RA1225-1DD23-1AC2 |
| SCER634-1MJ10G4 | 3RA1215-1ED15-1BG4 OR 3RA1215-1DD15-1BG4 | 3RA1225-1ED23-1BG4 OR 3RA1225-1DD23-1BG4 |
| SCER634-1MJ10K6 | 3RA1215-1ED15-1AK6 OR 3RA1215-1DD15-1AK6 | 3RA1225-1ED23-1AK6 OR 3RA1225-1DD23-1AK6 |
| SCER634-1MJ10M1 | 3RA1215-1ED15-1AM2 OR 3RA1215-1DD15-1AM2 | 3RA1225-1ED23-1AM2 OR 3RA1225-1DD23-1AM2 |
| SCER634-1MJ10P6 | 3RA1215-1ED15-1AP6 OR 3RA1215-1DD15-1AP6 | 3RA1225-1ED23-1AP6 OR 3RA1225-1DD23-1AP6 |
| SCER634-1MJ10Q0 | 3RA1215-1ED15-1AV0 OR 3RA1215-1DD15-1AV0 | 3RA1225-1ED23-1AV0 OR 3RA1225-1DD23-1AV0 |
| SCER634-1MJ10Q4 | 3RA1215-1ED15-1BP4 OR 3RA1215-1DD15-1BP4 | 3RA1225-1ED23-1BP4 OR 3RA1225-1DD23-1BP4 |
| SCER634-1MJ10U1 | 3RA1215-1ED15-1AU6 OR 3RA1215-1DD15-1AU6 | 3RA1225-1ED23-1AU6 OR 3RA1225-1DD23-1AU6 |
| SCER634-1MJ10W4 | 3RA1215-1ED15-1BW4 OR 3RA1215-1DD15-1BW4 | 3RA1225-1ED23-1BW4 OR 3RA1225-1DD23-1BW4 |
| SCER634-1MK10A4 | 3RA1215-1GD15-1BA4 OR 3RA1215-1FD15-1BA4 | 3RA1225-1GD23-1BA4 OR 3RA1225-1FD23-1BA4 |
| SCER634-1MK10B4 | 3RA1215-1GD15-1BB4 OR 3RA1215-1FD15-1BB4 | 3RA1225-1GD23-1BB4 OR 3RA1225-1FD23-1BB4 |
| SCER634-1MK10C2 | 3RA1215-1GD15-1AC2 OR 3RA1215-1FD15-1AC2 | 3RA1225-1GD23-1AC2 OR 3RA1225-1FD23-1AC2 |
| SCER634-1MK10G4 | 3RA1215-1GD15-1BG4 OR 3RA1215-1FD15-1BG4 | 3RA1225-1GD23-1BG4 OR 3RA1225-1FD23-1BG4 |
| SCER634-1MK10K6 | 3RA1215-1GD15-1AK6 OR 3RA1215-1FD15-1AK6 | 3RA1225-1GD23-1AK6 OR 3RA1225-1FD23-1AK6 |
| SCER634-1MK10M1 | 3RA1215-1GD15-1AM2 OR 3RA1215-1FD15-1AM2 | 3RA1225-1GD23-1AM2 OR 3RA1225-1FD23-1AM2 |
| SCER634-1MK10P6 | 3RA1215-1GD15-1AP6 OR 3RA1215-1FD15-1AP6 | 3RA1225-1GD23-1AP6 OR 3RA1225-1FD23-1AP6 |
| SCER634-1MK10Q0 | 3RA1215-1GD15-1AV0 OR 3RA1215-1FD15-1AV0 | 3RA1225-1GD23-1AV0 OR 3RA1225-1FD23-1AV0 |
| SCER634-1MK10Q4 | 3RA1215-1GD15-1BP4 OR 3RA1215-1FD15-1BP4 | 3RA1225-1GD23-1BP4 OR 3RA1225-1FD23-1BP4 |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| SCER634-1MK10U1 | 3RA1215-1GD15-1AU6 OR 3RA1215-1FD15-1AU6 | 3RA1225-1GD23-1AU6 OR 3RA1225-1FD23-1AU6 |
| SCER634-1MK10W4 | 3RA1215-1GD15-1BW4 OR 3RA1215-1FD15-1BW4 | 3RA1225-1GD23-1BW4 OR 3RA1225-1FD23-1BW4 |
| SCER634-1ML10A4 | 3RA1225-1JD24-1BA4 OR 3RA1215-1HD16-1BA4 | |
| SCER634-1ML10B4 | 3RA1225-1JD24-1BB4 OR 3RA1215-1HD16-1BB4 | |
| SCER634-1ML10C2 | 3RA1225-1JD24-1AC2 OR 3RA1215-1HD16-1AC2 | |
| SCER634-1ML10G4 | 3RA1225-1JD24-1BG4 OR 3RA1215-1HD16-1BG4 | |
| SCER634-1ML10K6 | 3RA1225-1JD24-1AK6 OR 3RA1215-1HD16-1AK6 | |
| SCER634-1ML10M1 | 3RA1225-1JD24-1AM2 OR 3RA1215-1HD16-1AM2 | |
| SCER634-1ML10P6 | 3RA1225-1JD24-1AP6 OR 3RA1215-1HD16-1AP6 | |
| SCER634-1ML10Q0 | 3RA1225-1JD24-1AV0 OR 3RA1215-1HD16-1AV0 | |
| SCER634-1ML10Q4 | 3RA1225-1JD24-1BP4 OR 3RA1215-1HD16-1BP4 | |
| SCER634-1ML10U1 | 3RA1225-1JD24-1AU6 OR 3RA1215-1HD16-1AU6 | |
| SCER634-1ML10W4 | 3RA1225-1JD24-1BW4 OR 3RA1215-1HD16-1BW4 | |
| SCER634-1MM10A4 | 3RA1225-4AD25-1BA4 OR 3RA1225-1KD23-1BA4 | |
| SCER634-1MM10B4 | 3RA1225-4AD25-1BB4 OR 3RA1225-1KD23-1BB4 | |
| SCER634-1MM10C2 | 3RA1225-4AD25-1AC2 OR 3RA1225-1KD23-1AC2 | |
| SCER634-1MM10G4 | 3RA1225-4AD25-1BG4 OR 3RA1225-1KD23-1BG4 | |
| SCER634-1MM10K6 | 3RA1225-4AD25-1AK6 OR 3RA1225-1KD23-1AK6 | |
| SCER634-1MM10M1 | 3RA1225-4AD25-1AM2 OR 3RA1225-1KD23-1AM2 | |
| SCER634-1MM10P6 | 3RA1225-4AD25-1AP6 OR 3RA1225-1KD23-1AP6 | |
| SCER634-1MM10Q0 | 3RA1225-4AD25-1AV0 OR 3RA1225-1KD23-1AV0 | |
| SCER634-1MM10Q4 | 3RA1225-4AD25-1BP4 OR 3RA1225-1KD23-1BP4 | |
| SCER634-1MM10U1 | 3RA1225-4AD25-1AU6 OR 3RA1225-1KD23-1AU6 | |
| SCER634-1MM10W4 | 3RA1225-4AD25-1BW4 OR 3RA1225-1KD23-1BW4 | |
| SCER634-1MN10A4 | 3RA1225-4BD26-1BA4 | |
| SCER634-1MN10B4 | 3RA1225-4BD26-1BB4 | |
| SCER634-1MN10C2 | 3RA1225-4BD26-1AC2 | |
| SCER634-1MN10G4 | 3RA1225-4BD26-1BG4 | |
| SCER634-1MN10K6 | 3RA1225-4BD26-1AK6 | |
| SCER634-1MN10M1 | 3RA1225-4BD26-1AM2 | |
| SCER634-1MN10P6 | 3RA1225-4BD26-1AP6 | |
| SCER634-1MN10Q0 | 3RA1225-4BD26-1AV0 | |
| SCER634-1MN10Q4 | 3RA1225-4BD26-1BP4 | |
| SCER634-1MN10U1 | 3RA1225-4BD26-1AU6 | |
| SCER634-1MN10W4 | 3RA1225-4BD26-1BW4 | |
| SCER634-1MP10A4 | 3RA1235-4ED34-1BA4 | |
| SCER634-1MP10B4 | 3RA1235-4ED34-1BB4 | |
| SCER634-1MP10C2 | 3RA1235-4ED34-1AC2 | |
| SCER634-1MP10G4 | 3RA1235-4ED34-1BG4 | |
| SCER634-1MP10K6 | 3RA1235-4ED34-1AK6 | |
| SCER634-1MP10M1 | 3RA1235-4ED34-1AM2 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| SCER634-1MP10P6 | 3RA1235-4ED34-1AP6 | |
| SCER634-1MP10Q0 | 3RA1235-4ED34-1AV0 | |
| SCER634-1MP10Q4 | 3RA1235-4ED34-1BP4 | |
| SCER634-1MP10U1 | 3RA1235-4ED34-1AU6 | |
| SCER634-1MP10W4 | 3RA1235-4ED34-1BW4 | |
| SMDBG024 | 3RA1115-1AD15-1AB0 OR 3RA1115-0KD15-1AB0 | 3RA1125-1AD23-1AC2 OR 3RA1125-0KD23-1AC2 |
| SMDBG120 | 3RA1115-1AD15-1AK6 OR 3RA1115-0KD15-1AK6 | 3RA1125-1AD23-1AK6 OR 3RA1125-0KD23-1AK6 |
| SMDBG208 | 3RA1115-1AD15-1AM2 OR 3RA1115-0KD15-1AM2 | 3RA1125-1AD23-1AM2 OR 3RA1125-0KD23-1AM2 |
| SMDBG240 | 3RA1115-1AD15-1AP6 OR 3RA1115-0KD15-1AP6 | 3RA1125-1AD23-1AP6 OR 3RA1125-0KD23-1AP6 |
| SMDBG277 | 3RA1115-1AD15-1AU6 OR 3RA1115-0KD15-1AU6 | 3RA1125-1AD23-1AU6 OR 3RA1125-0KD23-1AU6 |
| SMDBG480 | 3RA1115-1AD15-1AV6 OR 3RA1115-0KD15-1AV6 | 3RA1125-1AD23-1AV6 OR 3RA1125-0KD23-1AV6 |
| SMDBH024 | 3RA1115-1CD15-1AB0 OR 3RA1115-1BD15-1AB0 | 3RA1125-1CD23-1AC2 OR 3RA1125-1BD23-1AC2 |
| SMDBH120 | 3RA1115-1CD15-1AK6 OR 3RA1115-1BD15-1AK6 | 3RA1125-1CD23-1AK6 OR 3RA1125-1BD23-1AK6 |
| SMDBH208 | 3RA1115-1CD15-1AM2 OR 3RA1115-1BD15-1AM2 | 3RA1125-1CD23-1AM2 OR 3RA1125-1BD23-1AM2 |
| SMDBH240 | 3RA1115-1CD15-1AP6 OR 3RA1115-1BD15-1AP6 | 3RA1125-1CD23-1AP6 OR 3RA1125-1BD23-1AP6 |
| SMDBH277 | 3RA1115-1CD15-1AU6 OR 3RA1115-1BD15-1AU6 | 3RA1125-1CD23-1AU6 OR 3RA1125-1BD23-1AU6 |
| SMDBH480 | 3RA1115-1CD15-1AV6 OR 3RA1115-1BD15-1AV6 | 3RA1125-1CD23-1AV6 OR 3RA1125-1BD23-1AV6 |
| SMDBJ024 | 3RA1115-1ED15-1AB0 OR 3RA1115-1DD15-1AB0 | 3RA1125-1ED23-1AC2 OR 3RA1125-1DD23-1AC2 |
| SMDBJ120 | 3RA1115-1ED15-1AK6 OR 3RA1115-1DD15-1AK6 | 3RA1125-1ED23-1AK6 OR 3RA1125-1DD23-1AK6 |
| SMDBJ208 | 3RA1115-1ED15-1AM2 OR 3RA1115-1DD15-1AM2 | 3RA1125-1ED23-1AM2 OR 3RA1125-1DD23-1AM2 |
| SMDBJ240 | 3RA1115-1ED15-1AP6 OR 3RA1115-1DD15-1AP6 | 3RA1125-1ED23-1AP6 OR 3RA1125-1DD23-1AP6 |
| SMDBJ277 | 3RA1115-1ED15-1AU6 OR 3RA1115-1DD15-1AU6 | 3RA1125-1ED23-1AU6 OR 3RA1125-1DD23-1AU6 |
| SMDBJ480 | 3RA1115-1ED15-1AV6 OR 3RA1115-1DD15-1AV6 | 3RA1125-1ED23-1AV6 OR 3RA1125-1DD23-1AV6 |
| SMDBK024 | 3RA1115-1GD15-1AB0 OR 3RA1115-1FD15-1AB0 | 3RA1125-1GD23-1AC2 OR 3RA1125-1FD23-1AC2 |
| SMDBK120 | 3RA1115-1GD15-1AK6 OR 3RA1115-1FD15-1AK6 | 3RA1125-1GD23-1AK6 OR 3RA1125-1FD23-1AK6 |
| SMDBK208 | 3RA1115-1GD15-1AM2 OR 3RA1115-1FD15-1AM2 | 3RA1125-1GD23-1AM2 OR 3RA1125-1FD23-1AM2 |
| SMDBK240 | 3RA1115-1GD15-1AP6 OR 3RA1115-1FD15-1AP6 | 3RA1125-1GD23-1AP6 OR 3RA1125-1FD23-1AP6 |
| SMDBK277 | 3RA1115-1GD15-1AU6 OR 3RA1115-1FD15-1AU6 | 3RA1125-1GD23-1AU6 OR 3RA1125-1FD23-1AU6 |
| SMDBK480 | 3RA1115-1GD15-1AV6 OR 3RA1115-1FD15-1AV6 | 3RA1125-1GD23-1AV6 OR 3RA1125-1FD23-1AV6 |
| SMDBL024 | 3RA1125-1JD24-1AC2 OR 3RA1115-1HD16-1AB0 | |
| SMDBL120 | 3RA1125-1JD24-1AK6 OR 3RA1115-1HD16-1AK6 | |
| SMDBL208 | 3RA1125-1JD24-1AM2 OR 3RA1115-1HD16-1AM2 | |
| SMDBL240 | 3RA1125-1JD24-1AP6 OR 3RA1115-1HD16-1AP6 | |
| SMDBL277 | 3RA1125-1JD24-1AU6 OR 3RA1115-1HD16-1AU6 | |
| SMDBL480 | 3RA1125-1JD24-1AV6 OR 3RA1115-1HD16-1AV6 | |
| SMDCG024 | 3RA1115-1AD15-1AB0 OR 3RA1115-0KD15-1AB0 | 3RA1125-1AD23-1AC2 OR 3RA1125-0KD23-1AC2 |
| SMDCG120 | 3RA1115-1AD15-1AK6 OR 3RA1115-0KD15-1AK6 | 3RA1125-1AD23-1AK6 OR 3RA1125-0KD23-1AK6 |
| SMDCG208 | 3RA1115-1AD15-1AM2 OR 3RA1115-0KD15-1AM2 | 3RA1125-1AD23-1AM2 OR 3RA1125-0KD23-1AM2 |
| SMDCG240 | 3RA1115-1AD15-1AP6 OR 3RA1115-0KD15-1AP6 | 3RA1125-1AD23-1AP6 OR 3RA1125-0KD23-1AP6 |
| SMDCG277 | 3RA1115-1AD15-1AU6 OR 3RA1115-0KD15-1AU6 | 3RA1125-1AD23-1AU6 OR 3RA1125-0KD23-1AU6 |
| SMDCG480 | 3RA1115-1AD15-1AV6 OR 3RA1115-0KD15-1AV6 | 3RA1125-1AD23-1AV6 OR 3RA1125-0KD23-1AV6 |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| SMDCH024 | 3RA1115-1CD15-1AB0 OR 3RA1115-1BD15-1AB0 | 3RA1125-1CD23-1AC2 OR 3RA1125-1BD23-1AC2 |
| SMDCH120 | 3RA1115-1CD15-1AK6 OR 3RA1115-1BD15-1AK6 | 3RA1125-1CD23-1AK6 OR 3RA1125-1BD23-1AK6 |
| SMDCH208 | 3RA1115-1CD15-1AM2 OR 3RA1115-1BD15-1AM2 | 3RA1125-1CD23-1AM2 OR 3RA1125-1BD23-1AM2 |
| SMDCH240 | 3RA1115-1CD15-1AP6 OR 3RA1115-1BD15-1AP6 | 3RA1125-1CD23-1AP6 OR 3RA1125-1BD23-1AP6 |
| SMDCH277 | 3RA1115-1CD15-1AU6 OR 3RA1115-1BD15-1AU6 | 3RA1125-1CD23-1AU6 OR 3RA1125-1BD23-1AU6 |
| SMDCH480 | 3RA1115-1CD15-1AV6 OR 3RA1115-1BD15-1AV6 | 3RA1125-1CD23-1AV6 OR 3RA1125-1BD23-1AV6 |
| SMDCJ024 | 3RA1115-1ED15-1AB0 OR 3RA1115-1DD15-1AB0 | 3RA1125-1ED23-1AC2 OR 3RA1125-1DD23-1AC2 |
| SMDCJ120 | 3RA1115-1ED15-1AK6 OR 3RA1115-1DD15-1AK6 | 3RA1125-1ED23-1AK6 OR 3RA1125-1DD23-1AK6 |
| SMDCJ208 | 3RA1115-1ED15-1AM2 OR 3RA1115-1DD15-1AM2 | 3RA1125-1ED23-1AM2 OR 3RA1125-1DD23-1AM2 |
| SMDCJ240 | 3RA1115-1ED15-1AP6 OR 3RA1115-1DD15-1AP6 | 3RA1125-1ED23-1AP6 OR 3RA1125-1DD23-1AP6 |
| SMDCJ277 | 3RA1115-1ED15-1AU6 OR 3RA1115-1DD15-1AU6 | 3RA1125-1ED23-1AU6 OR 3RA1125-1DD23-1AU6 |
| SMDCJ480 | 3RA1115-1ED15-1AV6 OR 3RA1115-1DD15-1AV6 | 3RA1125-1ED23-1AV6 OR 3RA1125-1DD23-1AV6 |
| SMDCK024 | 3RA1115-1GD15-1AB0 OR 3RA1115-1FD15-1AB0 | 3RA1125-1GD23-1AC2 OR 3RA1125-1FD23-1AC2 |
| SMDCK120 | 3RA1115-1GD15-1AK6 OR 3RA1115-1FD15-1AK6 | 3RA1125-1GD23-1AK6 OR 3RA1125-1FD23-1AK6 |
| SMDCK208 | 3RA1115-1GD15-1AM2 OR 3RA1115-1FD15-1AM2 | 3RA1125-1GD23-1AM2 OR 3RA1125-1FD23-1AM2 |
| SMDCK240 | 3RA1115-1GD15-1AP6 OR 3RA1115-1FD15-1AP6 | 3RA1125-1GD23-1AP6 OR 3RA1125-1FD23-1AP6 |
| SMDCK277 | 3RA1115-1GD15-1AU6 OR 3RA1115-1FD15-1AU6 | 3RA1125-1GD23-1AU6 OR 3RA1125-1FD23-1AU6 |
| SMDCK480 | 3RA1115-1GD15-1AV6 OR 3RA1115-1FD15-1AV6 | 3RA1125-1GD23-1AV6 OR 3RA1125-1FD23-1AV6 |
| SMDCL024 | 3RA1125-1JD24-1AC2 OR 3RA1115-1HD16-1AB0 | |
| SMDCL120 | 3RA1125-1JD24-1AK6 OR 3RA1115-1HD16-1AK6 | |
| SMDCL208 | 3RA1125-1JD24-1AM2 OR 3RA1115-1HD16-1AM2 | |
| SMDCL240 | 3RA1125-1JD24-1AP6 OR 3RA1115-1HD16-1AP6 | |
| SMDCL277 | 3RA1125-1JD24-1AU6 OR 3RA1115-1HD16-1AU6 | |
| SMDCL480 | 3RA1125-1JD24-1AV6 OR 3RA1115-1HD16-1AV6 | |
| SMDCM024 | 3RA1125-4AD25-1AC2 OR 3RA1125-1KD23-1AC2 | |
| SMDCM120 | 3RA1125-4AD25-1AK6 OR 3RA1125-1KD23-1AK6 | |
| SMDCM208 | 3RA1125-4AD25-1AM2 OR 3RA1125-1KD23-1AM2 | |
| SMDCM240 | 3RA1125-4AD25-1AP6 OR 3RA1125-1KD23-1AP6 | |
| SMDCM277 | 3RA1125-4AD25-1AU6 OR 3RA1125-1KD23-1AU6 | |
| SMDCM480 | 3RA1125-4AD25-1AV6 OR 3RA1125-1KD23-1AV6 | |
| SMDCN024 | 3RA1135-4DD33-1AC2 OR 3RA1125-4CD26-1AC2 | |
| SMDCN120 | 3RA1135-4DD33-1AK6 OR 3RA1125-4CD26-1AK6 | |
| SMDCN208 | 3RA1135-4DD33-1AM2 OR 3RA1125-4CD26-1AM2 | |
| SMDCN240 | 3RA1135-4DD33-1AP6 OR 3RA1125-4CD26-1AP6 | |
| SMDCN277 | 3RA1135-4DD33-1AU6 OR 3RA1125-4CD26-1AU6 | |
| SMDCN480 | 3RA1135-4DD33-1AV6 OR 3RA1125-4CD26-1AV6 | |
| SMDDB024 | 3RA1125-4BD26-1AC2 OR 3RA1125-4AD25-1AC2 | |
| SMDDB120 | 3RA1125-4BD26-1AK6 OR 3RA1125-4AD25-1AK6 | |
| SMDDB208 | 3RA1125-4BD26-1AM2 OR 3RA1125-4AD25-1AM2 | |
| SMDDB240 | 3RA1125-4BD26-1AP6 OR 3RA1125-4AD25-1AP6 | |
| SMDDB277 | 3RA1125-4BD26-1AU6 OR 3RA1125-4AD25-1AU6 | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| SMDDB480 | 3RA1125-4BD26-1AV6 OR 3RA1125-4AD25-1AV6 | |
| SMDDC024 | 3RA1135-4DD33-1AC2 OR 3RA1125-4CD26-1AC2 | |
| SMDDC120 | 3RA1135-4DD33-1AK6 OR 3RA1125-4CD26-1AK6 | |
| SMDDC208 | 3RA1135-4DD33-1AM2 OR 3RA1125-4CD26-1AM2 | |
| SMDDC240 | 3RA1135-4DD33-1AP6 OR 3RA1125-4CD26-1AP6 | |
| SMDDC277 | 3RA1135-4DD33-1AU6 OR 3RA1125-4CD26-1AU6 | |
| SMDDC480 | 3RA1135-4DD33-1AV6 OR 3RA1125-4CD26-1AV6 | |
| SMDDD024 | 3RA1135-4ED34-1AC2 OR 3RA1135-4DD33-1AC2 | |
| SMDDD120 | 3RA1135-4ED34-1AK6 OR 3RA1135-4DD33-1AK6 | |
| SMDDD208 | 3RA1135-4ED34-1AM2 OR 3RA1135-4DD33-1AM2 | |
| SMDDD240 | 3RA1135-4ED34-1AP6 OR 3RA1135-4DD33-1AP6 | |
| SMDDD277 | 3RA1135-4ED34-1AU6 OR 3RA1135-4DD33-1AU6 | |
| SMDDD480 | 3RA1135-4ED34-1AV6 OR 3RA1135-4DD33-1AV6 | |
| SMDDE024 | 3RA1135-4FD35-1AC2 OR 3RA1135-4ED34-1AC2 | |
| SMDDE120 | 3RA1135-4FD35-1AK6 OR 3RA1135-4ED34-1AK6 | |
| SMDDE208 | 3RA1135-4FD35-1AM2 OR 3RA1135-4ED34-1AM2 | |
| SMDDE240 | 3RA1135-4FD35-1AP6 OR 3RA1135-4ED34-1AP6 | |
| SMDDE277 | 3RA1135-4FD35-1AU6 OR 3RA1135-4ED34-1AU6 | |
| SMDDE480 | 3RA1135-4FD35-1AV6 OR 3RA1135-4ED34-1AV6 | |
| SMLB2600 | CONTACT SALES OFFICE | |
| SMLBG600 | CONTACT SALES OFFICE | |
| SMLC2600 | CONTACT SALES OFFICE | |
| SMLCG600 | CONTACT SALES OFFICE | |
| SMLD2600 | CONTACT SALES OFFICE | |
| SMLDG600 | CONTACT SALES OFFICE | |
| SMLE2600 | CONTACT SALES OFFICE | |
| SMLF2600 | CONTACT SALES OFFICE | |
| SMLFG600 | CONTACT SALES OFFICE | |
| SMLG2600 | CONTACT SALES OFFICE | |
| SMLG2700 | CONTACT SALES OFFICE | |
| SMLGG600 | CONTACT SALES OFFICE | |
| SMLGG700 | CONTACT SALES OFFICE | |
| SMLH2600 | CONTACT SALES OFFICE | |
| SMLH2700 | CONTACT SALES OFFICE | |
| SMLHG600 | CONTACT SALES OFFICE | |
| SMLHG700 | CONTACT SALES OFFICE | |
| SMLJ2600 | CONTACT SALES OFFICE | |
| SMLJ2700 | CONTACT SALES OFFICE | |
| SMLJG600 | CONTACT SALES OFFICE | |
| SMLJG700 | CONTACT SALES OFFICE | |
| SMLK2600 | CONTACT SALES OFFICE | |

**Note: These items are listed as a cross-reference only. Contact a Siemens Sales Office or see Siemens catalog CPPC-06000 for more information. When replacing any items, please verify that all associated components will work with the replacement part. To search for a full or partial catalog number, press Ctrl + F or Edit - Find on the menu.**

| Old Catalog Number | SIRIUS Replacement (First Option) | SIRIUS Replacement (Second Option if Listed) |
|---|---|---|
| SMLK2700 | CONTACT SALES OFFICE | |
| SMLKG600 | CONTACT SALES OFFICE | |
| SMLKG700 | CONTACT SALES OFFICE | |
| SMLL2600 | CONTACT SALES OFFICE | |
| SMLL2700 | CONTACT SALES OFFICE | |
| SMLLG600 | CONTACT SALES OFFICE | |
| SMLLG700 | CONTACT SALES OFFICE | |
| SMLM2600 | CONTACT SALES OFFICE | |
| SMLM2700 | CONTACT SALES OFFICE | |
| SMLMG600 | CONTACT SALES OFFICE | |
| SMLMG700 | CONTACT SALES OFFICE | |
| SMLN2600 | CONTACT SALES OFFICE | |
| SMLN2700 | CONTACT SALES OFFICE | |
| SMLNG600 | CONTACT SALES OFFICE | |
| SMLNG700 | CONTACT SALES OFFICE | |
| SMLP2600 | CONTACT SALES OFFICE | |
| SMLP2700 | CONTACT SALES OFFICE | |
| SMLPG600 | CONTACT SALES OFFICE | |
| SMLPG700 | CONTACT SALES OFFICE | |
| SMLQ2700 | CONTACT SALES OFFICE | |
| SMLQG700 | CONTACT SALES OFFICE | |
| SMLR2600 | CONTACT SALES OFFICE | |
| SMLR2700 | CONTACT SALES OFFICE | |
| SMLRG600 | CONTACT SALES OFFICE | |
| SMLRG700 | CONTACT SALES OFFICE | |
| SMLS2600 | CONTACT SALES OFFICE | |
| SMLS2700 | CONTACT SALES OFFICE | |
| SMLSG600 | CONTACT SALES OFFICE | |
| SMLSG700 | CONTACT SALES OFFICE | |
| SMLT2600 | CONTACT SALES OFFICE | |
| SMLTG600 | CONTACT SALES OFFICE | |
| SMLU2600 | CONTACT SALES OFFICE | |
| SMLUG600 | CONTACT SALES OFFICE | |

30
30

30

30
30
30
30
30
30

30
30
30
30
30
30
30
30
30
30
30
30
30
30
30
30
30
30
30
30
30
30
30
30
30
30
30